

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2010/11. Weekly Edition No. 33, Dated 19 August 2010.

Last Amendment: Weekly Edition No. 32, dated 12 August 2010.

K2696-71	- Old Glebe Island Bridge. Centre	33 52-09 S 151 11-14 E	F W	1 on upstream end and 1 on downstream end of old Glebe Island Bridge
		*	*				
K3304-374	-	17 26-43 S 140 44-91 E	Fl Y 2-5s	Yellow x on beacon	
	*	*	*	*	*	*	*
K3304-375	-	17 26-62 S 140 45-02 E	Fl Y 2-5s	Yellow x on beacon	
	*	*	*	*	*	*	*
K3304-376	-	17 26-74 S 140 45-23 E	Fl Y 2-5s	Yellow x on beacon	
	*	*	*	*	*	*	*
K3608-2	- Coles Bay. Breakwater (AMSA)	42 07-71 S 148 17-32 E	F Bu	9	3	..	2 neon tubes mounted vertically. TE 2010
							*
K4710-5	- Pinder Reef. S	17 36-26 S 177 24-19 E	Fl W 8s	6	6	White structure, black stripe	
							*
K4712-4	- Bekana (Mbekana) Island. S part	17 35-66 S 177 26-24 E	Fl(2)W 5s	1	2	Concrete pile 2	
							*

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 33 dated 19 August 2010

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from the UKHO website. To obtain a colour version of these diagrams go to: www.ukho.gov.uk - select **PRODUCTS AND SERVICES** - select **Maritime Safety Info** - select **Visit NMs page and Download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-10-PAGE149_Week01_2010.pdf)

VOLUME 2, NP 282, 2010/11

Published Wk 10/10

(Last Amendments: Weekly Edition No. 32 dated 12 August 2010)

RADAR BEACONS

PAGE 56, GUINEA.

72750 Conakry Lt Buoy.

Delete position and replace by: 9°27'·57N 13°43'·51W

(former amendment 29/10)

French Notice 29/20/10 (RSDRA2010000124707) 33/10

PAGE 69, INDIA.

Insert:

Sikka Creek SPM Racon 22°33'·53N 69°45'·75E **78823**

B

Indian Notice 15/200/10 (RSDRA2010000124637) 33/10

PAGE 86, CHINA.

Insert:

Diandeng Shan Lt Racon 29°52'·55N 122°13'·83E **81673-5**

B

Chinese Notice 30/1344/10 (RSDRA2010000123710) 33/10

LEGAL TIME

PAGE 226, Egypt.

Delete entry and replace by:

Egypt	-2	-3	30 April 2010 0000h 10 September 2010 0000h 29 April 2011 0000h 27 April 2012 0000h	10 August 2010 2400h 30 September 2010 2400h 29 September 2011 2400h 27 September 2012 2400h
--------------	----	----	--	---

OAG Worldwide Limited (RSDRA2010000124304) 33/10

VOLUME 6, PART 4, NP 286(4), 2010/11

Published Wk 27/10

(Last Amendments: Weekly Edition No. 32 dated 12 August 2010)

PAGE 92, AUSTRALIA, THURSDAY ISLAND, Queensland, Pilots and Port, PROCEDURE, section (9).

Delete and replace by:

(9) **Pilot boards** in the following positions:

- (a) From the E: 10°33'·30S 142°17'·30E (S of Chapman Reef)
- (b) From the W:
 - (i) Torres Strait (Goods Island): 10°33'·99S 142°04'·34E (vessels over 90m LOA)
 - (ii) Normanby Sound: 10°34'·70S 142°08'·70E (vessels less than 90m LOA)
- (c) From the S: 10°36'·05S 142°12'·40E (W of Boat Channel Lt buoy)

Queensland Notice 631/2010. (RSDRA2010000124116). 33/10

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

NP44 Malacca Strait and West coast of Sumatera Pilot (2008 Edition)

Singapore - Tuas Power Station — Jetty

288

Paragraph 8.313 *l* lines 5-7 *Replace by:*

...able to handle the largest product tankers. Feedstock Jetty lies close E of the E end of the fuel oil unloading jetty, with a depth alongside of 10·3 m (2010). TS-01 Light Buoy (special) lies 1¾ cables SE, marking a 10·3 m shoal depth close N.

Maritime and Port Authority of Singapore Notice DB 15/2010
(SDD 2010000 121472) [33/10]

NP62 Pacific Islands Pilot Volume 3 (2010 Edition)

Pitcairn Islands - National limits

17

Paragraph 1.120 *l* line 1 *For* 12 mile *Read* 3 mile.

NP247(1) Annual Notice 12/10
(HH. 062/200/01)

[33/10]

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2010/11. Weekly Edition No. 34, Dated 26 August 2010.

Last Amendment: Weekly Edition No. 33, dated 19 August 2010.

K1299	- Tg Batu Gendang (ID)	8 45-18 S 115 49-27 E	Fl W 5s	65	12 White metal framework structure 10	<i>fl 0.5</i>	
		*		*	*		*
K1413-153	Sungai Barito. No 2	3 38-47 S 114 28-66 E	Fl R 4s Red □ on red beacon	<i>fl 0.5</i>	
		*	*	*	*		*
K1413-154	Sungai Barito. No 3	3 37-95 S 114 28-87 E	Fl G 3s Green △ on green beacon	<i>fl 0.5.</i> Destroyed (T) 2010	
		*	*	*	*		*
K1413-155	Sungai Barito. No 4	3 37-42 S 114 28-77 E	Fl R 3s Red □ on red beacon	<i>fl 0.5</i>	
		*	*	*	*		*
K1413-16	Sungai Barito. No 5	3 36-87 S 114 28-99 E	Fl G 5s Green △ on green beacon	<i>fl 0.5.</i> Destroyed (T) 2010	
		*	*	*	*		*
K1413-17	Sungai Barito. No 6	3 36-33 S 114 28-87 E	Fl R 4s Red □ on red beacon	<i>fl 0.5</i>	
		*	*	*	*		*
K1413-19	Sungai Barito. No 7	3 35-79 S 114 29-11 E	Fl G 3s Green △ on green beacon	<i>fl 0.5.</i> TE 2010	
		*	*	*	*		*
K1413-23	Sungai Barito. No 8	3 35-28 S 114 29-01 E	Fl R 6s Red □ on red beacon	<i>fl 0.5</i>	
		*	*	*	*		*
K3851-6	- Ruthe Passage	36 49-71 S 175 12-09 E	Q R	3	3 Red □ on red beacon		*
		*					*
K4612	- Mulifanua Harbour. Ldg Lts 148°. Front	13 49-37 S 172 02-61 W	LFl W 8s	6	6 White metal framework tower, red top 6		
		*	*				
K4620	- Salelologa. Ldg Lts 312°. Front	13 45-13 S 172 12-80 W	Fl W 2s	6	6 White concrete column		
		*	*				
K5000-12	- Passe Tamaketa (FR)	15 29-10 S 145 34-80 W	Oc R 4s	6	5 Red □ on red beacon	<i>ec 1</i>	
		*	*	*	*		*
K5000-121	- Passe Tamaketa. Eastward (FR)	15 29-10 S 145 34-70 W	Oc(2)R 6s	5	3 Red □ on red beacon		
		*	*	*	*		*
K5000-125	- Passe Tamaketa. Eastward (FR)	15 29-10 S 145 34-50 W	Fl G 4s	5	3 Green △ on green beacon	<i>fl 1</i>	
		*	*	*	*		*
K5000-13	- Passe Tamaketa. Eastward (FR)	15 29-20 S 145 34-20 W	Iso G 4s	5	3 Red and white beacon		
		*	*	*	*		*
K5000-131	- Motu Paparaoa. Eastward (FR)	15 29-20 S 145 34-20 W	Q W 1-2s	4	3 ⚠ on yellow beacon, black top		
		*	*	*	*		*
K5000-132	- Motu Paparaoa. Eastward (FR)	15 29-20 S 145 34-20 W	Iso G 4s	8	3 Red and white beacon		
		*	*	*	*		*
K5000-14	- Passe Tamaketa. Eastward (FR)	15 29-20 S 145 33-80 W	Oc(2)G 6s	4	3 Green △ on green beacon		
		*	*	*	*		*
K5000-141	- Motu Takutua. North-westward (FR)	15 29-30 S 145 33-30 W	Fl G 4s	4	3 Green △ on green beacon	<i>fl 1</i>	
		*	*	*	*		*

K5000-15	- Motu Takutua. North-westward (FR)	15 29-30 S 145 32-20 W	Oc(2)R 6s	5	3 Red □ on red beacon	
*	*	*	*	*	*	*
K5000-154	- Motu Takutua. North-westward (FR)	15 29-60 S 145 31-70 W	Oc(2)G 6s	4	3 Green △ on green beacon	
*	*	*	*	*	*	*
K5000-16	- Motu Takutua. North-north-eastward (FR)	15 29-70 S 145 30-60 W	VQ(6)+LFl W 10s	4	3 ∇ on black beacon, yellow top	
*	*	*	*	*	*	*
K5000-165	- Motu Takutua. North-eastward (FR)	15 30-30 S 145 30-50 W	VQ(9)W 10s	5	3 ∇ on yellow beacon, black band	
*	*	*	*	*	*	*
K5000-17	- Motu Paparara. North-westward (FR)	15 29-80 S 145 29-20 W	Fl R 4s	4	3 Red □ on red beacon	<i>fl 1</i>
*	*	*	*	*	*	*
K5000-171	- Motu Paparara. Westward (FR)	15 30-00 S 145 29-20 W	Oc(2)G 6s	4	3 Green △ on green beacon	
*	*	*	*	*	*	*
K5000-18	- Motu Paparara. North-westward (FR)	15 30-00 S 145 28-00 W	Oc(2)R 6s	5	3 Red □ on red beacon	
*	*	*	*	*	*	*
K5000-185	- Passe Fainukea. Westward (FR)	15 30-40 S 145 27-50 W	Fl G 4s	4	3 Green △ on green beacon	<i>fl 1</i>
*	*	*	*	*	*	*

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 34 dated 26 August 2010

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from the UKHO website. To obtain a colour version of these diagrams go to: www.ukho.gov.uk – select **PRODUCTS AND SERVICES** – select **Maritime Safety Info** – select **Visit NMs page and Download NMs** – select **Weekly** – select **Year** – select **Week** – go to **Selected Week Content** – select **File** (for example: NP286(3)-WK01-10-PAGE149_Week01_2010.pdf)

VOLUME 2, NP 282, 2010/11

Published Wk 10/10
(Last Amendments: Weekly Edition No. 33 dated 19 August 2010)

RADAR BEACONS

PAGE 110, INDONESIA (Sulawesi).
86630 Tanjung Lero Lt.

Delete position and replace by: 4°02'·83S 119°35'·81E

(former amendment 17/10)
[DISHIDROS 34/10](#)

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 167, FRANCE (English Channel).
After Ruytingen SW Lt Buoy insert:

Sandettié Lt Buoy MDW	51°19'·14N 1°59'·30E	992271104		Operational	
------------------------------	----------------------	-----------	--	-------------	--

(former amendment 21/10)
[French Notice 30/26/10 and French Lights List 30/10 \(RSDRA2010000125226\) 34/10](#)

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

NP34 Indonesia Pilot Volume 2 (2009 Edition)

Indonesia - South coast of Jawa - Tanjung Intan — Limiting conditions

61

After Paragraph 3.42 1 Insert:

- 2 Less water than charted has been reported (2010) to E and N of No 1 Light Buoy (starboard hand) (7°45'2S 109°03'3E).

Fleet Management Ltd, Hong Kong
(SDD 2010000 102609)

[34/10]

NP44 Malacca Strait and West coast of Sumatera Pilot (2008 Edition)

Peninsular Malaysia - West coast - Approaches to Port Dickson — Directions; wreck

207

Paragraph 6.260 2 lines 1-4 *Replace by:*

- 2 SSE of a wreck, depth unknown (reported 2010) (1.6 miles WSW), thence:
SSE of a 4.6 m (15 ft) shoal (1.5 miles WSW), thence:
SSE of No 3 Light Buoy (starboard hand) (1.2 miles WSW), thence:

Marine Department Peninsular Malaysian Notice 57/10
(SDD 2010000 127697) [34/10]
