

TEMPORARY AND PRELIMINARY NOTICES

In force on 9 May 2014

NEW SOUTH WALES

410(T)/2011 AUSTRALIA - NEW SOUTH WALES - Port Kembla - Spoil ground

Port Kembla Port Corporation Notice 2/2011 (AA528983)

A spoil ground marked by six lit special buoys exists in the vicinity of position 34° 28'.33 S 150° 54'.57 E.

Chart temporarily affected - Aus 194 - Aus 195

864(T)/2011 AUSTRALIA - NEW SOUTH WALES - Port Kembla - Obstruction

Port Kembla Port Corporation Notice 9/2011 (AA551936)

A silt curtain, marked by special light buoys Q.Y, exists in the outer harbour between the following positions:

34° 28'.18 S 150° 54'.15 E

34° 28'.15 S 150° 54'.27 E

34° 28'.47 S 150° 54'.33 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 194 - Aus 195

337(T)/2013 AUSTRALIA - NEW SOUTH WALES - Sydney - Millers Point - Harbour works

Former Notice - 1132(T)/2012 is cancelled

Sydney Ports Notice 9/2013 (AA664448)

Works are marked by a north cardinal light buoy, VQ (33° 51'.30 S 151° 12'.13 E), with six special light buoys, Q.Y, spaced equally to a north cardinal light buoy, VQ (33° 51'.32 S 151° 11'.99 E), with ten special light buoys, Q.Y, spaced equally to a west cardinal light buoy, VQ(9)10s (33° 51'.63 S 151° 12'.02 E).

A silt curtain exists within the boundary of the buoys.

An exclusion zone exists within the area.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 200 - Aus 202 - AX 00202T

393(T)/2013 AUSTRALIA - NEW SOUTH WALES - Port Kembla - Depth information

Former Notice - 335(T)/2013 is cancelled

Port Kembla Port Corporation Notice 1/2013 (AA662269, AA667485)

Available depths as at 18 April 2013:

<i>Berth</i>	<i>Metres</i>	<i>Remarks</i>
* Inner Harbour	15.1	
North West Basin	11.2	
101	11.4	Maximum transit draft 12m
102	15.7	
103	12.0	
104	15.4	
105	14.8	
106	13.6	
107	12.0	
108	-	Future Development
109	11.7	
110	10.7	(9.0)
111	15.2	
112	12.8	Maximum transit draft 13.6m
113	11.2	(9.5) West of 7m chainage
	10.5	East of 7m chainage to eastern end of berthing box
201	10.4	To 250m
201	10.2	To 280m
201	10.1	To 330m
202	10.5	To 205m mx LOA 180m
202	10.2	To 205m mx LOA 195m

202	10.0	To 210m
203	9.7	
204	4.2	
205	6.8	
206	11.0	

* Indicates revised entry.

Chart temporarily affected - Aus 194

457(T)/2013 AUSTRALIA - NEW SOUTH WALES - Broken Bay - Barrenjoey Head - Light range reduced

Former Notice - 1318(T)/2010 is cancelled

NSW Maritime (AA506509)

The light (33° 34'.82 S 151° 19'.79 E) has been temporarily altered to *Fl(4)20s 113m 12M*.

Chart temporarily affected - Aus 197 - Aus 204 - Aus 215 - Aus 489 - Aus 809 - Aus 4643 (INT 643) - AX 00215T - AX 00809S

697(T)/2013 AUSTRALIA - NEW SOUTH WALES - Cape Baily to Ben Buckler - Scientific instruments

Former Notice - 748(T)/2011 is cancelled

Date - Until 30 June 2015

Sydney Institute of Marine Science (AA375220, AA420046, AA545275, AA683400)

Subsea moorings (25 metres below the surface) exist in positions as follows:

33° 53'.76 S 151° 17'.30 E
33° 53'.99 S 151° 17'.30 E
33° 54'.23 S 151° 17'.72 E
33° 54'.51 S 151° 18'.14 E
33° 54'.76 S 151° 18'.56 E
33° 55'.02 S 151° 19'.01 E
33° 55'.28 S 151° 19'.45 E
33° 55'.54 S 151° 19'.89 E
33° 55'.80 S 151° 20'.31 E
33° 56'.06 S 151° 21'.17 E
33° 56'.32 S 151° 22'.61 E
33° 56'.60 S 151° 22'.06 E
33° 56'.85 S 151° 22'.50 E
33° 57'.12 S 151° 22'.95 E
33° 57'.40 S 151° 23'.39 E
33° 57'.91 S 151° 24'.25 E
33° 58'.65 S 151° 23'.84 E
33° 58'.20 S 151° 24'.64 E
33° 58'.49 S 151° 25'.08 E
33° 58'.77 S 151° 25'.57 E
33° 59'.08 S 151° 26'.06 E
33° 59'.33 S 151° 26'.47 E
33° 59'.97 S 151° 27'.33 E
34° 00'.21 S 151° 27'.85 E
34° 00'.48 S 151° 28'.27 E
34° 00'.77 S 151° 28'.74 E
34° 01'.33 S 151° 29'.16 E
34° 01'.31 S 151° 29'.63 E
34° 01'.59 S 151° 30'.08 E.

Chart temporarily affected - Aus 197 - Aus 200 - Aus 808 - Aus 809 - AX 00808S - AX 00809S - AX 63200

699(T)/2013 AUSTRALIA - NEW SOUTH WALES - Cabbage Tree Bay to Curl Curl Head - Scientific instruments

Former Notice - 750(T)/2011 is cancelled

Date - Until 30 June 2015

Sydney Institute of Marine Science (AA353372, AA353373, AA424523, AA545275, AA683400)

Subsurface scientific instruments exist in positions:

33° 48'.03 S 151° 18'.03 E
33° 47'.98 S 151° 17'.65 E
33° 47'.99 S 151° 17'.73 E
33° 47'.92 S 151° 17'.61 E
33° 47'.93 S 151° 17'.69 E.

Chart temporarily affected - Aus 197 - Aus 200 - Aus 201 - AX 00201T - AX 63200

906(T)/2013 AUSTRALIA - NEW SOUTH WALES - Sydney Harbour - Depth information
Sydney Ports Corporation (AA691471, AA691472)

Available depths as at 20 August 2013:

<i>Berth</i>	<i>Metres</i>
* Overseas Passenger Terminal	10.0
* Glebe Island 1	11.8
* Glebe Island 2	11.9
* Glebe Island 7	10.7
* Glebe Island 8	8.4
* White Bay 2	11.0
* White Bay 3	10.6
* White Bay 4	11.1
* White Bay Cruise Terminal	10.5
* Gore Cove 1	13.0
* Gore Cove 2	9.8
* Indicates new or revised entry.	

Chart temporarily affected - Aus 200 - Aus 202 - AX 00202T

217(T)/2014 AUSTRALIA - NEW SOUTH WALES - Botany Bay - Depth information

Former Notice - 902(T)/2013 is cancelled
Sydney Ports Corporation (AA724449)

Available depths as at 14 February 2014:

<i>Channel/Berth</i>	<i>Metres</i>
Main Channel to Molineux Point	15.6
Port Botany Swinging Basin	15.9
* Kurnell 2 Approaches	12.1
* Kurnell 1 & 3 Approaches	12.8
* Kurnell No1	12.8
* Kurnell No2	12.1
* Kurnell No3	14.0
* Hayes Dock (channel)	16.4
* Hayes No1	16.4
* Hayes No2	16.4
* Hayes No3	16.4
* Hayes No4	16.4
* Brotherson Dock No5	16.4
* Brotherson Dock No6	16.4
* Brotherson Dock No7	13.8
* Brotherson Dock No8	13.9
* Brotherson Dock No9	13.5
* Brotherson Dock No10	12.8
* Brotherson Dock No11	12.6
Brotherson Dock No12	14.6
Bulk Liquids 1	18.3
Bulk Liquids 2	19.0
* Indicates new or revised entry.	

Chart temporarily affected - Aus 196 - Aus 198 - Aus 199

337(T)/2014 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Goat Island - Scientific instrument

Date - Until 30 May 2014
Sydney Ports Corporation Notice 7/2014 (AA730209)

A scientific instrument marked by special light buoy, *Fl.Y.5s*, exists in position 33° 51'.02 S 151° 11'.70 E.

Chart temporarily affected - Aus 200 - Aus 202 - AX 00202T

373(T)/2014 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Watsons Bay - Scientific instrument

Date - Until 30 September 2014
Sydney Ports Corporation Notice 8/2014 (AA733137)

A scientific instrument marked by special light buoy, *Fl.Y.5s*, exists in position 33° 50'.64 S 151° 16'.82 E.

Chart temporarily affected - Aus 200 - Aus 201 - AX 00200T - AX 00201T

410(T)/2014 AUSTRALIA - NEW SOUTH WALES - Newcastle - Depth information

Former Notice - 267(T)/2014 is cancelled

Newcastle Port Corporation (AA735867)

Available depths as at 23 April 2014:

<i>Berth</i>	<i>Metres</i>	<i>Remarks</i>
* Eastern Basin 1	11.4	
Eastern Basin 2 North of Ch 450	11.6	
Eastern Basin 2 South of Ch 450	11.5	
Western Basin 3	11.6	
Western Basin 4	11.6	
Channel Berth	9.7	
Dyke 1	12.8	
Dyke 2	12.7	
Dyke 4	16.2	
Dyke 5	16.0	
Dyke 6	5.0	
Mayfield 4 Ch 27 to 266	12.7	
* BHP Wharf 6 to Ch 1050	7.6	
Kooragang 2	11.6	
Kooragang 2 North Dolphin Ch 182 to 243	11.6	
Kooragang 2 South Dolphin Ch -92 to 00	11.3	
Kooragang 3 Ch -40 to 00	11.8	
Kooragang 3 Ch 00 to 220	13.1	
Kooragang 4	16.5	
Kooragang 5	16.5	
Kooragang 6	16.5	
Kooragang 7	16.5	
Kooragang 8	16.3	
Kooragang 9	16.3	
Kooragang 10	16.2	
Throsby 1	8.4	
Carrington Wharf		To be sounded as and when required
Foreshore Park Berth	5.9	
Elgo Wharf		To be sounded as and when required
<i>Channels</i>		
Entrance Approach	17.7	
Entrance Channel (18.0m)	17.8	
Entrance Channel (17.4m)	17.4	
Entrance Channel (16.8m)	16.8	
Entrance Channel (16.2m)	16.2	
Entrance Channel to Horseshoe	15.2	
* Horseshoe	15.1	
* Steelworks Channel to Swinging Basin	15.1	
* Swinging Basin	14.8	
Hunter River South Arm (Kooragang 6 to buoy 16)	14.9	
Hunter River South Arm (buoy 16 to buoy 20)	14.8	
Basin Cutting	12.6	
Basin Area to Eastern & Western Basin Berths	12.3	
Basin Area to 1 Throsby	9.4	
Stockton Crossing	3.6	
* Indicates new or revised entry.		

Chart temporarily affected - Aus 207 - Aus 208 - Aus 809 - AX 00809S

QUEENSLAND

710(T)/2008 AUSTRALIA - QUEENSLAND - Moreton Bay - Spitfire Channel - Light buoys established

Former Notice - 649(T)/2008 is cancelled

Date - Until 31 December 2008

Maritime Safety Queensland Notice 389/2008 (AA345287)

Starboard lateral conical light buoys, *Fl.G.2-5s*, without topmark, exist in positions 27° 02'.73 S 153° 15'.84 E and 27° 03'.12 S 153° 16'.99 E.

Chart temporarily affected - Aus 235 - Aus 236

819(T)/2008 AUSTRALIA - QUEENSLAND - Airlie Beach - Light buoys established

Maritime Safety Queensland Notice 452(T)/2008 (AA351934)

A silt curtain exists across the southern entrance to Abel Point Marina, closing the entrance to navigation.

Special light buoys mark the location of the silt curtain in the following positions:

20° 16'.070 S 148° 42'.400 E

20° 16'.070 S 148° 42'.402 E

20° 16'.056 S 148° 42'.401 E

Chart temporarily affected - Aus 252 - Aus 253 - Aus 268

318(T)/2010 AUSTRALIA - QUEENSLAND - Heskett Rock - Light beacon destroyed

Maritime Safety Queensland Notice 273(T)/2010 (AA462501)

The south cardinal light beacon (20° 56'.19 S 149° 28'.98 E) has been destroyed.

Chart temporarily affected - Aus 251 - Aus 823 - Aus 824 - AX 0823E

763(T)/2010 AUSTRALIA - QUEENSLAND - Shute Harbour - Wreck

Maritime Safety Queensland Notice 568(T)/2010 (AA480151)

A wreck marked by a special light buoy, *Fl.Y.5s*, exists in position 20° 17'.76 S 148° 47'.24 E.

Chart temporarily affected - Aus 252 - Aus 253

1188(T)/2010 AUSTRALIA - QUEENSLAND - Io Reef - Light beacon destroyed; light buoy established

Former Notice - 382(T)/2010 is cancelled

Maritime Safety Queensland Notice 932(T)/2010 (AA500605)

The west cardinal light beacon (20° 41'.58 S 149° 07'.70 E) has been destroyed; a west cardinal light buoy, *Q(9)15s*, exists in situ.

Chart temporarily affected - Aus 251 - Aus 252 - Aus 824

1189(T)/2010 AUSTRALIA - QUEENSLAND - Whitsunday Group - Shaw Island - Platypus Rock - Light beacon destroyed; light buoy established

Former Notice - 511(T)/2010 is cancelled

Maritime Safety Queensland Notice 926(T)/2010 (AA500696)

The west cardinal light beacon (20° 31'.23 S 149° 02'.31 E) has been destroyed; a west cardinal light buoy, *VQ(9)10s*, exists in situ.

Chart temporarily affected - Aus 252 - Aus 254 - Aus 824

1191(T)/2010 AUSTRALIA - QUEENSLAND - Surprise Rock - Light beacon destroyed; light buoy established

Former Notice - 329(T)/2009 is cancelled

Maritime Safety Queensland Notice 929(T)/2010 (AA500615)

The isolated danger light beacon (20° 21'.3S 149° 01'.6 E) has been destroyed; an isolated danger light buoy, *Fl(2)6s*, exists in situ.

Chart temporarily affected - Aus 252 - Aus 253 - Aus 824

1193(T)/2010 AUSTRALIA - QUEENSLAND - Whitsunday Island - Reef Point - Light beacon destroyed; light buoy established

Former Notice - 446(T)/2010 is cancelled

Maritime Safety Queensland Notice 927(T)/2010 (AA500700)

The port lateral light beacon (20° 17'.45 S 148° 54'.71 E) has been destroyed; a port lateral light buoy, *Fl.R.2-5s*, exists in situ.

Chart temporarily affected - Aus 252 - Aus 253 - Aus 254

1394(T)/2010 AUSTRALIA - QUEENSLAND - Whitsundays - The Narrows - Buoy off station

Maritime Safety Queensland Notice 1042(T)/2010 (AA508738)

The port lateral buoy (20° 04'.34 S 148° 54'.17 E) is off station.

Chart temporarily affected - Aus 254

418(T)/2011 AUSTRALIA - QUEENSLAND - Gladstone - Anchorage area

Former Notice - 315(T)/2011 is cancelled

Maritime Safety Queensland Notice 318(T)/2011 (AA526389)

A small craft anchorage exists within an area bounded by the following positions:

23° 45'.0 S 151° 09'.8 E

23° 45'.0 S 151° 10'.0 E

23° 46'.4 S 151° 10'.4 E

23° 46'.4 S 151° 10'.0 E.

Mooring buoys exist within the area.

Permission must be obtained from Gladstone Port Corporation prior to anchoring or mooring within the area.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 245

470(T)/2011 AUSTRALIA - QUEENSLAND - Gladstone - North Passage Island to Redcliffe Island - Scientific instruments

Maritime Safety Queensland Notice 376(T)/2011 (AA531285)

Subsurface scientific instruments exist in positions:

23° 45'.91 S 151° 10'.93 E

23° 45'.81 S 151° 11'.11 E

23° 45'.33 S 151° 10'.48 E

23° 45'.23 S 151° 10'.66 E

23° 42'.44 S 151° 08'.84 E

23° 42'.34 S 151° 09'.05 E

23° 41'.39 S 151° 08'.20 E

23° 41'.29 S 151° 08'.41 E.

Chart temporarily affected - Aus 245 - Aus 819

648(T)/2011 AUSTRALIA - QUEENSLAND - Moreton Bay - Bramble Bay - Bridge construction

Former Notice - 465(T)/2011 is cancelled

Date - Until 21 July 2011

Maritime Safety Queensland Notices 171(T)/2008, 164(T)/2009, 166(T)/2009, 756(T)/2010, 393(T)/2011, 568(T)/2011 (AA323151, AA395818, AA396377, AA492668, AA532382, AA540981)

Construction of the Houghton Highway Bridge is in progress in position 27° 17'.01 S 153° 03'.89 E (WGS84 datum).

A falsework bridge exists to the east of the existing bridge. The seaward limit of the falsework bridge will be marked by lights, Q.Y.

Nav aids exist as follows:

<i>Position</i>	<i>Remarks</i>
27° 15'.84 S 153° 04'.62 E	port beacon
27° 15'.95 S 153° 04'.75 E	starboard buoy
27° 15'.97 S 153° 04'.74 E	port buoy
27° 16'.56 S 153° 04'.29 E	lit starboard buoy, Fl.G.2•5s
27° 16'.60 S 153° 04'.26 E	lit port buoy, Fl.R.2•5s
27° 16'.57 S 153° 04'.11 E	lit starboard buoy, Fl.G.2•5s
27° 16'.59 S 153° 04'.09 E	lit port buoy, Fl.R.2•5s

Works to remove temporary lit piles adjacent to the channel in Hays Inlet (27° 15'.82 S 153° 04'.70 E) are in progress. The channel will be closed to traffic until 21 July 2011.

Mariners should navigate with caution in the area.

Chart temporarily affected - Aus 236

757(T)/2011 AUSTRALIA - QUEENSLAND - Laguna Quays - Lights unlit; light beacons damaged

Former Notice - 444(T)/2010 is cancelled

Maritime Safety Queensland Notice 686(T)/2011 (AA546594)

Light beacons marking the entrance to Laguna Quays (20° 36'.03 S 148° 41'.21 E) may be damaged or unlit.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 252

758(T)/2011 AUSTRALIA - QUEENSLAND - Laguna Quays - Shoaling

Former Notice - 1052(T)/2006 is cancelled

Maritime Safety Queensland Notice 685/2011 (AA546595)

Shoaling exists within the entrance channel to Laguna Quays (20° 36'.03 S 148° 41'.21 E).

Mariners are advised to seek local knowledge prior to transiting the marina entrance and to navigate with caution in the area.

Chart temporarily affected - Aus 252

826(T)/2011 AUSTRALIA - QUEENSLAND - Mourilyan - Depth information

Maritime Safety Queensland Notice 702(T)/2011 (AA547518)

Available depths as at 29 July 2011:

	<i>Metres</i>
Departure Channel	9.6
Inner Channel	9.6
Swing Basin	6.7
Sugar Berth	10.1

* Indicates revised entry.

Chart temporarily affected - Aus 258

872(T)/2011 AUSTRALIA - QUEENSLAND - Bait Reef - Light beacon destroyed

Maritime Safety Queensland Notice 750(T)/2011 (AA549635)

The starboard lateral beacon (19° 48'.52 S 149° 03'.77 E) has been destroyed; a special buoy exists in situ.

Chart temporarily affected - Aus 254 - Aus 825

1020(T)/2011 AUSTRALIA - QUEENSLAND - Moreton Bay - Wynnum - Wreck; light buoy

Maritime Safety Queensland Notice 871/2011 (AA556300)

A wreck marked by a special light buoy, Fl.Y.2•5s, exists in position 27° 25'.90 S 153° 10'.73 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236

1091(T)/2011 AUSTRALIA - QUEENSLAND - Hay Point - Scientific instruments

Maritime Safety Queensland Notice 1018(T)/2011 (AA562002)

Special light buoys, Q.Y, exist in positions 21° 16'.04 S 149° 18'.09 E and 21° 24'.90 S 149° 20'.17 E.

Chart temporarily affected - Aus 249 - Aus 250 - AX 0249E

1210(T)/2011 AUSTRALIA - QUEENSLAND - Airlie Beach - Abel Point - Obstructions

Maritime Safety Queensland Notice 1123(T)/2011 (AA567586)

Underwater obstructions, marked by special buoys, exist in the following positions:

20° 15'.87 S 148° 42'.60 E

20° 15'.88 S 148° 42'.60 E

20° 15'.87 S 148° 42'.56 E.

Chart temporarily affected - Aus 268

59(T)/2012 AUSTRALIA - QUEENSLAND - Thursday Island - Depth information

Maritime Safety Queensland Notice 1(T)/2012 (AA574953)

Available depths as at 2 January 2012:

	<i>Metres</i>
Hovell Bar	3.2
Main Wharf	3.1 (4.1m alongside wharf)
Caltex Wharf	4.1
Engineers Wharf	3.5
Boat Channel	4.6
Inner Harbour	4.8

* Indicates revised entry.

Chart temporarily affected - Aus 293 - Aus 299

460(T)/2012 AUSTRALIA - QUEENSLAND - Hook Island - Cockatoo Point - Light beacon destroyed

Maritime Safety Queensland Notice 393(T)/2012 (AA596297)

The light beacon, *Fl.R.2-5s* (20° 04'.71 S 148° 54'.05 E) has been destroyed.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 252 - Aus 254

600(T)/2012 AUSTRALIA - QUEENSLAND - Moreton Bay - Scarborough - Shoaling

Maritime Safety Queensland Notice 609(T)/2012 (AA604629)

Shoaling with a least depth of 1.7m exists on the northern toeline adjacent to beacon No8 (27° 11'.62 S 153° 06'.18 E). A least depth of 2m exists between the entrance beacons (27° 10'.96 S 153° 06'.15 E) and the western boat ramp.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236

602(T)/2012 AUSTRALIA - QUEENSLAND - Curtis Channel - Wreck

Maritime Safety Queensland Notice 579(T)/2012 (AA603887)

A wreck exists in position 24° 08'.89 S 152° 12'.12 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 818

645(T)/2012 AUSTRALIA - QUEENSLAND - Moreton Bay - Rainbow Channel - Light beacon withdrawn

Maritime Safety Queensland Notice 655(T)/2012 (AA607798)

The starboard light beacon, *Fl.G.4s* (27° 26'.99 S 153° 24'.67 E), has been temporarily withdrawn.

Chart temporarily affected - Aus 236

694(T)/2012 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Shoaling

Former Notice - 1142(T)/2011 is cancelled

Maritime Safety Queensland Notice 705(T)/2012 (AA611629)

Available depths as at 4 July 2012:

	<i>Metres</i>
Centre line leads (255°)	3.6
Southern approach leads (291°)	3.8

A shoal area, with a least depth of 3.6m, is drifting northwards immediately east of the southern break wall towards the centreline leads. Deeper water, 5.5m, is found by leaving the centre line leads open to the north.

Mariners are advised to navigate with caution when using the southern approach leads as breaking waves may be experienced when seas rise above 1.4m.

Chart temporarily affected - Aus 230

737(T)/2012 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Shoaling

Former Notice - 695(T)/2012 is cancelled

Maritime Safety Queensland Notice 706(T)/2012 (AA611628)

Shoaling, with a least depth of 2.3m, exists in the North Channel between 27° 55'.86 S 153° 25'.30 E and 27° 55'.66 S 153° 25'.09 E.

Shoaling, with a least depth of 3.5m, exists in the South Channel between 27° 56'.20 S 153° 25'.49 E and 27° 56'.39 S 153° 25'.26 E.

Deeper water to 3.9m is found to the west of the channels centre line.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 230

740(T)/2012 AUSTRALIA - QUEENSLAND - Moreton Bay - Coochiemudlo Island - Light beacon

Maritime Safety Queensland Notice 768(T)/2012 (AA613763)

The special light beacon, *Fl.Y.2.5s* (27° 34'.78 S 153° 20'.37 E), has been temporarily replaced by a special light buoy, *Fl.Y.2.5s*, in situ.

Chart temporarily affected - Aus 236

859(T)/2012 AUSTRALIA - QUEENSLAND - Dent Island - Light beacon unlit; light buoy established

Former Notice - 508(T)/2012 is cancelled

Maritime Safety Queensland Notice 869(T)/2012 (AA618556)

The light beacon, *Fl.G.2.5s* (20° 20'.33 S 148° 56'.17 E) is unlit; a starboard lateral light buoy, *Fl.G.2.5s*, exists in situ.

Chart temporarily affected - Aus 253 - Aus 254

1085(T)/2012 AUSTRALIA - QUEENSLAND - Moreton Bay - Peel Island - Lazaret Gutter - Beacon destroyed

Maritime Safety Queensland Notice 1141(T)/2012 (AA632279)

The starboard beacon (27° 29'.18 S 153° 21'.06 E) has been destroyed.

Chart temporarily affected - Aus 236

1088(T)/2012 AUSTRALIA - QUEENSLAND - Hay Point - Exclusion zone; light buoys

Former Notice - 999(T)/2012 is cancelled

Maritime Safety Queensland Notice 1001(T)/2012 (AA626309, AA632277)

An exclusion zone exists in an area bounded as follows:

<i>Position</i>	<i>Remarks</i>
21° 15'.86 S 149° 18'.78 E	

21° 15'.88 S 149° 18'.83 E	
21° 16'.16 S 149° 19'.02 E	special light buoy, <i>Fl.Y.4s</i>
21° 16'.37 S 149° 18'.63 E	special light buoy, Q.Y
21° 16'.08 S 149° 18'.45 E	special light buoy, Q.Y
21° 16'.39 S 149° 17'.87 E	
21° 16'.24 S 149° 17'.54 E	
21° 15'.70 S 149° 18'.55 E	
21° 15'.53 S 149° 18'.47 E	
21° 15'.48 S 149° 18'.58 E.	

Chart temporarily affected - Aus 249 - Aus 250 - Aus 823

1209(T)/2012 AUSTRALIA - QUEENSLAND - Whitsunday Island - Craig Point - Wreck
Maritime Safety Queensland Notice 1243(T)/2012 (AA639290)

A wreck marked by a special light buoy, Q.Y, exists in position 20° 18'.58 S 149° 02'.07 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 252 - Aus 253

1265(T)/2012 AUSTRALIA - QUEENSLAND - Moreton Bay - Manly - Light beacon destroyed
Maritime Safety Queensland Notice 1301(T)/2012 (AA642817)

No3 light beacon, *Fl.G.4s* (27° 26'.87 S 153° 11'.93 E), has been destroyed; a starboard light buoy, Q.G, exists in situ.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236

1274(T)/2012 AUSTRALIA - QUEENSLAND - Port Douglas - Depth information
Former Notice - 463(T)/2012 is cancelled
Maritime Safety Queensland Notice 1297(T)/2012 (AA642027)

Available depths as at 6 December 2012:

	<i>Metres</i>
*Outer Channel	1.4
Inner Channel	2.1
Boat ramp to marina	1.9

*Indicates revised entry.

Chart temporarily affected - Aus 270

53(T)/2013 AUSTRALIA - QUEENSLAND - Round Hill Head - Wreck
Maritime Safety Queensland Notices 1321(T)/2012, 1342(T)/2012 (AA643596, AA644831))

A wreck marked by a special light buoy, *Fl.Y.2-5s*, exists in position 24° 10'.13 S 151° 52'.75 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 818

105(T)/2013 AUSTRALIA - QUEENSLAND - Bundaberg - Obstruction northeastwards
Maritime Safety Queensland Notice 23(T)/2013 (AA647424)

An obstruction exists in position 24° 37'.05 S 152° 37'.54 E. A 3700m radius exclusion zone exists around the obstruction.

Chart temporarily affected - Aus 243 - Aus 817 - Aus 818

149(T)/2013 AUSTRALIA - QUEENSLAND - Pumicestone Channel - Nav aids destroyed or off station; depths
Maritime Safety Queensland Notice 80(T)/2013 (AA649223)

Nav aids in Pumicestone Channel may be destroyed or off station due to recent flooding.

Depths may not be consistent with charted information.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 235

158(T)/2013 AUSTRALIA - QUEENSLAND - Mackay - Light beacon destroyed

Former Notice - 857(T)/2012 is cancelled

Maritime Safety Queensland Notice 75(T)/2013 (AA649210)

The port lateral light beacon, *Fl.R.2-5s* (21° 09'.00 S 149° 13'.18 E), has been destroyed.

Chart temporarily affected - Aus 249 - AX 00249S

167(T)/2013 AUSTRALIA - QUEENSLAND - Weipa - Depth information

Former Notice - 1002(T)/2012 is cancelled

Maritime Safety Queensland Notice 100(T)/2013 (AA649386)

Available depths as at 1 February 2013:

	<i>Metres</i>
* Weipa Approaches	11.5
* South Channel	11.5
Departure Channel	11.3
Cora Bank South Channel	7.3
Humbug Point Approaches	8.6
Humbug Point Berth	9.5
Evans Landing	9.6
Lorim Point East	12.3
Lorim Point West	12.3

*Indicates revised entry

Chart temporarily affected - Aus 4

203(T)/2013 AUSTRALIA - QUEENSLAND - Hervey Bay - Big Woody Island - Light beacon destroyed

Maritime Safety Queensland Notice 164(T)/2013 (AA653342)

The port lateral light beacon, *Q.R* (25° 16'.03 S 152° 55'.67 E), has been destroyed; an unlit buoy exists in situ.

Chart temporarily affected - Aus 241 - Aus 817

204(T)/2013 AUSTRALIA - QUEENSLAND - Gladstone - Depth information

Former Notice - 348(T)/2012 is cancelled

Maritime Safety Queensland Notice 142(T)/2013 (AA653496)

Available depths as at 12 February 2013:

	<i>Metres</i>
<i>Sea Channels:</i>	
Wild Cattle Cutting	16.1
* Boyne Island Cutting	16.3
Boyne Island Extension Channel	9.0
Golding Cutting	16.1
* South Bypass Channel	7.4
Gatcombe Channel	16.3
* Gatcombe Bypass Channel	13.4
<i>Inner Channels:</i>	
Auckland Channel	15.8
Auckland Bypass Channel	6.8
Clinton Channel	16.0
Clinton Bypass Channel	10.6
Clinton Swing Basin	10.6
* Targinie Channel	10.5
Targinie Swing Basin East	10.6
* Targinie Swing Basin West	8.9
<i>Berths:</i>	
Boyne Smelter Wharf	15.0
* South Trees East Wharf	13.8
* South Trees West Wharf	13.0
Barney Point Wharf	(east approach) 13.5

Barney Point Wharf	(west approach) 11.5
Barney Point Wharf	15.0
* Auckland Point No 1 Wharf	10.6
* Auckland Point No 2 Wharf	10.6
* Auckland Point No 3 Wharf	11.4
* Auckland Point No 4 Wharf	11.3
* Clinton No 1 Wharf	19.2
* Clinton No 2 Wharf	18.4
* Clinton No 3 Wharf	18.6
* Clinton No 4 Wharf	19.1
* Fishermans Landing Wharf No 1	13.6
* Fishermans Landing Wharf No 2	13.3
* Fishermans Landing Wharf No 4	10.9
* Fishermans Landing Wharf No 5	10.9
* Indicates revised entry.	

Chart temporarily affected - Aus 244 - Aus 245 - Aus 246

206(T)/2013 AUSTRALIA - QUEENSLAND - Gladstone - Wiggins Islands - Exclusion zone

Former Notice - 1138(T)/2012 is cancelled

Date - Until 31 January 2014

Maritime Safety Queensland Notice 177(T)/2013 (AA654021)

An exclusion zone marked by special light buoys, *Fl. Y. 2•5s*, exists in an area bounded by the following positions:

23° 49'.27 S 151° 12'.49 E
 23° 49'.10 S 151° 12'.56 E
 23° 48'.85 S 151° 12'.66 E
 23° 48'.59 S 151° 12'.76 E
 23° 48'.23 S 151° 12'.89 E
 23° 48'.41 S 151° 13'.45 E
 23° 48'.80 S 151° 13'.40 E
 23° 48'.89 S 151° 13'.25 E
 23° 49'.14 S 151° 12'.93 E
 23° 49'.21 S 151° 12'.87 E
 23° 49'.27 S 151° 12'.83 E.

Chart temporarily affected - Aus 245

207(T)/2013 AUSTRALIA - QUEENSLAND - Gladstone - Calliope River - Light buoys

Former Notice - 54(T)/2013 is cancelled

Maritime Safety Queensland Notice 178(T)/2013 (AA654022)

Light buoys exist as follows:

<i>Number</i>	<i>Position</i>	<i>Characteristic</i>
CR1	23° 48'.66 S 151° 13'.79 E	<i>Fl. G. 2•5s</i>
CR2	23° 48'.70 S 151° 13'.89 E	<i>Fl. R. 2•5s</i>
CR3	23° 48'.87 S 151° 13'.74 E	<i>Fl. G. 2•5s</i>
CR4	23° 48'.84 S 151° 13'.82 E	<i>Fl. R. 2•5s</i>
CR5	23° 48'.95 S 151° 13'.67 E	<i>Fl. G. 2•5s</i>
CR6	23° 49'.29 S 151° 13'.25 E	<i>Fl. R. 2•5s</i>
CR7	23° 49'.09 S 151° 13'.39 E	<i>Fl. G. 2•5s</i>
CR9	23° 49'.19 S 151° 13'.22 E	<i>Fl. G. 2•5s</i>
CR11	23° 49'.26 S 151° 13'.11 E	<i>Fl. Y. 2•5s</i>
CR13	23° 49'.36 S 151° 13'.04 E	<i>Fl. Y. 2•5s.</i>

Chart temporarily affected - Aus 244 - Aus 245

210(T)/2013 AUSTRALIA - QUEENSLAND - Port Alma - Depth information

Former Notice - 209(T)/2011 is cancelled

Maritime Safety Queensland Notice 143(T)/2013 (AA653498)

Available depths as at 12 February 2013:

<i>Berth</i>	<i>Metres</i>
* Balaclava Leads	7.5
Kazatch Leads	7.0
* Eupatoria Leads	7.7
* Shell Point Leads	6.8
* Swing Basin	5.6

* Berth No 1 9.0
* Berth No 2 9.0
* Berth No 3 9.0
* Indicates revised entry.

Chart temporarily affected - Aus 265

211(T)/2013 AUSTRALIA - QUEENSLAND - Fitzroy River - Wreck

Maritime Safety Queensland Notice 166(T)/2013 (AA653574)

A stranded wreck exists in position 23° 25'.58 S 150° 35'.60 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 819

215(T)/2013 AUSTRALIA - QUEENSLAND - Oyster Point - Shoaling; obstructions

Maritime Safety Queensland Notice 151(T)/2013 (AA652929)

Shoaling and obstructions exist in Port Hinchinbrook Marina (18° 16'.71 S 146° 02'.70 E) and Grande Canal (18° 16'.88 S 146° 02'.80 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 258

302(T)/2013 AUSTRALIA - QUEENSLAND - Moreton Bay - Garnet Rock - Light beacon destroyed; light buoy established

Former Notice - 148(T)/2013 is cancelled

Maritime Safety Queensland Notice 240(T)/2013 (AA658521), Maritime Safety Queensland Notice 238(T)/2013 (AA685522)

The starboard light beacon, *Fl.G.6s* (27° 14'.50 S 153° 07'.40 E) has been destroyed. A starboard lateral light buoy, *Fl.G.3s*, exists in situ.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236

400(T)/2013 AUSTRALIA - QUEENSLAND - Daydream Island - Lights unlit

Former Notice - 305(T)/2013 is cancelled

Maritime Safety Queensland Notice 317(T)/013 (AA667369)

The leading lights, *2F.Bu.5M (F Day)* (20° 15'.09 S 148° 48'.92 E), are unlit.

Chart temporarily affected - Aus 252 - Aus 253

401(T)/2013 AUSTRALIA - QUEENSLAND - Upstart Bay - Light buoy off station

Maritime Safety Queensland Notice 297(T)/2013 (AA666335)

The light buoy, *Fl.R.2.5s*, (19° 49'.44 S 147° 42'.33 E) is off station.

Chart temporarily affected - Aus 826

463(T)/2013 AUSTRALIA - QUEENSLAND - Great Sandy Strait - Wreck

Maritime Safety Queensland Notice 348(T)/2013 (AA669341)

A wreck exists in position 25° 32'.04 S 152° 55'.49 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 240 - Aus 241

512(T)/2013 AUSTRALIA - QUEENSLAND - North Keppel Island - Wreck

Maritime Safety Queensland Notice 379(T)/2013 (AA671710)

A wreck marked by a special buoy exists in position 23° 03'.80 S 150° 53'.24 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 820 - AX 00820S

559(T)/2013 AUSTRALIA - QUEENSLAND - Cape Cleveland - Wreck

Maritime Safety Queensland Notice 407(T)/2013 (AA674848)

A wreck marked by a special light buoy, *Fl.Y.2s*, exists in position 19° 10'.51 S 146° 59'.80 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 256 - Aus 827

602(T)/2013 AUSTRALIA - QUEENSLAND - Hinchinbrook Channel - Cardwell - Wreck

Former Notice - 1197(T)/2010 is cancelled

Maritime Safety Queensland Notice 443(T)/2012 (AA677081)

A wreck marked by a special light buoy, *Fl.Y.2.5s*, exists in position 18° 14'.71 S 146° 01'.66 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 259 - Aus 828

651(T)/2013 AUSTRALIA - QUEENSLAND - Muddy Bay - Harbour works

Date - Until 20 October 2013

Maritime Safety Queensland Notice 497(T)/2013 (AA680645)

Works associated with the development of the marina are in progress in the vicinity of 20° 16'.24 S 148° 43'.50 E. The construction area is marked by special buoys.

Chart temporarily affected - Aus 253 - Aus 268

653(T)/2013 AUSTRALIA - QUEENSLAND - Cooktown - Depth information

Former Notice - 751(T)/2012 is cancelled

Maritime Safety Queensland Notice 501(T)/2013 (AA680585)

Available depths as at 24 June 2013:

	<i>Metres</i>
* Entrance Channel	1.7
* Inner Channel	2.8
* Public Wharf	2.6
* Swing Basin	2.6
* Indicates revised entry.	

Chart temporarily affected - Aus 270

703(T)/2013 AUSTRALIA - QUEENSLAND - Boyne River - Shoaling; nav aids

Former Notice - 415(T)/2011 is cancelled

Maritime Safety Queensland Notice 529(T)/2013 (AA682825)

Shoaling exists within the entrance and approach channel to Boyne River (23° 56'.5 S 151° 21'.3 E).

A special light buoy, *Fl.Y.2.5s*, exists in position 23° 55'.64 S 151° 22'.06 E.

No5 starboard beacon (23° 55'.85 S 151° 21'.55 E) has been altered to a port beacon and renumbered No6.

No1, No3, No9 and No10 beacons have been removed and lateral buoys exist in situ.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 246

704(T)/2013 AUSTRALIA - QUEENSLAND - Gladstone - East Banks - Scientific instruments

Date - Until 4 July 2014

Maritime Safety Queensland Notice 524(T)/2013 (AA682836)

Scientific instruments marked by special light buoys, *Q. Y.*, exist in positions
23° 52'.06 S 151° 29'.30 E and 23° 51'.60 S 151° 26'.59 E.

Chart temporarily affected - Aus 246 - Aus 819

709(T)/2013 AUSTRALIA - QUEENSLAND - Port Alma - Scientific instruments

Date - Until 4 July 2014

Maritime Safety Queensland Notice 525(T)/2013 (AA682840)

Scientific instruments marked by special light buoys, *Fl. Y. 3s*, exist in positions
23° 34'.10 S 150° 51'.53 E and 23° 31'.59 S 150° 55'.39 E.

Chart temporarily affected - Aus 247 - Aus 265

768(T)/2013 AUSTRALIA - QUEENSLAND - Trinity Inlet to Haycock Island - Scientific instruments

Date - Until 31 July 2014

Maritime Safety Queensland Notice 551(T)/2013 (AA686131)

Subsurface scientific instruments exist in positions:

16° 45'.30 S 145° 42'.55 E
16° 48'.28 S 145° 44'.72 E
16° 51'.24 S 145° 54'.84 E
16° 51'.75 S 145° 50'.50 E
16° 53'.51 S 145° 47'.11 E
16° 57'.71 S 145° 47'.77 E.

Chart temporarily affected - Aus 262 - Aus 263 - Aus 264 - Aus 830 - AX 63262 - AXA 0830T

814(T)/2013 AUSTRALIA - QUEENSLAND - Magnetic Island - Nelly Bay - Obstruction

Maritime Safety Queensland Notice 602(T)/2013 (AA688518)

An obstruction exists in position 19° 09'.57 S 146° 51'.29 E.

Chart temporarily affected - Aus 256

821(T)/2013 AUSTRALIA - QUEENSLAND - Trinity Bay - Light buoy withdrawn

Maritime Safety Queensland Notice 605(T)/2013 (AA688713)

The safe water light buoy, *LFl. 10s* (16° 18'.76 S 145° 27'.19 E), has been temporarily withdrawn.

Chart temporarily affected - Aus 831

983(T)/2013 AUSTRALIA - TORRES STRAIT - Channel Rock - Wreck; light buoy

Former Notice - 775(T)/2013 is cancelled

Maritime Safety Queensland Notice 709(T)/2013 (AA695295)

A wreck marked by a special light buoy, *Fl. Y. 2-5s*, exists in position 10° 33'.14 S 142° 15'.13 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 292 - Aus 293 - Aus 299 - Aus 700

1014(T)/2013 AUSTRALIA - QUEENSLAND - Hay Point - Depth information

Former Notice - 650(T)/2012 is cancelled

Maritime Safety Queensland Notices 781/2013, 784/2013 (AA699549, AA699720)

Available depths as at 27 September 2013:

	<i>Metres</i>	<i>Remarks</i>
* Entrance Channel	14.7	Between No 4 beacon and the northern end.
	15.0	Seaward of beacon No 4.
* HPS Berth No 1	16.4	

* HPS Berth No 2	16.8	
* DBCT Berth No 1	17.6	
* DBCT Berth No 2	17.9	
* DBCT Berth No 3	17.9	
* DBCT Berth No 4	17.8	
Tug Harbour entrance channel	5.1	Lesser depths exist close to the outer edges of the channel and around tug berths and piers.
* Indicates revised entry.		

Lesser depth exist in an area south of Hay Point No 1 berth out to approximately 100m east northeast from the seaward edge of berth No 3 and leading southward to the southwest corner of the channel

Chart temporarily affected - Aus 249 - Aus 250 - AX 00249S

1059(T)/2013 AUSTRALIA - QUEENSLAND - Pumicestone Channel - Light beacon unlit
Maritime Safety Queensland Notice 812(T)/2013 (AA702174)

The starboard light beacon, *Fl.G.2-5s* (27° 02'.69 S 153° 07'.74 E), is unlit.

A starboard lateral light buoy, *Fl.G.2-5s*, exists in position 27° 02'.68 S 153° 07'.74 E.

Chart temporarily affected - Aus 235 - Aus 236

1061(T)/2013 AUSTRALIA - QUEENSLAND - Townsville - Stuart Creek - Wreck
Maritime Safety Queensland Notice 816(T)/2013 (AA701888)

A wreck marked by a special light buoy, *Fl.Y.2-5s*, exists in position 19° 16'.82 S 146° 49'.83 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 257

1098(T)/2013 AUSTRALIA - QUEENSLAND - Cape Tribulation - Wreck; exclusion zone
Former Notice - 1055(T)/2013 is cancelled
Maritime Safety Queensland Notice 831(T)/2013 (AA703110)

A wreck exists in position 16° 07'.64 S 145° 31'.22 E.

Salvage operations are in progress and a 1852m radius exclusion zone exists around the wreck.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 831 - AXA 0830T

1101(T)/2013 AUSTRALIA - QUEENSLAND - Hay Point - AIS trial
Date - Until 15 January 2014
Maritime Safety Queensland Notice 827(T)/2013 (AA703038, AA703683)

AIS exist as follows:

<i>MMSI</i>	<i>Position (WGS84 datum)</i>	<i>Remarks</i>	<i>Type</i>
995036068	21° 15'.96 S 149° 19'.70 E	Starboard lateral mark	Virtual
995036069	21° 16'.22 S 149° 19'.78 E	Port lateral mark	Virtual
995036067	21° 15'.61 S 149° 19'.54 E	Special mark	Virtual
995031021	21° 15'.33 S 149° 23'.18 E	Port lateral mark	Synthetic

Chart temporarily affected - Aus 249 - Aus 250 - AX 00249S

1104(T)/2013 AUSTRALIA - QUEENSLAND - Mooloolaba - Light beacon damaged
Maritime Safety Queensland Notice 832(T)/2013 (AA702961)

The No8 light beacon (26° 41'.01 S 153° 08'.12 E) has been damaged; a temporary light, *Fl.R.2-5s*, exists on the beacon.

Chart temporarily affected - Aus 235

1109(T)/2013 AUSTRALIA - QUEENSLAND - Whitsundays - Spitfire Rock - Light beacon destroyed

Former Notice - 422(T)/2011 is cancelled

Maritime Safety Queensland Notice 930(T)/2010, 837/2013 (AA500617, AA702934)

The west cardinal light beacon (20° 28'.59 S 149° 01'.70 E) has been destroyed; a west cardinal cylindrical light buoy Q(9)15s exists in situ.

Chart temporarily affected - Aus 252 - Aus 254 - Aus 824

1156(T)/2013 AUSTRALIA - QUEENSLAND - Great Sandy Strait - Tin Can Inlet - Snapper Creek - Wreck

Maritime Safety Queensland Notice 876(T)/2013 (AA705816)

A stranded wreck exists in position 25° 54'.44 S 153° 00'.06 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 240

1159(T)/2013 AUSTRALIA - QUEENSLAND - Mackay - Depth information

Former Notice - 1017(T)/2013 is cancelled

Maritime Safety Queensland Notice 888(T)/2013 (AA705666)

Available depths as at 6 November 2013:

<i>Remarks</i>	<i>Metres</i>
* Entrance Channel	8.6
* Swing Basin	8.5
* Berth No 1	11.0
* Berth No 3	12.5
* Berth No 3 & 4 composite	12.5
* Berth No 4	10.8
* Berth No 5	12.5
* Indicates revised entry.	

Chart temporarily affected - Aus 250

1214(T)/2013 AUSTRALIA - QUEENSLAND - Cape Bowling Green - Scientific instrument

Former Notice - 926(T)/2011 is cancelled

Australian Institute of Marine Science (AA710432)

A subsurface scientific instrument, depth 10m, exists in position 19° 18'.25 S 147° 37'.23 E.

Chart temporarily affected - Aus 826 - Aus 827

1217(T)/2013 AUSTRALIA - QUEENSLAND - Great Sandy Strait - Tin Can Inlet - Wreck

Maritime Safety Queensland Notice 908(T)/2013 (AA708493)

A stranded wreck, marked by a Q.Y light, exists in position 25° 51'.85 S 153° 02'.10 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 241

1223(T)/2013 AUSTRALIA - QUEENSLAND - Weipa - Light beacon destroyed

Former Notice - 1165(T)/2013 is cancelled

Maritime Safety Queensland Notices 896(T)/2013; 915/2013 (AA706057, AA708092)

SC24 light beacon, Q.R (12° 40'.16 S 141° 49'.74 E), has been destroyed; a port lateral light buoy, Q.R, exists in situ.

Chart temporarily affected - Aus 4

1268(T)/2013 AUSTRALIA - QUEENSLAND - Moreton Bay - Redland Bay - Light beacon destroyed

Maritime Safety Queensland Notice 951(T)/2013 (AA712577)

The starboard light beacon, Fl.G.3s (27° 36'.83 S 153° 18'.84 E), has been destroyed.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236

1270(T)/2013 AUSTRALIA - QUEENSLAND - Pumicestone Channel - Ningi Creek - Wreck
Maritime Safety Queensland Notice 938(T)/2013 (AA711733)

A wreck, marked by buoys, exists in position 27° 03'.91 S 153° 08'.04 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 235 - Aus 236

1274(T)/2013 AUSTRALIA - QUEENSLAND - Two Islands - Wreck
Maritime Safety Queensland Notice 933(T)/2013 (AA711818)

A wreck exists in position 15° 01'.72 S 145° 28'.01 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 831 - Aus 832

52(T)/2014 AUSTRALIA - QUEENSLAND - Brisbane River - Town Reach - Drilling operations
Date - Until 14 April 2014
Maritime Safety Queensland Notice 17(T)/2014 (AA715761)

Drilling operations are in progress in the vicinity of position 27° 28'.70 S 153° 01'.95 E.

The barge will display appropriate lights.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 238

53(T)/2014 AUSTRALIA - QUEENSLAND - Bundaberg - Depth information
Former Notice - 970(T)/2013 is cancelled
Maritime Safety Queensland Notice 973(T)/2013 (AA713986)

Available depths as at 19 December 2013:

	<i>Metres</i>
* Sea Reach	7.5
* Middle Reach	8.5
* Inner Reach	8.5
* Swing Basin	6.8
* Oil Berth	8.4
* BST Berth	8.5
Deep draught departure channel	8.6
* Indicates revised entry.	

Chart temporarily affected - Aus 242 - Aus 243

57(P)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Clinton Channel - Light beacons to be established
Date - On or about 21 March 2014
Maritime Safety Queensland Notice 961(T)/2013 (AA713818, AA715446)

Light beacons marked by temporary lights, *Fl. Y. 4s*, will be established in the following positions:

W2	23° 48'.558 S 151° 13'.903 E
W4	23° 48'.510 S 151° 13'.783 E
W6	23° 48'.439 S 151° 13'.607 E
W8	23° 48'.437 S 151° 13'.521 E
W10	23° 48'.434 S 151° 13'.448 E
Departure front lead	23° 48'.526 S 151° 14'.448 E
Departure rear lead	23° 48'.559 S 151° 14'.621 E.

Chart which will be affected - Aus 244 - Aus 245

64(T)/2014 AUSTRALIA - QUEENSLAND - Rib Reef - Light buoy withdrawn

Maritime Safety Queensland Notice 958(T)/2013 (AA714657)

The special light buoy, *Fl.Y.5s* (18° 28'.11 S 146° 52'.34 E), has been temporarily withdrawn.

Chart temporarily affected - Aus 828

129(T)/2014 AUSTRALIA - QUEENSLAND - Cairns - Trinity Inlet - Wreck

Maritime Safety Queensland Notice 20(T)/2014 (AA717934)

A stranded wreck, marked by a special buoy, exists in position 16° 55'.64 S 145° 47'.10 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 263

130(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Harbour works

Date - Until 25 August 2014

Maritime Safety Queensland Notice 46(T)/2014 (AA718636)

Harbour works associated with the construction of a tug base are in progress in an area bounded by the following:

<i>Position</i>	<i>Remarks</i>
23° 49'.59 S 151° 14'.69 E	
23° 49'.53 S 151° 14'.74 E	marked by special spar buoy
23° 49'.41 S 151° 14'.63 E	marked by special spar buoy
23° 49'.43 S 151° 14'.55 E	marked by special spar buoy
23° 49'.46 S 151° 14'.53 E.	

The vessels *Bambra*, *Babinda*, *Steel Trader*, *Okishin* and *Simone Jane* are on site and will monitor VHF Ch 13, Ch 15 and Ch 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 244 - Aus 245 - Aus 819

167(T)/2014 AUSTRALIA - QUEENSLAND - Airlie Beach - Muddy Bay - Wreck

Maritime Safety Queensland Notice 74(T)/2014 (AA721262)

A wreck marked by a special light buoy, *Q.Y.*, exists in position 20° 16'.07 S 148° 43'.64 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 252 - Aus 253 - Aus 268

168(T)/2014 AUSTRALIA - QUEENSLAND - Brisbane River - Shafston Reach - Harbour works

Former Notice - 1213(T)/2013 is cancelled

Date - Until 31 July 2014

Maritime Safety Queensland Notices 562(T)/2013, 920(T)/2013, 54(T)/2014 (AA686411, AA708740, AA720023)

Harbour works associated with the reconstruction of the New Farm riverwalk are in progress.

A temporary 6 knot speed limit, marked by four special light buoys, *Q.Y.*, exists between 27° 27'.83 S 153° 02'.15 E and 27° 27'.77 S 153° 02'.15 E; downstream to 27° 28'.37 S 153° 02'.38 E and 27° 28'.35 S 153° 02'.44 E.

Port lateral light buoys, *Fl.R.2.5s*, exist in positions 27° 27'.92 S 153° 02'.25 E and 27° 27'.87 S 153° 02'.21 E. The port lateral light buoy (27° 28'.09 S 153° 02'.32 E) has been repositioned to 27° 28'.10 S 153° 02'.30 E.

Three starboard lateral light buoys, *Fl.G.2.5s*, will be deployed to mark the starboard extremity of a reduced width channel and will be adjusted frequently to meet operational requirements.

The barges *MDT1803* and *AMS Gladstone*, along with two additional barges and tugs are on site and will monitor VHF Ch 13. The barges will display appropriate lights and shapes and the offshore anchor lines will be marked by special light buoys.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 238

171(T)/2014 AUSTRALIA - QUEENSLAND - Karumba - Depth information

Former Notice - 1015(T)/2013 is cancelled

Maritime Safety Queensland Notices 374(T)/2013, 89(T)/2014 (AA671724, AA722185))

Available depths as at 11 February 2014:

<i>Berth</i>	<i>Metres</i>	<i>Remarks</i>
* Entrance Channel	3.1	Shoaling exists on the northern side of the channel in the vicinity of position 17° 26'.64 S 140° 45'.32 E. Mariners are advised to navigate south of the centreline of the channel.
Mobil/Trinity Wharf	6.3	
Raptis Wharf	5.3	
Ruby Marine Wharf	5.3	
Gulf Freight Services Wharf	6.2	
Karumba Cold Stores Wharf	6.2	
Seaswift/Shell Wharf	6.2	
Karumba Livestock Loading Wharf	5.4	
Gulf Freight Services Ramp/Wharf	4.6	
Pasminco Export Wharf	4.2	
* Indicates revised entry.		

Chart temporarily affected - Aus 6

176(T)/2014 AUSTRALIA - QUEENSLAND - Townsville - Depth information

Former Notice - 66(T)/2014 is cancelled

Maritime Safety Queensland Notice 75(T)/2014 (AA721250)

Available depths as at 6 February 2014:

	<i>Metres</i>	<i>Remarks</i>
* Sea Channel	11.9	
* Platypus Channel	11.9	
<i>Outer Harbour:</i>		
* Arrival Channel	6.1	
* Departure Channel	10.6	
<i>Inner Harbour:</i>		
* Harbour	11.5	
<i>Berths:</i>		
* No 1	11.8	
No 2	12.5	
No 3	11.4	
No 4	10.3	
No 7	11.7	
No 8	12.8	
No 9	11.4	
Between No 9 and No 10	7.3	Seaward of 0 mark at No 10
No 10	12.6	
* No 11	10.9	
* Ross River Channel	2.2	Entrance to beacon No 6
Ross River	-	Upstream of beacon No 6
Ross Creek	-	
* Indicates new or revised entry.		

Chart temporarily affected - Aus 256 - Aus 257

177(T)/2014 AUSTRALIA - QUEENSLAND - Whitehaven Bay - Light beacon destroyed

Former Notice - 213(T)/2013 is cancelled

Maritime Safety Queensland Notice 73(T)/2014 (AA721260)

The north cardinal light beacon, Q (20° 17'.53 S 149° 03'.35 E), has been destroyed.

Chart temporarily affected - Aus 252 - Aus 253

222(T)/2014 AUSTRALIA - QUEENSLAND - Burnett River - Millaquin Reach - Tide board

Maritime Safety Queensland Notice 464(T)/2012 (AA598153)

A tide board marked by a light, *Fl.Y.2-5s*, exists in position 24° 49'.74 S 152° 22'.38 E.

Chart temporarily affected - Aus 242

224(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Light beacon destroyed; light buoy

Former Notice - 131(T)/2014 is cancelled

Maritime Safety Queensland Notice 100(T)/2014 (AA723557)

S1 starboard light beacon, *Fl.G.2s* (23° 53'.90 S 151° 30'.40 E), has been destroyed; a starboard light buoy, *Fl.G.2s*, exists in situ.

Chart temporarily affected - Aus 246 - Aus 490 - Aus 819

225(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Curtis Island - Pipeline

Date - Until 23 March 2014

Maritime Safety Queensland Notice 102(T)/2014 (AA723559)

Pipeline marked by special light buoys, *Q.Y.*, exists between:

23° 44'.95 S 151° 10'.49 E

23° 44'.97 S 151° 10'.34 E

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 245 - Aus 819

226(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Light buoys withdrawn

Date - Until 28 April 2014

Maritime Safety Queensland Notice 1001(T)/2014 (AA723560)

TSB7 light buoy (23° 47'.02 S 151° 10'.38 E) and *TSB5* light buoy (23° 46'.98 S 151° 10'.49 E) have been temporarily withdrawn.

Chart temporarily affected - Aus 244 - Aus 245

228(T)/2014 AUSTRALIA - QUEENSLAND - Moreton Bay - Brisbane - Manly Boat Harbour - Dredging operations

Date - Until 30 April 2014

Maritime Safety Queensland Notice 92(T)/2014 (AA722597)

The dredge *Ken Harvey* is conducting dredging operations in the entrance channel of Manly Boat Harbour (27° 27'.06 S 153° 11'.56 E).

mooring buoys exist in the following positions:

27° 26'.74 S 153° 12'.05 E

27° 26'.70 S 153° 12'.14 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236

229(T)/2014 AUSTRALIA - QUEENSLAND - Moreton Bay - Redcliffe - Light beacon withdrawn

Maritime Safety Queensland Notice 108(T)/2014 (AA724472)

The east cardinal light beacon, *Q(3)10s* (27° 13'.57 S 153° 07'.13 E), has been temporarily withdrawn.

Chart temporarily affected - Aus 236

232(T)/2014 AUSTRALIA - QUEENSLAND - Townsville - Wreck

Maritime Safety Queensland Notice 109(T)/2014 (AA723945)

A wreck marked by a special light buoy, *Fl.Y.4s*, exists in position 19° 14'.90 S 146° 49'.64 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 256 - Aus 257

269(T)/2014 AUSTRALIA - QUEENSLAND - Bowen - Wreck

Former Notice - 221(T)/2014 is cancelled

Maritime Safety Queensland Notice 144(T)/2014 (AA727566)

A stranded wreck marked by a light, *Fl. Y. 4s*, exists in position 20° 01'.37 S 148° 15'.58 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 268

271(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Light buoy

Former Notice - 950(T)/2012 is cancelled

Maritime Safety Queensland Notice 143(T)/2014 (AA727568)

Special light buoy, *Fl. Y. 2.5s*, exists in position 23° 49'.57 S 151° 14'.86 E.

Chart temporarily affected - Aus 244 - Aus 245

272(T)/2014 AUSTRALIA - QUEENSLAND - Gold Coast - Nerang River - Harbour works

Former Notice - 1100(T)/2013 is cancelled

Maritime Safety Queensland Notice 327(T)/2013, 124(T)/2014 (AA668391, AA726476)

Construction works on the Gold Coast bridge are in progress.

The *F. Bu* lights in positions 27° 58'.62 S 153° 25'.27 E and 27° 58'.61 S 153° 25'.28 E are unlit.

Lateral light buoys will be positioned to guide vessels through the construction zone and beneath the relevant bridge navigation span as required. The temporary navigation span clearance is 4.5m HAT.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 230

277(T)/2014 AUSTRALIA - QUEENSLAND - Shoalwater Bay - Raynham Island - Live firing

Former Notice - 175(T)/2014 is cancelled

Date - Until 30 June 2014

Maritime Safety Queensland Notice 119(T)/2014 (AA725007)

Live firing activities will be conducted in the Shoalwater Bay training area during the period 14 March to 30 June 2014.

Flares will be fired within a 3704m radius of Raynham Island (22° 16'.06 S 150° 32'.43 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 260 - Aus 367 - Aus 822 - AX 00260S - AX 00260T - AX 00367S - AX 00822S

278(T)/2014 AUSTRALIA - QUEENSLAND - Townsville - Ross River - Harbour works

Date - Until 24 April 2014

Maritime Safety Queensland Notice 118(T)/2014 (AA725017)

Harbour works associated with the removal of mooring piles are in progress in the vicinity of position 19° 16'.45 S 146° 49'.97 E.

The barge *PMG 121* and support vessels *Swordfish*, *Samsson 11*, *Punt 1* and *PMG Tender* are on site. MT *Swordfish* will monitor VHF Ch 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 257

339(T)/2014 AUSTRALIA - QUEENSLAND - Burnett River - Millaquin Reach - Dredging operations

Date - Until 28 May 2014

Maritime Safety Queensland Notice 159(T)/2014 (AA730565)

The dredge *Nu Endeavour* and support vessel *MV Tramp* are conducting dredging operations in the Burnett River between

positions 24° 48'.95 S 152° 22'.00 E and 24° 50'.74 S 152° 22'.17 E.

A pipeline exists between the dredge and a barge.

The dredge and support vessel will monitor UHF and VHF Ch 13, Ch 16 and Ch 81.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 242

340(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Scientific instrument

Former Notice - 158(T)/2013 is cancelled

Date - Until 30 June 2014
Maritime Safety Queensland Notice 158(T)/2013 (AA729213)

A special light buoy, *Fl. Y. 3s*, exists in position 23° 47'.73 S 151° 14'.29 E.

Chart temporarily affected - Aus 245

345(T)/2014 AUSTRALIA - QUEENSLAND - Moreton Bay - Brisbane River - Luggage Point - Harbour works

Former Notice - 63(T)/2014 is cancelled

Date - Until 13 June 2014

Maritime Safety Queensland Notice 154(T)/2014 (AA729100)

Harbour works are in progress in the vicinity of position 27° 22'.86 S 153° 09'.40 E.

The barge *Steel Hauler* is on site and will deploy four anchors marked by special light buoys, *Q. Y.* The barge will display appropriate lights and shapes and will monitor VHF Ch 12.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 237

346(T)/2014 AUSTRALIA - QUEENSLAND - Schooner Rock - Light beacon destroyed

Former Notice - 55(T)/2013 is cancelled

Maritime Safety Queensland Notice 163(T)/2014 (AA729526)

The north cardinal light beacon (20° 54'.04 S 149° 25'.91 E) has been destroyed.

Chart temporarily affected - Aus 251 - Aus 824

374(T)/2014 AUSTRALIA - QUEENSLAND - Abbot Point - Scientific instruments

Former Notice - 220(T)/2014 is cancelled

Date - Until 30 July 2014

Maritime Safety Queensland Notice 191(T)/2014 (AA731613)

Special light buoys, *Fl. Y. 4s*, exist in the following positions:

19° 48'.06 S 148° 18'.38 E
19° 41'.67 S 148° 07'.26 E
19° 41'.61 S 148° 07'.54 E
19° 41'.53 S 148° 07'.74 E
19° 41'.89 S 148° 17'.89 E
19° 41'.68 S 148° 18'.23 E.

Chart temporarily affected - Aus 825 - Aus 826

376(T)/2014 AUSTRALIA - QUEENSLAND - Cape Bowling Green - Light buoy off station

Maritime Safety Queensland Notice 193(T)/2014 (AA731849)

The west cardinal light buoy, *Q(9)15s* (19° 17'.86 S 147° 22'.28 E) is off station and reported to be in position 19° 17'.13 S 147° 23'.08 E.

Chart temporarily affected - Aus 827

377(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Nav aids repositioned

Former Notice - 1056(T)/2013 is cancelled

Nav aids exist as follows:

	<i>Positions</i>	<i>Remarks</i>
JC1	23° 47'.93 S 151° 13'.04 E	Light beacon <i>Fl.G.2.5s</i>
JC 2	23° 47'.78 S 151° 12'.59 E	Light beacon <i>Fl.R.2.5s</i>
JC 3	23° 47'.61 S 151° 12'.67 E	Light beacon <i>Fl.G.2.5s</i>
JC 4	23° 47'.54 S 151° 12'.30 E	Light beacon <i>Fl.R.2.5s</i>
JC 5	23° 47'.42 S 151° 12'.43 E	Light beacon <i>Fl.G.2.5s</i>
JC 6	23° 47'.23 S 151° 11'.78 E	Light buoy <i>Fl.Y.2.5s</i>
JC 7	23° 47'.10 S 151° 12'.27 E	Light buoy <i>Fl.Y.2.5s</i>
JC 8	23° 47'.12 S 151° 11'.76 E	Light beacon <i>Fl.R.2.5s</i>
JC 9	23° 46'.87 S 151° 11'.99 E	Light buoy <i>Fl.Y.2.5s</i>
JC 10	23° 47'.05 S 151° 11'.64 E	Light buoy <i>Fl.Y.2.5s</i>
JC 11	23° 46'.58 S 151° 11'.63 E	Light buoy <i>Fl.Y.2.5s</i>
JC 12	23° 46'.84 S 151° 11'.41 E	Light buoy <i>Fl.Y.2.5s</i>
JC 13	23° 46'.56 S 151° 11'.47 E	Light beacon <i>Fl.G.2.5s</i>
JC 14	23° 46'.71 S 151° 11'.35 E	Light beacon <i>Fl.R.2.5s</i>
JC 15	23° 46'.39 S 151° 11'.34 E	Light beacon <i>Fl.G.2.5s</i>
JC 16	23° 46'.41 S 151° 11'.13 E	Light beacon <i>Fl.R.2.5s</i>
JC 17	23° 46'.26 S 151° 11'.37 E	Light buoy <i>Fl.G.2.5s</i>
JC 18	23° 46'.35 S 151° 11'.09 E	Light buoy <i>Fl.Y.2.5s</i>
JC 19	23° 46'.10 S 151° 11'.41 E	Light buoy <i>Fl.G.2.5s</i>
JC 20	23° 46'.07 S 151° 10'.89 E	Light buoy <i>Fl.Y.2.5s</i>
JC 21	23° 46'.15 S 151° 11'.23 E	Light buoy <i>Fl.Y.2.5s</i>
JC 22	23° 46'.01 S 151° 10'.90 E	Light buoy <i>Fl.R.2.5s</i>
JC 23	23° 45'.98 S 151° 11'.24 E	Light buoy <i>Fl.Y.2.5s</i>
JC 24	23° 45'.75 S 151° 10'.79 E	Light buoy <i>Fl.R.2.5s</i>
JC 25	23° 45'.70 S 151° 11'.06 E	Light buoy <i>Fl.Y.2.5s</i>
JC 26	23° 45'.58 S 151° 10'.75 E	Light buoy <i>Fl.R.2.5s</i>
JC 27	23° 45'.76 S 151° 10'.95 E	Light buoy <i>Fl.Y.2.5s</i>
JC 28	23° 45'.47 S 151° 10'.66 E	Light buoy <i>Fl.R.2.5s</i>
JC 29	23° 45'.84 S 151° 10'.94 E	Light buoy <i>Fl.G.2.5s</i>
JC 30	23° 45'.34 S 151° 10'.67 E	Light buoy <i>Fl.Y.2.5s</i>
JC 31	23° 45'.71 S 151° 10'.89 E	Light buoy <i>Fl.G.2.5s</i>
JC 33	23° 45'.57 S 151° 10'.86 E	Light buoy <i>Fl.G.2.5s</i>
JC 35	23° 45'.51 S 151° 10'.89 E	Light buoy <i>Fl.G.2.5s</i>
JC 37	23° 45'.30 S 151° 10'.73 E	Light buoy <i>Fl.Y.2.5s</i>
JCAF	23° 46'.32 S 151° 11'.02 E	Front Lead <i>Q.Bu (F. Day) & Fl(2)5s</i>
JCAR	23° 45'.84 S 151° 10'.46 E	Rear Lead <i>Iso.Bu.2s (F. Day) & VQ(9)10s</i>
APAF	23° 45'.49 S 151° 10'.58 E	Front Lead <i>Q.Bu (F. Day) & Fl.R.2.5s</i>
APAR	23° 45'.18 S 151° 10'.35 E	Rear Lead <i>Iso.Bu.2s (F. Day) & Fl(2)5s</i>
APDF	23° 47'.45 S 151° 12'.00 E	Front Lead <i>Q.Bu (F. Day) & Fl(2)5s</i>
APDR	23° 47'.68 S 151° 12'.17 E	Rear Lead <i>Iso.Bu.2s (F. Day) & Fl.G.4s</i>
JCDF	23° 48'.65 S 151° 13'.72 E	Front Lead <i>Q.Bu (F. Day) & Fl.Y.6s</i>
JCDR	23° 49'.03 S 151° 14'.19 E	Rear Lead <i>Iso.Bu.2s (F. Day)</i>

New charts Aus 271 and Aus 272 and new editions Aus 244 and Aus 245 are due for publication 2/3Q 2014.

ENC AU5244X5 has been updated.

Chart temporarily affected - Aus 244 - Aus 245

378(T)/2014 AUSTRALIA - QUEENSLAND - Hinchinbrook Channel - Light buoys off station

Maritime Safety Queensland Notice 197(T)/2014 (AA732796)

The following light buoys are reported off station:

No 17	<i>Fl.G.2.5s</i>	18° 30'.05 S 146° 18.65 E
No 18	<i>Q.R</i>	18° 30'.43 S 146° 19.12 E
No 19	<i>Q.G</i>	18° 30'.19 S 146° 18.73 E

Chart temporarily affected - Aus 259 - Aus 267

379(T)/2014 AUSTRALIA - QUEENSLAND - Magnetic Island - Bremner Point - Scientific instrument

Date - Until 5 November 2015

Maritime Safety Queensland 91(T)/2014 (AA731108)

A scientific instrument marked by special light buoy, *Fl. Y. 3s*, exists in position 19° 09'.32 S 146° 52'.57 E.

Chart temporarily affected - Aus 256

381(T)/2014 AUSTRALIA - QUEENSLAND - Moreton Bay - Victoria Point - Dredging operations

Date - Until 6 June 2014

Maritime Safety Queensland Notice 194(T)/2014 (AA732380)

The dredge BSB1, and support vessels, *Little Toot* and *Groper* are conducting dredging operations in the vicinity of 27° 35'.0 S 153° 19'.2 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236

383(T)/2014 AUSTRALIA - QUEENSLAND - Townsville - Ross River - Dredging operations

Date - Until 30 April 2014

Maritime Safety Queensland Notice 190(t)/2014 (AA731608)

The dredge *Laura F* will be conducting dredging operations in Ross River in the vicinity of position 19° 16'.52 S 146° 49'.72 E.

The dredge will tow a 40m floating pipeline connecting the dredge to the shore and marked by lights *Fl. Y. 2s*.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 257

411(T)/2014 AUSTRALIA - QUEENSLAND - Cairns - Depth information

Former Notice - 861(T)/2013 is cancelled

Maritime Safety Queensland Notice 213(T)/2014 (AA734557)

Available depths as of 13 April 2014:

	<i>Metres</i>	<i>Remarks</i>
* Entrance Channel	8.0	
Crystal Swing Basin at:		
360 metre diameter	6.8	
380 metre diameter	6.4	
Swing Basin at:		
310 metre diameter	8.7	
320 metre diameter	7.8	
Marlin Marina	4.2	
<i>Berths:</i>		
No 1	8.4	
No 2	8.5	
No 3	8.4	
No 4	8.4	
No 5	8.2	
No 6	8.1	between 500 metres and 550 metres
No 6	7.7	between 550 metres and 600 metres
No 7	9.9	
No 8	10.0	
No 10	9.3	
No 12	10.5	
Smiths Creek 1	4.7	
* Indicates revised entry.		

Chart temporarily affected - Aus 262 - Aus 263 - Aus 264 - Aus 830 - AX 00262T

412(T)/2014 AUSTRALIA - QUEENSLAND - Cairns - Senrab Point - Pile driving

Former Notice - 270(T)/2014 is cancelled

Date - Until 30 June 2014

Maritime Safety Queensland Notice 227(T)/2014 (AA735226)

The barge *Steel Trader* will be conducting pile driving operations in the vicinity of position 16° 56'.44 S 145° 46'.74 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 263 - Aus 264

414(T)/2014 AUSTRALIA - QUEENSLAND - Cooktown - Endeavour River - Light buoys off station
Maritime Safety Queensland Notice 216(T)/2014 (AA734759)

The following light buoys are off station:
No1, Fl.G.2-5s (15° 27'. 21 S 145° 15'. 33 E)
No2, Fl.R.2-5s (15° 27'. 22 S 145° 15'. 37 E)

Chart temporarily affected - Aus 270

415(T)/2014 AUSTRALIA - QUEENSLAND - Cooktown - Endeavour River - Wreck
Maritime Safety Queensland Notice 225(T)/2014 (AA735181)

A wreck marked by a light, *Fl.Y.2-5s*, exists in position 15° 27'.84 S 145° 14'.92 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 270

419(T)/2014 AUSTRALIA - QUEENSLAND - Port Douglas - Nav aids unreliable
Maritime Safety Queensland Notice 223(T)/2014 (AA735179)

Nav aids in Port Douglas are unreliable; mariners are advised to navigate with caution.

Chart temporarily affected - Aus 270

420(T)/2014 AUSTRALIA - QUEENSLAND - Port Douglas - Dicksons Inlet - Dredging operations
Former Notice - 173(T)/2014 is cancelled
Date - Until 16 May 2014
Maritime Safety Queensland Notice 224(T)/2014 (AA35180)

The dredge *Everglades* is conducting dredging operations in Dickson Inlet (16° 29'.00 S 145° 27'.55 E).

A submerged pipeline is marked by lateral light buoys as follows:
Q.R, 16° 29'. 172 S 145° 27'. 439 E
Q.G, 16° 29'. 157 S 145° 27'. 479 E.

The dredge will monitor VHF Ch 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 270

423(T)/2014 AUSTRALIA - QUEENSLAND - Yorkeys Knob - Light beacon destroyed
Maritime Safety Queensland Notice 222(T)/2014 (AA735178)

The port lateral light beacon (16° 48'.01 S 145° 43'.03 E) has been destroyed.

Chart temporarily affected - Aus 262 - AX 00262T

447(T)/2014 AUSTRALIA - QUEENSLAND - Decapolis Reef - Light beacon; light buoy
Former Notice - 413(T)/2014 is cancelled
Date - Until 30 June 2015
Australian Maritime Safety Authority Final ATH 10/2014 (AA740294)

The light beacon, *Fl.2-5s 6m 10M* (14° 51'.10 S 145° 16'.41 E), has been destroyed.

A temporary starboard lateral pillar light buoy, *Fl.G.2-5s*, exists in position 14° 50'.97 S 145° 16'.54 E.

Chart temporarily affected - Aus 832

448(T)/2014 AUSTRALIA - QUEENSLAND - Gladstone - Harbour works

Date - Until 20 May 2014

Maritime Safety Queensland Notice 238(T)/2014 (AA736562)

Harbour works are in progress at beacons S1 (23° 53'.89 S 151° 30'.40 E) and Q2 (23° 50'.47 S 151° 18'.75 E).

The barge *Jack Up 1* and support vessels *Sledgehammer*, *AMS Nova*, *AMS Orion* and *Burnu* will be on site to conduct works. The barge will display appropriate lights and shapes and will monitor VHF Ch 12.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 245 - Aus 246 - Aus 819

449(T)/2014 AUSTRALIA - QUEENSLAND - Mooloolaba - Shoaling

Former Notice - 417(T)/2014 is cancelled

Maritime Safety Queensland Notice 233(T)/2014 (AA736045)

Shoaling with a least depth of 2.4m exists within the main channel to Mooloolah River.

A least depth of 2.2m exists adjacent to the end of the eastern breakwater, in the vicinity of position 26° 40'.76 S 153° 07'.94 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 235

450(T)/2014 AUSTRALIA - QUEENSLAND - Moreton Bay - East Channel - Scientific instruments

Date - Until 30 January 2015

Maritime Safety Queensland Notice 241(T)/2014 (AA737310)

Special light buoys, Q.Y, exist in the following positions:

27° 09'.85 S 153° 21'.83 E

27° 13'.18 S 153° 20'.84 E

27° 11'.98 S 153° 19'.70 E.

Chart temporarily affected - Aus 236

451(T)/2014 AUSTRALIA - QUEENSLAND - Moreton Bay - Brisbane River - Depth information

Former Notice - 418(T)/2014 is cancelled

Brisbane Port Corporation (AA739471)

Available depths and under keel clearances (UKC) at 6 May 2014:

<i>Berth</i>	<i>Metres</i>	<i>Remarks</i>
* Fisherman Islands No12	13.8	
Fisherman Islands No11	14.0	
Fisherman Islands No10	14.1	
Fisherman Islands No9	14.0	
Fisherman Islands No8	13.9	
Fisherman Islands No7	13.8	
* Fisherman Islands No6	13.9	
* Fisherman Islands No5	13.7	
* Fisherman Islands No4	13.7	
* Fisherman Islands No3	13.6	
Fisherman Islands No2	14.1	
* Fisherman Islands No1	14.0	
* Fisherman Islands Grain and Woodchip	13.1	
* Caltex Fisherman Islands	14.5	
* Fisherman Islands Coal	13.8	
* Fisherman Islands General Purpose	11.2	
BP Luggage Point	13.8	
* Caltex Products	9.9	
* Cement Australia Co Wharf	9.6	
* BP Products	9.7	
Shell	10.7	
* Graincorp Liquid Terminal	10.4	
Incitec North	9.7	
* Incitec South	9.4	
* Pinkenba 1	10.0	
* Pinkenba 2	10.0	

Riverside Marina	-
Sugar Terminal	9.7
Cairncross Fitting Out Wharf	7.1
Cairncross Breasting Wharf	4.7
Brisbane Naval Wharf	4.3
* Maritime No1	9.0
* Hamilton No4	10.3
Hamilton No1	8.5
Brisbane Cruise Ship Terminal	8.5

	<i>Metres</i>	<i>UKC/Remarks</i>
<i>Moreton Bay:</i>		
North West Channel	15.0	2.3 (280m width)
North West Bypass Channel	9.2	1.6
Spitfire Channel	15.0	1.5 (600m width)
East Knoll Bypass Channel	6.0	1.4
East Channel	15.0	1.5 (300m width from western side)
Main Channel (M8 - M9)	10.0	1.8
Entrance Channel (E5 - EBCN)	14.7	1.5
<i>Brisbane River:</i>		
Outer Bar Cutting	13.7	1.46
* Inner Bar Cutting	13.7	1.46
* Fisherman Islands Swing Basin	13.7	1.3
River	9.1	0.6 / 0.9 (draft/tide)
Cement Australia Swing Basin	9.1	0.6 / 0.9 (draft/tide)
* Pinkenba Swing Basin	8.9	0.6 / 0.9 (draft/tide)
* Hamilton Swing Basin	8.5	0.6 / 0.9 (draft/tide)
* Indicates new or revised entry.		

Chart temporarily affected - Aus 235 - Aus 236 - Aus 237 - Aus 238 - Aus 814 - Aus 815

NORTHERN TERRITORY

223(T)/2009 AUSTRALIA - TIMOR SEA - Sahul Banks - Navaid; racon non operational

Former Notice - 671(T)/2008 is cancelled

Modec Management Services (AA384494)

A lit riser turret mooring exists in position 10° 52'.50 S 126° 34'.19 E. The racon is non operational.

Chart temporarily affected - Aus 312 - Aus 4721 (INT 721) - AX 0312F - AX 4721F

814(T)/2012 AUSTRALIA - NORTHERN TERRITORY - Darwin - Light buoy withdrawn

Darwin Port Corporation Notice 83(T)/2012 (AA616039)

The light buoy, *Fl. Y. 4s*, (12° 28'.08 S 130° 49'.77 E), has been temporarily withdrawn.

Chart temporarily affected - Aus 24 - Aus 26 - AX 72026

910(T)/2012 AUSTRALIA - NORTHERN TERRITORY - Darwin - Cossack Creek - Obstruction

Darwin Port Corporation Notice 103/2012 (AA622006)

An obstruction exists in position 12° 31'.37 S 130 54'.08 E.

Chart temporarily affected - Aus 28

1003(T)/2012 AUSTRALIA - NORTHERN TERRITORY - Darwin - Lee Point to Fannie Bay - Obstructions

Date - Until 30 September 2013

Darwin Port Corporation Notice 120(T)/2012 (AA627292)

Obstructions exist in positions 12° 21'.69 S 130° 51'.23 E and 12° 25'.88 S 130° 49'.84 E.

Chart temporarily affected - Aus 24 - Aus 26 - AX 72026

1004(T)/2012 AUSTRALIA - NORTHERN TERRITORY - Darwin - Depth information

Former Notice - 62(T)/2012 is cancelled

Darwin Port Corporation (AA627294)

Available depths as at 26 September 2012:

<i>Berths</i>	<i>Metres</i>
* LNG 1-2	10.1
DLNG	13.1 (11.7 in Turning Basin)
* East Arm 0-100m	11.3
* East Arm 100-200m	12.2
* East Arm 200-300m	12.6
* East Arm 300-400m	12.6
* East Arm 400-500m	12.5
* East Arm 500-600m	13.3
East Arm 600-700m	11.8
Bulk Solids Wharf	12.4
Bulk Liquids Wharf	11.4
No 2 Fort Hill East	10.6
No 2 Fort Hill West	10.2
No 3 Stokes Hill East	4.7
No 3 Stokes Hill West	4.9
No 4 Stokes Hill East	1.7
No 4 Stokes Hill Middle	0.8
No 4 Stokes Hill West	3.2
Fishermans Wharf East	2.1
Fishermans Wharf West	0.7
Perkins International	-0.7
Perkins Domestic North	-0.9
Perkins Domestic South	-1.7
Frances Bay Marina approach channel	-0.9
* Indicates new or revised entry.	

Chart temporarily affected - Aus 24 - Aus 27 - Aus 28

1096(T)/2012 AUSTRALIA - NORTHERN TERRITORY - Darwin - Blaydin Point - Pontoon

Former Notice - 1096(T)/2012 is cancelled

Date - Until 4 December 2012
Darwin Port Corporation Notice 146(T)/2012 (AA633169)

A pontoon with a tide gauge exists in position 12° 30'.29 S 130° 55'.18 E.

Anchors will be marked by lights.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 26 - Aus 28 - AX 72026

1146(T)/2012 AUSTRALIA - NORTHERN TERRITORY - Fenton Patches - Scientific instruments

Former Notice - 960(T)/2012 is cancelled

Date - Until 31 August 2014

Darwin Port Corporation Notice 158(T)/2012 (AA636819)

Special light buoys, *Fl. Y. 3-5s*, exist in positions 12° 15'.17 S 130° 46'.39 E and 12° 14'.10 S 130° 50'.38 E.

Chart temporarily affected - Aus 309 - Aus 722 - AX 00309U - AX 72309 - AX 72722

1148(T)/2012 AUSTRALIA - NORTHERN TERRITORY - Darwin - Blaydin Point - Scientific instruments

Former Notice - 961(T)/2012 is cancelled

Date - Until 31 August 2014

Darwin Port Corporation Notice 159(T)/2012 (AA637096)

Special light buoys, *Fl. Y. 3-5s*, exist in positions 12° 30'.40 S 130° 53'.16 E and 12° 31'.47 S 130° 56'.13 E.

Chart temporarily affected - Aus 26 - Aus 28 - AX 72026

518(T)/2013 AUSTRALIA - NORTHERN TERRITORY - Darwin - Middle Ground - Obstruction

Darwin Port Corporation Notice 75(T)/2013 (AA670992)

An obstruction exists within a 50m radius of position 12° 23'.75 S 130° 46'.43 E.

Mariners are advised not to anchor within the area.

Chart temporarily affected - Aus 26 - AX 00026T

873(T)/2013 AUSTRALIA - NORTHERN TERRITORY - Darwin - East Arm - Blaydin Point - Harbour works

Former Notice - 826(T)/2013 is cancelled

Darwin Port Corporation Notice 138(T)/2013 (AA691150)

Works associated with the construction of the module offloading facility are in progress in an area bounded by the following positions:

12° 30'.51 S 130° 54'.25 E
12° 30'.29 S 130° 55'.63 E
12° 30'.92 S 130° 55'.97 E
12° 31'.05 S 130° 55'.68 E
12° 30'.57 S 130° 55'.28 E
12° 30'.90 S 130° 54'.64 E
12° 30'.66 S 130° 54'.26 E.

An exclusion zone exists within the area of the works.

The causeway is marked at the extremities by *Q. Y* lights. A silt curtain marked by *Q. Y* lights exists around the causeway.

Test piles marked by white spherical light buoys, *Q. Y*, exist in the following positions:

12° 30'.61 S 130° 54'.53 E
12° 30'.65 S 130° 54'.63 E
12° 30'.57 S 130° 54'.79 E
12° 30'.70 S 130° 54'.86 E.

Scientific instruments marked by special light buoys, *Q. Y*, exist in the following positions:

12° 30'.00 S 130° 53'.65 E
12° 30'.38 S 130° 53'.49 E
12° 30'.28 S 130° 54'.09 E
12° 30'.49 S 130° 53'.98 E
12° 30'.19 S 130° 54'.86 E
12° 29'.75 S 130° 55'.19 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 26 - Aus 28 - AX 00026T

919(T)/2013 AUSTRALIA - NORTHERN TERRITORY - Darwin - Weed Reef to Elizabeth River - Scientific instruments
Former Notices - 410(T)/2013, 654(T)/2013 are cancelled
Darwin Port Corporation Notice 145(T)/2013 (AA692841)

Special spar light buoys, *Fl. Y. 4s*, exist in the following positions:

12° 29'.39 S 130° 48'.12 E.
12° 29'.84 S 130° 52'.40 E
12° 30'.19 S 130° 53'.85 E
12° 32'.88 S 130° 50'.75 E.

Special conical light buoys, *Fl. Y. 6s*, exist in the following positions:

12° 29'.82 S 130° 53'.10 E
12° 29'.94 S 130° 52'.46 E
12° 31'.77 S 130° 56'.14 E
12° 32'.91 S 130° 52'.51 E.

Chart temporarily affected - Aus 24 - Aus 26 - Aus 27 - Aus 28 - AX 00026T

986(T)/2013 AUSTRALIA - NORTHERN TERRITORY - Darwin - East Arm - Dredging operations
Former Notice - 872(T)/2013 is cancelled
Darwin Port Corporation Notice 164(T)/2013 (AA695325)

The dredges *Eastern Aurora* and *Gungner R* and support vessel MT *Skinfaxe R* are conducting dredging operations in the vicinity of position 12° 29'.60 S 130° 53'.46 E.

A floating pipeline, marked by special buoys and lights *Q. Y*, exists from the dredge *Eastern Aurora* to position 12° 29'.50 S 130° 53'.47 E and a submerged pipeline exists between positions 12° 29'.50 S 130° 53'.47 E and 12° 29'.39 S 130° 53'.47 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 26 - Aus 28 - AX 00026T

1063(P)/2013 AUSTRALIA - NORTHERN TERRITORY - Darwin - Blaydin Point - Light beacons
Date - On or about 30 March 2014
Darwin Port Corporation Notice 177(T)/2013 (AA699032, AA700174)

Light beacons, marked by temporary lights and special light buoys, *Q. Y*, will be established as follows:

<i>Position</i>	<i>Characteristic</i>	<i>Remarks</i>
12° 30'.300 S 130° 54'.846 E	<i>Fl. G. 3s</i>	M21
12° 30'.245 S 130° 54'.583 E	<i>Fl. R. 3s</i>	M22
12° 30'.229 S 130° 54'.933 E	<i>Fl. G. 3s</i>	M23
12° 30'.067 S 130° 54'.880 E	<i>Fl. R. 3s</i>	M24
12° 30'.260 S 130° 55'.477 E	<i>Fl. G. 3s</i>	M25
12° 30'.107 S 130° 55'.285 E	<i>Fl. R. 3s</i>	M26
12° 30'.148 S 130° 55'.689 E	<i>Fl. R. 3s</i>	M28
12° 30'.474 S 130° 55'.608 E	<i>Fl. G. 3s</i>	M29
12° 30'.398 S 130° 55'.868 E	<i>Fl. R. 3s</i>	M30
12° 30'.730 S 130° 56'.015 E	<i>Fl. R. 3s</i>	M32
12° 30'.944 S 130° 55'.830 E	<i>Fl. R. 3s</i>	M34

Chart which will be affected - Aus 26 - Aus 28 - AX 00026T

1282(P)/2013 AUSTRALIA - NORTHERN TERRITORY - Darwin - East Arm - Light beacons
Former Notice - 1225(P)/2013 is cancelled
Darwin Port Corporation Notice 217(P)/2013 (AA708867)

Light beacons will be established as follows:

<i>Position</i>	<i>Characteristic</i>	<i>Remarks</i>
12° 29'.914 S 130° 53'.132 E	<i>Fl.R.2.5s</i>	MS2
12° 29'.927 S 130° 53'.276 E	<i>Fl.G.2.5s</i>	MS3
12° 29'.779 S 130° 53'.339 E	<i>Fl.R.2.5s</i>	MS4
12° 29'.807 S 130° 53'.417 E	<i>Fl.G.2.5s</i>	MS5
12° 29'.648 S 130° 53'.384 E	<i>Fl.R.2.5s</i>	MS6
12° 29'.662 S 130° 53'.443 E	<i>Fl.G.2.5s</i>	MS7
12° 29'.579 S 130° 53'.493 E	<i>Fl.G.2.5s</i>	MS9
12° 29'.650 S 130° 53'.583 E	<i>DirWRG & Fl.Y.2s</i>	SL with sectors Green 052.5° - 053.4° (0.9°), AI WG 053.4° - 054.4° (1°), White 054.4° - 055.6° (1.2°), AI WR 055.6° - 056.6° (1°), Red 056.6° - 057.5° (0.9°).

Chart which will be affected - Aus 28

70(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Darwin - Preston Point - Scientific instruments

Darwin Port Corporation Notice 236(T)/2013 (AA715149)

Scientific instruments marked by special spar light buoys, Q.Y, exist in positions 12° 30'.52 S 130° 53'.22 E and 12° 30'.29 S 130° 55'.03 E.

Chart temporarily affected - Aus 26 - Aus 28 - AX 00026T

178(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Darwin - Cullen Bay - Light altered

Darwin Port Corporation Notice 12(T)/2014 (AA721033)

The light (12° 27'.05 S 130° 49'.15 E) has been temporarily altered to *F*.

Chart temporarily affected - Aus 24

304(T)/2014 INDIAN OCEAN - Sumatera - Scientific instruments westwards

Former Notice - 870(T)/2012 is cancelled
JAMSTEC (AA727730)

Scientific instruments, Triton buoys, exist as follows:

<i>Number</i>	<i>Position</i>
17	5° 02'.12 S 94° 58'.61 E
18	1° 36'.41 S 90° 04'.85 E
19	8° 03'.97 S 95° 07'.43 E.

Chart temporarily affected - Aus 4070 (INT 70) - Aus 4071 (INT 71)

351(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Darwin - East Arm - Dredging operations

Former Notice - 73(T)/2014 is cancelled

Date - Until 1 May 2014

Darwin Port Corporation Notice 32(T)/2014 (AA729041)

The dredges *Rotterdam*, *Athena*, *Queen of the Netherlands* and *Vox Maxima* are conducting dredging operations in an area bounded by the following positions:

12° 29'.50 S 130° 51'.99 E
12° 29'.23 S 130° 52'.31 E
12° 30'.01 S 130° 53'.11 E
12° 30'.30 S 130° 53'.71 E
12° 30'.19 S 130° 54'.16 E
12° 30'.33 S 130° 54'.94 E
12° 30'.47 S 130° 54'.99 E
12° 30'.65 S 130° 54'.36 E
12° 30'.40 S 130° 53'.23 E.

The dredge *Athena* will tow a 600m floating pipeline marked by flashing yellow lights. The dredges *Queen of the Netherlands* and *Vox Maxima* will connect to the pipeline to receive dredge spoil.

The Orion barge is in position 12° 30'.49 S 130° 53'.42 E and is marked by lights.

A 250m safety zone exists around the dredges.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 26 - Aus 27 - Aus 28 - AX 00026T

352(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Darwin - Middle Pass - Dredging operations

Date - Until 15 April 2014

Darwin Port Corporation Notice 40(T)/2014 (AA730410)

The dredge *Eastern Aurora* is conducting dredging operations in the vicinity of position 12° 21'.10 S 130° 43'.47 E.

The dredge will tow a 300m floating pipeline marked by lights, Q.Y.

The barge *Constructor 1* is in position 12° 21'.53 S 130° 43'.47 E and has deployed anchors marked by lights.

A 250m safety zone exists around the dredge and barge.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 26 - Aus 722 - AX 00026T - AX 00722T

385(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Lynedoch Bank - Drill rig

Date - Until 30 June 2014

MODU *Nan Hai 6* (AA732715)

Drill rig *Nan Hai 6* is conducting drilling operations in position 9° 50'.33 S 130° 20'.67 E.

Chart temporarily affected - Aus 310 - Aus 4721 (INT 721) - AX 00310U - AX 04721U

425(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Darwin - Charles Point Patches to Middle Arm - Dredging; buoys

Date - Until 15 May 2014

Darwin Port Corporation Notice 59/2014 (AA735339)

Dredgers *Simpson* and *Baldur*, with barges *Cornelis Lely* and *Pieter Caland* are conducting dredging operations parallel to the existing submarine gas pipeline between positions 12° 32'.15 S 130° 50'.65 E and 12° 19'.75 S 130° 39'.75 E.

Temporary anchors marked by special cylindrical buoys exist in position 12° 32'.01 S 130° 51'.91 E and 12° 32'.08 S 130° 52'.01 E.

A 250m radius safety zone exists around all vessels.

Chart temporarily affected - Aus 24 - Aus 26 - Aus 309 - Aus 722 - AX 00026T - AX 00309U - AX 00309T - AX 00722T

455(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Darwin - Middle Pass - Light buoy repositioned

Darwin Port Corporation Notice 63/2014 (AA737300)

LNG2 port lateral light buoy, *Iso.R.2s* (12° 21'.02 S 130° 43'.54 E), has been repositioned to 12° 21'.03 S 130° 43'.61 E.

Chart temporarily affected - Aus 26 - AX 00026T

456(T)/2014 AUSTRALIA - NORTHERN TERRITORY - Darwin - Middle Pass - Shoaling

Former Notice - 424(T)/2014 is cancelled

Darwin Port Corporation Notice 64/2014 (AA739632)

Shoaling, least depth 4.3m, exists within an area bounded by the following positions:

12° 21'.30 S 130° 43'.25 E

12° 22'.15 S 130° 43'.77 E

12° 22'.08 S 130° 43'.91 E

12° 21'.25 S 130° 43'.41 E

Shoaling, least depth 6.3m, exists within an area bounded by the following positions:

12° 21'.00 S 130° 43'.67 E

12° 21'.00 S 130° 43'.75 E

12° 21'.08 S 130° 43'.75 E

12° 21'.08 S 130° 43'.67 E.

Chart temporarily affected - Aus 26 - Aus 309 - Aus 722 - AX 00026T - AX 00309T - AX 00309U - AX 00722T

WESTERN AUSTRALIA

518(T)/2009 AUSTRALIA - WESTERN AUSTRALIA - Geographe Bay - Scientific instrument

Former Notice - 1260(T)/2006 is cancelled

Department for Planning and Infrastructure WA (AA400740)

A scientific instrument exists in position 33° 36'.7 S 115° 13'.7 E (WGS84 datum).

Chart temporarily affected - Aus 334 - Aus 335 - Aus 755 - Aus 756 - AX 0334E - AX 0755E

776(T)/2011 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Pipeline infrastructure

Former Notice - 718(T)/2011 is cancelled

Date - Until 10 December 2011

Department of Transport WA Notice 93/2011 (AA546427)

Works associated with pipeline infrastructure installation are in progress. An exclusion zone marked by special light buoys, Q.Y, exists within an area bounded by the following positions (WGS84 datum):

20° 41'.40 S 115° 23'.71 E

20° 41'.79 S 115° 24'.68 E

20° 41'.00 S 115° 25'.03 E

20° 40'.55 S 115° 24'.08 E.

MV *Carlisle* will monitor VHF Ch 16 and all vessels involved in the operations will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 327 - Aus 328 - Aus 742

127(T)/2012 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Mermaid Sound - Obstructions

Former Notice - 911(T)/2009 is cancelled

Dampier Port Authority Notice 1/2012 (AA578115)

Obstructions marked by special light buoys, Q, exist in the following positions:

20° 31'.47 S 116° 45'.16 E

20° 31'.96 S 116° 44'.57 E

20° 32'.49 S 116° 44'.51 E

20° 32'.79 S 116° 44'.51 E.

Chart temporarily affected - Aus 57 - Aus 58

418(T)/2012 AUSTRALIA - WESTERN AUSTRALIA - Esperance - Depth information

Former Notice - 337(T)/2010 is cancelled

Esperance Ports Sea and Land Notice 3/2012 (AA593980)

Esperance Ports Sea and Land Notice 3/2012 (AA593980)

Available depths as of 11 April 2012:

<i>Location</i>	<i>Metres</i>
* Berth No 1	13.0
* Berth No 2	13.0
* Berth No 3	17.6
Swing Basin	12.9/14.5
Entrance Channel	18.5

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 119

661(T)/2012 AUSTRALIA - WESTERN AUSTRALIA - Dampier - King Bay - Light beacon damaged

Former Notice - 521(T)/2012 is cancelled

Dampier Port Authority Notice 12/2012 (AA606820)

The No3 light beacon (20° 37'.75 S 116° 44'.29 E) has been damaged; a temporary light, *Fl(2)G.5s*, exists on the beacon and a light buoy, *Fl.5s*, exists in situ.

Chart temporarily affected - Aus 59

713(T)/2012 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Scientific instrument northeastwards

Former Notice - 943(T)/2011 is cancelled

MetOcean Engineers (AA609181)

A subsurface scientific instrument exists in position 19° 34'.47 S 116° 09'.53 E.

Chart temporarily affected - Aus 327

1057(T)/2012 AUSTRALIA - WESTERN AUSTRALIA - Fremantle - Depth information

Former Notice - 438(T)/2011 is cancelled

Fremantle Ports Notice 8(T)/2012 (AA630746)

Available depths as at 17 October 2012:

<i>Berth</i>	<i>Metres</i>
No 1	11.0
No 2	11.0
No 4	14.6
No 5	14.6
No 6	14.6
* No 7	14.5
* No 8	14.5
* No 9	14.5
* No 10	14.5
* No 11	10.4
* No 12	10.6
C	10.4
* D	10.4
* E	10.1
* F	10.0
* G	10.2
* H	10.1

* Indicates revised entry.

Maximum draft of vessels using inner harbour berths must be obtained by contacting the Harbour Master's office.

Chart temporarily affected - Aus 113

1105(T)/2012 AUSTRALIA - WESTERN AUSTRALIA - Fremantle - Swan River - Light beacon

Date - Until 31 October 2014

Department of Transport WA (AA631861, AA831862)

A special light beacon, *Fl. Y. 4s*, exists in position 32° 00'.21 S 115° 49'.67 E.

Chart temporarily affected - Aus 112 - AX 63112

1108(T)/2012 AUSTRALIA - WESTERN AUSTRALIA - Albany - Harbour works

Date - Until 15 January 2013

Department of Transport WA Notice 103/2012 (AA634951)

Harbour works associated with the construction of a jetty are in progress in the vicinity of position 35° 01'.82 S 117° 53'.22 E.

The area will be marked by special light buoys. All vessels involved in the works will display appropriate lights and shapes and will monitor VHF Ch 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 109

116(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Ashburton Road to Moresby Shoals - Scientific instruments

Date - Until 31 January 2014

Department of Transport WA Notice 10/2013 (AA645987)

Light buoys, *Fl(6)Y. 20s*, exist in the following positions:

21° 27'.92 S 115° 10'.19 E

21° 29'.91 S 115° 06'.16 E
21° 34'.01 S 115° 01'.10 E
21° 36'.17 S 115° 08'.97 E
21° 36'.31 S 115° 04'.62 E
21° 36'.45 S 115° 04'.01 E
21° 36'.86 S 115° 04'.49 E
21° 40'.02 S 115° 00'.63 E.

Chart temporarily affected - Aus 64 - Aus 328 - Aus 743

228(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Bunbury - Leschenault Estuary - Shoaling

Former Notice - 1058(T)/2012 is cancelled

Department of Transport WA (AA653972)

Shoaling exists inside the northern groyne of The Cut entrance channel (33° 18'.2 S 115° 40'.3 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 115

271(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Obstruction

Dampier Port Authority Notice 9/2013 (AA655652)

An obstruction exists in position 20° 38'.8 S 116° 32'.2 E.

Chart temporarily affected - Aus 57 - Aus 741 - Aus 742

316(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Perth - Scientific instruments westwards

Former Notice - 1220(T)/2012 is cancelled

CSIRO (AA661219)

Subsurface scientific instruments, suspended 20m below the surface, exist in positions:

31° 37'.60 S 115° 14'.75 E
31° 38'.80 S 115° 11'.75 E
31° 41'.60 S 115° 07'.00 E
31° 43'.16 S 115° 01'.80 E
31° 46'.23 S 114° 56'.60 E
31° 59'.00 S 115° 14'.00 E
32° 03'.20 S 115° 04'.96 E
32° 00'.00 S 115° 25'.00 E
32° 00'.00 S 115° 24'.16 E.

Chart temporarily affected - Aus 334 - Aus 754 - AX 00334S - AX 00754S - AXA 0754S

425(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Anchorage

Former Notice - 175(T)/2013 is cancelled

Department of Transport WA Notice 111/2011 (AA649470)

An anchorage exists in an area bounded by the following positions:

20° 41'.93 S 115° 29'.52 E
20° 41'.93 S 115° 30'.09 E
20° 42'.47 S 115° 30'.09 E
20° 42'.47 S 115° 29'.80 E
20° 42'.20 S 115° 29'.80 E
20° 42'.20 S 115° 29'.51 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 62 - Aus 67 - Aus 742

428(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island to Ashburton Road - Dredging operations; exclusion zones

Date - Until 31 March 2016

Department of Transport WA Notices 57/2013, 58/2013, Chevron (AA666513, AA666514), Dampier Port Authority Notice 8/2013 (AA666508)

The dredges *Ambiorix*, *Brabo* and *Breydel* are conducting dredging operations in an area, marked by light buoys *Fl. Y. 6s*, bounded by the following positions:

21° 40'.44 S 114° 58'.81 E
21° 39'.36 S 114° 58'.81 E
21° 33'.43 S 114° 58'.07 E
21° 30'.54 S 115° 02'.14 E
21° 30'.95 S 115° 03'.96 E
21° 39'.40 S 115° 01'.77 E
21° 41'.14 S 115° 01'.77 E.

A floating pipeline exists between the dredges. Spoil will be deposited in a restricted area, marked by light buoys *Fl. Y. 6s*, bounded by the following positions:

21° 26'.68 S 115° 05'.50 E
21° 26'.74 S 115° 10'.85 E
21° 31'.04 S 115° 10'.83 E
21° 30'.98 S 115° 05'.42 E.

All vessels will monitor VHF Ch 14 and Ch 16.

An exclusion zone marked by special light buoys, *Fl. Y. 6s*, exists in an area bounded by the following positions:

21° 40'.44 S 114° 58'.81 E
21° 39'.36 S 114° 58'.81 E
21° 39'.40 S 115° 01'.77 E
21° 41'.14 S 115° 01'.77 E.

Mariners are advised to navigate with caution in the area and are to contact Ashburton Marine on VHF Ch 14 when entering the area of dredging operations.

Chart temporarily affected - Aus 64 - Aus 743

433(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Geraldton - Depth information

Former Notice - 946(T)/2008 is cancelled

Geraldton Port Authority (AA666328, AA666329)

Available depths as at 31 January 2013:

<i>Berth</i>	<i>Metres</i>
* No 1	9.1
* No 2	9.7
* No 3	12.9
* No 4	12.8
* No 5	13.3
* No 6	12.4
* No 7	13.1
<i>Channel</i>	
Harbour Basin	12.4
* Inside western breakwater beacon 20 to 22	12.6
Beacon 20	13.1
* Beacon 16 to 20	13.2
* Beacon 4 to 14	13.8
* Beacon 2	14.1
* North Channel over Reef	9.1 in channel
* Indicates new or revised entry	

Chart temporarily affected - Aus 81

435(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Garden Island - Light beacon northeastwards

Date - Until 10 April 2014

Fremantle Ports Notice 1(P)/2013 (AA666502)

A special light beacon, *Fl. Y. 4s*, exists in position 32° 08'.10 S 115° 40'.65 E.

Chart temporarily affected - Aus 117 - Aus 754 - AX 00117T - AX 00754S - AXA 0754S

486(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Port Gregory - Shoaling

Department of Transport WA Notice 66/2012 (AA668957)

Shoaling, with a least depth of *0.1m*, exists adjacent to the jetty (28° 11'.44 S 114° 14'.95 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 84

523(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Harbour works

Former Notice - 421(T)/2013 is cancelled

Date - Until 31 March 2014

Department of Transport WA Notices 129/2012, 14/2013 (AA644896, AA671110)

Works associated with the construction of a jetty are in progress at Town Point. An exclusion zone exists in an area bounded by the following:

<i>Position</i>	<i>Remarks</i>
20° 47'.48 S 115° 28'.07 E	
20° 47'.48 S 115° 29'.04 E	
20° 48'.40 S 115° 30'.55 E	special conical light buoy, Q.Y
20° 50'.19 S 115° 30'.53 E	special conical light buoy, Q.Y
20° 50'.17 S 115° 28'.82 E	special conical light buoy, Q.Y
20° 48'.95 S 115° 28'.84 E	special conical light buoy, Q.Y
20° 47'.52 S 115° 28'.56 E.	

The infrastructure associated with the works is marked by lights, Fl.3s.

Barges and support vessels will monitor VHF Ch 10 and Ch 73 and display appropriate lights and shapes.

Chart temporarily affected - Aus 62 - Aus 66 - Aus 327 - Aus 328 - Aus 742 - Aus 743

564(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Light buoys

Date - Until 1 March 2014

Dampier Port Authority Notice 19/2013 (AA675281)

A lit orange mooring buoy, Q.Y, exists in position 20° 37'.01 S 116° 44'.87 E.

Special light buoys, Q.Y, exist in the following positions:

20° 36'.99 S 116° 44'.90 E
20° 37'.00 S 116° 44'.87 E
20° 37'.00 S 116° 44'.84 E
20° 36'.95 S 116° 44'.83 E.

Chart temporarily affected - Aus 59

613(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands to Barrow Island - Lit mooring buoys

Former Notice - 418(T)/2013 is cancelled

Date - Until 30 June 2014

Department of Transport WA Notice 80/2013 (AA622588), Chevron Australia Pty Ltd (AA677845, AA677846)

Lit yellow mooring buoys, Fl.Y.10s, exist in positions:

20° 30'.48 S 115° 33'.86 E
20° 43'.96 S 115° 29'.31 E
20° 47'.30 S 115° 30'.30 E
20° 47'.66 S 115° 29'.24 E
20° 49'.85 S 115° 30'.40 E
20° 51'.56 S 115° 29'.54 E
20° 51'.62 S 115° 31'.96 E
20° 54'.09 S 115° 27'.74 E
20° 57'.75 S 115° 28'.07 E
21° 05'.94 S 115° 30'.83 E.

Chart temporarily affected - Aus 61 - Aus 62 - Aus 63 - Aus 66 - Aus 67 - Aus 742 - Aus 743

615(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Serrurier Island - Mooring buoy off station northwards

BHP Billiton Petroleum Pty Ltd (AA677207)

The lit riser turret mooring buoy, Mo(U)15s, is off station and an obstruction with least depth 35m exists in position 21° 13'.31 S 114° 38'.74 E.

Chart temporarily affected - Aus 328 - Aus 744 - Aus 4060 (INT 60) - Aus 4070 (INT 70) - Aus 4708 (INT 708) - Aus 4723 (INT 723) - Aus 4725 (INT 725) - AX 04708U - AX 04723U

657(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Mermaid Sound - Scientific instruments

Date - Until 31 October 2013

MetOcean Engineers (AA679768)

Scientific instruments exist as follows:

<i>Position</i>	<i>Remarks</i>
20° 33'.25 S 116° 43'.10 E	<i>Fl(5)Y.20s</i>
20° 33'.23 S 116° 43'.15 E	5 poly floats.

Chart temporarily affected - Aus 58 - Aus 59

784(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island - Scientific instrument southwards

Date - Until 1 November 2013

Department of Transport WA Notice 104/2013 (AA686394)

A special pillar light buoy, *Q(5)Y.20s*, exists in position 21° 31'.81 S 115° 01'.74 E.

Chart temporarily affected - Aus 64 - Aus 743

831(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Harbour works

Date - Until 10 December 2013

Dampier Port Authority Notice 28/2013 (AA688922)

Harbour works are in progress in the vicinity of position 20° 36'.89 S 116° 45'.00 E. An exclusion zone exists within a 50m radius of this position.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 59

922(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Browse Island - Drill rig northwestwards

Date - Until 30 August 2015

MODU *Noble Clyde Boudreaux* (AA693287), Australian Maritime Safety Authority Auscoast Warning 214/2013 (AA693323)

Drill rig *Noble Clyde Boudreaux* is conducting drilling operations in position 13° 49'.01 S 123° 19'.60 E.

Chart temporarily affected - Aus 319 - Aus 320 - Aus 4721 (INT 721) - Aus 4722 (INT 722) - AX 00319U - AX 04721U - AX 04722U

1034(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - West Reef to Fly Island - Scientific instruments

Former Notice - 524(T)/2013 is cancelled

Date - Until 29 February 2016

Department of Transport WA Notice 142/2013 (AA700043)

Scientific instruments marked by special spar light buoys, *Fl.Y.6s*, exist in the following positions:

21° 19'.66 S 115° 23'.45 E
21° 19'.66 S 115° 09'.50 E
21° 27'.04 S 115° 02'.00 E
21° 28'.93 S 115° 01'.54 E
21° 30'.02 S 114° 50'.23 E
21° 30'.16 S 114° 55'.44 E
21° 31'.73 S 114° 46'.25 E
21° 33'.78 S 115° 00'.48 E
21° 33'.85 S 115° 00'.45 E
21° 34'.69 S 114° 54'.30 E
21° 35'.20 S 114° 56'.38 E
21° 35'.17 S 114° 56'.40 E
21° 37'.84 S 114° 41'.51 E
21° 37'.88 S 114° 41'.49 E
21° 43'.17 S 114° 46'.17 E.

Chart temporarily affected - Aus 64 - Aus 743 - Aus 744

1068(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Port Hedland - Depth information

Former Notice - 875(T)/2013 is cancelled
Port Hedland Port Authority Notice 13/2013 (AA701792)

Available depths as at 11 October 2013:

Berth	Metres
PHPA berth 1	13.2
PHPA berth 2	13.2
* PHPA berth 3	13.5
* PHPA berth 4 (Utah Point)	14.7
* BHP Billiton Nelson Point berth A	19.2
* BHP Billiton Nelson Point berth B	19.0
BHP Billiton Nelson Point berth C	19.1
* BHP Billiton Nelson Point berth D	19.0
BHP Billiton Finucane Island berth A	19.2
* BHP Billiton Finucane Island berth B	19.3
* BHP Billiton Finucane Island berth C	18.5
* BHP Billiton Finucane Island berth D	19.3
* Anderson Point berth 1	19.9
* Anderson Point berth 2	19.7
* Anderson Point berth 3	19.8
* Anderson Point berth 4	19.7
* Indicates new or revised entry.	

Chart temporarily affected - Aus 52 - Aus 54

1118(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Wells and pipelines northwards

Date - Until 26 December 2013

SapuraClough Offshore (AA703831)

Vessels *Stellaprima* and *SapuraKencana Constructor* are conducting works, which include the installation of subsea structures and flowlines, in an area bounded by the following positions:

21° 33'.0 S 114° 04'.5 E

21° 33'.0 S 114° 10'.0 E

21° 30'.0 S 114° 10'.0 E

21° 30'.0 S 114° 04'.5 E.

Chart temporarily affected - Aus 328 - Aus 329 - Aus 744

1172(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Glomar Shoal - Scientific instruments

Date - Until 30 June 2014

MetOcean Engineers (AA706103, AA706104)

Scientific instruments marked by special light buoys, Q(5)Y.20s, exist in the following positions:

18° 45'.07 S 117° 01'.90 E

19° 31'.40 S 117° 02'.66 E

19° 31'.37 S 117° 02'.90 E.

Chart temporarily affected - Aus 327 - Aus 741

1173(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Glomar Shoal - Scientific instruments

Former Notice - 1067(T)/2013 is cancelled

Date - Until 30 June 2014

University of Western Australia (AA707013), MetOcean Engineers (AA706103, AA706104)

Subsurface scientific instruments, >20m below the surface, exist in the following positions:

19° 03'.00 S 117° 03'.60 E

19° 04'.80 S 116° 36'.00 E

19° 31'.20 S 117° 03'.00 E

19° 45'.46 S 117° 01'.23 E.

A subsurface scientific instrument, 12m below the surface, exists in position 19° 32'.38 S 116° 31'.66 E.

Chart temporarily affected - Aus 327 - Aus 741

1174(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Kwinana - Scientific instrument

Date - Until 7 May 2015

Fremantle Ports (AA706386)

A special cylindrical light buoy, *Fl.Y.4s*, exists in position 32° 12'.07 S 115° 46'.20 E.

Chart temporarily affected - Aus 114 - Aus 117 - AX 00117T

1226(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Dampier - King Bay - Light buoy unlit; light buoy off station
Dampier Port Authority Notice 38/2013 (AA710497)

No13 light buoy (20° 37'.97 S 116° 45'.03 E) is unlit.

No17 light buoy (20° 37'.97 S 116° 45'.17 E) is off station.

Chart temporarily affected - Aus 59

1284(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Cape Preston - Light buoys

Date - Until 31 May 2014

Department of Transport WA Notice 194/2013 (AA710742)

Special cylindrical light buoys, Q, exist in positions 20° 43'.91 S 116° 09'.85 E and 20° 43'.75 S 116° 10'.13 E.

Chart temporarily affected - Aus 68 - Aus 742

1291(T)/2013 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands northwestwards - Mooring buoy; pipeline infrastructure

Former Notice - 314(T)/2013 is cancelled

Apache Energy Ltd (AA711597, AA711732, AA711758), Australian Maritime Safety Authority Auscoast Warning 289/2013 (AA711582)

A lit riser turret mooring buoy, *Mo(U)15s*, exists in position 20°03'.52 S 115°11'.52 E.

MV *Deep Orient* will be conducting pipeline installation in the area.

A 500m exclusion zone exists around the vessel and mooring buoy.

FPSO *Armada Claire* is scheduled to arrive on site mid February 2014.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 328

77(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Gas field infrastructure northwards

Date - Until 29 January 2014

DOF Management Australia Pty Ltd (AA715946)

The vessel *Skandi Hercules* is installing gas field infrastructure in an area bounded by the following positions:

20° 00'.0 S 115° 15'.5 E

19° 38'.6 S 115° 15'.5 E

19° 38'.6 S 115° 25'.5 E

20° 00'.0 S 115° 25'.5 E.

Chart temporarily affected - Aus 327 - Aus 328 - Aus 4723 (INT 723) - AX 04723U

81(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Seismic survey northwestwards

Date - Until 30 April 2014

Woodside Energy Ltd (AA713179)

SSV *WG Vespucci*, with a 7000m towed array, and support vessels *Offshore Quest*, *Unlimited* and *Limitless* are conducting a survey in the area bounded by the following positions:

19° 37'.59 S 115° 29'.20 E

19° 18'.61 S 116° 00'.16 E

19° 11'.41 S 116° 28'.97 E

19° 12'.27 S 116° 34'.43 E

19° 18'.12 S 116° 48'.37 E

19° 23'.66 S 116° 50'.99 E

19° 36'.05 S 116° 54'.47 E

19° 58'.05 S 116° 19'.06 E
19° 58'.05 S 116° 02'.65 E
20° 04'.68 S 115° 52'.03 E
20° 04'.66 S 115° 35'.60 E
19° 48'.57 S 115° 19'.98 E.

Chart temporarily affected - Aus 327 - Aus 328 - Aus 741 - Aus 742 - Aus 4722 (INT 722) - Aus 4723 (INT 723) - AX 04722U - AX 04723U

84(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Drill rig northwestwards

Former Notice - 1064(T)/2013 is cancelled

Chevron Australia Pty Ltd (AA714805)

Drill rig *Atwood Osprey* is conducting drilling operations in position 19° 54'.35 S 115° 16'.12 E.

Chart temporarily affected - Aus 328 - Aus 4723 (INT 723) - AX 04723U

86(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Drill rig northwards

Former Notice - 1286(T)/2013 is cancelled

MODU *Atwood Falcon* (AA714607), Australian Maritime Safety Authority Auscoast Warning 296/2013 (AA714758)

Drill rig *Atwood Falcon* is conducting drilling operations in position 21° 20'.95 S 114° 04'.39 E.

Chart temporarily affected - Aus 328 - Aus 329 - Aus 744

88(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Port Hedland - Light beacons unlit; light buoys

Port Hedland Port Authority Notice 1(T)/2014 (AA715226)

The west cardinal light beacon, Q(9)15s 11m 6M E2 (20° 03'.07 S 118° 32'.80 E), and east cardinal light beacon, Q(3)10s 10m 6M E3 (20° 03'.19 S 118° 32'.59 E), are unlit.

Special conical light buoys, F, exist in positions 20° 03'.18 S 118° 32'.60 E and 20° 03'.07 S 118° 32'.76 E.

Chart temporarily affected - Aus 53 - Aus 739 - Aus 740

89(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Rosemary Island - Scientific instruments

Date - Until 31 May 2014

Department of Transport WA Notice 9/2014 (AA715870)

Subsurface scientific instruments exist on the seabed in the following positions:

20° 27'.18 S 116° 35'.41 E
20° 27'.23 S 116° 35'.48 E
20° 27'.46 S 116° 35'.63 E
20° 27'.61 S 116° 35'.72 E.

Chart temporarily affected - Aus 57 - Aus 741 - Aus 742

91(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island - Scientific instruments

Former Notice - 1230(T)/2013 is cancelled

Date - Until 31 May 2014

Department of Transport WA Notice 9/2014 (AA715870)

Subsurface scientific instruments exist on the seabed in the following positions:

21° 25'.27 S 114° 58'.09 E
21° 26'.75 S 114° 58'.83 E
21° 27'.11 S 114° 59'.11 E
21° 27'.05 S 114° 59'.92 E
21° 26'.55 S 114° 59'.98 E.

Chart temporarily affected - Aus 64 - Aus 743 - Aus 744

137(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Depth information

Former Notice - 1066(T)/2013 is cancelled

Dampier Port Authority Notice 5/2014 (AA717652)

Available depths as at 16 January 2014:

	<i>Metres</i>	<i>Remarks</i>
East Intercourse Island	19.1	
East Intercourse Island Layby berth	19.4	
East Intercourse Island Departure Channel	15.5	
* Rio Tinto Deep Water Channel	15.5	
Parker Point berth 2	18.7	
Parker Point berth 3	18.8	
Parker Point berth 4	19.5	
Parker Point berth 5	19.1	
* Parker Point Departure Channel	15.4	
Parker Point Approach Channel	8.0	
Fuel Wharf	11.4	
Service Wharf	6.7	
Mermaid Marine Supply Base Outer Channel	5.4	
Mermaid Marine Supply Base Inner Channel	3.0	
Berthing pocket	7.2	
Burrup Materials Facility	7.0	
Dampier Cargo Wharf	9.0	Western side
	6.5	Eastern side
Bulk Liquids Berth	12.4	
Facilities Channel	11.0	
* Indicates new or revised entry.		

Chart temporarily affected - Aus 58 - Aus 59 - Aus 60

138(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Pipeline northwestwards

Former Notice - 82(T)/2014 is cancelled

Technip (AA712427, AA718859)

Vessel *Global 1201* and support vessels *Mermaid Vantage* and *Go Sirius* are conducting pipe lay operations between the following positions:

19° 39'.14 S 115° 55'.77 E

19° 42'.42 S 115° 52'.52 E

19° 45'.65 S 115° 53'.43 E.

Anchors marked by displaced surface buoys exist as follows:

Anchors

Buoys

19° 42'.72 S 115° 52'.19 E 19° 42'.47 S 115° 52'.25 E

19° 41'.99 S 115° 52'.40 E 19° 42'.17 S 115° 52'.21 E

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 327 - Aus 4723 (INT 723) - AX 04723U

141(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Flinders Bay - Harbour works

Former Notice - 1107(T)/2012 is cancelled

Date - Until 30 September 2014

Department of Transport WA Notice 26/2014 (AA718868)

Harbour works are in progress within an exclusion zone bounded by the following:

Positions

Remarks

34° 20'.98 S 115° 10'.09 E

34° 21'.00 S 115° 10'.30 E marked by special light buoy, Q.Y

34° 21'.46 S 115° 10'.13 E marked by special light buoy, Q.Y

34° 21'.41 S 115° 09'.96 E.

All hazards to navigation will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 116

144(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank to Exmouth Plateau - Scientific instruments

Date - Until 31 July 2015

MetOcean Engineers (AA716119)

Subsurface scientific instruments exist in positions 18° 43'.00 S 115° 59'.00 E and 20° 37'.42 S 112° 33'.66 E.

Chart temporarily affected - Aus 327 - Aus 328 - Aus 329 - Aus 4603 (INT 603) - AX 04603U

183(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Pipeline

Date - Until 21 March 2014

Apache Energy Ltd (AA721970)

SPV *Lorelay* is conducting pipe laying operations in an area bounded by the following positions:

19° 54'.71 S 115° 23'.06 E

19° 56'.06 S 115° 23'.87 E

20° 02'.51 S 115° 11'.87 E

20° 01'.16 S 115° 11'.06 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 327 - Aus 328

185(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Scientific instruments northwestwards

Former Notice - 1171(T)/2013 is cancelled

Date - Until 30 June 2014

MetOcean Engineers (AA706103, AA706104)

Scientific instruments exist as follows:

<i>Position</i>	<i>Remarks</i>
19° 36'.00 S 116° 06'.70 E	lit buoy, Q(5)Y.20s
19° 35'.91 S 116° 06'.85 E	5 poly floats

Chart temporarily affected - Aus 327

189(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Mullaloo - Light buoy

Date - Until 31 May 2014

Department of Transport WA Notice 192/2013 (AA720974)

An orange spherical light buoy, *Fl(5)Y.20s*, exists in position 31° 47'.13 S 115° 43'.84 E.

Chart temporarily affected - Aus 754 - AX 00754S - AXA 0754S

191(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - FPSO off station

Date - Until 16 May 2014

Apache Energy Ltd (AA721645)

The FPSO *Ningaloo Vision* (21° 24'.2 S 114° 05'.3 E) is off station; a riser turret mooring exists in situ.

Chart temporarily affected - Aus 328 - Aus 329 - Aus 744 - Aus 4723 (INT 723) - Aus 4725 (INT 725) - AX 04723U

233(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Broome - Scientific instrument

Former Notice - 1216(T)/2012 is cancelled

Date - Until 19 December 2014

Broome Port Authority (AA640508, AA725097)

A scientific instrument marked by a special light buoy, *Fl.Y.3s*, exists in position 18° 00'.06 S 122° 12'.93 E.

Chart temporarily affected - Aus 50 - Aus 51

236(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Garden Island - Submarine pipeline

Former Notice - 195(T)/2014 is cancelled

Date - Until 31 March 2014

Department of Transport WA Notice 47/2014 (AA720971)

Barge *ASL96* and support vessels are laying a submarine pipeline between 32° 14'.55 S 115° 40'.80 E and 32° 15'.06 S 115° 39'.06 E.

All vessels with display appropriate lights and shapes and will monitor VHF Ch 16 and Ch 74.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 111 - Aus 117 - Aus 334 - Aus 754 - Aus 755 - AX 00117T - AX 00334S - AX 00754S - AX 00755S - AXA 0754S

238(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Scott Reef - Drill rig northeastwards

Former Notice - 1033(T)/2013 is cancelled

Date - Until 30 June 2014

MODU *Transocean Legend* (AA724151), Australian Maritime Safety Authority Auscoast Warning 46/2014 (AA724138)

Drill rig *Transocean Legend* is conducting drilling operations in position 13° 34'.42 S 122° 20'.41 E.

Chart temporarily affected - Aus 322 - Aus 4722 (INT 722) - AX 00322U - AX 04722U

283(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Scientific instrument

Former Notice - 422(T)/2013 is cancelled

Date - Until 31 January 2015

Department of Transport WA Notice 62/2014 (AA726681)

A special light buoy, *Fl(5)Y.20s*, exists in position 20° 49'.47 S 115° 30'.85 E.

Chart temporarily affected - Aus 62 - Aus 66

285(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Pipeline westwards

SPV *Solitaire* (AA727019)

SPV *Solitaire* is conducting pipe laying operations in an area bounded by the following positions:

21° 27'.97 S 114° 49'.60 E

21° 28'.00 S 114° 52'.43 E

20° 37'.25 S 114° 52'.98 E

19° 56'.33 S 115° 23'.82 E

19° 55'.22 S 115° 22'.03 E

20° 37'.17 S 114° 43'.32 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 64 - Aus 327 - Aus 328 - Aus 742 - Aus 743 - Aus 744

287(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Browse Island - Drill rig southwestwards

Date - Until 10 May 2014

Australian Maritime Safety Authority Auscoast Warning 57/2014 (AA727251), AGR (Australia) Pty Ltd (AA727169)

Drill rig *Stena Clyde* is conducting drilling operations in position 14° 12'.56 S 123° 06'.53 E.

Chart temporarily affected - Aus 320 - Aus 322 - Aus 4721 (INT 721) - Aus 4722 (INT 722) - AX 00322U - AX 04721U - AX 04722U

292(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Drill rig northwestwards

Date - Until 30 June 2014

MODU *Atwood Eagle* (AA727296), Australian Maritime Safety Authority Auscoast Warning 58/2014 (AA727300)

Drill rig *Atwood Eagle* is conducting drilling operations in position 20° 01'.82 S 115° 12'.11 E.

Chart temporarily affected - Aus 328 - Aus 4723 (INT 723) - AX 04723U

299(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Light altered

Former Notice - 1227(T)/2013 is cancelled

Date - Until 7 July 2014

Australian Maritime Safety Authority Temporary ATH 2/2014 (AA726889)

The light (21° 48'.37 S 114° 09'.61 E) has been temporarily altered to *Fl.10s 129m 21M*

Chart temporarily affected - Aus 328 - Aus 329 - Aus 744 - Aus 745 - Aus 4723 (INT 723) - Aus 4725 (INT 725) - AX 04723U

300(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Passage Islands - Obstructions

Former Notice - 472(T)/2012 is cancelled

Date - Until 31 March 2015

Department of Transport WA Notice 53/2012 (AA597010, AA727668)

Obstructions exist in the following positions:

21° 11'.28 S 115° 47'.70 E

21° 07'.76 S 115° 50'.10 E

21° 06'.01 S 115° 46'.93 E

21° 08'.15 S 115° 43'.83 E.

Chart temporarily affected - Aus 743

302(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Scott Reef - Survey operations

Date - Until 30 April 2014

Woodside Energy Ltd (AA727186)

MV *Fugro Equinox* is conducting a geophysical survey with an AUV in an area bounded by the following positions:

13° 54'.92 S 121° 55'.08 E

13° 54'.92 S 121° 45'.08 E

14° 29'.92 S 121° 25'.08 E

14° 34'.92 S 121° 25'.08 E

14° 44'.92 S 121° 35'.08 E

14° 44'.92 S 121° 40'.08 E

14° 39'.92 S 121° 45'.08 E

14° 14'.92 S 121° 45'.08 E

14° 14'.92 S 121° 52'.00 E

14° 04'.92 S 122° 05'.08 E

13° 54'.92 S 122° 05'.08 E

13° 54'.92 S 122° 10'.08 E

13° 49'.92 S 122° 10'.08 E

13° 49'.92 S 121° 55'.08 E.

Chart temporarily affected - Aus 43 - Aus 322 - Aus 4722 (INT 722) - AX 00322U - AX 04722U

303(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Seringapatam Reef - Drill rig eastwards

Date - Until 4 July 2014

MODU *Jack Bates* (AA719796)

Drill rig *Jack Bates* is conducting drilling operations in position 13° 41'.53 S 122° 48'.20 E.

Chart temporarily affected - Aus 322 - Aus 4721 (INT 721) - Aus 4722 (INT 722) - AX 00322U - AX 04721U - AX 04722U

354(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Drill rig northwestwards

Former Notice - 234(T)/2014 is cancelled

Date - Until 9 May 2014

MODU *Ocean America* (AA730381)

Drill rig *Ocean America* is conducting drilling operations in position 20° 19'.37 S 114° 27'.83 E.

Chart temporarily affected - Aus 328 - Aus 4723 (INT 723) - AX 04723U

355(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Manilya Sandbank - Scientific instrument

Date - Until 30 June 2014

Port Hedland Port Authority Notice 32(T)/2014 (AA729090)

A subsurface scientific instrument marked by a special light buoy, *Fl.Y.2s*, exists in position 20° 08.99 S 118° 38'.23 E.

Chart temporarily affected - Aus 52 - Aus 53

387(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Apsley Strait - Light buoy off station

Department of Transport NT (AA732851)

The port lateral light buoy, *Fl.R.5s*, 11° 44'.2 S 130° 37'.7 E, is off station:

Chart temporarily affected - Aus 23

388(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Harbour Works

Date - Until 15 May 2014

Port of Barrow Notice 2/2014 (AA733151)

Works associated with the installation of nav aids are in progress in an area bounded by the following positions:

20° 48'.54 S 115° 29'.03 E

20° 48'.55 S 115° 31'.05 E

20° 49'.45 S 115° 33'.29 E

20° 50'.69 S 115° 33'.29 E

20° 50'.69 S 115° 31'.67 E

20° 49'.83 S 115° 29'.03 E.

All hazards to navigation will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 62 - Aus 66

390(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Mooring buoys northwestwards

Date - Until 10 June 2014

Viking Seatech (AA733722)

12 yellow mooring buoys, *Fl.3s*, exist within 1NM radius of position 19° 48'.68 S 115° 17'.78 E.

Chart temporarily affected - Aus 328

392(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Rowley Shoals - Seismic survey northwards

Date - Until 30 June 2014

Woodside Energy Ltd (AA732736)

SSV *Polarcus Alima*, with a 7000m towed array, and support vessels *Sealink161* and *Empress* are conducting a survey in the area bounded by the following positions:

15° 10'.88 S 119° 33'.51 E

15° 10'.47 S 120° 00'.35 E

15° 50'.18 S 120° 00'.36 E

15° 49'.92 S 119° 33'.35 E.

Chart temporarily affected - Aus 4722 (INT 722) - AX 04722U

428(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Exmouth Plateau - Scientific instruments

Date - Until 30 June 2015

MetOcean Engineers (AA735327), Woodside Energy Ltd (AA735354)

Scientific instruments marked by special light buoys, Q(5)Y.20s, exist in positions:

19° 50'.41 S 112° 37'.37 E

19° 50'.06 S 112° 39'.51 E.

A subsurface scientific instrument exists 20 meters below the surface in position 19° 50'.07 S 112° 38'.63 E.

Chart temporarily affected - Aus 4723 (INT 723) - AX 04723U

429(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Drill rig northwestwards

Former Notice - 291(T)/2014 is cancelled

Date - Until 11 May 2014

MODU *Deepwater Frontier* (AA734224), AMSA Auscoast 86/2014

MODU *Deepwater Frontier* is conducting drilling operations in position 19° 50'.12 S 114° 34'.10 E.

Chart temporarily affected - Aus 328 - Aus 4723 (INT 723) - AX 04723U

430(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Drill rig northwestwards

Date - Until 20 June 2014

MODU *Deepwater Millennium* (AA735326)

MODU *Deepwater Millennium* is conducting drilling operations in position 21° 25'.86 S 113° 25'.59 E.

Chart temporarily affected - Aus 329 - Aus 4723 (INT 723) - Aus 4725 (INT 725) - AX 04723U

458(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Ashburton Road - Pipeline

Date - Until 30 August 2014

Inchcape Shipping Services (AA737816)

Barge *Tog Mor* and support vessels *Mermaid Vantage*, *Fiona F*, *Lewik Avior* and *Caroline Tide* are conducting pipe laying operations between the following positions:

21° 28'.08 S 114° 51'.09 E

21° 35'.15 S 114° 57'.38 E

21° 38'.31 S 114° 59'.25 E

21° 40'.66 S 114° 59'.57 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 64 - Aus 328 - Aus 743 - Aus 744

459(T)/2014 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Seismic survey northwestwards

Date - Until 30 June 2014

Apache Energy Ltd (AA737810)

SSV *Geo Caspian*, with a 8000m towed array, and support vessels *Pacific Parrot* and *Browse Invincible* are conducting a survey in the area bounded by the following positions:

19° 51'.38 S 116° 10'.67 E

19° 51'.34 S 116° 22'.62 E

19° 58'.60 S 116° 31'.76 E

20° 22'.61 S 116° 27'.02 E

20° 22'.64 S 116° 07'.27 E

20° 12'.20 S 116° 07'.29 E.

Chart temporarily affected - Aus 57 - Aus 327 - Aus 741 - Aus 742 - Aus 4722 (INT 722) - Aus 4723 (INT 723) - AX 04722U - AX 04723U

SOUTH AUSTRALIA

720(T)/2008 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Shoaling

Former Notice - 240(T)/2006 is cancelled

Department for Transport, Energy and Infrastructure Notice 38/2007 (AA346443)

Silting has resulted in width restrictions being imposed in the main channel of the Port Adelaide River between No 40 beacon (34° 47'.86 S 138° 30'.79 E) and No 41 beacon (34° 48'.52 S 138° 30'.77 E).

Mariners should avoid the western side of the main channel and navigate with caution in this part of the River as the available navigable channel is now only 90 metres wide measured from the eastern edge.

Mariners intending to transit this section should contact the Manager Marine Operations, Flinders Ports Pty Ltd on (08) 8447 0622 to confirm maximum widths.

Chart temporarily affected - Aus 137

1344(T)/2011 AUSTRALIA - SOUTH AUSTRALIA - Gulf St Vincent - Obstruction

Former Notice - 534(T)/2011 is cancelled

Fugro LADS Corporation (AA534581)

An obstruction is reported to exist in position 34° 42'.37 S 138 15'.94 E.

Chart temporarily affected - Aus 781

71(T)/2012 AUSTRALIA - SOUTH AUSTRALIA - Wallaroo - Depth information

Former Notice - 176(T)/2009 is cancelled

Department for Transport, Energy and Infrastructure SA Notice 38/2010 (AA515239, AA515240)

Available depths as at 24 August 2010:

	<i>Metres</i>	<i>Remarks</i>
* No 1 South Berth	8.7	Berth pocket is 313m x 36m and is 84m in from outer edge of wharf.
* No 2 North Berth	8.7	Berth pocket is 246m x 36m and is 20m in from outer edge of wharf.
* Indicates new or revised entry.		

Chart temporarily affected - Aus 133

194(T)/2014 AUSTRALIA - SOUTH AUSTRALIA - Port Douglas - Light beacon destroyed

Department of Planning, Transport and Infrastructure SA Notice 5/2014 (AA721989)

No7 light beacon, Q.G (34° 32'.29 S 135° 21'.88 E), has been destroyed; a starboard lateral light buoy, Q.G, exists in situ.

Chart temporarily affected - Aus 121

305(T)/2014 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Depth information

Former Notice - 1295(T)/2013 is cancelled

Department of Planning, Transport and Infrastructure SA Notice 9/2014 (AA726464)

Available depths as at 3 March 2014:

<i>Berth</i>	<i>Metres</i>
Outer Harbor No1	11.0
Outer Harbor No2	10.5
Outer Harbor No3	10.5
Outer Harbor No4	10.5
Outer Harbor No6	13.8
Outer Harbor No8	15.7
Swinging Basin	13.7
Osborne Wharf No1	8.3
* Inner Harbor No29	9.5
Inner Harbor M	10.7
* Indicates new or revised entry	

Chart temporarily affected - Aus 137

466(T)/2014 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Dredging operations

Date - Until 13 June 2014

Department of Planning, Transport and Infrastructure SA Notice 16/2014 (AA737299)

Dredging operations are in progress in the vicinity of position 34° 46'.48 S 138° 29'.04 E.

A dredge and support vessels are on site and will display appropriate lights and shapes.

A floating pipeline exists between berth No4 (34° 46'.48 S 138° 29'.04 E) and berth No8 (34° 45'.99 S 138° 29'.60 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 137

467(T)/2014 AUSTRALIA - SOUTH AUSTRALIA - Port Macdonnell - Harbour works

Date - Until 31 December 2014

Department of Planning, Transport and Infrastructure SA Notice 21/2014 (AA737290)

Harbour works associated with the upgrade of the existing boat ramp and wharf in position 38° 03'.46 S 140° 41'.74 E are in progress.

Temporary rock groynes marked by lights, *Fl. Y. 2s*, exist in the vicinity of the boat ramp.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 348

468(T)/2014 AUSTRALIA - SOUTH AUSTRALIA - Spencer Gulf - Thistle Island - Defence trials

Date - Until 22 May 2014

Department of Planning, Transport and Infrastructure SA Notice 13/2014 (AA734532, AA731679), Department of Defence (AA739627)

Defence trials will be conducted within a 2M radius of position 35° 00'.10 S 136° 15'.14 E during the period 18 May to 21 May 2014.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 343 - Aus 776 - AX 00343S - AX 00776S

VICTORIA

514(T)/2008 AUSTRALIA - VICTORIA - Western Port - Phillip Island - Shoaling northwards

Victorian Notice 64(T)/2008 (AA333884)

Shoaling, least depth *13.4 metres*, exists at position 38° 25'.53 S 145° 13'.90 E extending 100 metres into the shipping channel .

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 150 - Aus 151

942(T)/2010 AUSTRALIA - VICTORIA - Port Phillip - Geelong - Depth information

Former Notice - 465(T)/2009 is cancelled

Victorian Notice 31(T)/2005, 104(T)/2005 (AA131863, AA203894), Victorian Regional Channels Authority (AA490300, AA490301)

Available depths as at 19 August 2010:

<i>Berth</i>	<i>Metres</i>
Bulk Grain Pier 1	9.0
Bulk Grain Pier 2	11.0
Point Wilson Jetty North	8.6
Point Henry Pier Alcoa	11.6

*Indicates new or revised entry.

Chart temporarily affected - Aus 153 - Aus 157

1291(T)/2010 AUSTRALIA - VICTORIA - Ninety Mile Beach - Obstructions

Former Notice - 458(T)/2007 is cancelled

Victorian Notice 51(T)/2007 (AA242065)

Suspended well heads exists within a 300m radius of position 38° 37'.65 S 146° 53'.75 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 357

723(T)/2011 AUSTRALIA - VICTORIA - Port Phillip - Great Ship Channel - Shoaling

Victorian Notice 89(T)/2011 (AA543561)

Shoaling, with a least depth of *16.7m*, exists in position 38° 18'.04 S 144° 37'.69 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 144 - Aus 158

1346(T)/2011 AUSTRALIA - VICTORIA - Port Phillip - South Channel - Exclusion zones

Victorian Notice 146(T)/2011 (AA571787)

As a result of shoaling, exclusion zones exists in the areas bounded by the following positions:

38° 17'.50 S 144° 39'.08 E
38° 17'.50 S 144° 39'.45 E
38° 17'.56 S 144° 39'.45 E
38° 17'.55 S 144° 39'.08 E,
and
38° 17'.65 S 144° 41'.13 E
38° 17'.88 S 144° 42'.27 E
38° 17'.90 S 144° 42'.27 E
38° 17'.67 S 144° 41'.13 E,
and
38° 17'.99 S 144° 42'.65 E
38° 18'.01 S 144° 42'.72 E
38° 18'.02 S 144° 42'.72 E
38° 18'.00 S 144° 42'.65 E,
and

38° 17'.80 S 144° 42'.85 E
 38° 18'.14 S 144° 44'.52 E
 38° 18'.17 S 144° 44'.51 E
 38° 17'.83 S 144° 42'.84 E,
 and
 38° 18'.18 S 144° 45'.07 E
 38° 18'.37 S 144° 46'.35 E
 38° 18'.38 S 144° 46'.35 E
 38° 18'.19 S 144° 45'.07 E.

Chart temporarily affected - Aus 144 - Aus 158

131(T)/2012 AUSTRALIA - VICTORIA - Anderson Inlet - Shoaling

Former Notice - 1300(T)/2009 is cancelled

Victorian Notice 8(T)/2012 (AA577182)

Shoaling exists in the outer entrance channel of the Anderson Inlet entrance bar (38° 39'.0 S 145° 43'.0 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 801

772(T)/2012 AUSTRALIA - VICTORIA - Port Phillip - Werribee South - Harbour works

Date - Until 30 January 2014

Victorian Notice 106(T)/2012 (AA613718)

Harbour works associated with the construction of a new marina are in progress in an area bounded by the following:

<i>Position</i>	<i>Remarks</i>
37° 58'.29 S 144° 42'.27 E	special conical buoy, without topmark
37° 58'.31 S 144° 42'.36 E	special conical light buoy, <i>Fl. Y. 7s</i> , with topmark
37° 58'.32 S 144° 42'.46 E	special conical buoy, without topmark
37° 58'.28 S 144° 42'.55 E	special conical light buoy, <i>Fl. Y. 7s</i> , with topmark
37° 58'.23 S 144° 42'.63 E	special conical buoy, without topmark
37° 58'.17 S 144° 42'.69 E	special conical light buoy, <i>Fl. Y. 7s</i> , with topmark
37° 58'.10 S 144° 42'.75 E	special conical buoy, without topmark
37° 58'.04 S 144° 42'.81 E	special conical light buoy, <i>Fl. Y. 7s</i> , with topmark
37° 57'.97 S 144° 42'.86 E	special conical buoy, without topmark
37° 57'.89 S 144° 42'.85 E	special conical light buoy, <i>Fl. Y. 7s</i> , with topmark
37° 57'.81 S 144° 42'.82 E	special conical buoy, without topmark.

All hazards to navigation will display appropriate lights.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143 - Aus 155

75(T)/2013 AUSTRALIA - VICTORIA - Port Phillip - River Yarra - Appleton Dock - Harbour works

Former Notice - 77(T)/2011 is cancelled

Date - Until 30 June 2014

Victorian Notice 183(T)/2012 (AA643590)

Works associated with the remediation of berths B to F are in progress (37° 49'.02 S 144° 55'.31 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 154

935(T)/2013 AUSTRALIA - VICTORIA - Port Phillip - Patterson River - Shoaling

Victorian Notice 119(T)/2013 (AA693049)

Shoaling, with least depth *0.5m*, exists within the entrance to Patterson River (38° 04'.41 S 145° 07'.17 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143

937(T)/2013 AUSTRALIA - VICTORIA - Port Phillip - South Channel - Shoaling; virtual AIS

Former Notice - 1063(T)/2012 is cancelled

Victorian Notices 141(T)/2012, 28(T)/2013, 122(T)/2013 (AA630248, AA655972, AA694016)

Virtual AIS exist as follows:

<i>Identification message</i>	<i>Position</i>
TB1	38° 18'.11 S 144° 43'.86 E
TB2	38° 18'.23 S 144° 44'.39 E
TB3	38° 18'.29 S 144° 45'.51 E

Shoaling with a least depth of 14.8m exists in the vicinity and north of the virtual buoys. Deep draught vessels should pass to the south of the buoys.

Chart temporarily affected - Aus 144 - Aus 158

1072(P)/2013 AUSTRALIA - VICTORIA - Western Port - Rutherford Inlet - Beacons; mooring piles

Date - On or about 5 November 2013

Victorian Notice 132(T)/2013 (AA701188)

Beacons will be repositioned as follows:

	<i>Current Position</i>	<i>New Position</i>
No24	38° 14'.08 S 145° 18'.44 E	38° 14'.076 S 145° 18'.447 E
No13	38° 13'.99 S 145° 18'.45 E	38° 13'.993 S 145° 18'.442 E
No26	38° 13'.75 S 145° 18'.36 E	38° 13'.752 S 145° 18'.368 E

28 unlit mooring piles will be established between positions 38° 14'.08 S 145° 18'.47 E and 38° 13'.78 S 145° 18'.38 E.

Chart which will be affected - Aus 151 - Aus 152

1184(P)/2013 AUSTRALIA - VICTORIA - Port Phillip - South Channel - Toe lines

Victorian Notice 149/2013 (AA707025)

Toe lines have been amended to the following positions:

38° 17'.55 S 144° 38'.38 E
38° 17'.49 S 144° 39'.02 E
38° 17'.51 S 144° 40'.33 E
38° 17'.58 S 144° 40'.67 E
and
38° 18'.16 S 144° 44'.60 E
38° 18'.55 S 144° 47'.19 E.

Note: new editions of charts are in production.

Chart which will be affected - Aus 143 - Aus 144 - Aus 158

1185(T)/2013 AUSTRALIA - VICTORIA - Port Phillip - Port Melbourne Channel - Light buoys

Date - Until 30 March 2014

Victorian Notice 142(T)/2013 (AA707098, AA707099)

Special pillar light buoys, VQ(4)Y.4s, exist in the following positions:

37° 58'.87 S 144° 55'.69 E
37° 58'.86 S 144° 54'.96 E
37° 56'.58 S 144° 55'.77 E
37° 56'.57 S 144° 55'.07 E.

Chart temporarily affected - Aus 155

1232(T)/2013 AUSTRALIA - VICTORIA - Port Phillip - St Leonards - Harbour works

Date - Until 28 March 2014

Victorian Notice 169(T)/2013 (AA710411)

Harbour works associated with the remediation of the jetty (38° 10'.21 S 144° 43'.25 E) are in progress.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143 - Aus 157 - Aus 158

1296(T)/2013 AUSTRALIA - VICTORIA - Western Port - Drilling operations; survey

Date - Until 30 June 2014

Victorian Notices 162(T)/2013, 177(T)/2013 (AA712873, AA712875)

Survey and drilling operations are in progress between the fairway buoy (38° 30'.21 S 145° 05'.36 E) and Crawfish Rock (38° 16'.21 S 145° 17'.78 E); plus extends into East Arm within the area of the port limits.

Barges *Sealift 1* and *Sealift 2* and support vessels are on site. A 100m exclusion zone exists around the barges.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 150 - Aus 151 - Aus 152

101(T)/2014 AUSTRALIA - VICTORIA - Western Port - Yaringa - Dredging operations

Date - Until 30 March 2014

Victorian Notice 187(T)/2013 (AA715166)

Dredging operations are in progress in the channel (38° 14'.89 S 145° 15'.87 E).

A pipeline exists from the dredge to an area south of the channel where spoil will be deposited.

All hazards to navigation will be marked appropriately.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 151

102(P)/2014 AUSTRALIA - VICTORIA - Western Port - Western Channel - AIS trial

Victorian Notice 6(P)/2014 (AA716215)

An AIS unit MMSI 995031001 has been established at the light buoy, *Fl.R.4s No8* (38° 27'.23 S 145° 09'.40 E).

Chart which will be affected - Aus 150 - Aus 151

147(T)/2014 AUSTRALIA - VICTORIA - Port Phillip - Great Ship Channel - AIS trial

Date - Until 31 July 2014

Victorian Notice 26(T)/2014 (AA718268), Port of Melbourne Corporation (AA718270)

Virtual AIS exist as follows:

<i>MMSI</i>	<i>Position</i>	<i>Remarks</i>
995036085	38° 18'.43 S 144° 37'.12 E	GSC1 port lateral buoy
995036086	38° 18'.05 S 144° 37'.56 E	GSC2 port lateral buoy
995036087	38° 17'.83 S 144° 37'.69 E	GSC3 port lateral buoy
995036088	38° 17'.91 S 144° 37'.96 E	GSC4 starboard lateral buoy
995036089	38° 18'.48 S 144° 37'.28 E	GSC5 starboard lateral buoy

Chart temporarily affected - Aus 143 - Aus 144 - Aus 158

197(T)/2014 AUSTRALIA - VICTORIA - Port Phillip - Mornington - Harbour works

Date - Until 23 December 2014

Victorian Notice 30(T)/2014 (AA721994)

Works associated with the reconstruction of Mornington Pier are in progress in an area marked by special conical light buoys, *Fl.Y.3s*, bounded by the following positions:

38° 12'.70 S 145° 02'.13 E

38° 12'.68 S 145° 02'.11 E

38° 12'.72 S 145° 02'.01 E

38° 12'.76 S 145° 02'.01 E.

All hazards to navigation will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143

239(T)/2014 AUSTRALIA - VICTORIA - Port Phillip - Yarra River - Dredging operations

Date - Until 30 June 2014

Victorian Notice No 38(T)/2014 (AA723556)

The dredge *Storken*, and support vessels are conducting dredging operations in the Port of Melbourne between 37° 51'.80 S 144° 55'.15 E and 37° 49'.15 S 144° 55'.85 E.

The dredge will monitor VHF Ch 16.

Spoil will be deposited in the vicinity of 38° 01'.00 S 144° 52'.80 E

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143 - Aus 154 - Aus 155

240(T)/2014 AUSTRALIA - VICTORIA - Western Port - Rhyll - Harbour works

Date - Until 4 April 2014

Victorian Notice 48(T)/2014 (AA724972)

Works associated with the construction of a pontoon are in progress in an area bounded by the following positions:

38° 27'.98 S 145° 18'.53 E

38° 28'.00 S 145° 18'.51 E

38° 28'.02 S 145° 18'.52 E

38° 28'.01 S 145° 18'.55 E.

All hazards to navigation will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 150

394(T)/2014 AUSTRALIA - VICTORIA - Port Phillip - River Yarra - Victoria Dock - Obstruction

Former Notice - 196(T)/2014 is cancelled

Date - Until 6 May 2014

Port of Melbourne Corporation Notice 74(T)/2014 (AA732792)

Works are in progress to remove an obstruction in position 37° 49'.10 S 144° 55'.76 E. The berth east of the 230 chainage mark is temporarily closed.

Chart temporarily affected - Aus 154

434(T)/2014 AUSTRALIA - BASS STRAIT - Light unlit

AMSA (AA735003)

The light, *Mo(U)15s* (38° 11'.23 S 148° 23'.23 E), is unlit.

Chart temporarily affected - Aus 357 - Aus 4644 (INT 644)

471(P)/2014 AUSTRALIA - VICTORIA - Port Phillip - Anchorages

Victorian Notice 19/2014 (AA717682)

Anchorages have been repositioned as follows:

<i>Anchorage desig</i>	<i>Position</i>
S1	37° 58'.21 S 144° 54'.30 E
S2	37° 57'.56 S 144° 53'.25 E
S3	37° 56'.90 S 144° 52'.20 E
S4	37° 56'.24 S 144° 51'.17 E
S5	37° 57'.17 S 144° 50'.32 E
S6	37° 57'.80 S 144° 51'.39 E
S7	37° 58'.42 S 144° 52'.45 E
S8	37° 58'.81 S 144° 50'.88 E
S9	37° 58'.10 S 144° 49'.67 E
S10	37° 59'.03 S 144° 49'.01 E
S11	37° 59'.74 S 144° 50'.23 E
S12	38° 00'.67 S 144° 49'.58 E
S13	37° 59'.96 S 144° 48'.36 E.

Anchorage with a 926m radius swinging circle exist as follows:

<i>Anchorage desig</i>	<i>Position</i>
G1	38° 01'.60 S 144° 48'.93 E
G2	38° 01'.82 S 144° 47'.06 E
G3	38° 02'.53 S 144° 48'.27 E
G4	38° 02'.74 S 144° 46'.40 E.

ENC cells AU438144 and AU439144 have been updated. These amendments will be incorporated in new edition Aus 155 to be published shortly. A block update for Aus 143 and Aus 157 will be published in due course.

Chart which will be affected - Aus 143 - Aus 155 - Aus 157

472(T)/2014 AUSTRALIA - VICTORIA - Port Phillip - South Channel - Dredging operations

Date - Until 30 June 2014

Victorian Notice 82(T)/2014 (AA736027)

The dredge *Brisbane* and support vessel *Lydia* are conducting dredging operations in the South Channel.

Dredge spoil will be deposited in the spoil ground at 38° 20'.2 S 144° 51'.9 E

Vessels will monitor VHF Ch 12.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143 - Aus 144 - Aus 158

473(T)/2014 AUSTRALIA - VICTORIA - Port Phillip - Port Melbourne - Webb Dock - Silt curtains

Date - Until 31 December 2014

Victorian Notice 84(T)/2014 (AA739510)

Two silt curtains, marked by lit flashing and unlit yellow buoys, exist between:

- 1- 37° 50'.44 S 144° 54'.23 E and 37° 50'.65 S 144° 54'.28 E
- 2- 37° 50'.35 S 144° 54'.30 E, 37° 50'.37 S 144° 54'.29 E and 37° 50'.38 S 144° 54'.25 E.

Chart temporarily affected - Aus 154

474(T)/2014 AUSTRALIA - VICTORIA - Western Port - Stony Point - Harbour works

Date - Until 30 May 2014

Victorian Notice 85(T)/2014 (AA737293)

Harbour works are in progress in the vicinity of position 38° 22'.47 S 145° 13'.37 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 152

TASMANIA

91(T)/2010 AUSTRALIA - TASMANIA - Georges Bay - Wreck

Former Notice - 1204(T)/2009 is cancelled

Marine and Safety Tasmania Notice M3/2010 (AA447779)

A stranded wreck exists in position 41° 16'.24 S 148° 20'.07 E, with a floating line marked by a white poly-float leading to an anchor in position 41° 16'.20 S 148° 20'.13 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 169

576(T)/2012 AUSTRALIA - TASMANIA - Frederick Henry Bay - Scientific instruments

Former Notice - 1229(T)/2011 is cancelled

Date - Until 20 September 2013

Marine and Safety Tasmania (AA602526)

Scientific instruments marked by special conical light buoys exist as follows:

<i>Position</i>	<i>Characteristic</i>
42° 56'.2 S 147° 37'.2 E	<i>Iso.4s</i>
42° 58'.2 S 147° 34'.0 E	<i>Oc.3s.</i>

Chart temporarily affected - Aus 171 - Aus 796

122(T)/2013 AUSTRALIA - TASMANIA - Maria Island - Scientific instruments

Date - Until 28 February 2014

University of Tasmania (AA647460, AA647461)

Subsurface scientific instruments exist on the seabed in the following positions:

42° 40'.08 S 147° 58'.04 E
42° 39'.99 S 147° 58'.60 E
42° 39'.91 S 147° 59'.16 E
42° 39'.82 S 147° 59'.72 E
42° 39'.74 S 148° 00'.28 E.

Subsurface scientific instruments exist 30m below the surface in the following positions:

42° 39'.08 S 148° 10'.40 E
42° 39'.28 S 148° 10'.92 E
42° 39'.48 S 148° 11'.44 E
42° 39'.68 S 148° 11'.96 E
42° 39'.88 S 148° 12'.49 E
42° 40'.08 S 148° 13'.01 E
42° 40'.28 S 148° 13'.53 E
42° 40'.48 S 148° 14'.05 E
42° 40'.68 S 148° 14'.57 E
42° 40'.88 S 148° 15'.10 E
42° 41'.08 S 148° 15'.62 E
42° 41'.28 S 148° 16'.14 E
42° 41'.48 S 148° 16'.66 E
42° 41'.68 S 148° 17'.18 E
42° 41'.88 S 148° 17'.71 E
42° 42'.08 S 148° 18'.23 E
42° 42'.28 S 148° 18'.75 E
42° 42'.48 S 148° 19'.27 E
42° 42'.68 S 148° 19'.79 E
42° 42'.87 S 148° 20'.32 E
42° 43'.07 S 148° 20'.84 E
42° 43'.26 S 148° 21'.26 E.

Chart temporarily affected - Aus 170 - Aus 766 - Aus 797

1074(T)/2013 AUSTRALIA - TASMANIA - Cape Barren Island - Scientific instruments

Date - Until 30 June 2015

Institute for Marine and Antarctic Studies (AA701662 - AA701664), Marine and Safety Tasmania Notice M104/2013 (AA701665)

Subsurface scientific instruments exist on the seabed in the following positions:

40° 26'.38 S 148° 28'.97 E
40° 26'.51 S 148° 29'.51 E
40° 26'.65 S 148° 30'.05 E
40° 26'.78 S 148° 30'.59 E.

Subsurface scientific instruments exist >30m below the surface in the following positions:

40° 26'.91 S 148° 31'.12 E
40° 27'.05 S 148° 31'.66 E
40° 27'.18 S 148° 32'.20 E
40° 27'.31 S 148° 32'.74 E
40° 27'.44 S 148° 33'.27 E
40° 27'.58 S 148° 33'.81 E
40° 27'.71 S 148° 34'.35 E
40° 27'.84 S 148° 34'.89 E
40° 27'.97 S 148° 35'.43 E
40° 28'.11 S 148° 35'.96 E
40° 28'.24 S 148° 36'.50 E
40° 28'.37 S 148° 37'.04 E
40° 28'.50 S 148° 37'.58 E
40° 28'.64 S 148° 38'.12 E
40° 28'.77 S 148° 38'.65 E
40° 28'.90 S 148° 39'.19 E
40° 29'.03 S 148° 39'.73 E
40° 29'.16 S 148° 40'.27 E
40° 29'.30 S 148° 40'.81 E
40° 29'.43 S 148° 41'.35 E
40° 29'.56 S 148° 41'.88 E
40° 29'.69 S 148° 42'.42 E
40° 29'.82 S 148° 42'.96 E
40° 29'.96 S 148° 43'.50 E
40° 30'.09 S 148° 44'.04 E
40° 30'.22 S 148° 44'.58 E
40° 30'.35 S 148° 45'.12 E
40° 30'.48 S 148° 45'.65 E
40° 30'.61 S 148° 46'.19 E
40° 30'.75 S 148° 46'.73 E
40° 30'.88 S 148° 47'.27 E
40° 31'.01 S 148° 47'.81 E
40° 31'.14 S 148° 48'.35 E
40° 31'.27 S 148° 48'.89 E
40° 31'.40 S 148° 49'.40 E
40° 31'.52 S 148° 49'.90 E.

Chart temporarily affected - Aus 487 - Aus 798 - Aus 800

1189(T)/2013 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instruments

Marine and Safety Tasmania M119/2013 (AA706392)

Subsurface scientific instruments >20m below the surface, marked by a subsurface buoy 15m below the surface, exist in the following positions:

42° 16'.22 S 145° 19'.41 E
42° 17'.72 S 145° 20'.52 E
42° 22'.93 S 145° 27'.79 E
42° 11'.74 S 145° 17'.71 E
42° 18'.16 S 145° 24'.42 E
42° 21'.63 S 145° 24'.74 E
42° 09'.74 S 145° 19'.21 E
42° 19'.28 S 145° 22'.48 E
42° 22'.58 S 145° 28'.26 E
42° 18'.56 S 145° 23'.77 E
42° 16'.02 S 145° 18'.69 E
42° 14'.99 S 145° 20'.10 E.

Subsurface scientific instruments <20m below the surface, marked by a subsurface buoy 3m above the seabed, exist in the following positions:

42° 20'.24 S 145° 20'.78 E
42° 15'.80 S 145° 14'.42 E
42° 17'.44 S 145° 18'.18 E
42° 12'.65 S 145° 21'.45 E

42° 21'.45 S 145° 32'.87 E
 42° 17'.23 S 145° 18'.69 E
 42° 14'.53 S 145° 21'.48 E
 42° 22'.82 S 145° 32'.28 E
 42° 11'.51 S 145° 18'.13 E
 42° 22'.13 S 145° 28'.61 E
 42° 21'.88 S 145° 32'.15 E
 42° 17'.04 S 145° 16'.25 E
 42° 14'.64 S 145° 21'.02 E
 42° 10'.31 S 145° 19'.20 E
 42° 17'.04 S 145° 19'.29 E
 42° 10'.93 S 145° 18'.39 E
 42° 21'.06 S 145° 30'.19 E
 42° 12'.21 S 145° 17'.45 E
 42° 17'.16 S 145° 17'.73 E
 42° 14'.53 S 145° 21'.48 E
 42° 19'.56 S 145° 21'.94 E
 42° 22'.57 S 145° 31'.12 E
 42° 16'.72 S 145° 18'.90 E
 42° 18'.74 S 145° 18'.90 E
 42° 22'.59 S 145° 31'.90 E
 42° 17'.55 S 145° 19'.23 E
 42° 18'.61 S 145° 19'.55 E
 42° 18'.01 S 145° 20'.12 E
 42° 21'.66 S 145° 29'.68 E
 42° 21'.92 S 145° 24'.65 E
 42° 24'.86 S 145° 27'.47 E
 42° 16'.82 S 145° 19'.69 E
 42° 17'.41 S 145° 19'.90 E
 42° 23'.78 S 145° 28'.02 E.

Chart temporarily affected - Aus 177 - Aus 792

1297(T)/2013 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instrument

Date - Until 11 June 2014

Marine and Safety Tasmania M129/2013 (AA711802)

A scientific instrument 15m below the surface exists in position 42° 20'.82 S 145° 25'.20 E

Chart temporarily affected - Aus 177 - Aus 792

103(T)/2014 AUSTRALIA - TASMANIA - Schouten Passage - Wreck

Marine and Safety Tasmania Notice M135/2013 (AA715862)

A stranded wreck exists in position 42° 17'.53 S 148° 17'.77 E.

Chart temporarily affected - Aus 169 - Aus 766

149(T)/2014 AUSTRALIA - TASMANIA - Hobart - Wrest Point - Beacon destroyed

Marine and Safety Tasmania Notice M14/2014 (AA717937)

The port lateral beacon (42° 54'.13 S 147° 20'.34 E) has been destroyed.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 172

199(T)/2014 AUSTRALIA - TASMANIA - Franklin Sound - Great Dog Island to Vansittart Island - Lights unreliable

Marine and Safety Tasmania Notice M24/2014 (AA719636)

The following lights are unreliable:

<i>Position</i>	<i>Remarks</i>
40° 14'.80 S 148° 15.78 E	<i>F.WRG. 8m 6M</i>
40° 16'.24 S 148° 17.32 E	<i>F.WRG. 7/5M</i>

Chart temporarily affected - Aus 179 - Aus 800

201(T)/2014 AUSTRALIA - TASMANIA - Franklin Sound - Lady Barron - Shoaling; light unreliable

Marine and Safety Tasmania Notice M144/2011 (AA569730)

Shoaling exists in the vicinity of position 40° 14'.8 S 148° 25.7 E. The light, *F.WRG.48m 10M* (40° 12'.45 S 148° 14.76 E), is unreliable due to shoaling.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 179 - Aus 800

309(T)/2014 AUSTRALIA - TASMANIA - Pipe Clay Head to Pitt Water - Scientific instruments

Date - Until 15 May 2015

Marine and Safety Tasmania (AA725256)

Subsurface scientific instruments exist in the following positions:

42° 48'.25 S 147° 29'.91 E
42° 48'.29 S 147° 31'.42 E
42° 48'.43 S 147° 30'.02 E
42° 49'.18 S 147° 34'.71 E
42° 50'.70 S 147° 33'.57 E
42° 50'.74 S 147° 35'.11 E
42° 50'.90 S 147° 36'.91 E
42° 51'.05 S 147° 32'.08 E
42° 51'.33 S 147° 35'.89 E
42° 51'.69 S 147° 34'.85 E
42° 51'.82 S 147° 30'.92 E
42° 51'.82 S 147° 33'.36 E
42° 52'.35 S 147° 32'.10 E
42° 52'.70 S 147° 36'.29 E
42° 52'.94 S 147° 34'.16 E
42° 53'.24 S 147° 31'.16 E
42° 53'.79 S 147° 32'.67 E
42° 53'.88 S 147° 37'.33 E
42° 54'.20 S 147° 35'.44 E
42° 54'.37 S 147° 30'.53 E
42° 54'.47 S 147° 40'.80 E
42° 54'.67 S 147° 33'.87 E
42° 54'.92 S 147° 40'.78 E
42° 55'.13 S 147° 31'.80 E
42° 55'.36 S 147° 40'.76 E
42° 55'.81 S 147° 40'.74 E
42° 56'.99 S 147° 39'.68 E
42° 57'.04 S 147° 38'.01 E
42° 57'.15 S 147° 39'.22 E
42° 57'.15 S 147° 37'.41 E
42° 57'.28 S 147° 36'.79 E
42° 57'.40 S 147° 36'.20 E
42° 57'.51 S 147° 35'.59 E
42° 57'.62 S 147° 34'.99 E
42° 57'.73 S 147° 34'.44 E
42° 57'.86 S 147° 33'.85 E
42° 57'.96 S 147° 33'.30 E.

Chart temporarily affected - Aus 171 - Aus 796

475(T)/2014 AUSTRALIA - TASMANIA - Port Sorell - Lights unreliable

Date - Until 6 June 2014

Marine and Safety Tasmania Notice M62/2014 (AA739588)

The lights, *Q.Bu & Iso.Bu.2s* (41° 09'.81 S 146° 33.47 E), are unreliable.

Chart temporarily affected - Aus 799

PAPUA NEW GUINEA and SOUTH PACIFIC

404(T)/2008 PAPUA NEW GUINEA - Port Moresby - Fish aggregation device southwards

Former Notice - 665(T)/2006 is cancelled

Department of Transport and Civil Aviation PNG Notice 8/2004 (AA84295)

A fish aggregation device, marked by a buoy, exists in position 9° 44'.5 S 147° 17'.5 E (datum unknown).

Chart temporarily affected - Aus 379 - Aus 505 - Aus 4620 (INT 620)

904(T)/2012 PAPUA NEW GUINEA - Lae - Dredging operations

Date - Until 31 January 2014

PNG Ports Corporation Ltd (AA622596 - AA622602)

Dredges *Tianji* and *Jinhangjun* 406 and support vessels are conducting dredging operations associated with the new harbour development in an area bounded by the following:

<i>Position</i>	<i>Remarks</i>
6° 43'.81 S 146° 58'.15 E	
6° 43'.57 S 146° 58'.83 E	
6° 44'.21 S 146° 58'.84 E	
6° 44'.24 S 146° 58'.92 E	
6° 44'.53 S 146° 58'.86 E	special pillar light buoy, Q.Y
6° 44'.83 S 146° 59'.06 E	special pillar light buoy, Q.Y
6° 44'.83 S 146° 58'.51 E	special pillar light buoy, Q.Y
6° 44'.35 S 146° 58'.56 E.	

An exclusion zone exists within this area.

A lit floating pipeline exists between positions 6° 44'.54 S 146° 58'.84 E and 6° 44'.22 S 146° 58'.69 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 643

164(T)/2013 PAPUA NEW GUINEA - Nuakata Passage - Oreore Channel - Light beacon destroyed

National Maritime Safety Authority PNG Notice 2(T)/2013 (AA650413)

The port lateral light beacon, Q.R (10° 13'.69 S 150° 52'.77 E), has been destroyed.

Chart temporarily affected - Aus 628

166(T)/2013 PAPUA NEW GUINEA - Condor Point - Light unlit

National Maritime Safety Authority PNG Notice 4(T)/2013 (AA649248)

The light, *Fl(2)8s 15m 10M* (4° 07'.12 S 144° 51'.70 E), is unlit.

Chart temporarily affected - Aus 388 - Aus 4622 (INT 622)

771(T)/2013 PAPUA NEW GUINEA - Cape Sueusat - Light unlit

National Maritime Safety Authority PNG Notice 34(T)/2013 (AA686044)

The light, *Fl.5s 9m 10M* (2° 37'.02 S 150° 46'.60 E), is unlit.

Chart temporarily affected - Aus 392 - Aus 393 - Aus 543 - Aus 666

824(T)/2013 PAPUA NEW GUINEA - Cape Croisilles - Light unlit

National Maritime Safety Authority PNG Notice 37/2013 (AA688010)

The light, *Fl(2)6s 17m 10M* (4° 50'.89 S 145° 48'.33 E), is unlit.

Chart temporarily affected - Aus 387 - Aus 388 - Aus 4622 (INT 622)

918(T)/2013 PAPUA NEW GUINEA - Port Moresby - Lark Patch - Light beacon destroyed

National Maritime Safety Authority PNG Notice 39(T)/2013 (AA692723)

The light beacon, *Fl.R.3s 7m 4M* (9° 31'.56 S 147° 08'.53 E), has been destroyed.

Chart temporarily affected - Aus 505 - Aus 621

1062(T)/2013 PAPUA NEW GUINEA - Unei Island - Light unlit

National Maritime Safety Authority PNG Notice 49(T)/2013 (AA701693)

The light, *Fl(4)16s 6m 9M* (3° 22'.69 S 143° 24'.58 E), is unlit.

Chart temporarily affected - Aus 389 - Aus 651 - Aus 4622 (INT 622)

268(T)/2014 PACIFIC OCEAN - Scientific instruments

Former Notice - 351(T)/2013 is cancelled

JAMSTEC (AA727730)

Scientific instruments, Triton buoys, exist as follows:

<i>Number</i>	<i>Position</i>
4	0° 01'.00 S 155° 57'.80 E
5	1° 59'.00 S 156° 01'.99 E
6	4° 57'.99 S 156° 01'.00 E
9	0° 01'.49 S 147° 00'.09 E.

Chart temporarily affected - Aus 399 - Aus 4622 (INT 622)

279(T)/2014 PAPUA NEW GUINEA - Bougainville Island - Lights unlit

Former Notice - 1286(T)/2011 is cancelled

National Maritime Safety Authority PNG Notices 22/2011, 46/2011, 52/2011, 5/2014, 6/2014, 7/2014 (AA535709, AA565338, AA569723, AA726330)

The following lights are unlit:

<i>Location</i>	<i>Position</i>
Otua Island (K4886)	6° 27'.50 S 155° 58'.40 E
Takanupei Island (K4884.4)	6° 08'.86 S 155° 34'.31 E
Banaru Reef (K4885.7)	6° 08'.30 S 155° 39'.03 E
Moto Reef (K4885.8)	6° 08'.77 S 155° 39'.52 E
Wogoromodo Reef (K4885.6)	6° 10'.12 S 155° 39'.03 E
Cape Laverdy (K4884)	5° 32'.49 S 155° 03'.88 E.

Chart temporarily affected - Aus 399 - Aus 683 - Aus 4622 (INT 622)

384(T)/2014 PAPUA NEW GUINEA - Vitiaz Strait - Light unlit

National Maritime Safety Authority PNG Notice 12/2014 (AA733145)

The light, *Fl(2)8s 26m 10M* (6° 19'.16 S 147° 48'.35 E), is unlit.

Chart temporarily affected - Aus 386 - Aus 387

EAST TIMOR

NIL

MISCELLANEOUS

75(T)/2014 INDONESIA - Pulau Selaru - Scientific instruments southwestwards

Date - Until 1 March 2015

Fugro GEOS Pte Ltd (AA715135)

A special spherical light buoy, *Fl(5)Y.20s*, exists in position 9° 07'.22 S 130° 28'.57 E.

A special pillar light buoy, *Fl(5)Y.20s*, exists in position 9° 06'.09 S 130° 28'.23 E.

Chart temporarily affected - Aus 310 - AX 00310U

92(T)/2014 SOUTHERN OCEAN - Great Australian Bight - Seismic survey

Date - Until 30 June 2014

Dolphin Geophysical Pte Ltd (AA715401)

Survey vessel *Polar Duchess*, with a 8000m towed array, and support vessels *Andromeda* and *Strait Shooter* are conducting a survey in the area bounded by the following positions:

33° 50'.0 S 130° 54'.0 E

33° 50'.0 S 131° 39'.0 E

35° 00'.0 S 133° 10'.0 E

35° 45'.0 S 132° 55'.0 E

35° 43'.0 S 132° 05'.0 E

35° 15'.0 S 131° 28'.0 E

34° 27'.0 S 130° 54'.0 E.

Chart temporarily affected - Aus 4727 (INT 727)