



Australian Notices to Mariners are the authority for correcting Australian Charts

AUSTRALIAN NOTICES TO MARINERS

© Commonwealth of Australia 2005 - Copyright restrictions apply to Notices to Mariners



Notices 848 - 881

Published fortnightly by the Australian Hydrographic Service

R. NAIRN

Hydrographer of Australia

- SECTIONS.**
- I. **Australian Notices to Mariners, including blocks and notes.**
 - II. **Amendments to Admiralty List of Lights and Fog Signals, Vol K**
 - III. **Navigational Warnings.**
 - IV. **Hydrographic Reports.**
 - V. **Amendments to Admiralty List of Radio Signals (NP 281(2), 282, 283(2), 285, 286(4))**
 - VI. **Amendments to Admiralty Sailing Directions (NP 9, 13, 14, 15, 17, 33, 34, 35, 36, 39, 44, 51, 60, 61, 62, 100, 136)**

[British Admiralty Notices to Mariners](#)

[New Zealand Notices to Mariners](#)

The substance of these notices should be inserted on the charts affected.

Bearings are referred to the true compass and are reckoned clockwise from 000° (North) to 359°; those relating to lights are given as seen by an observer from seaward. Positions quoted in permanent notices relate to the horizontal datum for the chart(s). When preliminary or temporary notices affect multiple charts, positions will be provided in relation to only one horizontal datum and that datum will be specified. When the multiple charts do not have a common horizontal datum, mariners will be required to adjust the position(s) for those charts not on the specified datum. The range quoted for a light is its nominal range. Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices. A star () adjacent to the number of a notice indicates that the notice is based on original information.*

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 Wollongong, NSW 2500 (Fax 02-4221 8599, e-mail Hydro.NTM@defence.gov.au or, alternatively by filling in and submitting the [Hydrographic Notes](#) forms located on the web site – www.hydro.gov.au), immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).

Copies of these notices can be obtained from the AUSTRALIAN HYDROGRAPHIC OFFICE, 8 Station Street, Wollongong; Distributors for the sale of Australian Navigational Products; AHS website www.hydro.gov.au or register for eNotices at www.hydro.gov.au/enotices/enotices.htm.

The Notices may be copied for the purpose of inserting their substance on official charts and other publications. However, any copies of the notices may not be sold for profit.

IMPORTANT NOTICE

This edition of Notices to Mariners includes all significant information affecting AHS products which the AHS has become aware of since the last edition. All reasonable efforts have been made to ensure the accuracy and completeness of the information, including third party information, on which these updates are based. The AHS regards third parties from which it receives information as reliable, however the AHS cannot verify all such information and errors may therefore exist. The AHS does not accept liability for errors in third party information.

This work is copyright. Apart from any use permitted under the Copyright Act 1968, no part may be reproduced by any process, adapted, communicated or commercially exploited without prior written permission from The Commonwealth represented by the Australian Hydrographic Service. Copyright in some of the material in this publication may be owned by another party and permission for the reproduction of that material must be obtained from the owner.

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 20

30 September 2005

Notices	Aus Chart, INT Chart, ENC Cell
848.....	Aus 654
849.....	Amendment to Australian Notice to Mariners No 10C
850.....	Amendment to Australian Seafarers Handbook AHP 20
851.....	Aus 644, 684, 710, 717, 725, 727, 729, 730, 733, 748, 753, 790, 791, 800, 801, 810, 901, 902, 903, 905
852.....	Aus 198
853.....	Aus 198
854.....	Aus 4620, INT 620, AU220140
855.....	Aus 376, 840, AU210140
856.....	Aus 377, 379, 4603, 4620, INT 603, 620, AU210140, 220140
857.....	Aus 628, 629, 630, AU220150
858.....	Aus 26, 309, 722, AX72026, 70309, 70722, 72309, 72722
859.....	Aus 26, 28, AX 72026
860.....	Aus 4708, INT 708
861.....	Aus 4071, INT 71
862.....	Aus 52, 53, 54
863.....	Aus 134
864.....	Aus 778
865.....	Aus 167
866.....	Aus 4601, INT 601
867.....	Aus 4060, 4602, INT 60, 602
868(T).....	Aus 236
869(T).....	Aus 236, 237
870(T).....	Aus 237
871(T).....	Aus 238
872(T).....	Aus 817, 818, AU325153, 425151
873(T).....	Aus 256, 257, AU420146, 5XX257
874(T).....	Aus 256, 257, AU5XX257
875(T).....	Aus 828, AU419146
876(P).....	Aus 289, 292, 293, 294, 296, 299, 376,700, 839, AU499142
877(T).....	Aus 308, 309, 721, AX 70308, 70309, 70721, 72309
878(T).....	Aus 26, 28, AX 72026
879(T).....	Aus 141
880(P).....	Aus 349
881(T).....	Summer Time

848 AUSTRALIA - Products.

AHO (A164917), HSA (A163095), Newcastle Ports Corp.

New Edition to be published shortly

<i>Chart</i>	<i>Title</i>	<i>Scale</i>	<i>Expected Publication Date</i>	<i>Expected Stock Availability</i>
Aus 654	Plans in Papua New Guinea (Sheet 1) Plan:		14 October 2005	11 November 2005
	Nares Harbour	1:75 000		
	Southwest Bay	1:75 000		
	Round Hill Anchorage	1:50 000		
	Inverary Bay	1:37 500		
	St Andrew Anchorage	1:37 500		
	Kelaua Harbour	1:25 000		
	Langemark Bay and Finsch Harbour	1:18 000		
	Papitalai Harbour	1:15 000		
	Dreger and Schneider Harbours	1:12 000		
	Melanua Harbour	1:10 000		
	Discovery Bay	1:7 500		
	Kana Kopi Bay	1:7 500		
	Maika Harbour	1:5 000		

Amendment to Notice to Mariners Edition 18 of 2005

Section 1 page 5 Notice 768	position of first light <i>Fl. R.</i> 3s should read 32° 55'.183 S 151° 45'.681 E longitude of buoy to be moved should read 151° 45'.64 S latitudes of depths to be deleted should read 32°.....
Section 1 page 7 Notice 777	longitude of light to be moved should read 136° 50'.05 E.

849 AUSTRALIA - Products - Amendment to Australian Notice to Mariners No 10C.

AMSA (A164981 & A164980).

Substitute [accompanying page](#) for Notice 10C on pages 91 and 92

850 AUSTRALIA - Products - Amendment to Australian Seafarers Handbook AHP 20.

AHO (A162787 & A162969).

Chapter 6 Great Barrier Reef Cruise Ship Anchorages

Page 75 Cruise Ship Activities para 2

amend first sentence to read: The GBRMPA has identified **27** cruise ship anchorages.....

amend third sentence to read: There are 11 anchorages in the Far Northern Section of the Marine Park, 3 in the Cairns Area, **2 in the Hinchinbrook Area**, 8 in the Whitsunday Area and 3 in the Mackay/Capricorn Section.

851* AUSTRALIA - Miscellaneous correction.

AHO (A121281).

Aus 644 [NC 24/1/2003]

Substitute [accompanying legend](#) for ZOC CATEGORIES in NE corner

Aus 684 (plan, Empress Augusta Bay) [690/2002]

Substitute [accompanying legend](#) for ZOC CATEGORIES 6° 12'.2 S 155° 08'.6 E

Aus 710 [425/2002]

Substitute [accompanying legend](#) for ZOC CATEGORIES 15° 18'.4 S 136° 17'.0 E

Aus 717 [831/2003]

Substitute [accompanying note](#) for AMJ note 12° 13'.7 S 134° 39'.5 E

[accompanying table](#) for ZOC CATEGORIES table 12° 22'.0 S 134° 46'.5 E

Aus 725 [274/2004]

Substitute [accompanying note](#) for AMJ note 14° 17'.5 S 129° 46'.0 E

[accompanying legend](#) for ZOC CATEGORIES 15° 03'.2 S 129° 45'.5 E

Aus 727 [833/2004]		
Substitute	accompanying note for AMJ note	14° 14'.0 S 127° 05'.5 E
	accompanying legend for ZOC CATEGORIES	14° 11'.8 S 127° 15'.3 E
Aus 729 [931/2004]		
Substitute	accompanying note for AMJ note	14° 47'.3 S 125° 34'.7 E
	accompanying legend for ZOC CATEGORIES	14° 53'.0 S 124° 09'.7 E
Aus 730 [778/2005]		
Substitute	accompanying note for AMJ note	15° 28'.2 S 125° 28'.5 E
	accompanying legend for ZOC CATEGORIES	14° 51'.8 S 125° 27'.0 E
Aus 733 [872/2004]		
Substitute	accompanying note for AMJ note	17° 14'.7 S 123° 16'.5 E
	accompanying note for Historic Wreck note	17° 14'.7 S 123° 11'.6 E
	accompanying legend for ZOC CATEGORIES	17° 20'.9 S 122° 54'.4 E
Aus 748 [337/2002]		
Amend	MEPA note to read <i>see Australian Seafarers Handbook AHP 20.</i>	25° 32'.8 S 114° 15'.0 E
Aus 753 [200/2005]		
Substitute	accompanying note for Historic Wreck note	30° 18'.6 S 115° 21'.0 E
	accompanying note for MPA note	30° 20'.8 S 115° 21'.0 E
Aus 790 [NC 12/11/2004]		
Substitute	accompanying note for AMJ note	40° 19'.0 S 145° 32'.2 E
	accompanying legend for ZOC CATEGORIES	40° 49'.4 S 144° 59'.0 E
Aus 791 [204/2005]		
Substitute	accompanying note for AMJ note	40° 57'.8 S 144° 59'.0 E
	accompanying legend for ZOC CATEGORIES	41° 10'.9 S 144° 56'.5 E
Aus 800 [60/2005]		
Substitute	accompanying note for Historic Wreck note	39° 59'.0 S 147° 58'.5 E
	accompanying legend for ZOC CATEGORIES	40° 31'.0 S 147° 47'.5 E
Aus 801 [792/2004]		
Substitute	accompanying note for Historic Wreck note	38° 37'.5 S 145° 59'.5 E
Aus 810 [632/2005]		
Substitute	accompanying note for Historic Wreck note	31° 57'.5 S 152° 15'.0 E
	accompanying legend for ZOC CATEGORIES	32° 14'.5 S 152° 12'.0 E
Aus 901 [NC 4/4/2003]		
Substitute	accompanying legend for ZOC CATEGORIES	8° 33'.41 S 125° 31'.70 E
Aus 902 (plan, Approaches to Karabela) [NC 2/5/2003]		
Substitute	accompanying legend for ZOC CATEGORIES	8° 28'.93 S 126° 17'.10 E
Aus 903 [NC 2/5/2003]		
Substitute	accompanying legend for ZOC CATEGORIES in SE corner	
Aus 905 [NC 16/5/2003]		
Substitute	accompanying legend for ZOC CATEGORIES	9° 16'.82 S 125° 17'.29 E

852* AUSTRALIA - NEW SOUTH WALES - Port Hacking - Light beacon.
UKHO (A162510).

Aus 198 [811/2005]

Amend legend to G

34° 04'.31 S 151° 06'.44 E

853* AUSTRALIA - NEW SOUTH WALES - Botany Bay to Woronora River - Light beacon; dredged area.
UKHO (A162510).

Aus 198 [852/2005]

Insert legend, G

34° 00'.82 S 151° 02'.88 E

Substitute black dashed line for magenta pecked line between

33° 59'.65 S 151° 12'.71 E
33° 59'.71 S 151° 12'.68 E
33° 59'.64 S 151° 12'.50 E
33° 59'.58 S 151° 12'.53 E
33° 59'.65 S 151° 12'.71 E

854* AUSTRALIA - QUEENSLAND - Noggin Reef to Euston Reef - Depths.
LADS HI 357 MMI 3-1-21746 (A97328), UKHO (A164540).

Aus 4620 (INT 620) [775/2005]

Insert depth, 21₆ m, enclosed by contour

17° 00'.8 S 146° 24'.2 E

Substitute depth, 7₈ m, for depth 9₁ m

17° 08'.1 S 146° 34'.5 E

depth, 30m, for depth 37m and extend contour S to enclose

17° 03'.0 S 146° 32'.0 E

depth, 5m, for depth 7₃ m

17° 00'.0 S 146° 31'.0 E

depth, 5₂ m, for depth 5₅ m

16° 45'.4 S 146° 20'.5 E

AU220140 [682/2005]

855* AUSTRALIA - TORRES STRAIT - Warrior Reefs - Depths.

HMAS *Melville* HI 399 (A164924 & A164928), HMAS' *Paluma* and *Mermaid* (A159086 & A165096).

Aus 376 [809/2005]

Insert depth, 2₁ m

9° 33'.27 S 143° 10'.27 E

depth, 7₉ m

9° 26'.38 S 143° 03'.45 E

depth, 5₉ m

9° 26'.90 S 142° 59'.04 E

danger line between

9° 34'.85 S 143° 09'.80 E

9° 34'.24 S 143° 09'.91 E

9° 33'.91 S 143° 09'.43 E

danger line between

9° 33'.50 S 143° 10'.62 E

9° 33'.50 S 143° 11'.57 E

Delete depth 10₃ m

9° 37'.3 S 143° 13'.2 E

depth 7₃ m

9° 33'.5 S 143° 10'.0 E

danger line between

9° 34'.9 S 143° 09'.8 E

9° 34'.5 S 143° 10'.9 E

9° 33'.9 S 143° 09'.4 E

danger line between

9° 33'.5 S 143° 10'.6 E

9° 34'.5 S 143° 11'.7 E

9° 33'.5 S 143° 11'.6 E

Aus 840 [774/2005]

Insert	depth, 2 ₁ m	9° 33'.18 S	143° 10'.33 E
	depth, 4 ₄ m, and semi enclose with contour to SW	9° 33'.35 S	143° 07'.58 E
	depth, 4 ₉ m, and semi enclose with contour to SW	9° 32'.51 S	143° 05'.84 E
	depth, 7 ₉ m	9° 26'.29 S	143° 03'.51 E
	depth, 5 ₉ m	9° 26'.81 S	142° 59'.10 E
	depth, 1 ₃ m	(a) 9° 34'.43 S	143° 09'.57 E
	insert a contour enclosing (a) between	9° 35'.00 S	143° 09'.08 E
		9° 34'.17 S	143° 08'.83 E
	unsurveyed boundary between	9° 28'.54 S	142° 58'.00 E
		9° 25'.90 S	142° 58'.00 E
		9° 25'.90 S	143° 08'.18 E
Delete	depth 6 ₄ m	9° 32'.61 S	143° 05'.60 E
	unsurveyed boundary between	9° 28'.5 S	143° 06'.4 E
		9° 28'.5 S	142° 58'.0 E

AU210140 [NC 773/2005]**856* AUSTRALIA - CORAL SEA - Shoals disproved.**

University of Hawaii mA105451 (A164896 & A164897).

Aus 377 [774/2005]

Insert	contour between	9° 47'.57 S	145° 58'.52 E
		9° 41'.06 S	146° 15'.24 E
Delete	depth 1971m and enclosing contour	10° 02'.8 S	146° 17'.2 E
	depth 1244m and enclosing contour	9° 56'.4 S	146° 21'.3 E
	depth 1902m	9° 50'.8 S	146° 13'.8 E
	depth 1500m	9° 44'.1 S	146° 09'.6 E
	contour between	9° 47'.6 S	145° 58'.5 E
		9° 51'.2 S	146° 14'.9 E
		9° 41'.1 S	146° 15'.2 E

Aus 379 [720/2001]

Delete	depth 1902m and enclosing contour	9° 50'.6 S	146° 13'.9 E
	depth 1924m and enclosing contour	9° 45'.9 S	146° 14'.2 E
	depth 225m and legend Co	8° 47'.6 S	146° 02'.3 E

Aus 4603 (INT 603) [821/2005]

Delete	depth 225m	8° 47'.6 S	146° 02'.3 E
--------	------------	------------	--------------

Aus 4620 (INT 620) [854/2005]

Insert	contour between	9° 47'.5 S	145° 58'.6 E
		9° 41'.0 S	146° 15'.3 E
Delete	depth 1971m and enclosing contour	10° 02'.8 S	146° 17'.2 E
	depth 1902m and enclosing contour	9° 50'.6 S	146° 13'.9 E
	depth 225m, enclosing contour and legend Co	8° 47'.6 S	146° 02'.3 E
	contour between	9° 47'.5 S	145° 58'.6 E
		9° 51'.1 S	146° 15'.0 E
		9° 41'.0 S	146° 15'.3 E

AU210140 [855/2005]**AU220140 [854/2005]**

857* PAPUA NEW GUINEA - Nuakata Passage - Preferred route.
Nautical Consulting (A164978).

Aus 628 [637/2005]

Insert	preferred route, with legend <i>Preferred Route (see Note)</i> 062° - 242°, between	10° 25'.86 S 10° 23'.00 S	150° 54'.00 E 150° 59'.44 E
	preferred route, with legend <i>Preferred Route (see Note)</i> 176° - 356°, between	10° 23'.00 S 10° 13'.31 S	150° 59'.44 E 150° 58'.76 E
	preferred route, with legend <i>Preferred Route (see Note)</i> 147° - 327°, between	10° 13'.31 S 10° 10'.20 S	150° 58'.76 E 150° 56'.72 E
	preferred route, with legend <i>Preferred Route (see Note)</i> 121.5° - 301.5°, between	10° 10'.20 S 10° 07'.34 S	150° 56'.72 E 150° 52'.00 E
	accompanying note	10° 26'.4 S	150° 54'.4 E

Aus 629 [819/2005]

Insert	preferred route, with legend <i>Preferred Route (see Note)</i> 062° - 242°, between	10° 25'.95 S 10° 23'.09 S	150° 53'.94 E 150° 59'.38 E
	preferred route, with legend <i>Preferred Route (see Note)</i> 176° - 356°, between	10° 23'.09 S 10° 13'.40 S	150° 59'.38 E 150° 58'.70 E
	preferred route, with legend <i>Preferred Route (see Note)</i> 147° - 327°, between	10° 13'.40 S 10° 10'.29 S	150° 58'.70 E 150° 56'.66 E
	preferred route, with legend 121.5° - 301.5°, between	10° 10'.29 S 10° 09'.40 S	150° 56'.66 E 150° 55'.22 E
	accompanying note	10° 29'.4 S	150° 25'.7 E

Aus 630 [681/2005]

Insert	preferred route, with legend <i>Preferred Route (see Note)</i> 062° - 242°, between	10° 25'.38 S 10° 23'.09 S	150° 55'.00 E 150° 59'.38 E
	preferred route, with legend <i>Preferred Route (see Note)</i> 176° - 356°, between	10° 23'.09 S 10° 13'.40 S	150° 59'.38 E 150° 58'.70 E
	preferred route, with legend <i>Preferred Route (see Note)</i> 147° - 327°, between	10° 13'.40 S 10° 11'.00 S	150° 58'.70 E 150° 57'.13 E
	accompanying note	10° 17'.5 S	151° 30'.5 E

AU220150 [856/2005]

858* AUSTRALIA - NORTHERN TERRITORY - Darwin - Light altered in position.

List of Lights Vol K/2005 - 3323

HMAS *Bunbury* (A77218), Darwin International Airport (A163099), AHO (A165054).

Aus 26 [640/2005]

Substitute	light, Aero Al. Fl. WG. 72m 26M RADIO TR, for tower	12° 24'.55 S	130° 52'.88 E
Delete	light	12° 25'.17 S	130° 52'.12 E

Aus 309 [820/2005]

Insert	light, Aero Al. Fl. WG. 26M	12° 24'.63 S	130° 52'.82 E
Delete	light	12° 25'.3 S	130° 51'.9 E

Aus 722 [359/2005]

Substitute	light, Aero Al. Fl. WG. 26M RADIO TR, for tower	12° 24'.55 S	130° 52'.88 E
Delete	light	12° 25'.17 S	130° 52'.12 E

AX 70309 [820/2005]

Insert	light, Aero Al. Fl. WG. 26M	12° 24'.63 S	130° 52'.82 E
Delete	light	12° 25'.3 S	130° 51'.9 E

AX 70722 [359/2005]			
Substitute	light, Aero Al. Fl. WG. 26M RADIO TR, for tower	12° 24'.55 S	130° 52'.88 E
Delete	light	12° 25'.17 S	130° 52'.12 E
AX 72026 [NC 22/7/2005]			
Substitute	light, Aero Al. Fl. WG. 72m 26M RADIO TR, for tower	12° 24'.55 S	130° 52'.88 E
Delete	light	12° 25'.17 S	130° 52'.12 E
AX 72309 [820/2005]			
Insert	light, Aero Al. Fl. WG. 26M	12° 24'.63 S	130° 52'.82 E
Delete	light	12° 25'.3 S	130° 51'.9 E
AX 72722 [NC 22/7/2005]			
Substitute	light, Aero Al. Fl. WG. 26M RADIO TR, for tower	12° 24'.55 S	130° 52'.88 E
Delete	light	12° 25'.17 S	130° 52'.12 E
859* AUSTRALIA - NORTHERN TERRITORY - Darwin - Light buoy. Port of Darwin Notice 22/2005 (A163776).			
Aus 26 [858/2005]			
Insert	starboard lateral spar light buoy, Fl(2) G. 4s, with topmark	12° 28'.371 S	130° 48'.368 E
Aus 28 (plan, Port Darwin) [640/2005]			
Insert	starboard lateral spar light buoy, Fl(2) G. 4s No 9A, with topmark	12° 28'.371 S	130° 48'.368 E
AX 72026 [858/2005]			
Insert	starboard lateral spar light buoy, Fl(2) G. 4s, with topmark	12° 28'.371 S	130° 48'.368 E
860 INDONESIA - Jawa - Pu Panaitan - Depth northwards. British Admiralty Notice 4096/35/2005 (A163621).			
Aus 4708 (INT 708) [628/2005]			
Insert	depth 69m enclosed by contour	6° 24'.0 S	105° 00'.0 E
Delete	depth 208m	6° 24'.0 S	105° 03'.0 E
861 INDONESIA - Sumatera - Breueh - Depth northwards. British Admiralty Notice 4104/35/2005 (A163620).			
Aus 4071 (INT 71) [598/2005]			
Substitute	depth, 7m, enclosed by danger circle, for depth 10m	5° 49'.0 N	94° 50'.0 E
862* WESTERN AUSTRALIA - Port Hedland - Towers. N Lemon (A162951).			
Aus 52 [129/2002]			
Insert	radio mast	20° 18'.642 S	118° 35'.216 E
Move	tower to	20° 18'.56 S 20° 18'.573 S	118° 36'.67 E 118° 36'.663 E
Aus 53 [92/2003]			
Insert	radio mast	20° 18'.642 S	118° 35'.216 E
	tower with legend WATER TR	20° 18'.573 S	118° 36'.663 E
Delete	tower	20° 18'.60 S	118° 36'.67 E

Aus 54 [548/2005]			
Insert	radio mast	20° 18'.562 S	118° 35'.276 E
Delete	tank	20° 18'.57 S	118° 35'.27 E

863* SOUTH AUSTRALIA - Port Lincoln - Light beacon.
 Transport SA Notice 28/2005 (A163172).

Aus 134 [514/2005]			
Insert	port lateral light beacon, <i>Q. R. 4m 2M</i> , with topmark	34° 42'.15 S	135° 51'.32 E

864* SOUTH AUSTRALIA - Port Augusta - Beacons.
 Transport SA (A161220).

Aus 778 (plan, Port Augusta) [809/2005]			
Delete	beacon with legend	32° 29'.97 S	137° 45'.40 E
		32° 29'.95 S	137° 45'.34 E

865* AUSTRALIA - TASMANIA - Bell Bay - Middle Island - Light beacon altered in position.
 Port of Launceston (A163248).

Aus 167 (plan, Bell Bay) [736/2005]			
Move	light beacon	41° 08'.58 S	146° 51'.78 E
	to	41° 08'.589 S	146° 51'.787 E

866 SOUTHERN OCEAN - Stewart Island - Depths southward.
 British Admiralty Notice 4043/34/2005 (A162851).

Aus 4601 (INT 601) [446/2005]			
Insert	depth, <i>99m</i>	48° 42'.0 S	166° 44'.0 E
	depth, <i>90m</i>	47° 38'.2 S	167° 28'.7 E
Substitute	depth, <i>26m</i> , enclosed by contour, for depth 42m	47° 25'.0 S	167° 48'.0 E

867 PACIFIC OCEAN - Kiwi Seamount - Depths northward.
 British Admiralty Notices 4042/34/2005 & 4043/35/2005 (A162851).

Aus 4060 (INT 60) [638/2005]			
Insert	depth, <i>635m</i> , enclosed by contour	29° 53'.0 S	174° 06'.0 E
Substitute	depth, <i>559m</i> , for depth 1315m	30° 27'.0 S	174° 17'.0 E
Delete	depth 1405m	29° 50'.0 S	173° 40'.0 E

Aus 4602 (INT 602) [462/2005]			
Insert	depth, <i>559m</i> , and extend contour N to enclose	30° 27'.0 S	174° 17'.0 E
	depth, <i>635m</i> , enclosed by contour	29° 53'.0 S	174° 06'.0 E
Delete	depth 1315m and enclosing contour	30° 29'.0 S	174° 15'.0 E
	depth 1783m and enclosing contour	29° 50'.0 S	174° 01'.0 E

868(T)/2005 AUSTRALIA - QUEENSLAND - Moreton Bay - Moreton Island - Scientific instruments westward.

Date - Until 5 October 2005

Maritime Safety Queensland Notice 487(T)/2005 (A165319).

Scientific instruments, special spherical light buoys, *Fl. Y. 4s*, exist in positions:

27° 12'.22 S 153° 18'.21 E

27° 09'.52 S 153° 20'.04 E

27° 08'.68 S 153° 21'.12 E

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 236.

869(T)/2005 AUSTRALIA - QUEENSLAND - Brisbane River - Fisherman Islands - Inner Bar Reach - Harbour works completed.

Former Notices - 100(T)/2005 & 379(T)/2005 are cancelled

Maritime Safety Queensland Notice 475/2005 (A163469).

Cancel this notice on receipt.

Chart formerly affected - Aus 236 - Aus 237.

870(T)/2005 AUSTRALIA - QUEENSLAND - Brisbane River - Harbour works completed.

Former Notice - 382(T)/2005 is cancelled

Maritime Safety Queensland Notice 475/2005 (A163469).

Cancel this notice on receipt.

Chart formerly affected - Aus 237.

871(T)/2005 AUSTRALIA - QUEENSLAND - Brisbane River - Petrie - Geotechnical investigations and core drilling operations completed.

Former Notice - 697(T)/2005 is cancelled

Maritime Safety Queensland Notice 473/2005 (A163472).

Cancel this notice on receipt.

Chart formerly affected - Aus 238.

872(T)/2005 AUSTRALIA - QUEENSLAND - Rooney Point to Round Hill Head - Scientific instruments.

Date - Until 30 November 2005

HMAS *Melville* (A165442 & A165639).

Scientific instruments, tide gauges marked with special buoys, exist in positions (WGS 84 datum):

24° 46'.12 S 153° 06'.31 E

24° 09'.40 S 151° 52'.97 E

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 817 - Aus 818 - AU325153 - AU425151.

873(T)/2005 AUSTRALIA - QUEENSLAND - Townsville - Depth information.

Former Notice - 705(T)/2005 is cancelled

Maritime Safety Queensland Notice 491(T)/2005 (A165700).

Available depths as at 9 September 2005:

<i>Metres</i>		<i>Remarks</i>
Sea Channel	11.7	
* Platypus Channel	11.5	
Outer Harbour:		
* Arrival Channel	7.7	West of a line from dolphin across end of berth pocket to edge of arrival channel
* Departure Channel	11.5	
Inner Harbour:		
* Harbour	11.6	
Berths:		
No 1	12.0	
* No 2	12.7	
* No 3	12.1	
No 4	10.2	
No 7	11.2	
No 8	10.4	
* No 9	12.2	
* No 10	9.6	To seaward dolphin
* No 11	11.0	
* Between No 7 and No 8	10.7	Seaward of zero mark at No 7 berth
Between No 9 and No 10	10.3	Seaward of zero mark at No 10 berth
Ross River Channel	1.1	
Ross River and Ross Creek	-	No declared depth
* Indicates revised entry.		

Chart temporarily affected – Aus 256 - Aus 257 - AU420146 - AU5XX257.

874(T)/2005 AUSTRALIA - QUEENSLAND - Townsville - Dredging operations.

Maritime Safety Queensland Notice 500(T)/2005 (A165793).

Dredge *Brisbane* is operating in Townsville Harbour in the vicinity of 19° 15' S 146° 50' E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 256 - Aus 257 - AU5XX257.

875(T)/2005 AUSTRALIA - QUEENSLAND - Rockingham Bay - Garden Island - Wreck salvaged; light buoy withdrawn.

Former Notice - 837(T)/2005 is cancelled

Maritime Safety Queensland Notice 499/2005 (A165798).

Cancel this notice on receipt.

Chart formerly affected - Aus 828 - AU419146.

876(P)/2005 AUSTRALIA - TORRES STRAIT - Hammond Hill - Changes to tide gauge broadcast.

Former Notice - 750(P)/2005 is cancelled

AMSA (A164980 & A164891).

Note: Notice to Mariners 849/2005 refers.

Cancel this notice on receipt.

Chart formerly affected - Aus 289 - Aus 292 - Aus 293 - Aus 294 - Aus 296 - Aus 299 - Aus 376 - Aus 700 - Aus 839 - AU499142.

877(T)/2005 AUSTRALIA - NORTHERN TERRITORY - Melville Island - Cache Point - Scientific instruments recovered.

Former Notice - 751(T)/2005 is cancelled

HMAS *Leeuwin* (A165440).

Cancel this notice on receipt.

Chart formerly affected - Aus 308 - Aus 309 - Aus 721 - AX 70308 - AX 70309 - AX 70721 - AX 72309.

878(T)/2005 AUSTRALIA - NORTHERN TERRITORY - Darwin - Pipeline; pumping stations.

Date - Until 28 February 2006

Port of Darwin Notice 21/2005 (A163777).

A submerged pipeline, marked with special light buoys, Q. Y, exists between approx positions 12° 27'.8 S 130° 51'.0 E and 12° 29'.1 S 130° 53'.5 E.

Pumping stations exist in positions:

12° 28'.32 S 130° 51'.86 E

12° 28'.67 S 130° 52'.69 E

Anchoring within 100 metres of the pipeline is prohibited.

Chart temporarily affected - Aus 26 - Aus 28 - AX 72026.

879(T)/2005 AUSTRALIA - VICTORIA - Port Fairy - Light buoy off station.

Victorian Notice 79(T)/2005 (A165779).

The light buoy (38° 23'.03 S 142° 15'.25 E) is submerged.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 141.

880(P)/2005 AUSTRALIA - VICTORIA - Port Campbell - Pipeline southwestwards.

Date - On or about 30 October 2005

Santos Ltd (A162767, A162768, A164787 - A126790, A164797, A164822 - A164826).

Pipelay vessel Seaway Falcon will undertake pipelaying operations to establish the Casino gas field pipeline as follows:

<i>Position (WGS 84)</i>	<i>Remarks</i>
38° 37'.42 S 142° 57'.71 E	HWL
38° 39'.99 S 142° 57'.62 E	TP1
38° 40'.76 S 142° 57'.12 E	TP2 thence a straight line to
38° 47'.61 S 142° 46'.51 E	TP3
38° 47'.84 S 142° 45'.37 E	TP4 thence a straight line to
38° 47'.29 S 142° 41'.87 E	Casino 4

Mariners are advised to navigate with caution in the area.

Charting action will take place on receipt of as laid positions.

Chart which will be affected - Aus 349.

881(T)/2005 AUSTRALIA - Summer time.

Date - Until 26 March 2006

NSW Govt (A162926), ABC (A165755).

Clocks will be advanced/retarded one hour in the following states at 0200/0300 local time as follows:

	<i>Advanced</i>	<i>Retarded</i>
Australian Capital Territory	30 OCT 2005	26 MAR 2006
New South Wales	30 OCT 2005	26 MAR 2006
South Australia	30 OCT 2005	26 MAR 2006
Victoria	30 OCT 2005	26 MAR 2006
Tasmania	2 OCT 2005	26 MAR 2006

No changes will be made in Queensland, Northern Territory and Western Australia.

II

AMENDMENTS TO ADMIRALTY LIST OF LIGHT AND FOG SIGNALS VOLUME K 2005/06

Edition No 20 dated 30 September 2005.

Last Amendment: Edition No 19 dated 16 September 2005

1411-23	Gosong Berasbasah	3 06-50 111 32-67	Fl W 5s	8	3	Wooden post 6	<i>fl 0-5</i>
				*	*	*	
1437	<i>Remove from List</i>						
1438-2	<i>Remove from List</i>						
1438-3	-- Pier. Elbow	3 12-40 116 17-23	Fl W	...	...	Beacon	
*	*	*	*	*	*	*	*
1438-32	- Pontoon. NE Head	3 13-42 116 17-06	Fl W	...	...	Beacon	
*	*	*	*	*	*	*	*
1438-33	-- SW Head	3 13-58 116 16-98	Fl W	...	...	Beacon	
*	*	*	*	*	*	*	*
1438-4	<i>Remove from List</i>						
2104-3	- Penneshaw	35 43-20 137 56-12	Fl G 5s				
*	*	*	*	*	*	*	*
2337	- PORT MELBOURNE CHANNEL. Fawkner	37 57-01 144 55-55	Fl W 5s	17	17	White round tower, red bands, on pile structure	Emergency light Fl W5s 10M. Racon
							*
2355	-No 21	37 51-2 144 54-8	Fl G 5s	7	2	Green metal pile beacon	<i>fl 1. Destroyed; starboard lateral light buoy in situ (T) 2005</i>
							*
2574	- Entrance. E Point	36 25-4 150 04-5	Iso W 2s	...	10	Mast	
							*
2945-5	-	25 30-53 152 58-95	Fl G 2-5s	...	...	Green △ on beacon	
							*
2989-91	--- Rear. 0-8M from front	23 49-15 151 15-60	Iso W 2s	...	...	Orange □, yellow stripe, on black pile	
	----	...	Fl(2) W 6s	...	...	Same structure	
							*
3235-05	- Diamond Reign Reefs (COM)	13 11-56 143 47-55	Fl(2) WRG 8s	22	W 14 R 11 G 11	White GRP tower on white piles 20	<i>fl 1, ec 2, fl 1, ec 4, R 166°-173.3°(7.3°), W 173.3°-309°(135.7°), G 309°-329°(20°), W 329°-331.5°(2.5°), R 331.5°-350°(18.5°), W 350°-166°(176°). Racon</i>
							*
3640-5	-	43 09-57 147 14-54	VQ(3) W 5s	...	...	◊ on black beacon, yellow band	
*	*	*	*	*	*	*	*
3640-6	-	43 10-71 147 17-23	Q(6)+LFl W 15s	...	...	▽ on black beacon, yellow top	
*	*	*	*	*	*	*	*

Volume K *continued*

3645-2	- Butts Reef	43 16-6 147 07-5	Fl(2) W 8s	...	...	⊗ on black beacon, red band	
*	*	*	*	*	*	*	*
3759	Hobson Point	36 51-05 174 48-26	Fl R 5s	3	2	Red □ on wooden pile 3	
*	*	*	*	*	*	*	*

III

NAVIGATION WARNINGS

The following radio messages have been received during the period to 16 September 2005. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNING

232 SE Coast. Drill rig *Ensco 102* in position 38° 11'.0 S 147° 50'.3 E. 2.5M clearance requested.
 233 NW Coast. Drill rig *Ensco 67* in position 20° 43'.1 S 115° 29'.4 E. 2.5M clearance requested.
 234 NW Coast. Drill rig *Ensco 56* in position 20° 40'.1 S 115° 30'.9 E. 2.5M clearance requested.
 235 Cancelled.
 236 Cancelled.
 237 Cancelled.
 238 Cancelled.
 239 Cancelled.
 240 Cancelled.

NAVAREA X WARNINGS

Nil issued.

Navigational warnings in force as at 150001UTC SEP 05.

Auscoast

216 224 225 229 232 233 234.

Navarea X

003.

Summary of mobile drilling rigs as at 150001UTC SEP 05.

Name	Position
Ocean Bounty	10° 08'.1 S 130° 08'.5 E
Atwood Eagle	14° 26'.6 S 121° 38'.5 E
Sedco 703	19° 34'.1 S 116° 29'.2 E
Ensco 106	20° 34'.5 S 115° 38'.3 E
Ensco 56	20° 40'.1 S 115° 30'.9 E
Ensco 67	20° 43'.1 S 115° 29'.4 E
Jack Bates	21° 28'.9 S 113° 59'.3 E
Ocean Patriot	38° 18'.0 S 148° 42'.4 E
Ensco 102	38° 11'.0 S 147° 50'.3 E

NAVAREA XIV WARNINGS

045 South Pacific. Fiji. Wailagilala light K4752 (16° 45' S 179° 06' W) unlit and Racon (W) ALRS 88520 inoperable.
 Following lights also unit:

Cape Washington.	K4662	(19° 07' S 177° 58' E)
Vanuatubu	K4663	(19° 02' S 178° 29' E)
Beqa SW Reef.	K4695	(18° 30' S 177° 59' E)
Naqelelelevu E.	K4756	(16° 05' S 179° 09' W)
Totoya Is	K4758	(19° 00' S 179° 52' W)

046 Cancelled.
 047 Cancelled.

Navarea XIV warnings in force as at 150001UTC SEP 05.

045.

HYDROGRAPHIC REPORTS

Nil Reports

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS 2005

Edition No 20 dated 30 September 2005

VOLUME 1, PART 2, NP 281(2), 2005/06

Published BA Wk 26/05

(Last Amendments: Edition No 19 dated 16 September 2005)

MARITIME RADIO STATIONS

Page 50, diagram, BERMUDA & CARIBBEAN, **MRCC & MRSC, MARITIME RADIO STATIONS**, in approximate position 25°15'N 60°00'W, **Fort-de-France (MRCC)** Martinique Windward Islands Centre for co-ordination of SAR within West Indies, contacts table, row 3, delete E-mail: cross.fort-de-france@equipement.gouv.fr and replace by:

E-mail: fortdefrance.mrcc@equipement.gouv.fr

MRCC Fort de France Ad36/05

Page 86, **CHILE**, after **CHAÑARAL**, insert station:

CHILE (MRCC)					
33°05'S 71°37'W					
 +56(0)32 208637, 208638 & 208639			 +56(0)32 208662		
E-MAIL mrccchile@directemar.cl					
NOTES:					
1. Chile MRCC is located in Valparaíso. A network of Maritime Radio Stations maintains a continuous listening watch on international distress frequencies, monitored by the MRCC. RT communications should be established in Spanish. English can be used, employing the standardized international vocabulary					
2. HF DSC facilities are located at Valparaíso Playa Ancha (CBV) (refer to page 103)					

MRCC Chile Ad36/05

Page 114, **CHINA, HONG KONG MARINE RESCUE RADIO (VRC) [1481]**, contacts table, delete and replace by:

22°24'·56N 114°07'·46E	MMSI 004773500	DSC VHF MF HF		Diagram page 107
 +852 22337999 & 25450181		 +852 25417714		
TELEX +802 82952 MRCC HX		E-MAIL hkmrcc@mardep.gov.hk		
Inmarsat C (IOR) 447735011=MRCC X 447735012=MRCC X				
NOTE: This station is under the control of the Director of Marine, Hong Kong SAR (MRCC Hong Kong located at 22°17'·60N 114°09'·25E)				

Hong Kong MRCC & IMO Ad36/05

Page 115, **HONG KONG RADIO (VRX) [1480]**, contacts table, row 2, Telephone, delete +852 28889708 and replace by:

+852 28882326

Hong Kong MRCC & IMO Ad36/05

VOLUME 2, NP 282, 2005/06

Published BA Wk 6/05

(Last Amendments: Edition No 19 dated 16 September 2005)

RADAR BEACONSPage 64, **MAURITIUS** section,**74260 Port Louis, Lt Bn No 4**

Delete entry and replace by:

Port Louis, Lt Bn Racon 20°08'·27S 57°28'·51E **74260**
T

NAVARIA VIII Warning 496/05 Ad36/05

Page 80, **CHINA** section, insert:**Qiongzhou Haixia, North Channel, Racon** 20°31'·00N 110°56'·56E **81160**
Lt Buoy
Q

Chinese Notice 29/625/05 Ad35/05

Page 82, insert:

Xinghua Wan, Jidan Dao Lt Bn Racon 25°18'·96N 119°29'·02E **81512**
M

Chinese Notice 30/645/05 Ad35/05

Dongxiang Dao Lt Racon 25°36'·16N 119°53'·99E **81523**
K

Chinese Notice 31/678/05 Ad36/05

Page 83, insert:

Longwan Tou Lt Racon 27°58'·32N 120°48'·16E **81628**
Y

Chinese Notice 32/706/05 Ad36/05

Page 86, insert:

Lüsi Gang Northwestwards Lt Bn Racon 32°04'·99N 121°35'·78E **81948**
M

Chinese Notice 32/699/05 Ad36/05

Xiaoyang Gang Lt Bn Racon 32°33'·81N 121°02'·25E **81949**
X

Chinese Notice 32/701/05 Ad36/05

Haizhou Wan, Racon 34°50'·10N 119°11'·51E **81983**
Qinshan Dao Westsouthwestwards, Lt Bn
B

Chinese Notice 30/644/05 Ad36/05

VOLUME 3, PART 2, NP 283(2), 2005/06

Published BA Wk 11/05

(Last Amendments: Edition No 18 dated 2 September 2005)

RADIO WEATHER SERVICES AND NAVIGATIONAL WARNINGSPage 163, **GUAM (USA), GUAM (NRV) (U.S. COAST GUARD), Weather Bulletins** section, row 2, delete broadcast times and replace by:**A-C: 0500 1500 1900 2315**

NOAA Ad36/05

Page 229, **UNITED STATES (Alaska), KODIAK (U.S. COAST GUARD),** delete Weather Bulletins and Navigational Warnings sections and replace by:

Weather Bulletins	
A-J: On receipt	Gale and storm warnings.
B: 0203 1645	Offshore forecast for Gulf of Alaska and Bering Sea and high seas forecast for Pacific.
Navigational Warnings	
A-J: On receipt E, F, H: 0130 1430 C, I: 0230 1800 G, J: 0530 1600	Navigational warnings.
B: 0203 1645	Tsunami watch / warning for Alaska and west coast of United States.

(former amendment Ad26/05)

NOAA Ad36/05

(30 September 2005)

(Last Amendments: Edition No 19 dated 16 September 2005)

Page 226, **Chapter 14: MARITIME SAFETY INFORMATION (MSI) UNDER THE GMDSS, BRAZIL,**
RIO DE JANEIRO NAVAL (PWZ-33), delete section and replace by:

RIO DE JANEIRO NAVAL (PWZ-33)		
A	4266 ¹	RADIO-TELEX
	6448	
	8580	
	12709	
	16974	
B	4266 ¹	RADIO DATA
	6448	
	8580	
	12709	
	16974	
(1) On request.		
Weather Bulletins		
A: 0600 1845 B: 0230	METAREA V weather bulletins and warnings in Portuguese and English	
Navigational Warnings		
A: 0400 2130 B: 1430	NAVAREA V warnings in Portuguese and English. Coastal warnings in Portuguese and English. Local warnings in Portuguese.	

Brazilian Navy Ad35/05

Page 303, **STATIONS WITH OPERATIONAL NAVTEX FACILITIES, NETHERLANDS,** section, heading, delete and replace by:

Netherlands Coastguard Radio [P] 52°06'N 4°15'E
TELEPHONE: +31 9000111 (H24 Emergency) Diagram X1
+31 223 542300 (H24 Operational)
FAX: +31 223 658358
TELEX: +44 71088 KUSTW NL
E-MAIL: ccc@kustwacht.nl
Inmarsat C: 424426512 CGHQ X (Main facility)
424477710 NLCG X (Back up facility)
MMSI: 002442000

Netherlands Coast Guard Ad35/05

Page 311, **Chapter 16: STATIONS WITH OPERATIONAL NAVTEX FACILITIES, UNITED KINGDOM,**
Cullercoats [G] [U], delete FAX: +44(0) 1326 316342 and replace by: FAX: +44(0) 1326 315610

HMCG Falmouth Ad36/05

Page 312, **Niton [E] [K] [T] [I], delete FAX: +44(0) 1326 316342 and replace by: FAX: +44(0) 1326 315610**

HMCG Falmouth Ad36/05

Page 312, **Portpatrick [O] [C], delete FAX: +44(0) 1326 316342 and replace by: FAX: +44(0) 1326 315610**

HMCG Falmouth Ad36/05

Page 341, **Chapter 17: DISTRESS, SEARCH AND RESCUE, DIEGO GARCIA (BRITISH INDIAN OCEAN TERRITORY)**, delete section and replace by:

National SAR Agency: Police / British Representative Address: BFPO 485, United Kingdom Tel: +246 370 2938 & 370 2939 Fax: +246 370 3943 E-mail: BritRep@dg.navy.mil			
Continuous listening watch is maintained on the following frequencies 282.8 MHz, 243.0 MHz, 121.5 MHz and VHF Ch 16 (Port Control)			
	Telephone +246	Fax +246	Others
AIRPORT CONTROL (NKW)	370 3322	370 3206	
BRITISH REPRESENTATIVE (BritRep)	370 3500	370 3943	
PORT CONTROL (Diego Garcia)	370 4313	370 3028	

Commander British Forces Ad36/05

Page 345, **FØROYAR (Denmark)**, delete section and replace by:

National SAR Agency: Ministry of Fisheries and Marine Affairs Address: Heykavegur 6, FR-110 Tórshavn, Føroyar Tel: +298 353030 Fax: +298 353035			
The Føroyar Search and Rescue Centre (MRCC Tórshavn), is responsible for co-ordinating Search and Rescue operations within Føroyar regional SRR. Tórshavn Radio (OXJ) maintains a continuous listening watch on VHF Ch16, 2182kHz and DSC for distress calls.			
	Telephone +298	Fax +298	Others
MRCC TÓRSHAVN	351300	351301	Inmarsat B (AOR-E) 323116220 (Tel) Inmarsat C (AOR-E) 423116210 E-Mail mrcc@mrcc.fo
TÓRSHAVN RADIO (OXJ)	312965	315546	E-Mail telegramm@mrcc.fo

MRCC Tórshavn Ad36/05

Page 347, **GERMANY**, contacts table, MRCC BREMEN, **Others** column, insert **Inmarsat C** (AOR-E) 492621021

MRCC Bremen & IMO Ad35/05

Page 351, **HONG KONG SAR (CHINA)**, contacts table, MRCC HONG KONG, **Telephone** column, delete 25450181

HONG KONG RADIO (VRX), **Telephone** column, delete 28889708 and replace by: 28882326

MRCC Hong Kong Ad35/05

Page 354, **IRAN**, delete **National SAR Agency** and replace by:

National SAR Agency: Director General, Safety and Marine Environment Protection, Ports and Shipping Organization Address: 751 Enghelab Avenue, Tehrān 1599661464, Iran Tel: +98 218 8809326 & 218 8809555 Fax: +98 218 8804100 & 218 8809324 Telex: +88 212271 BNDR IR & 214260 BNDR IR E-mail: tehran-mrcc@ir-pso.com			
---	--	--	--

ITU Bulletin 841-13 Ad35/05

MRCC TEHRAN, delete entry and replace by:

MRCC TEHRĀN	218 8809326	218 8809555	Telex +88 214260 BNDR IR E-mail tehran-mrcc@ir-pso.com
-------------	-------------	-------------	---

ITU Bulletin 841-13 Ad35/05

Page 367, **NETHERLANDS**, delete section and replace by:

National SAR Agency: SAR Commission, Transport Safety Directorate Address: P.O. Box 20904, 2500 EX The Hague, The Netherlands Tel: +31 70 351 1553 Fax: +31 70 351 1548 E-mail: jacques.van.Kooten@minvenw.nl			
The Netherlands Coastguard is responsible for co-ordinating Search and Rescue operations through JRCC Den Helder. The Netherlands Coastguard Radio (PBK) maintains a continuous listening watch on international VHF distress frequency Ch 16, DSC VHF Ch 70 and MF 2187.5 kHz. Call sign used during Search and Rescue operations is "DEN HELDER RESCUE".			
	Telephone +31	Fax +31	Others
JRCC DEN HELDER	9000111 (H24 Emergency) 223 542300 (H24 Operational)	223 658358	Telex +44 71088 KUSTW NL E-mail ccc@kustwacht.nl Inmarsat C (AOR-E) 424426512 CGHQ X (Main facility) SARNET Only (AOR-E) 424477710 NLCG X (Back Up facility) SARNET Only

Netherlands Coast Guard Ad35/05

Page 373, **RUSSIA, Baltic Coast**, contacts table, MRCC SANKT PETERBURG, **Telephone** column, delete 812 1188995 and replace by: 812 7188995

MRCC Sankt Peterburg Ad35/05

Black Sea Coast, contacts table, MRCC NOVOROSSIIYSK delete entry and replace by:

MRCC NOVOROSSIIYSK	8617 676417	8617 676420	Inmarsat B (IOR) 327325510 (Tel) (IOR) 327325515 (Fax) (IOR) 327325517 (Data) (IOR) 327325518 (Telex) E-mail gmssb3@mapn.morflot.ru
--------------------	-------------	-------------	---

MRCC Novorossiysk Ad35/05

Page 377, **SOUTH AFRICA**, contacts table, MRCC CAPETOWN, **Others** column, insert: **Telex** +095 521037

MRCC South Africa Ad35/05

Page 382, **TRINIDAD AND TOBAGO**, delete section and replace by:

National SAR Agency: Trinidad and Tobago Coast Guard Address: Staubles Bay, Chaguaramas, c/o Carenage Post Office, Trinidad Tel: +1 868 6342717 & 6342727 Fax: +1 868 6344944 E-mail: 1ttcg1@tstt.net.tt			
The Trinidad and Tobago Coast Guard are responsible for co-ordinating Search and Rescue Operations. Vessels in distress should call or radio either the Coast Guard or North Post Radio (Trinidad) (9YL) for assistance. North Post Radio maintains a continuous listening watch on 2182 kHz and VHF Channel 16 for distress calls.			
	Telephone +1 868	Fax +1 868	Others
ARCC PIARCO (ATC)	6694852	6694259	E-mail ttaa@tstt.net.tt
MRCC PORT OF SPAIN (Trinidad and Tobago Coast Guard) SAR Direct line	6344939 6252717 6342727 6341476	6344944	
NORTH POST (9YL)	6379023	6379104	E-mail npradio-9yl@tstt.net.tt

Trinidad and Tobago Coast Guard Ad36/05

Page 383, **TURKEY**, contacts table, delete and replace by:

	Telephone +90	Fax +90	Others
MSRCC ANKARA (Main SAR Co-ordination Centre) Undersecretariat for Maritime Affairs	312 2319105 312 2324783	312 2320823	Telex +607 44144 DZMSTR E-mail trmrcc@denizcilik.gov.tr Inmarsat C: (IOR) 427122324 Inmarsat mini-M: (IOR) 764142267
MRCC ANKARA (Turkish Coast Guard command)	312 4175050 312 4253337	312 4172845	
RCC İSTANBUL (Marmara Sea and Turkish Straits) (Turkish Coast Guard)	212 2429710 212 2429712	212 2423093	Telex +607 26905 SGKTR
RCC SAMSUN (Black Sea Region) (Turkish Coast Guard)	362 4452908	362 4452908	Telex +607 82016 SGKSTR
RCC İZMİR (Aegean Sea Region) (Turkish Coast Guard)	232 3656825	232 3659575	Telex +607 53299 SGKETR
RCC MERSİN (Mediterranean Sea Region) (Turkish Coast Guard)	324 2388790	324 2388691	
RSC ÇANAKKALE (Turkish Coast Guard)	286 2127500	286 2127202	
RSC TRABZON (Turkish Coast Guard)	462 3254782 462 3280793	462 3250118 462 3280793	Telex +607 83015 SGTKTR
RSC AMASRA (Turkish Coast Guard)	378 3151004 378 3151035	378 3153925	
RSC MARMARİS (Turkish Coast Guard)	252 4128538 252 4127722	252 4127777	
RSC ANTALYA (Turkish Coast Guard)	242 2591315 242 2591376	242 2590953	
RSC İSKENDERUN (Turkish Coast Guard)	326 6142311 326 6133448	326 6132054	Telex +607 67007 SGKHTR

MSRCC Ankara Ad36/05

Page 385, **UNITED KINGDOM, Scotland and Northern Ireland Region**, MRCC ABERDEEN, delete section and replace by:

MRCC ABERDEEN	(0)1224 592334	(0)1224 212862	E-mail aberdeencoastguard@mcga.gov.uk
---------------	----------------	----------------	--

HMCG Falmouth Ad36/05

VOLUME 6, PART 4, NP 286(4), 2004/05

Published BA Wk 28/04

(Last Amendments: Edition No 18 dated 2 September 2005)

A New Edition of this volume is in the press and will be published shortly

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS 2005

Nil Reports