



Australian Notices to Mariners are the authority for correcting Australian Charts

AUSTRALIAN NOTICES TO MARINERS

© Commonwealth of Australia 2001 - Copyright restrictions apply to Notices to Mariners



Notices 129-162

Published fortnightly by the Australian Hydrographic Service

B. J. KAFER,
Hydrographer of Australia

- SECTIONS. I. **Australian Notices to Mariners, including blocks and notes.**
III. **Navigational Warnings.**
IV. **Hydrographic Reports.**

New Zealand Notices to Mariners

The substance of these notices should be inserted on the charts affected.

Notices to Mariners information relating to British Admiralty Publications unavailable on this web site at this stage but still available in printed form:-

- Section II. Corrections to Admiralty List of Lights, Vol K.**
Section V. Amendments to Admiralty List of Radio Signals.
Section VI. Corrections to Sailing Directions.

Bearings are referred to the true compass and are reckoned clockwise from 000° (North) to 359°: those relating to lights are given as seen by an observer from seaward. The range quoted for a light is its nominal range. Fog signals are sounded only during thick or foggy weather, unless otherwise stated. Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices. A star () adjacent to the number of a notice indicates that the notice is based on original information.*

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 South Coast Mail Centre, NSW 2521 (Fax 02-4221 8599), e-mail hni.hydro@navy.gov.au or, alternatively by filling in and submitting the **Hydrographic Notes forms, immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).**

Copies of these notices can be obtained from the AUSTRALIAN HYDROGRAPHIC OFFICE, 8 Station Street, Wollongong, and Agents for the sale of charts and hydrographic publications.

The Commonwealth of Australia is the owner of, or is otherwise responsible for, the copyright in this work. It is protected under the Copyright Act 1968 and international convention. Except as expressly authorised below, the work may not be copied, reproduced, adapted, changed or commercially exploited, in whole or in part, or the format in which it is stored altered, without the prior written permission of the Australian Hydrographic Office. The Notices may be copied for the purpose of inserting their substance on official charts and other publications. However, any copies of the notices may not be sold for profit.

© Commonwealth of Australia 2001

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 5

2 March 2001

Notices	Aus Chart
129	Admiralty publication
130	Amendment to Australian National Tide Tables
131	Aus 220
132	Aus 235
133	Aus 236
134	Aus 246
135	Aus 252
136	Aus 252, 253, 254, 824
137	Aus 372, 828
138	Aus 258, 829
139	Aus 376, 839
140	Aus 376, 837, 839
141	Aus 376, 377, 840
142	Aus 376, 377, 378, 840, 4620
143	Aus 4
144	Aus 309
145	Aus 55
146	Aus 55, 740, 741
147	Aus 605
148	Aus 343
149	Aus 801
150(P)	Aus 235, 236, 814
151(T)	Aus 235, 236, 237, 238, 814
152(T)	Aus 236
153(T)	Aus 236
154(T)	Aus 238
155(T)	Aus 238
156(T)	Aus 238
157(T)	Aus 236
158(T)	Aus 259, 828
159(T)	Aus 303, 410
160(T)	Aus 134
161(T)	Aus 781
162(T)	Aus 143, 157

129 AUSTRALIA - Publications.
BA Edition 5/2001 (01/630). (AH 99/226)

New edition of British Admiralty publication

NP No	Title	Date	RRP(UK)	Remarks
NP 83	Admiralty List of Lights and Fog Signals, Volume K 2001/02, Indian and Pacific Ocean, South of the Equator.	4/01/01	£20.00	Volume K 2000 is thereby cancelled.

130 AUSTRALIA - Publication - Amendment to Australian National Tide Tables.
AHS (01/631). (AH 99/424)

Page xi, amend to read *Moon phases are shown in Universal Time Coordinated (UTC),.....*

Page xxxii, amend Port Moresby to read *4.086 below PSM 16566,.....*

Page 276, insert Heard Island time zone to *-0500*.

Page 291, amend 62960 SKUA to *4.8, 4.1, 2.9, 2.4, 1.9, 0.7*.

Page 292, amend 54150 SUAI to *-0527 2.5, 2.3, 1.7, 1.4, 1.1, 0.4*.

Page 293, amend 63430 ENTRANCE ISLAND to *+0112 4.5, 3.9, 3.1, 2.5, 2.0, 1.1*.

Pages 298 & 299, amend 54150 SUAI to ZO (LAT) *1.37, M2 0.6212 3.60, S2 0.3206 60.89, K1 0.2435 301.13, O1 0.1392 281.0, M4 0.0068 182.70*.

Page 298, amend 54170 SAENAMO to *54170 SAENAMO (LORE) 8° 41' S 126° 59' E -0800*.

Page 298, amend Heard Island time zone to *-0500*.

Pages 368 & 369, amend 62960 SKUA to ZO (LAT) *2.38, M2 1.1080 301.51, S2 0.6246 358.60, K1 0.2924 298.21, O1 0.1865 278.07, MM 0.0150 173.50, MSF 0.0266 148.04, Q1 0.0468 277.34, P1 0.0849 299.02, N2 0.2187 284.80, K2 0.1800 357.69, L2 0.1070 316.94, MU2 0.0242 275.69, M4 0.0114 77.31, MS4 0.0087 167.07, 2MS6 0.0033 319.71*.

Pages 378 & 379, amend 63430 ENTRANCE ISLAND to ZO (LAT) *2.53, M2 0.9821 194.15, S2 0.4344 280.50, K1 0.2435 64.79, O1 0.3237 17.36, MM 0.0365 251.07, MSF 0.0120 251.85, Q1 0.0949 346.59, N2 0.2377 159.98, L2 0.0586 221.12, MU2 0.0632 150.60, M4 0.0502 238.30, MS4 0.0495 320.75, 2MS6 0.0215 293.70*.

Note: Mariners are advised that data provided for East Timor is time zone *-0800*, whilst local time has been changed to *-0900*

131* AUSTRALIA - NEW SOUTH WALES - Yamba - Buoyage.

List of Lights Vol K/2000 -- 2819.90,2820.00
HM Yamba (01/552). (AH 99/19-02)

Aus 220 (plan, Clarence River Entrance) [705/2000]

Insert	starboard lateral conical light buoy, <i>Fl. G. 3s</i> , without topmark	29° 22'.951 S	153° 17'.910 E
Amend	light to <i>Q. Bu</i>	29° 25'.61 S	153° 20'.99 E
	light to <i>Fl. R. 3s & Oc. Bu 3s</i>	29° 25'.55 S	153° 20'.56 E
Delete	port lateral light buoy	29° 25'.49 S	153° 21'.04 E
	starboard lateral buoy	29° 22'.90 S	153° 17'.75 E

132* AUSTRALIA - QUEENSLAND - Moreton Bay - Northwest Channel - Wreck.

Queensland Transport Notice 38/2001 (01/553). (AH 98/292)

Aus 235 [670/2000]

Insert	depth, <i>12m</i> , enclosed by danger circle, with legend <i>Wk</i>	26° 54'.94 S	153° 11'.25 E
Delete	depth <i>12m</i>	26° 54'.95 S	153° 11'.00 E

133* AUSTRALIA - QUEENSLAND - Moreton Bay - Coonungai Bank - Light beacon.
Queensland Transport Notice 35/2001 (01/553). (AH 00/107)

Aus 236 [97/2001]

Insert	west cardinal light beacon, Q(9) 15s, with topmark	27° 19'.56 S	153° 21'.44 E
--------	--	--------------	---------------

134* AUSTRALIA - QUEENSLAND - Gladstone - Light buoy moved.
Queensland Notice 37/2001 (01/553). (AH 99/14)

Aus 246 [71/2001]

Move	light buoy	23° 53'.07 S	151° 31'.06 E
	to	23° 53'.09 S	151° 31'.09 E

135* AUSTRALIA - QUEENSLAND - Repulse Bay - Light buoys moved.
Queensland Transport Notice 32/2001 (01/447). (AH 99/14)

Aus 252 [41/2001]

Insert	starboard lateral cylindrical light buoy, Fl. G. 3s No1, with topmark	20° 29'.70 S	148° 44'.06 E
	starboard lateral cylindrical light buoy, Fl. G. 3s No3, with topmark	20° 29'.99 S	148° 43'.53 E
Delete	light buoy	20° 30'.6 S	148° 43'.9 E
		20° 29'.9 S	148° 43'.4 E

136* AUSTRALIA - QUEENSLAND - Plum Pudding Island - Depth; rock.
Queensland Transport (01/597). (AH 99/176-02)

Aus 252 [135/2001]

Delete	rock which covers and uncovers, with enclosing danger circle	20° 20'.2 S	148° 56'.3 E
--------	--	-------------	--------------

Aus 253 [42/2001]

Delete	rock which covers and uncovers	20° 20'.18 S	148° 56'.22 E
--------	--------------------------------	--------------	---------------

Aus 254 (plan, Fitzalan Passage) [576/2000]

Insert	depth, 2 ₂ m	20° 20'.159 S	148° 56'.213 E
Delete	rock which covers and uncovers, height 1 ₁ m	20° 20'.18 S	148° 56'.22 E

Aus 254 (plan, Hamilton and Dent Islands)

Insert	depth, 2 ₂ m	20° 20'.159 S	148° 56'.213 E
	depth, 2 ₃ m	20° 20'.200 S	148° 56'.265 E
Delete	rock which covers and uncovers, height 1 ₁ m	20° 20'.18 S	148° 56'.22 E
	depth 2 ₇ m	20° 20'.16 S	148° 56'.25 E

Aus 824 [41/2001]

Insert	islet	20° 20'.15 S	148° 56'.35 E
Delete	rock which covers and uncovers	20° 20'.2 S	148° 56'.1 E
	depth 5 ₅ fm	20° 20'.1 S	148° 56'.1 E

137* AUSTRALIA - QUEENSLAND - Brittomar Reef - Shoal.
PV New Investigator (01/486). (AH 99/175-02)

Aus 372 [98/2001]

Insert	depth, 1 ₄ fm, enclosed by contour, with legend <i>Rep (2001)</i>	18° 10'.45 S	146° 47'.50 E
--------	--	--------------	---------------

Aus 828 [98/2001]

Insert	depth, 3 ₂ m, enclosed by contour, with legend <i>Rep (2001)</i>	18° 10'.47 S	146° 47'.29 E
--------	---	--------------	---------------

138* AUSTRALIA - QUEENSLAND - Clump Point - Light beacon.
Queensland Transport Notice 36/2001 (01/553). (AH 00/137)

Aus 258 [706/2000]

Substitute	light, <i>Fl.</i> 2.5s, for pile	17° 51'.3 S	146° 06'.9 E
------------	----------------------------------	-------------	--------------

Aus 829 [706/2000]

Insert	light, <i>Fl.</i> 2.5s	17° 51'.28 S	146° 06'.92 E
--------	------------------------	--------------	---------------

139* AUSTRALIA - QUEENSLAND - Ackers Shoal - Light beacon.

Former Notice - 752(P)/2000 is cancelled

List of Lights Vol K/2000 -- 3278.70

AMSA ATH 2001/06 (01/608), Auscoast 035/01 (01/924). (AH 00/137)

Aus 376 [680/2000]

Substitute	south cardinal light beacon, <i>Q(6) + LFl.</i> 15s, without topmark, for beacon	10° 18'.7 S	142° 48'.6 E
------------	--	-------------	--------------

Aus 839 [583/2000]

Insert	south cardinal light beacon, <i>Q(6) + LFl.</i> 15s 7m 6M, without topmark	10° 18'.58 S	142° 48'.66 E
--------	--	--------------	---------------

Delete	south cardinal beacon	10° 18'.4 S	142° 48'.7 E
--------	-----------------------	-------------	--------------

140* AUSTRALIA - QUEENSLAND - Caldbeck Reef - Light beacon.

Former Notice - 753(P)/2000 is cancelled

List of Lights Vol K/2000 -- 3282.00

AMSA ATH 2001/07 (01/637), Auscoast 022/01 (01/447). (AH 00/137)

Aus 376 [139/2001]

Substitute	east cardinal light beacon, <i>Q(3)</i> 10s, without topmark, for beacon	10° 06'.4 S	143° 09'.9 E
------------	--	-------------	--------------

Aus 837 [176/2000]

Substitute	east cardinal light beacon, <i>Q(3)</i> 10s 7m 9M, without topmark, for beacon	10° 06'.3 S	143° 10'.0 E
------------	--	-------------	--------------

Aus 839 [139/2001]

Substitute	east cardinal light beacon, <i>Q(3)</i> 10s 7m 9M, without topmark, for beacon	10° 06'.3 S	143° 10'.0 E
------------	--	-------------	--------------

141* AUSTRALIA - QUEENSLAND - Dalrymple Islet - Racon established.

Former Notice - 694(P)/2000 is cancelled

Admiralty List of Radio Signals Vol 2, 2001 – 8828.5

AMSA ATH 2001/08 (01/636), Auscoast 024/01 (01/491). (AH 99/11)

Aus 376 [140/2001]

Insert	Racon (M) at light	9° 37'.0 S	143° 17'.7 E
--------	--------------------	------------	--------------

Aus 377 [117/2001]

Insert	Racon (M) at light	9° 37'.0 S	143° 17'.7 E
--------	--------------------	------------	--------------

Aus 840 [680/2000]

Insert	Racon (M) at light	9° 36'.9 S	143° 17'.9 E
--------	--------------------	------------	--------------

Aus 4620 [117/2001]

Insert	Racon (M) at light	9° 36'.9 S	143° 17'.9 E
--------	--------------------	------------	--------------

142* AUSTRALIA - QUEENSLAND - Bramble Cay - Light altered.

Former Notice - 754(P)/2000 is cancelled

List of Lights Vol K/2000 -- 3292.00

AMSA ATH 2001/09 (01/638), Auscoast 026/01 (01/494). (AH 00/137)

Aus 376 [141/2001]

Amend	light to Fl(4) 15s 16M	9° 08'.6 S	143° 52'.5 E
-------	------------------------	------------	--------------

Aus 377 [141/2001]

Amend	light to Fl(4) 15s 16M	9° 08'.6 S	143° 52'.5 E
-------	------------------------	------------	--------------

Aus 378 [680/2000]

Amend	light to Fl(4) 15s 16M	9° 08'.6 S	143° 52'.5 E
-------	------------------------	------------	--------------

Aus 840 [141/2001]

Amend	light to Fl(4) 15s 19m 16M	9° 08'.5 S	143° 52'.6 E
-------	----------------------------	------------	--------------

Aus 4620 [141/2001]

Amend	light to Fl(4) 16M	9° 08'.5 S	143° 52'.6 E
-------	--------------------	------------	--------------

143* AUSTRALIA - QUEENSLAND - Mission River - Mooring buoy withdrawn.

Queensland Transport Notice 26/2001 (01/376). (AH 99/13)

Aus 4 [43/2001]

Delete	mooring buoy	12° 36'.50 S	141° 51'.92 E
--------	--------------	--------------	---------------

144* AUSTRALIA - NORTHERN TERRITORY - Beagle Gulf - Depths.

AHS (01/595). (AH 99/388)

Aus 309 [377/1999]

Insert	accompanying block	11° 55'.0 S	130° 30'.0 E
--------	--------------------	-------------	--------------

145* WESTERN AUSTRALIA - Port Walcott - Spoil ground.

North Limited (01/500). (AH 00/332)

Aus 55 [663/1998]

Insert	pecked line, with legend Spoil Ground, between	20° 33'.30 S	117° 14'.30 E
		20° 33'.40 S	117° 15'.30 E
		20° 32'.45 S	117° 16'.00 E
		20° 32'.30 S	117° 15'.00 E

146* WESTERN AUSTRALIA - Delambre Reef - Wrecks; fishing prohibited.
P Horton (01/483), Transport WA (01/231). (AH 98/232, AH 99/215)

Aus 55 [145/2001]

Insert	depth, 13m, enclosed by danger circle, with legend Wks fishing prohibited area, circle of radius 500metres, centred on (a)	(a) 20° 25'.89 S	117° 12'.72 E
--------	--	------------------	---------------

Delete	depth 14m and enclosing danger circle, with legend Wk	20° 25'.8 S	117° 12'.7 E
	depth 13m and enclosing danger circle, with legend Wk	20° 25'.9 S	117° 12'.9 E

Aus 740 [267/2000]

Delete	depth 14m and enclosing danger circle	20° 25'.9 S	117° 12'.9 E
--------	---------------------------------------	-------------	--------------

Aus 741 [683/2000]

Delete	depth 14m and enclosing danger circle	20° 25'.9 S	117° 12'.9 E
--------	---------------------------------------	-------------	--------------

147* SOUTHERN OCEAN - Heard Island - Depth.
AAD (00/7038 & 01/489). (AH 99/524)

Aus 605 (plan, Heard and McDonald Islands) [NE 03/03/2000]

Insert	depth, 17m, enclosed by contour	53° 02'.7 S	73° 58'.3 E
--------	---------------------------------	-------------	-------------

148* SOUTH AUSTRALIA - Eyre Peninsula - Depths southwestward.
AHS (01/632). (AH 99/442)

Aus 343 [715/2000]

On certain copies only

Substitute	depth, 138m, for 38m	35° 20'.7 S	134° 45'.2 E
	depth, 135m, for 35m	35° 23'.0 S	134° 50'.9 E

149* AUSTRALIA - VICTORIA - Inverloch - Light.

List of Lights Vol K/2000 -- 2480.00

Victorian Notice 9/2001 (01/596). (AH 99/21)

Aus 801 [612/1999]

Insert	light Fl. R. 5s 6m 2M	38° 38'.16 S	145° 44'.06 E
--------	-----------------------	--------------	---------------

Delete	light	38° 38'.3 S	145° 44'.1 E
--------	-------	-------------	--------------

150(P)/2001 AUSTRALIA - QUEENSLAND - Flinders Reef - Mooring buoy.

Date - On or about 16 March 2001

Queensland Transport Notice 45/2001 (01/598). (AH 99/14)

A mooring buoy is to be established in position 26° 58'.6 S 153° 29'.0 E.

Chart which will be affected – Aus 235 – Aus 236 – Aus 814.

151(T)/2001 AUSTRALIA - QUEENSLAND - Moreton Bay and Brisbane River - Depth information and keel clearances.

Former Notice - 748(T)/2000 is cancelled

Date - Until further notice

Queensland Transport Notice 39/2001 (01/553). (AH 99/323)

Available depths as at 31 January 2001:

	<i>Metres</i>
Moreton Bay:	
North East Channel	5.0
* North West Channel	13.5
Spitfire Channel	13.5
Main Channel	9.7
East Channel	14.0
Brisbane River:	
Entrance Beacons to Fisherman Islands Swing Basin	13.0
Pelican Bank Cutting to Hamilton Reach	9.1
Keel clearances are required for approach channels as follows:	
North West Channel	1.6
For vessels with a beam of 35 metres or more	1.8
Spitfire Channel	1.2
East Channel	1.2
Entrance Beacons to Swing Basin	1.0
Swing Basin Reach to Hamilton Reach	0.6 to 0.9
Alongside all berths	0.3

*Indicates new or revised entry.

Chart temporarily affected – Aus 235 – Aus 236 – Aus 237 – Aus 238 – Aus 814.

152(T)/2001 AUSTRALIA - QUEENSLAND - Moreton Island - Reeder's Point - Light beacon destroyed.

Date - Until further notice

Queensland Transport Notice 53/2001 (01/721). (AH 00/107)

The port lateral light beacon (27° 21'.82 S 153° 25'.32 E) has been destroyed.

Chart temporarily affected – Aus 236.

153(T)/2001 AUSTRALIA - QUEENSLAND - Moreton Bay - Manly - Dredging; moorings.

Date - Until 4 May 2001

Queensland Transport Notice 40/2001 (01/553). (AH 99/323)

The clam dredge *Ken Harvey* is conducting dredging in Manly Boat Harbour (27° 27'.4 S 153° 11'.4 E).

The dredge will be moored by six anchors; each marked by a special buoy.

Spoil will be moved by barges *Sampson* and *Hercules*, attended by MT *Sealoin*. The dredge and tug will monitor VHF Ch 13.

Two moorings, marked by special light buoys Q, have been established in positions 27° 26'.736 S 153° 12'.054 E and 27° 26'.695 S 153° 12'.107 E.

Mariners are advised to navigate with caution in vicinity of the dredge.

Chart temporarily affected – Aus 236.

154(T)/2001 AUSTRALIA - QUEENSLAND - Brisbane River - Upper Lytton Reach - Light buoy.

Date - Until further notice

Queensland Transport Notice 41/2001 (01/598). (AH 99/14)

A port lateral light buoy, *Fl. R. 2s*, has been established in position 27° 25'.509 S 153° 08'.03 E. The buoy marks the outer extremity of a set of temporary piles.

Chart temporarily affected – Aus 238.

155(T)/2001 AUSTRALIA - QUEENSLAND - Brisbane River - Aquarium Passage - Wreck.

Date - Until further notice

Queensland Transport Notice 42/2001 (01/598). (AH 98/292)

A stranded wreck exists in position 27° 25'.85 S 153° 07'.73 E.

Chart temporarily affected – Aus 238.

156(T)/2001 AUSTRALIA - QUEENSLAND - Brisbane River - Hamilton Reach - Light buoys.

Date - Until further notice

Queensland Transport Notice 50/2001 (01/639). (AH 99/14)

Two special light buoys, *Q. Y*, have been established to mark mooring lines extending from a vessel at Wrights Slipway (27° 26'.55 S 153° 03'.65 E).

Chart temporarily affected – Aus 238.

157(T)/2001 AUSTRALIA - QUEENSLAND - Moreton Island - Redcliffe - Light beacon destroyed; light buoy.

Date - Until further notice

Queensland Transport Notice 49/2001 (01/639). (AH 00/107)

The port lateral light beacon (27° 13'.62 S 153° 07'.07 E) has been destroyed; a port lateral light buoy, *Fl. R. 2.5s*, has been established in situ.

Chart temporarily affected – Aus 236.

158(T)/2001 AUSTRALIA - QUEENSLAND - Lucinda - Obstruction.

Date - Until further notice

Queensland Transport Notice 56/2001 (01/721). (AH 99/175-02)

An obstruction, least depth *12 metres*, exists in position 18° 31'.154 S 146° 23'.205 E.

Chart temporarily affected – Aus 259 – Aus 828.

159(T)/2001 AUSTRALIA - QUEENSLAND - Spring Creek - Wreck northwestward.

Date - Until further notice

Queensland Transport Notice 57/2001 (01/813), Auscoast 044/01 (01/940). Wreck is MV *Gununggal*. (AH 98/288)

A dangerous wreck, marked by a light buoy *Fl. 4s*, exists in position 16° 44'.2 S 141° 01'.9 E.

Chart temporarily affected – Aus 303 – Aus 410.

160(T)/2001 SOUTH AUSTRALIA - Port Lincoln - Boston Bay - Mooring buoy damaged.

Date - Until further notice

SA Transport Notice 8/2001 (01/720). (AH 99/36)

The mooring buoy (34° 42'.96 S 136° 53'.47 E) has been damaged and the light is unreliable.

Chart temporarily affected – Aus 134.

161(T)/2001 SOUTH AUSTRALIA - Barcoo - Obstruction.

Date - Until 11 April 2001

SA Transport Notice 3/2001 (01/713). (AH 00/58)

A coffer dam, marked by lights Q. Y, exists between:

34° 57'.71 S 138° 30'.30 E

34° 57'.74 S 138° 30'.20 E

34° 57'.76 S 138° 30'.19 E

34° 57'.77 S 138° 30'.20 E

34° 57'.77 S 138° 30'.21 E

34° 57'.73 S 138° 30'.30 E

Chart temporarily affected – Aus 781.

162(T)/2001 AUSTRALIA - VICTORIA - Port Phillip - Werribee - Prohibited area; beacons.

Date - Until 31 January 2002

Victorian Notice 6/2001 (01/821). (AH 99/225)

Special beacons, marking scientific instruments, exist in positions:

38° 02'.65 S 144° 32'.58 E

38° 00'.86 S 144° 35'.00 E

38° 00'.65 S 144° 35'.65 E

38° 00'.50 S 144° 37'.94 E.

A prohibited area, radius 400metres , exist around the beacons.

Chart temporarily affected – Aus 143 – Aus 157.

III

NAVIGATION WARNINGS

The following radio messages have been received during the period to 16 February 2001. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNINGS

- 035 NE Coast. Ackers Shoal light, Q(6) + LFI. 15s 7m 10M established in position 10° 18'.5 S 142° 48'.6 E.
- 036 Cancelled.
- 037 Cancelled.
- 038 NE Coast. Maxwell Reef light, FI. WR. 10s 9m 10/7M, established in position 14° 47'.1S 145° 18'.9 E, red sector 140° - 152° (12°).
- 039 Cancelled.
- 040 NW Coast Drill Rig Sedco 703 in position 12° 19'.3 S 124° 18'.1 E. 2.5 NM clearance requested.
- 041 Cancelled.
- 042 Cancelled.
- 043 E Coast. Gneering Shoal light buoy re-established in position 26° 39'.2 S 153° 12'.8 E.
- 044 N Coast. 17 metre barge sunk in position 16° 44'.2 S 141° 01'.9 E, marked by light float, FI. 4s.
- 045 Cancelled.
- 046 N Coast. Shoal depths reported vicinity Gannet Passage, 8.6 metres (10° 34'.8 S 141° 54'.3 E) and 10.4 metres (10° 36'.5 S 141° 51'.3 E).
- 047 NW Coast. Seismic Survey vessel Geco Beta towing seven 3.0 M cables in area 17° 24' S to 18° 04' S and 117° 54' E to 118° 33' E.
- 048 Cancelled.
- 049 NW Coast. Drill rig Ron Tappmeyer in position 20° 42'.0 S 115° 33'.8 E. 2.5M clearance requested.
- 050 NE Coast. Albany Rock light K3254 (10° 43'.1 S 142° 37'.8 E) unreliable.
- 051 S Coast. Seismic Survey vessel Geco Angler towing 3.5 M cable in area 33° 00' S to 35° 48' E and 129° 00' E to 133° 00' E.

NAVAREA X WARNINGS

- 008 Cancelled.
- 009 Cancelled.

Navigational warnings in force as at 151500UTC FEB 01.

Auscoast

2000 317 321.

2001 005 006 010 013 014 015 018 020 022 024 026 033 034 035 038 040 043 044 046 047 049 050 051

Navarea X

2000 020.

2001 001 002 003 004 005 006 007

Summary of mobile drilling rigs as at 151500UTC FEB 01.

Name	Position
Ocean General	11° 43'.9 S 126° 06'.4 E
Sedco 703	12° 19'.3 S 124° 18'.1 E
Ron Tappmeyer	20° 42'.0 S 115° 33'.8 E
Ensco 56	20° 38'.2 S 115° 43'.6 E
Ocean Legend	19° 42'.3' S 116° 42'.4 E
Marine 500	19° 56'.6 S 114° 53'.2 E
Sideson 1	34° 07'.6 S 137° 12'.1 E

NAVAREA XIV WARNINGS

- 028 Cancelled.
- 029 Cancelled.
- 030 Cancelled.
- 031 Cancelled.
- 032 Niue Island. Alofi Bay leading lights K4656 and K4656.1 and Alofi North light K4660 (19° 03' S 169° 55' W) extinguished.
- 033 Cancelled.
- 034 Cancelled.
- 035 Cancelled.
- 036 Cancelled.

037 French Polynesia. 28 foot speedboat, NAIH02, orange hull, white deck, unreported since departure Rurutu Island
140000Z FEB.
038 Cancelled.

Navarea XIV warnings in force as at 150001UTC FEB 01.

024 032 037

IV

HYDROGRAPHIC REPORTS

<i>Locality</i>	<i>Report</i>	<i>Ship/Authority</i>	<i>Observer</i>
Pacific Ocean- Niue	Lights	MT <i>Pacific Mariner</i>	B Keane
Charts	Nomenclature		ER Whitmore