**TEMPORARY AND PRELIMINARY NOTICES**
**In force on 13 November 2026**

**NEW SOUTH WALES**

**709(T)/2016 AUSTRALIA - NEW SOUTH WALES - Cape Byron - Obstructions eastwards**
HMAS *Gascoyne*

Obstructions exist in positions 28° 36'.20 S 153° 44'.30 E and 28° 36'.95 S 153° 44'.02 E.

**Chart temporarily affected - Aus 813**

**604(T)/2020 AUSTRALIA - NEW SOUTH WALES - Jervis Bay - Hyams Beach - Light buoy**
Australian Maritime Warfare Centre

A special light buoy, *Fl.Y.5s,* exists in position 35° 06'.23 S 150° 42'.85 E.

**Chart temporarily affected - Aus 807 - Aus 808**

**997(T)/2020 AUSTRALIA - NEW SOUTH WALES - Merimbula Bay to Broulee Island - Scientific instruments**
Transport for NSW

Special light buoys, *Fl(5)Y.20s*, exist in the following positions:
35° 50'.9 S 150° 11'.3 E
35° 52'.8 S 150° 09'.7 E
36° 54'.5 S 149° 55'.0 E.

**Chart temporarily affected - Aus 806 - Aus 807**

**105(T)/2021 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Berrys Bay - Jetties ruined**
Transport for NSW , NSW Roads and Maritime Services

Jetties and piers are ruined, and partially submerged obstructions may exist in an area bounded by the coast and the following positions:
33° 50'.70 S 151° 11'.69 E
33° 50'.70 S 151° 11'.76 E
33° 50'.67 S 151° 11'.85 E
33° 50'.63 S 151° 11'.84 E.

A west cardinal light beacon, *Q(9)15s*, exists in position 33° 50'.59 S 151° 11'.50 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 200**

**880(T)/2021 AUSTRALIA - NEW SOUTH WALES - Cape Byron - Light buoy off station northwards**
Byron Bay Deep Sea Fishing Club

The special light buoy, *Fl.Y.5s* (28° 35'.40 S 153° 38'.11 E), is off station.

**Chart temporarily affected - Aus 813**

**727(T)/2022 AUSTRALIA - NEW SOUTH WALES - Tathra to Seal Rocks - Obstructions**
Transport for NSW Notice SY2028

Shipping containers and debris may exists along the coast and in offshore waters between Tathra (36° 43'.55 S 149° 59'.46 E) and Seal Rocks (32° 27'.86 S 152° 33'.22 E).

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 489 - Aus 806 - Aus 807 - Aus 808 - Aus 809 - Aus 810 - Aus 4601 (INT 601) - Aus 4602 (INT 602)**

**133(T)/2023 AUSTRALIA - NEW SOUTH WALES - Crabbes Creek Beach - Wreck eastwards**

Australian Maritime Safety Authority

A wreck exists in position 28° 29'.43 S 153° 38'.52 E.

**Chart temporarily affected - Aus 813**

**808(T)/2023 AUSTRALIA - NEW SOUTH WALES - Clarence River - Scientific instrument**
NSW Department of Planning and Environment

A special light buoy, *Fl.Y.5s*, exists in position 29° 25'.31 S 153° 21'.32 E.

**Chart temporarily affected - Aus 222**

**105(T)/2024 AUSTRALIA - NEW SOUTH WALES - Green Bluff - Scientific instruments eastwards**
Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 30° 12'.27 S 153° 16'.54 E | 43 |
| 30° 12'.27 S 153° 17'.05 E | 50 |
| 30° 12'.31 S 153° 15'.46 E | 23 |
| 30° 12'.44 S 153° 14'.95 E | 30 |
| 30° 12'.49 S 153° 14'.43 E | 31 |
| 30° 12'.55 S 153° 13'.92 E | 35 |
| 30° 12'.58 S 153° 13'.40 E | 34 |
| 30° 12'.64 S 153° 12'.90 E | 25 |
| 30° 12'.67 S 153° 10'.48 E | 16 |
| 30° 12'.70 S 153° 12'.41 E | 26 |
| 30° 12'.73 S 153° 11'.91 E | 24 |
| 30° 12'.77 S 153° 11'.40 E | 23 |
| 30° 12'.81 S 153° 10'.87 E | 20. |

**Chart temporarily affected - Aus 812**

**106(T)/2024 AUSTRALIA - NEW SOUTH WALES - Montague Island - Scientific instruments**
Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 36° 15'.28 S 150° 14'.20 E | 49 |
| 36° 15'.40 S 150° 13'.08 E | 7 |
| 36° 15'.47 S 150° 12'.58 E | 33 |
| 36° 15'.52 S 150° 12'.04 E | 38 |
| 36° 15'.59 S 150° 11'.50 E | 31 |
| 36° 15'.66 S 150° 10'.96 E | 30 |
| 36° 15'.71 S 150° 10'.43 E | 29 |
| 36° 15'.75 S 150° 09'.15 E | 12 |
| 36° 15'.77 S 150° 09'.97 E | 29. |

**Chart temporarily affected - Aus 806 - Aus 807**

**107(T)/2024 AUSTRALIA - NEW SOUTH WALES - Seal Rocks - Scientific instruments**
Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 32° 27'.16 S 152° 33'.47 E | 35 |
| 32° 27'.16 S 152° 32'.75 E | 28 |
| 32° 27'.45 S 152° 32'.94 E | 26 |
| 32° 28'.45 S 152° 33'.80 E | 38 |
| 32° 28'.81 S 152° 34'.11 E | 42. |

**Chart temporarily affected - Aus 810**

**741(T)/2024 AUSTRALIA - TASMAN SEA - Tasman Basin - Light buoy off station**
Australian Bureau of Meteorology

The special light buoy, *Fl.Y.2s* (44° 47'.40 S 161° 42'.03 E), is off station.

**Chart temporarily affected - Aus 4601 (INT 601)**

**900(T)/2024 AUSTRALIA - NEW SOUTH WALES - Port Stephens - Scientific instrument**
*Former Notice* - 750(T)/2023 is cancelled
Manly Hydraulics Laboratory

A special light buoy, *Fl.Y.3s*, exists in position 32° 41'.77 S 152° 05'.10 E.

**Chart temporarily affected - Aus 209**

**742(T)/2025 AUSTRALIA - NEW SOUTH WALES - Clarence River - Yamba - Light buoys**
Port Authority of New South Wales Notice 1/2025

Lateral light buoys exist as follows:

| *Position* | *Characteristics* |
|---|---|
| 29° 25'.65 S 153° 21'.68 E | *Fl.R.3s* |
| 29° 25'.71 S 153° 21'.48 E | *Fl.G.3s* |
| 29° 25'.76 S 153° 21'.47 E | *Fl.R.3s.* |

**Chart temporarily affected - Aus 222**

**870(P)/2025 AUSTRALIA - NEW SOUTH WALES - The Entrance - Shoaling eastwards**
Australian Hydrographic Office

Latest survey indicates shoaler depths than those charted may exist in an area bounded by the following positions:
33° 20'.97 S 151° 31'.17 E
33° 21'.19 S 151° 32'.26 E
33° 24'.22 S 151° 30'.14 E
33° 24'.41 S 151° 29'.00 E.

Mariners are advised to navigate with caution in the area.

Products will be updated in due course.

**Chart which will be affected - Aus 809**

**942(P)/2025 AUSTRALIA - NEW SOUTH WALES - Sydney Harbour - Wreck**
Port Authority of New South Wales

Latest surveys indicate that the wreck in position 33° 52'.02 S 151° 17'.41 E is shoaler than charted, with a least depth of *22.8m.*

Charts will be updated in due course.

**Chart which will be affected - Aus 200**

**987(T)/2025 AUSTRALIA - NEW SOUTH WALES - Brooms Head - Fish aggregating devices off station eastwards**
Department of Primary Industries and Regional Development

The special light buoy, *Fl.Y.5s FAD (Sep-Jun)* (29° 36'.75 S 153° 29'.19 E) is off station and in position 29° 37'.27 S 153° 29'.15 E.

**Chart temporarily affected - Aus 812 - Aus 813**

**1030(T)/2025 AUSTRALIA - NEW SOUTH WALES - Maroubra Bay - Scientific instrument**
Department of Climate Change, Energy, the Environment and Water

A special light buoy, *Fl.Y.2·5s*, exists in position 33° 56'.28 S 151° 15'.83 E.

**Chart temporarily affected - Aus 808**

**102(T)/2026 AUSTRALIA - NEW SOUTH WALES - Bulli - Obstruction eastwards**
Port Kembla Water Police

A floating obstruction exists in position 34° 20'.79 S 151° 10'.82 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 808**

**147(T)/2026 AUSTRALIA - NEW SOUTH WALES - Port Macquarie - Light buoy off station eastwards**
NSW Department of Primary Industries and Regional Development

The special light buoy, *Fl.Y.5s FAD (Sep-Jun)* (31° 24'.55 S 153° 04'.73 E), is off station and is currently in position 31° 26'.44 S 153° 04'.34 E.

**Chart temporarily affected - Aus 811**

**243(T)/2026 AUSTRALIA - NEW SOUTH WALES - Cape Banks - Fish aggregating device off station eastwards**
NSW Department of Primary Industries and Regional Development

The special light buoy, *Fl.Y.5s (Oct-May)* (33° 59'.32 S 151° 20'.95 E) is off station and in position 34° 00'.28 S 151° 20'.36 E.

**Chart temporarily affected - Aus 808**

**244(T)/2026 AUSTRALIA - NEW SOUTH WALES - Newcastle - Belmont - Construction works**
Transport for NSW

Construction works from a jack up barge are underway in the vicinity of position 33° 03'.12 S 151° 40'.58 E.
An exclusion zone marked by yellow flashing buoys and 24 hour surveillance, exists for all vessels not involved in the works.

Mariners should navigate with caution.

**Chart temporarily affected - Aus 809**

**286(T)/2026 AUSTRALIA - NEW SOUTH WALES - Kurnell Peninsula - Cape Baily - Light buoy off station eastwards**
Port Authority of New South Wales Notice 9/2026

The special light buoy, *Fl(5)Y.20s* (34° 02'.47 S 151° 15'.20 E), is off station and is currently in position 34° 02'.72 S 151° 15'.04 E with light temporary altered to *Fl(5)Y.20s & Fl.2s*.

**Chart temporarily affected - Aus 198**

**330(T)/2026 AUSTRALIA - NEW SOUTH WALES - Cape Banks to Cabbage Tree Bay - Scientific instruments eastwards**
*Former Notice* - 701(T)/2023 is cancelled
Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 33° 47'.92 S 151° 17'.71 E | 9 |
| 33° 48'.05 S 151° 18'.33 E | 24 |
| 33° 49'.59 S 151° 17'.89 E | 28 |
| 33° 49'.85 S 151° 17'.64 E | 28 |
| 33° 50'.05 S 151° 17'.48 E | 27 |
| 33° 50'.25 S 151° 17'.30 E | 26.5 |
| 33° 53'.74 S 151° 17'.30 E | 27 |
| 33° 53'.91 S 151° 17'.75 E | 41 |
| 33° 54'.17 S 151° 18'.16 E | 58 |
| 33° 54'.43 S 151° 18'.59 E | 63 |
| 33° 54'.69 S 151° 19'.05 E | 64 |
| 33° 54'.96 S 151° 19'.51 E | 64 |
| 33° 55'.21 S 151° 19'.93 E | 71 |
| 33° 55'.46 S 151° 20'.36 E | 70 |
| 33° 55'.72 S 151° 20'.79 E | 80 |
| 33° 55'.98 S 151° 21'.24 E | 80 |
| 33° 56'.25 S 151° 21'.71 E | 82 |

| | |
|---|---|
| 33° 56'.49 S 151° 22'.16 E | 87 |
| 33° 56'.75 S 151° 22'.59 E | 90 |
| 33° 57'.06 S 151° 23'.02 E | 98 |
| 33° 57'.32 S 151° 23'.47 E | 119. |


**Chart temporarily affected - Aus 200 - Aus 489 - Aus 808 - Aus 809**

**512(T)/2026 AUSTRALIA - NEW SOUTH WALES - Botany Bay - Autonomous vessel operations**
Transport for NSW Notice 17(T)/2026

Autonomous vessel operations are underway in Botany Bay and the Tasman Sea in the vicinity of position 34° 00'.84 S 151° 14'.57 E.

Mariners are advised to navigate with caution in the area.

Figure 2: Operational zones




**Legend:** *Green - Autonomous Transit Zone*
*White - Restricted Autonomous Zone*
*Magenta - Unrestricted Autonomous Zone [Excluding Ports area]*

**Chart temporarily affected - Aus 198 - Aus 808**

**637(T)/2026 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Sydney Cove - Harbour works**
Port Authority of New South Wales Notice 19/2026

A crane barge is conducting scour protection works in an area 30m out from the wharf face (33° 51'.49 S 151° 12'.62 E).

Special buoys will mark the edge of the works area.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 200**

**722(T)/2026 AUSTRALIA - NEW SOUTH WALES - Port Kembla - Obstruction**
Port Authority of New South Wales

Anchorage PKA7 (34° 24'.81 S 151° 01'.22 E) is unavailable for anchoring due to a lost anchor and cable.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 195 - Aus 808**

**765(T)/2026 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Hunters Bay to Sow & Pigs Reef - Scientific instruments**
Transport for NSW

Special light buoys, *Fl.Y.5s,* exist in positions 33° 49'.30 S 151° 15'.41 E and 33° 49'.94 S 151° 16'.40 E.

**Chart temporarily affected - Aus 200**

**819(T)/2026 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Spectacle Island - Lights unlit**
Port Authority of New South Wales

The lights, *Fl.Y.3s* (33° 50'.81 S 151° 09'.91 E) and *Fl.Y.3s* (33° 50'.84 S 151° 09'.78 E), are unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 200**

**857(T)/2026 AUSTRALIA - NEW SOUTH WALES - Broken Bay - Military exercise**
Department of Defence

During the period 5 to 11 October 2026, a military exercise will be conducted in an area bounded by the following positions:
33° 35'.07 S 151° 20'.05 E
33° 37'.58 S 151° 20'.50 E
33° 37'.58 S 151° 28'.00 E
33° 31'.15 S 151° 32'.40 E
33° 31'.15 S 151° 25'.25 E
33° 31'.73 S 151° 24'.23 E
33° 32'.87 S 151° 20'.75 E
33° 32'.90 S 151° 18'.65 E
33° 34'.63 S 151° 18'.50 E.

During the military exercise there will be increased surface vessels and underwater activities/demolitions in the area.

Mariners are advised to navigate with caution in the area and avoid if possible.

**Chart temporarily affected - Aus 204 - Aus 809**

**858(T)/2026 AUSTRALIA - NEW SOUTH WALES - Jervis Bay - Military exercise**
Department of Defence

During the period 5 October to 1 November 2026, a military exercise will be conducted in an area bounded by the following positions:
34° 57'.38 S 150° 44'.23 E
35° 02'.37 S 150° 38'.30 E
35° 16'.50 S 150° 49'.52 E
35° 08'.48 S 150° 59'.13 E.

During the military exercise there will be increased surface vessels and underwater activities/demolitions in the area.

Mariners are advised to navigate with caution in the area and avoid if possible.

**Chart temporarily affected - Aus 807 - Aus 808**

## QUEENSLAND

**470(T)/2017 AUSTRALIA - QUEENSLAND - North Gardner Bank - Foul ground**
Maritime Safety Queensland Notice 24/2017

A foul ground exists in position 24° 56'.30 S 153° 26.90 E.

**Chart temporarily affected - Aus 816**

**72(T)/2018 AUSTRALIA - QUEENSLAND - Fitzroy Island - Bird Rock - Light buoys**
*Former Notice* - 29(T)/2018 is cancelled
Maritime Safety Queensland Notice 503(T)/2017

Two special light buoys, *Fl.Y.2·5s* exist in position 16° 55'.43 S 145° 59'.43 E.

**Chart temporarily affected - Aus 830**

**213(T)/2018 AUSTRALIA - QUEENSLAND - Bribie Island - South Point - Shoaling**
Maritime Safety Queensland

Shoaling exists at the southern end of Bribie Island, with a least depth of *0.5m* in position 27° 06'.18 S 153° 11'.24 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 236**

**488(T)/2019 AUSTRALIA - QUEENSLAND - Karumba - Wreck northwards**
Maritime Safety Queensland Notice 188(T)/2019

A stranded wreck marked by a special light buoy, *Fl.Y.2·5s,* exists in position 17° 15'.36 S 140° 53'.89 E.

**Chart temporarily affected - Aus 303**

**548(P)/2019 AUSTRALIA - QUEENSLAND - Hydrographers Passage - Shoaling**
LADS Flight

Latest survey shows shoaler depths than those charted may exist in an area bounded by the following positions:
20° 36'.52 S 150° 04'.39 E
20° 30'.63 S 150° 17'.03 E
20° 23'.93 S 150° 16'.63 E
20° 06'.15 S 150° 04'.79 E
20° 11'.27 S 150° 00'.18 E
20° 21'.88 S 150° 04'.70 E
20° 27'.57 S 150° 09'.82 E
20° 32'.65 S 150° 01'.91 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 821 - Aus 824**

**1049(P)/2020 AUSTRALIA - TORRES STRAIT - Deliverance Island - Shoaling**
HMAS *Albany*

Latest survey shows shoaling exists as follows:

| *Depth* | *Position* |
|---|---|
| *1.1m* | 9° 32'.89 S 141° 27'.03 E |
| *3.6m* | 9° 32'.22 S 141° 27'.73 E. |

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 842**

**21(T)/2021 AUSTRALIA - CORAL SEA - Middleton Reef - Unexploded ordnance**
Parks Australia

An exclusion zone exists in an area bounded by the following positions:
29° 27'.12 S 159° 02'.92 E
29° 26'.58 S 159° 02'.92 E
29° 26'.58 S 159° 03'.55 E
29° 27'.12 S 159° 03'.55 E.

Unexploded ordnance may exist in the area and mariners are advised to navigate with caution.

**Chart temporarily affected - Aus 618**

**247(T)/2021 AUSTRALIA - QUEENSLAND - Cape Ferguson - Scientific instrument**
Australian Institute of Marine Science

A special spar light buoy, *Q(4)Y.18s,* exists in position 19° 16'.52 S 147° 03'.84 E.

**Chart temporarily affected - Aus 256**

**337(P)/2021 AUSTRALIA - TORRES STRAIT - Boigu Island - Shoaling**
HMAS *Leeuwin*

Latest survey shows shoaler depths than those charted may exist in areas bounded by the following positions:
9° 14'.38 S 142° 15'.82 E
9° 15'.78 S 142° 19'.88 E
9° 15'.49 S 142° 20'.00 E
9° 13'.58 S 142° 16'.26 E;
and
9° 12'.49 S 142° 15'.50 E
9° 12'.33 S 142° 13'.73 E
9° 13'.16 S 142° 13'.24 E
9° 13'.20 S 142° 15'.21 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 841**

**738(T)/2021 AUSTRALIA - QUEENSLAND - Fitzroy River - Middle Channel - Scientific instrument**
Maritime Safety Queensland Notice 31/2021

A special light buoy, *Q.Y,* exists in position 23° 28'.23 S 150° 56'.37 E.

**Chart temporarily affected - Aus 265**

**741(T)/2021 AUSTRALIA - QUEENSLAND - Fraser Island - Elbow Point - Shoaling**
Navionics

Depths of less than 1m have been reported in an area bounded by the following positions:
25° 44'.40 S 152° 59'.29 E
25° 44'.71 S 152° 59'.37 E
25° 44'.89 S 153° 00'.30 E
25° 44'.66 S 153° 00'.38 E
25° 44'.40 S 152° 59'.77 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart temporarily affected - Aus 817**

**980(T)/2021 AUSTRALIA - QUEENSLAND - Fitzroy River - South Channel - Scientific instrument**
*Former Notice* - 661(T)/2016 is cancelled
Maritime Safety Queensland Notice 400(T)/2021

A special light buoy, *Fl.Y.4s*, exists in position 23° 30'.23 S 150° 45'.83 E.

**Chart temporarily affected - Aus 819**

**1025(T)/2021 AUSTRALIA - TORRES STRAIT - Great North East Channel - Coconut Island - Scientific instrument**
*Former Notice* - 486(T)/2021 is cancelled
Maritime Safety Queensland Notice 427(T)/2021

A special light buoy, *Fl(5)Y.20s*, exists in position 10° 03'.18 S 143° 03'.12 E.

**Chart temporarily affected - Aus 839**

**27(P)/2022 AUSTRALIA - TORRES STRAIT - Boigu Island - Shoaling**
Australian Institute of Marine Science

The drying area (9° 15'.51 S 142° 06'.09 E) extends 0.27M northwest to position 9° 15'.31 S 142° 05'.91 E.

The reef (9° 11'.96 S 142° 10'.56 E) extends 0.27M south to position 9° 12'.23 S 142° 10'.56 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 841**

**422(T)/2022 AUSTRALIA - QUEENSLAND - Palm Beach - Light buoy off station**
Maritime Safety Queensland Notice 220(T)/2022

The special light buoy, *Fl.Y.5s* (28° 06'.34 S 153° 28'.42 E), is off station.

**Chart temporarily affected - Aus 814**

**490(T)/2022 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Light buoy destroyed eastwards**
Maritime Safety Queensland Notice 266/2022

The special light buoy, *Fl.Y.4s* (27° 54'.93 S 153° 27'.59 E), has been destroyed and has sunk in position.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 814**

**788(P)/2022 AUSTRALIA - CORAL SEA - Diamond Islets - Shoaling**
LADS Flight

Shoaler depths than those charted exist in the vicinity of the Diamond Islets.

Charts will updated in due course.

**Chart which will be affected - Aus 614**

**877(T)/2022 AUSTRALIA - QUEENSLAND - Brisbane River - Hamilton Reach - Wreck**
Maritime Safety Queensland Notice 172(T)/2022

A wreck marked by a special light buoy, *Fl.Y.2·5s,* exists in position 27° 26'.43 S 153° 03'.28 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 237**

**1026(T)/2022 AUSTRALIA - QUEENSLAND - Upstart Bay - Obstructions**

Maritime Safety Queensland

Obstructions on the seabed exist within a 1M radius of position 19° 44'.13 S 147° 40'.74 E.

Mariners area advised not to anchor or trawl in the area.

**Chart temporarily affected - Aus 826**

**67(T)/2023 AUSTRALIA - QUEENSLAND - Townsville - Shoaling**
Maritime Safety Queensland

Flooding and latest survey shows shoaler depths than those charted may exist in Ross River between positions 19° 15'.36 S 146° 50'.85 E and 19° 17'.00 S 146° 49'.51 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart temporarily affected - Aus 256**

**68(T)/2023 AUSTRALIA - QUEENSLAND - Townsville - Obstructions**
Maritime Safety Queensland Notice 24(T)/2023

Due to recent flooding, floating and submerged obstructions may exist in the coastal waters between Dunk Island (17° 56'.72 S 146° 09'.47 E) and Bowen (20° 00'.54 S 148° 17'.40 E).

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 255 - Aus 256 - Aus 268 - Aus 825 - Aus 826 - Aus 827 - Aus 828 - Aus 829**

**99(T)/2023 AUSTRALIA - QUEENSLAND - Brisbane River - Lytton and Quarantine Reach - Obstruction; light buoy**
Maritime Safety Queensland Notice 37(T)/2023

An obstruction marked by a special light buoy, *Fl.Y.2·5s*, exists in position 27° 24'.74 S 153° 08'.90 E.

**Chart temporarily affected - Aus 237**

**357(T)/2023 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Wreck eastwards**
Australian Maritime Safety Authority Auscoast Warning 95/2023

A wreck exists in the vicinity of position 27° 53'.8 S 153° 38'.5 E.

**Chart temporarily affected - Aus 814**

**360(T)/2023 AUSTRALIA - QUEENSLAND - Hinchinbrook Channel - Light buoy off station**
Maritime Safety Queensland Notice 168(T)/2023

The starboard lateral light buoy, *Fl.G.4·3s No15* (18° 29'.63 S 146° 17'.30 E), is off station.

**Chart temporarily affected - Aus 259**

**484(T)/2023 AUSTRALIA - QUEENSLAND - Fitzroy River - Middle Channel - Scientific instrument**
Maritime Safety Queensland Notice 229(T)/2023

A special light buoy, *Fl.Y.5s,* exists in position 23° 27'.85 S 150° 56'.60 E.

**Chart temporarily affected - Aus 265 - Aus 819**

**813(T)/2023 AUSTRALIA - QUEENSLAND - Moreton Bay - Bramble Bay - Pine River - Obstruction; light buoy**
Maritime Safety Queensland Notice 398(T)/2023

An obstruction marked by a special light buoy, *Fl.Y.2·5s*, exists in position 27° 16'.48 S 153° 04'.19 E.

**Chart temporarily affected - Aus 236**

**17(T)/2024 AUSTRALIA - TORRES STRAIT - Yorke Islands - Scientific instrument**
Maritime Safety Queensland Notice 592(T)/2023

A special light buoy, *Fl(5)Y.20s*, exists in position 9° 44'.70 S 143° 24'.29 E.

**Chart temporarily affected - Aus 377 - Aus 840**

**250(T)/2024 AUSTRALIA - QUEENSLAND - Great Sandy Strait - Light buoys**
*Former Notice* - 219(T)/2024 is cancelled
Maritime Safety Queensland Notice 146/2017, 145(T)/2021, 70/2020

Light buoys exist as follows:

| *Number* | *Position* | *Characteristics* |
|---|---|---|
| S3 | 25° 12'.70 S 152° 54'.75 E | *Fl.G.2·5s* |
| NG1 | 25° 20'.20 S 153° 01'.40 E | *Fl.G.2·5s.* |

**Chart temporarily affected - Aus 817**

**408(T)/2024 AUSTRALIA - QUEENSLAND - North Stradbroke Island - Point Lookout - Scientific instruments**
Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 27° 25'.29 S 153° 35'.08 E | 50 |
| 27° 25'.34 S 153° 34'.57 E | 46 |
| 27° 25'.37 S 153° 34'.08 E | 45 |
| 27° 25'.42 S 153° 33'.31 E | 36 |
| 27° 25'.44 S 153° 33'.31 E | 28. |

**Chart temporarily affected - Aus 236 - Aus 814**

**409(T)/2024 AUSTRALIA - QUEENSLAND - One Tree Island to Heron Island - Scientific instruments**
Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 23° 25'.97 S 151° 55'.61 E | 19 |
| 23° 26'.20 S 151° 58'.84 E | 10 |
| 23° 26'.38 S 151° 53'.98 E | 9 |
| 23° 26'.85 S 151° 54'.74 E | 15 |
| 23° 28'.26 S 151° 56'.82 E | 16 |
| 23° 28'.26 S 151° 56'.82 E | 8 |
| 23° 28'.34 S 151° 58'.69 E | 15 |
| 23° 28'.76 S 152° 04'.96 E | 12 |
| 23° 29'.52 S 152° 02'.75 E | 16 |
| 23° 30'.37 S 152° 02'.43 E | 8 |
| 23° 30'.52 S 152° 03'.33 E | 13 |
| 23° 30'.83 S 152° 05'.63 E | 18. |

**Chart temporarily affected - Aus 819**

**528(T)/2024 AUSTRALIA - QUEENSLAND - Moreton Bay - Chain Banks - Scientific instrument**
Maritime Safety Queensland Notice 323(T)/2024

A special light buoy, *Fl.Y.4s*, exists in position 27° 25'.79 S 153° 18'.38 E.

**Chart temporarily affected - Aus 236**

**711(T)/2024 AUSTRALIA - QUEENSLAND - Yorkeys Knob - Shoaling; light buoy**
Maritime Safety Queensland Notice 444(T)/2024

Shoaling exists at the entrance to the marina and is marked by a special light buoy, *Fl.Y.2·5s*, in position 16° 48'.02 S 145° 43'.01 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 262**

**866(T)/2024 AUSTRALIA - TORRES STRAIT - Cook Reef - Scientific instruments southwards**
Fugro

Tide gauges exist in positions 10° 27'.06 S 141° 20'.32 E and 10° 28'.40 S 141° 41'.78 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 700 - Aus 842**

**901(T)/2024 AUSTRALIA - QUEENSLAND - Brisbane River - Hamilton Reach - Scientific instrument**
Maritime Safety Queensland Notice 565(T)/2024

A special light buoy, *Fl.Y.3s,* exists in position 27° 26'.49 S 153° 03'.48 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 237**

**968(T)/2024 AUSTRALIA - QUEENSLAND - Duyfken Point - Scientific instrument westwards**
Maritime Safety Queensland Notice 578(T)/2024

A special light buoy, *Fl(5)Y.20s*, exists in position 12° 10'.16 S 140° 16'.80 E.

**Chart temporarily affected - Aus 4603 (INT 603)**

**28(T)/2025 AUSTRALIA - QUEENSLAND - Laguna Quays - Shoaling**
*Former Notice* - 972(T)/2023 is cancelled
Maritime Safety Queensland

Shoaling exists within Laguna Quays Marina (20° 36'.0 S 148° 41'.0 E).

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 252**

**98(T)/2025 AUSTRALIA - QUEENSLAND - Deception Bay - Light buoy**
Maritime Safety Queensland NTM 010(T)/2025

A special light buoy, *Fl.Y.4s*, exists in position 27° 06'.63 S 153° 07'.32 E.

**Chart temporarily affected - Aus 236**

**135(T)/2025 AUSTRALIA - QUEENSLAND - Brisbane River - Hamilton Reach - Light buoys**
Maritime Safety Queensland Notice 30(T)/2025

The special light buoy, *Fl.Y.3s* (27° 26'.77 S 153° 04'.48 E), has been temporarily relocated to position 27° 26'.80 S 153° 04'.49 E.

The special light buoy, *Fl.Y.3s* (27° 26'.72 S 153° 04'.24 E), has been temporarily relocated to position 27° 26'.73 S 153° 04'.23 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 237**

**173(T)/2025 AUSTRALIA - QUEENSLAND - Laguna Quays - Lights unlit**
Maritime Safety Queensland

The leading lights, *F.Bu (F Day) (*20° 36'.19 S 148° 40'.80 E) and *F.Bu (F Day) (*20° 36'.16 S 148° 40'.86 E), are unlit.

**Chart temporarily affected - Aus 252**

**257(T)/2025 AUSTRALIA - QUEENSLAND - Moreton Bay - Brisbane River - Navaids destroyed or off station; depths**
Maritime Safety Queensland

Navaids in Moreton Bay and the Brisbane River may be destroyed or off station due to recent flooding.

Obstructions may exist and depths may not be consistent with charted information.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 236 - Aus 237**

**334(T)/2025 AUSTRALIA - TORRES STRAIT - Holmes Reef - Wreck**
Maritime Safety Queensland

A stranded wreck marked by a special light buoy, *Fl.Y.4s*, exists in position 10° 36'.23 S 142° 14'.17 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 293 - Aus 299**

**408(T)/2025 AUSTRALIA - QUEENSLAND - Karumba - Scientific instrument**
Maritime Safety Queensland Notice 176(T)/2025

A special light buoy, *Fl.Y.2·5s*, exists in position 17° 21'.29 S 140° 43'.69 E.

**Chart temporarily affected - Aus 303**

**410(T)/2025 AUSTRALIA - QUEENSLAND - North Stradbroke Island - Light buoy off station eastwards**
*Former Notice* - 258(T)/2025 is cancelled
Department of Primary Industries

The special light buoy, *Fl.Y.3s FAD* (27° 41'.28 S 153° 36'.83 E), is off station and in position 27° 40'.55 S 153° 36'.17 E.

**Chart temporarily affected - Aus 814**

**551(T)/2025 AUSTRALIA - QUEENSLAND - Moreton Bay - Chain Banks - Wreck**
Maritime Safety Queensland Notice 256(T)/2025

A wreck marked by a special light buoy, *Fl.Y.2·5s*, exists in position 27° 23'.78 S 153° 18'.49 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 236**

**611(T)/2025 AUSTRALIA - QUEENSLAND - Mackay - Light buoys**
Maritime Safety Queensland Notie 301(T)/2025

Special light buoys, *Fl.Y.3s*, exist in positions 21° 06'.38 S 149° 14'.52 E and 21° 06'.48 S 149° 14'.27 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 250**

**665(P)/2025 AUSTRALIA - QUEENSLAND - Old Reef - Rock**
XOCEAN

An uncharted rock, with least depth 42m, has been reported in position 19° 26'.39 S 148° 05'.46 E.

Mariners are advised to navigate with caution in the area.

Charts will updated in due course.

**Chart which will be affected - Aus 826**

**745(T)/2025 AUSTRALIA - QUEENSLAND - Capricorn Group - One Tree Island - Scientific instrument eastwards**
Maritime Safety Queensland Notice 385(T)/2025

A special light buoy, *Fl(5)Y.20s*, exists in position 23° 28'.65 S 152° 12'.21 E.

Mariners are advised to navigate with caution in the area and not to use the buoy as a mooring.

**Chart temporarily affected - Aus 490 - Aus 819**

**872(T)/2025 AUSTRALIA - QUEENSLAND - Mackay - Virtual AIS**
Maritime Safety Queensland Notice 437(T)/2025

A port lateral virtual AIS exists in position 21° 06'.38 S 149° 14'.16 E.

**Chart temporarily affected - Aus 249 - Aus 250**

**874(T)/2025 AUSTRALIA - QUEENSLAND - Pearl Bay - Obstruction**
Maritime Safety Queensland Notice 439(T)/2025

An obstruction exists, 1m below the surface, in position 22° 25'.37 S 150° 43'.66 E.

**Chart temporarily affected - Aus 260 - Aus 820 - Aus 822**

**908(T)/2025 AUSTRALIA - QUEENSLAND - Gladstone - Harbour works; restricted area**
*Former Notice* - 746(T)/2025 is cancelled
Maritime Safety Queensland Notice 362(T)/2025, Notice 470(T)/2025

Works associated with the construction of a reclamation bund wall are in progress.

A restricted area exists bounded by the following positions:
23° 47'.00 S 151° 08'.98 E
23° 46'.82 S 151° 09'.32 E
23° 46'.05 S 151° 09'.45 E
23° 45'.88 S 151° 09'.74 E
23° 45'.40 S 151° 09'.07 E
23° 46'.10 S 151° 08'.56 E.

Light buoys, *Fl.Y.2·5s*, exist in the following positions:
23° 45'.87 S 151° 09'.70 E
23° 45'.82 S 151° 09'.63 E
23° 45'.77 S 151° 09'.56 E
23° 45'.69 S 151° 09'.44 E
23° 45'.60 S 151° 09'.33 E
23° 45'.52 S 151° 09'.21 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 245 - Aus 819**

**990(T)/2025 AUSTRALIA - QUEENSLAND - Dunk (Coonanglebah) Island - Scientific instrument southeastwards**
*Former Notice* - 606(T)/2025 is cancelled
Maritime Safety Queensland Notice 497(T)/2025

A special light buoy, *Fl.Y.2·5s*, exists in position 17° 58'.45 S 146° 11'.66 E.

**Chart temporarily affected - Aus 258 - Aus 828 - Aus 829**

**1031(P)/2025 AUSTRALIA - QUEENSLAND - Cape Upstart - Wreck northeastwards**
XOCEAN

Latest survey indicates a wreck, least depth *29.7m*, exists in position 19° 35'.47 S 147° 53'.72 E.

Charts will be updated in due course.

**Chart which will be affected - Aus 826**

**1075(P)/2025 AUSTRALIA - QUEENSLAND - Great Barrier Reef - Joist Reef to Hydrographers Passage - Shoaling**
LADS Flight

Latest survey shows shoaler depths than those charted may exist in an area bounded by the following positions:
19° 27'.1 S 149° 38'.9 E
20° 12'.2 S 149° 39'.1 E
20° 12'.2 S 150° 18'.5 E
19° 39'.2 S 150° 18'.5 E.

Charts will updated in due course.

**Chart which will be affected - Aus 821 - Aus 825**

**105(T)/2026 AUSTRALIA - QUEENSLAND - Bribie Island - Pumicestone Channel - Dredging operations**
*Former Notice* - 871(T)/2025 is cancelled
Maritime Safety Queensland Notice 50(T)/2026

Dredging operations are in progress in an area bounded by the following positions:
26° 50'.29 S 153° 07'.73 E
26° 49'.04 S 153° 07'.96 E
26° 48'.92 S 153° 07'.44 E
26° 50'.27 S 153° 07'.21 E.

A floating and submerged pipeline, marked by pink and yellow buoys, exists in the area.

Mariners should navigate with extreme caution in the area and stay within the marked navigation channel due to constant moving of sandbanks.

**Chart temporarily affected - Aus 236**

**148(T)/2026 AUSTRALIA - QUEENSLAND - Cleveland Bay - Scientific instruments**
*Former Notice* - 57(T)/2026 is cancelled
Maritime Safety Queensland Notice 60(T)/2026

Special light buoys, *Fl.Y.2·5s*, exist in the following positions:
19° 06'.45 S 146° 33'.86 E
19° 07'.34 S 146° 52'.92 E
19° 09'.36 S 146° 52'.07 E
19° 11'.81 S 146° 49'.07 E
19° 14'.80 S 146° 48'.90 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 256 - Aus 827**

**150(T)/2026 AUSTRALIA - QUEENSLAND - Gladstone - South Channel - Light beacon destroyed**
*Former Notice* - 58(T)/2026 is cancelled
Maritime Safety Queensland Notice 66(T)/2026

The light beacon, *Fl.R.4s* (23° 54'.17 S 151° 23'.55 E), has been destroyed and partly removed below the water surface; a port lateral light buoy, *Fl.R.4s*, exists in situ.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 246**

**151(P)/2026 AUSTRALIA - QUEENSLAND - Slade Island - Shoaling southeastwards**
Maritime Safety Queensland

Latest survey indicates shoaler depths than those charted may exist in an area bounded by the following positions:
21° 05'.92 S 149° 15'.22 E
21° 06'.07 S 149° 15'.27 E
21° 06'.14 S 149° 14'.99 E

21° 05'.99 S 149° 14'.93 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 250**

**202(T)/2026 AUSTRALIA - QUEENSLAND - Brisbane River - Hamilton Reach - Harbour works**
Maritime Safety Queensland Notice 079(T)/2026

Works associated with the demolition of a 400m section of Hamilton Wharf in the vicinity of position 27° 26'.57 S 153° 04'.46 E are underway.

8 special light buoys, *Fl.Y.1·5s,* mark the anchors of a silt curtain around the works.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 237**

**247(T)/2026 AUSTRALIA - QUEENSLAND - Brisbane River - Construction works**
Maritime Safety Queensland Notice 099(T)/2026

Construction works have commenced at the Port North Common User Berth on the Brisbane River. The works are being carried out from the heavy lift barge *Maeve Anne* and its support craft, in the vicinity of position 27° 23'.027 S, 153° 09'.280 E.

Flashing lights will be displayed at the four corners of the barge and it will be secured using four anchors, each marked with buoys fitted with flashing yellow lights. The works are scheduled to occur between 0600 and 1800 hours, Monday to Saturday.

During working hours, the barge and support craft will monitor VHF Ch 13 and Ch 16. Mariners are advised to navigate with caution when transiting the area and to pass at a slow speed when requested.

**Chart temporarily affected - Aus 237**

**253(P)/2026 AUSTRALIA - TORRES STRAIT - Horn Island to Thursday Island - Shoaling**
Maritime Safety Queensland

Latest survey indicates shoaler depths than those charted may exist in the vicinity of positions 10° 35'.46 S 142° 14'.75 E and 10° 35'.18 S 142° 13'.37 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 299**

**289(T)/2026 AUSTRALIA - QUEENSLAND - Caloundra Head - Scientific instruments**
*Former Notice* - 56(T)/2026 is cancelled
Maritime Safety Queensland Notice 141(T)/2026

Special light buoys, *Fl.Y.3s*, exist in the following positions:
26° 50'.55 S 153° 08'.27 E
26° 48'.97 S 153° 08'.67 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 236 - Aus 815**

**370(T)/2026 AUSTRALIA - QUEENSLAND - Hinchinbrook Channel - Cardwell - Wreck**
Maritime Safety Queensland Notice 216(T)/2026

A stranded wreck marked by a special light buoy, *Fl.Y.4s,* exists in position 18° 11'.95 S 146° 01'.08 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 828**

**372(T)/2026 AUSTRALIA - QUEENSLAND - Shute Harbour - Rooper Inlet - Obstruction**
Maritime Safety Queensland Notice 152(T)/2026

A semi-submerged mooring buoy exists in position 20° 18'.01 S 148° 47'.23 E.

**Chart temporarily affected - Aus 252 - Aus 253**

**430(T)/2026 AUSTRALIA - QUEENSLAND - Double Island Point - Light buoy off station**
Maritime Safety Queensland Notice 245(T)/2026

The special light buoy, *Fl.Y.4s* (25° 56'.33 S 153° 10'.19 E), is off station.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 815 - Aus 817**

**432(T)/2026 AUSTRALIA - QUEENSLAND - Kawana Waters - Subsea operations**
Maritime Safety Queensland Notice 236(T)/2026

Vessel *Iluka* is conducting subsea operations associated with the upgrade to the diffusers on the outfall piepline in the vicinity of position 26° 43'.86 S 153° 08'.63 E.

The works area is marked by special light buoys, *Fl.Y.0·5s.*

Mariners are advised to maintain a safe distance and navigate with caution in the area.

**Chart temporarily affected - Aus 236**

**515(T)/2026 AUSTRALIA - QUEENSLAND - Boyd Point - Scientific instruments**
Maritime Safety Queensland Notice 278(T)/2026

Special light buoys, *Fl(5).Y.20s*, exist in the following positions:
12° 50'.79 S 141° 36'.89 E
12° 54'.50 S 141° 36'.09 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4**

**516(P)/2026 AUSTRALIA - QUEENSLAND - Gladstone - East Channel - Shoaling**
Maritime Safety Queensland

Latest survey indicates shoaler depths than those charted exist in an area bounded by the following positions:
23° 50'.95 S 151° 24'.59 E
23° 52'.01 S 151° 24'.25 E
23° 52'.94 S 151° 23'.68 E
23° 53'.05 S 151° 23'.56 E
23° 53'.23 S 151° 22'.48 E
23° 53'.10 S 151° 22'.34 E
23° 52'.91 S 151° 23'.04 E
23° 52'.51 S 151° 23'.59 E
23° 50'.90 S 151° 24'.36 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 245 - Aus 246 - Aus 819**

**519(T)/2026 AUSTRALIA - QUEENSLAND - Weipa - Dredging operations; survey operations**
Maritime Safety Queensland Notice 306(T)/2024

TSHD *Brisbane* and survey vessel *Sounds Pacific* are conducting dredging and survey operations in the Port of Weipa (12° 40'.70 S 141° 47'.00 E).

The dredge will monitor VHF Ch 12 and Ch 16.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4**

**558(P)/2026 AUSTRALIA - QUEENSLAND - Sandy Strait - Mary River - Shoaling**
Maritime Safety Queensland

Latest survey indicates shoaler depths than those charted may exist in Mary River between positions 25° 32'.47 S 152° 42'.71 E and 25° 25'.22 S 152° 58'.35 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 817**

**638(T)/2026 AUSTRALIA - QUEENSLAND - Cairns - Scientific instrument**
Maritime Safety Queensland Notice 365(T)/2026

A special light buoy, *Fl.Y.2·5s,* exists in position 16° 53'.48 S 145° 47'.69 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 262**

**639(P)/2026 AUSTRALIA - QUEENSLAND - Moreton Bay - Yule Bank - Shoaling**
Port of Brisbane

Latest survey indicates shoaler depths than those charted may exist in the vicinity of position 27° 06'.53 S 153° 20'.39 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 236 - Aus 814**

**641(T)/2026 AUSTRALIA - QUEENSLAND - Port of Airlie - Muddy Bay - Wrecks**
Maritime Safety Queensland Notice 380(T)/2026, 388(T)/2026

Stranded wrecks marked by a special light buoy, *Fl.Y.3s,* exist in positions 20° 16'.06 S 148° 43'.87 E and 20° 16'.02 S 148° 43'.83 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 252 - Aus 253**

**686(T)/2026 AUSTRALIA - QUEENSLAND - Hook Island - Ian Point - Buoy damaged**
Maritime Safety Queensland Notice 378(T)/2026

The special buoy (20° 06'.22 S 148° 54'.13 E) is damaged and partially submerged.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 254**

**767(T)/2026 AUSTRALIA - QUEENSLAND - Bundaberg - Burnett Heads - Harbour works**
Maritime Safety Queensland Notice 467(T)/2026

Works associated with the construction of the new marina are in progress. The works area is marked by special light buoys,

*Fl.Y.3s*, which exist in the following positions:
24° 45'.57 S 152° 24'.09 E
24° 45'.52 S 152° 24'.13 E
24° 45'.53 S 152° 24'.18 E.

Mariners are not to enter the area as there will be a number of unlit piles.

Workboats can be contacted via Marine Rescue Bundaberg on VHF 81.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 242**

**770(T)/2026 AUSTRALIA - QUEENSLAND - Hesket Rock - Light buoy off station**
Maritime Safety Queensland Notice 446(T)/2026

The south cardinal light buoy, *Q(6)+LFl.15s* (20° 56'.29 S 149° 28'.99 E), is off station.

**Chart temporarily affected - Aus 251**

**771(T)/2026 AUSTRALIA - QUEENSLAND - Hinchinbrook Island - Missionary Bay - Light beacon destroyed**
*Former Notice* - 361(T)/2023 is cancelled
Maritime Safety Queensland Notice 169(T)/2023, 475(T)/2026

The special light beacon, *Fl.Y.3s* (18° 15'.20 S 146° 11'.79 E), has been destroyed.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 259 - Aus 828**

**772(T)/2026 AUSTRALIA - QUEENSLAND - Moreton Bay - Amity Banks - Wreck**
Maritime Safety Queensland Notice 466(T)/2026

A stranded wreck marked by a special light buoy, *Fl.Y.2·5s,* exists in position 27° 25'.53 S 153° 21'.25 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 236 - Aus 814**

**773(T)/2026 AUSTRALIA - QUEENSLAND - Moreton Bay - Skirmish Banks - Scientific instrument**
Maritime Safety Queensland Notice 468(T)/2026

A special light buoy, *Fl(5)Y.20s,* exists in position 27° 03'.95 S 153° 12'.91 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 236 - Aus 814 - Aus 815**

**820(T)/2026 AUSTRALIA - QUEENSLAND - Brisbane River - Hamilton Reach - Wreck**
Port of Brisbane Pty Ltd

A wreck with depth, $7_4$m, exists in position 27° 26'.82 S 153° 05'.38 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 237**

**824(T)/2026 AUSTRALIA - TORRES STRAIT - Cook Reef to Deliverance Island - Survey operations; tide gauges**
Fugro

On or about 1 October 2026, survey operations will begin in the vicinity of Deliverance Island (9° 31'.10 S 141° 34'.29 E), Turu Cay (9° 49'.43 S 141° 25'.54 E) and in an area bounded by the following positions:
10° 21'.42 S 141° 12'.19 E
10° 24'.01 S 141° 28'.18 E
10° 17'.29 S 141° 29'.03 E

10° 13'.94 S 141° 49'.61 E
10° 02'.73 S 141° 49'.61 E
9° 55'.46 S 141° 44'.53 E
10° 15'.23 S 141° 12'.19 E.

Tide gauges exist as follows:

| *Position* | *Remarks* |
|---|---|
| 10° 15'.4 S 141° 12'.4 E | 2m above the seabed |
| 10° 08'.9 S 141° 23'.1 E | 2m above the seabed |
| 10° 01'.9 S 141° 34'.3 E | 2m above the seabed |
| 9° 55'.7 S 141° 44'.9 E | 2m above the seabed |
| 10° 02'.7 S 141° 49'.6 E | 2m above the seabed |
| 10° 13'.8 S 141° 49'.7 E | 2m above the seabed |
| 10° 15'.5 S 141° 35'.7 E | special conical buoy |
| 10° 18'.0 S 141° 19'.4 E | 2m above the seabed |
| 10° 08'.6 S 141° 39'.2 E | 2m above the seabed |
| 9° 50'.3 S 141° 24'.4 E | 2m above the seabed |
| 9° 34'.2 S 141° 33'.8 E | special conical buoy |
| 10° 23'.0 S 141° 28'.8 E | 3m above the seabed |
| 10° 20'.7 S 141° 11'.7 E | 2m above the seabed |
| 10° 15'.5 S 141° 35'.7 E | 2m target cube. |

A special buoy may be deployed in the vicinity of the above positions during the survey.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 700 - Aus 842**

**862(T)/2026 AUSTRALIA - QUEENSLAND - Long Island - East Rock - Obstruction; light buoy**
Maritime Safety Queensland Notice 205/2026

An underwater obstruction marked by a special light buoy, *Fl.Y.3s*, exists in position 20° 20'.28 S 148° 51'.77 E.


Mariners are advised to navigate with caution in the area and to stay well clear.

**Chart temporarily affected - Aus 252 - Aus 253**

**863(T)/2026 AUSTRALIA - QUEENSLAND - NORTHERN TERRITORY - Townsville to Cape Wessel - Survey operations**
EGS Survey Pty Ltd

Vessel *Bold Explorer*, with a 5000m towed array, is conducting geophysical and geotechnical survey operations as follows:

| POINT | LATITUDE | LONGITUDE | APPROX. MONTHS OPERATING |
|---|---|---|---|
| I | 15°39.95'S | 154°23.98'E | October 2026; March – April 2027 |
| F | 10°53.57'S | 145°13.36'E | October – November 2026; December 2026 – January 2027 |
| H | 14°27.87'S | 150°42.58'E | October 2026; December 2026 – April 2027 |
| E | 10°31.87'S | 141°53.40'E | November 2026 |
| D | 10°49.73'S | 137°22.87'E | November – December 2026 |
| G | 19°16.33'S | 147°03.52'E | January – March 2027 |




The vessel will display appropriate lights and shapes and will monitor VHF Ch 16.

Mariners are advised to navigate with caution in the area and keep well clear.


*Note:* For e-notice users, please see full edition for map.

**Chart temporarily affected - Aus 256 - Aus 292 - Aus 293 - Aus 296 - Aus 299 - Aus 301 - Aus 306 - Aus 377 - Aus 615 - Aus 617 - Aus 700 - Aus 826 - Aus 827 - Aus 828 - Aus 837 - Aus 839 - Aus 841 - Aus 842 - Aus 4060 (INT 60) - Aus 4602 (INT 602) - Aus 4603 (INT 603) - Aus 4604 (INT 604)**

**864(T)/2026 AUSTRALIA - QUEENSLAND - NORTHERN TERRITORY - Townsville to Darwin - Survey operations**
EGS Survey Pty Ltd

Vessel *PMG Emerald*, with a 1000m towed array, is conducting geophysical and geotechnical survey operations as follows:

| POINT | LATITUDE | LONGITUDE | APPROX. MONTHS OPERATING |
|---|---|---|---|
| F | 10°53.57'S | 145°13.36'E | October – November 2026 |
| E | 10°31.87'S | 141°53.40'E | October – November 2026 |
| G | 19°16.33'S | 147°03.52'E | October 2026; February 2027 |
| D | 10°49.73'S | 137°22.87'E | November 2026; January 2027 |
| C | 9°30.00'S | 133°30.00'E | November 2026 – January 2027 |
| B | 11°56.71'S | 130°02.13'E | December 2026 – January 2027 |
| A | 12°26.38'S | 130°49.67'E | January 2027 |
| J | 13°11.32'S | 140°03.33'E | January 2027 |
| K | 14°36.39'S | 140°39.61'E | January 2027 |
| L | 17°27.50'S | 140°49.80'E | January – February 2027 |




The vessel will display appropriate lights and shapes and will monitor VHF Ch 16.

Mariners are advised to navigate with caution in the area and keep well clear.

*Note:* For e-notice users, please see full edition for map.

**Chart temporarily affected - Aus 6 - Aus 21 - Aus 25 - Aus 292 - Aus 293 - Aus 296 - Aus 299 - Aus 301 - Aus 302 - Aus 303 - Aus 306 - Aus 309 - Aus 316 - Aus 377 - Aus 700 - Aus 714 - Aus 721 - Aus 837 - Aus 839 - Aus 841 - Aus 842 - Aus 4060 (INT 60) - Aus 4603 (INT 603)**

**907(T)/2026 AUSTRALIA - QUEENSLAND - Gladstone - Pelican Banks - North Channel - Scientific instrument**
Maritime Safety Queensland Notice 518(T)/2026

On or about 26 October 2026, a special light buoy, *Fl.Y.4·5s*, will be deployed in position 23° 46'.97 S 151° 18'.38 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 245**

**909(T)/2026 AUSTRALIA - QUEENSLAND - Hay Point - Mooring buoy**
Maritime Safety Queensland Notice 528(T)/2026

A tug mooring exists in position 21° 18'.42 S 149° 18'.27 E.

Mariners are advised to navigate with caution in the area

**Chart temporarily affected - Aus 249 - Aus 823**

**910(T)/2026 AUSTRALIA - QUEENSLAND - Weipa - Cora Bank - Scientific instrument**
Maritime Safety Queensland Notice 531(T)/2026

A special light buoy, *Fl(5)Y.20s,* exists in position 12° 40'.72 S 141° 52'.15 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4**

**941(T)/2026 AUSTRALIA - QUEENSLAND - Great Sandy Strait - Scientific instruments**
*Former Notice* - 59(T)/2026 is cancelled
Maritime Safety Queensland Notice 578(T)/2026

Special light buoys exists as follows:

| *Position* | *Remarks* |
|---|---|
| 25° 16'.21 S 152° 51'.07 E | *Fl.Y.2·5s* |
| 25° 16'.81 S 152° 51'.23 E | *Fl.Y.2·5s* |
| 25° 07'.37 S 152° 47'.99 E | *Fl(5)Y.20s.* |

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 817**

**942(T)/2026 AUSTRALIA - QUEENSLAND - Moreton Bay - Scientific instruments**
Maritime Safety Queensland Notice 560(T)/2026

A special light buoy, *Fl.Y.2s*, exists in position 27° 10'.04 S 153° 18'.93 E.

Subsurface scientific instruments exist in positions 27° 20'.41 S 153° 14'.12 E and 27° 22'.12 S 153° 21'.66 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 236**

**945(T)/2026 AUSTRALIA - QUEENSLAND - Port Musgrave - Wreck**
Maritime Safety Queensland Notice 551(T)/2026

A stranded wreck marked by a special light buoy, *Fl.Y.4s,* exists in position 11° 54'.82 S 141° 54'.22 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 301**

**984(T)/2026 AUSTRALIA - QUEENSLAND - Airlie Beach - Wreck**
Maritime Safety Queensland Notice 597(T)/2026

A stranded wreck marked by a special light buoy, *Fl.Y.3s,* exists in position 20° 15'.46 S 148° 42'.40 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 252 - Aus 253**

**985(T)/2026 AUSTRALIA - QUEENSLAND - Gladys Inlet - Light buoy repositioned**
*Former Notice* - 108(T)/2026 is cancelled
Maritime Safety Queensland Notice 438(T)/2026

The port lateral light buoy, *Fl.R.3s* (17° 30'.43 S 146° 04'.87 E), has been temporarily repositioned to 17° 30'.37 S 146° 04'.77 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 258**

**986(T)/2026 AUSTRALIA - QUEENSLAND - Laguna Quays - Lights unlit**
Maritime Safety Queensland Notice 569(T)/2026

The lights, *VQ.R No8* (20° 36'.15 S 148° 40'.99 E), *Q.R No10* (20° 36'.23 S 148° 41'.02 E) and *Q.R No12* (20° 36'.26 S 148° 40'.92 E), are unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 252**

**989(T)/2026 AUSTRALIA - TORRES STRAIT - Turu Cay - Wreck**
Australian Hydrographic Office

A wreck with least depth, *9m*, exists in position 9° 49'.85 S 141° 25'.87 E.

**Chart temporarily affected - Aus 842**

## NORTHERN TERRITORY

**183(T)/2022 INDIAN OCEAN - Christmas Island - Mooring buoy off station**
L Miocevich

The mooring buoy (10° 25'.92 S 105° 39'.5 E) is off station and is currently in position 10° 26'.48 S 105° 39'.45 E.

**Chart temporarily affected - Aus 920**

**904(T)/2023 INDIAN OCEAN - Cocos Islands - Light buoy**
LINX

A special light buoy, *FlY.2·5s*, exists in position 12° 08'.65 S 96° 51'.95 E.

**Chart temporarily affected - Aus 607**

**532(T)/2024 AUSTRALIA - NORTHERN TERRITORY - Apsley Strait - Medina Inlet - Light buoys off station**
*Former Notice* - 293(T)/2024 is cancelled
Northern Territory Government Notice 11(T)/2024

The following light buoys are off station:

| *Position* | *Remarks* |
|---|---|
| 11° 45'.85 S 130° 39'.80 E | *Fl.R.4s* |
| 11° 46'.36 S 130° 39'.99 E | *Fl.R.4s* |
| 11° 51'.65 S 130° 35'.07 E | *Fl.G.4s.* |

**Chart temporarily affected - Aus 23**

**909(T)/2024 AUSTRALIA - NORTHERN TERRITORY - Bathurst Island - Tide gauges; buoys westwards**
*Former Notice* - 874(T)/2024 is cancelled
MMA Offshore , Tidewater Offshore Operations

Post hydrographic survey, subsurface tide gauges and buoys may exist in the vicinity of the following positions:
10° 58'.5 S 129° 00'.0 E
10° 58'.4 S 129° 11'.7 E
10° 57'.7 S 129° 23'.5 E
11° 10'.1 S 129° 00'.3 E
11° 08'.1 S 129° 12'.4 E
11° 06'.3 S 129° 31'.2 E
11° 21'.7 S 129° 03'.9 E
11° 18'.6 S 129° 15'.2 E
11° 15'.9 S 129° 24'.5 E
11° 11'.8 S 129° 44'.0 E
11° 24'.4 S 129° 35'.6 E
11° 23'.0 S 129° 47'.7 E
11° 35'.7 S 129° 42'.8 E
11° 33'.6 S 129° 52'.5 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 309 - Aus 310 - Aus 311**

**39(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Fish Reef - Light unlit**
Northern Territory Government Notice 23(T)/2024

The light, *LFl.WR.10s 10/8M* (12° 25'.93 S 130° 26'.56 E), is unlit.

**Chart temporarily affected - Aus 309 - Aus 316**

**40(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Orontes Reef - Obstruction**
Northern Territory Government Notice 2(T)/2025

A ghost net exists in position 11° 02'.88 S 132° 04'.94 E. An electronic beacon has been attached to the ghost net.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 18 - Aus 721**

**448(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Lynedoch Bank - Light buoy northwestwards**
Santos

A special light buoy, *Fl.Y*, exists in position 9° 49'.28 S 130° 16'.17 E.

**Chart temporarily affected - Aus 310**

**491(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Darwin - Harbour works; dredging operations**
*Former Notice* - 447(T)/2025 is cancelled
Northern Territory Government Notice 57/2025

A closed waters area marked by special buoys for dredging and harbour works has been established in the vicinity of position 12° 29'.50 S 130° 53'.75 E.

Entry into or transit through closed waters is prohibited to all vessels except those authorised.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 26**

**667(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Darwin - Dredging operations**
Northern Territory Government Notice 83(T)/2025

Dredge Ngurunderi and support vessels are conducting dredging operations in the vicinity of position 12° 30'.06 S 130° 53'.64 E.

A submerged pipeline marked by special light buoys, *Q.Y*, and a lit floating pontoon exist between the dredge and position 12° 29'.40 S 130° 53'.52 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 26**

**668(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Emu Reefs - Obstruction**
Northern Territory Government Notice 26/2025

A ghost net exists in position 13° 47'.70 S 129° 27'.54 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 316**

**669(T)/2025 AUSTRALIA - TIMOR SEA - Margaret Harries Banks - Survey operations**
Revelare Hydrospatial

Survey vessel *7-Oceans* is conducting survey operations in an area bounded by the following positions:
10° 24'.23 S 128° 37'.84 E
10° 16'.32 S 128° 50'.52 E
10° 34'.47 S 129° 02'.39 E
11° 02'.06 S 128° 19'.80 E
11° 17'.04 S 128° 15'.48 E
11° 10'.16 S 127° 40'.58 E
11° 03'.71 S 127° 39'.06 E
10° 28'.89 S 128° 12'.45 E
10° 16'.64 S 128° 32'.95 E.

Tide gauges marked by special light buoys, *Fl.Y.1·5s*, exist in the following positions:
11° 07'.3 S 127° 36'.3 E
10° 53'.6 S 127° 50'.3 E
10° 45'.3 S 127° 59'.7 E
10° 31'.5 S 128° 12'.0 E
10° 22'.7 S 128° 27'.3 E

10° 08'.1 S 128° 50'.3 E
10° 19'.6 S 128° 57'.0 E
10° 32'.0 S 128° 39'.7 E
10° 43'.0 S 128° 23'.5 E
10° 53'.1 S 128° 11'.9 E
11° 02'.3 S 128° 01'.3 E
11° 15'.6 S 127° 49'.0 E
11° 21'.7 S 128° 05'.8 E
11° 12'.2 S 128° 20'.0 E
11° 00'.8 S 128° 24'.2 E
10° 51'.4 S 128° 38'.4 E
10° 44'.0 S 128° 50'.1 E
10° 35'.7 S 129° 03'.7 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 309 - Aus 310 - Aus 311 - Aus 315**

**753(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Darwin - Light buoy removed**
Northern Territory Government

The west cardinal light buoy, *Q(9)15s* (12° 30'.14 S 130° 53'.68 E), has been temporarily removed.

**Chart temporarily affected - Aus 26**

**877(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Charles Point - Obstruction northeastwards**
Northern Territory Government Notice 36/2025

A ghost net exists in position 12° 21'.58 S 130° 37'.66 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 25**

**913(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Darwin - Scientific instruments**
*Former Notice* - 680(T)/2024 is cancelled
Northern Territory Government Notice 69(T)/2024

Special light buoys, *Fl.Y.1·5s*, exist in the following positions:
12° 29'.50 S 130° 53'.75 E
12° 29'.67 S 130° 53'.80 E
12° 29'.67 S 130° 54'.15 E
12° 29'.42 S 130° 54'.14 E.

**Chart temporarily affected - Aus 26**

**914(P)/2025 AUSTRALIA - NORTHERN TERRITORY - Goulburn Islands - Shoaling**
Cyan Renewables

Latest survey indicates shoaler depths than those charted exist in the vicinity of Sand Point (11° 33'.05 S 133° 22'.77 E) and Ngurrgu Point (11° 34'.68 S 133° 24'.59 E).

Mariners are advised to navigate with caution in the area.

**Chart which will be affected - Aus 719**

**996(T)/2025 AUSTRALIA - NORTHERN TERRITORY - Darwin - Scientific instruments**
*Former Notice* - 910(T)/2024 is cancelled
Northern Territory Government Notice 116(T)/2025

Special light buoys, *Fl.Y.4s*, exist in the following positions:
12° 29'.26 S 130° 47'.99 E
12° 32'.91 S 130° 52'.50 E
12° 30'.09 S 130° 52'.48 E
12° 29'.72 S 130° 52'.96 E.

**Chart temporarily affected - Aus 25 - Aus 26**

**1037(T)/2025 AUSTRALIA - TIMOR SEA - Sahul Banks - Subsea operations**
Department of Industry, Science and Resources

On or about 18 December 2025, works associated with the decommissioned FPSO *Northern Endeavour* (10° 36'.89 S 125° 59'.13 E) involving removal of buoyancy modules will take place.

Mariners should navigate with caution in the area.

**Chart temporarily affected - Aus 312**

**20(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Cuthbert Point - Tide gauges; light buoys northeastwards**
Cyan Renewables

Tide gauges, 1m above the seabed, marked by special light buoys exist in positions 11° 37'.18 S 133° 56'.54 E and 11° 37'.16 S 133° 56'.66 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 718 - Aus 719**

**153(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Groote Eylandt - Bartalumba Bay to Milner Bay - Mooring buoys**
*Former Notice* - 111(T)/2026 is cancelled
Northern Territory Government Notice 33(T)/2025, 35(T)/2025, 3(T)/2026, 4(T)/2026

Daytime mooring buoys, *Fl.Y.3s*, exist in the following positions:
13° 48'.44 S 136° 28'.87 E
13° 48'.35 S 136° 28'.38 E
13° 48'.07 S 136° 28'.04 E
13° 48'.15 S 136° 27'.14 E
13° 48'.56 S 136° 27'.58 E
13° 48'.77 S 136° 27'.80 E
13° 48'.89 S 136° 28'.27 E.

Daytime mooring buoys, *Fl.Y.5s*, exist in positions 13° 51'.08 S 136° 24'.57 E and 13° 51'.19 S 136° 24'.66 E.

**Chart temporarily affected - Aus 14**

**205(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Groote Eylandt - Milner Bay - Mooring buoys**
Northern Territory Government Notice 6(T)/2026, 7(T)/2026

Private lit mooring buoys, for GEMCO contractors only, exist as follows:

| *Position* | *Remarks* |
|---|---|
| 13° 51'.29 S 136° 24'.79 E | *Fl.Y.3s* |
| 13° 51'.36 S 136° 24'.81 E | *Fl.Y.3s* |
| 13° 51'.65 S 136° 25'.03 E | *Q.* |

**Chart temporarily affected - Aus 14**

**207(T)/2026 AUSTRALIA - TIMOR SEA - Flat Top Bank - Scientific instruments southwards**
RPS Group

Special light buoys, *Q(5)Y.20s*, exist in positions 12° 48'.07 S 128° 40'.13 E and 12° 49'.15 S 128° 40'.14 E.

A subsurface scientific instrument, 10m below the surface, exists in position 12° 48'.61 S 128° 40'.15 E.

Subsurface scientific instruments, 20m above the seabed, exist in the following positions:
12° 39'.70 S 129° 00'.18 E
12° 34'.47 S 129° 18'.18 E
12° 29'.86 S 129° 29'.14 E
12° 24'.61 S 129° 48'.55 E.

**Chart temporarily affected - Aus 309 - Aus 315 - Aus 316**

**481(T)/2026 AUSTRALIA - TIMOR SEA - Margaret Harries Banks to Evans Shoal - Survey operations; tide gauges**
Revelare Hydrospatial

Survey vessel *7-Oceans* is conducting survey operations in an area bounded by the following positions:
10° 08'.69 S 128° 45'.60 E
9° 58'.78 S 129° 01'.45 E
9° 45'.00 S 129° 30'.00 E
9° 39'.00 S 130° 06'.00 E
9° 39'.72 S 130° 10'.44 E
10° 14'.81 S 129° 50'.96 E
10° 32'.63 S 129° 27'.14 E
10° 32'.73 S 129° 13'.62 E
10° 26'.96 S 128° 57'.20 E.

Tide gauges marked by special light buoys, *Fl.Y.1·5s*, exist in the following positions:
9° 54'.9 S 129° 33'.5 E
9° 58'.1 S 129° 45'.7 E
9° 59'.6 S 129° 56'.5 E
10° 17'.9 S 129° 51'.3 E
10° 18'.8 S 129° 44'.3 E
10° 19'.1 S 129° 32'.2 E
10° 19'.1 S 129° 19'.1 E
10° 33'.5 S 129° 27'.6 E
10° 33'.9 S 129° 12'.8 E
10° 23'.1 S 129° 05'.9 E
10° 29'.8 S 128° 55'.4 E
10° 11'.1 S 128° 45'.6 E
10° 11'.1 S 129° 01'.0 E
9° 59'.4 S 129° 02'.4 E
9° 52'.4 S 129° 18'.7 E
10° 02'.8 S 129° 16'.9 E
10° 08'.0 S 129° 32'.1 E
10° 08'.0 S 129° 41'.3 E
10° 37'.8 S 129° 27'.9 E
10° 16'.1 S 129° 09'.4 E
10° 10'.9 S 129° 36'.9 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 310 - Aus 311**

**482(T)/2026 AUSTRALIA - TIMOR SEA - The Boxers - Tide gauges westwards**
Reach Subsea

Tide gauges marked by special light buoys, *Fl.Y.5s*, exist in positions 11° 23'.20 S 127° 51'.30 E and 11° 19'.60 S 127° 21'.20 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 311 - Aus 315**

**597(T)/2026 AUSTRALIA - TIMOR SEA - Sahul Banks - Scientific instruments eastwards**
Cyan Renewables

Scientific instruments marked by special light buoys, *Fl(5)Y.20s*, exist in the following positions:
11° 57'.91 S 125° 36'.14 E
11° 44'.95 S 126° 18'.92 E
11° 35'.34 S 126° 54'.83 E
11° 24'.83 S 127° 35'.18 E.

**Chart temporarily affected - Aus 311 - Aus 314 - Aus 315**

**774(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Apsley Strait - Saint Asaph Bay - Obstruction**
Australian Hydrographic Office

A lost anchor and cable exists in the vicinity of position 11° 19'.10 S 130° 22'.92 E.

Mariners are advised to navigate with caution and to avoid anchoring or trawling in the area.

**Chart temporarily affected - Aus 22**

**775(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Beagle Gulf - Fenton Patches - Fish aggregating devices**
*Former Notice* - 62(T)/2026 is cancelled
Northern Territory Government Notice 1(T)/2026, Australian Border Force

Special light buoys, *Q(4)Y.19s FAD*, exist in the following positions:
12° 06'.67 S 130° 34'.13 E
12° 08'.93 S 130° 44'.83 E
12° 09'.50 S 130° 44'.83 E
12° 10'.30 S 130° 38'.50 E.

**Chart temporarily affected - Aus 309**

**778(T)/2026 AUSTRALIA - TIMOR SEA - The Boxers - Survey operations westwards**
Reach Subsea

Survey vessel *Offshore Surveyor* and USV *Reach Remote 2* are conducting survey operations in an area bounded by the following positions:
11° 12'.66 S 127° 04'.60 E
11° 04'.66 S 127° 39'.52 E
11° 16'.25 S 128° 13'.48 E
11° 35'.13 S 127° 55'.54 E
11° 51'.28 S 127° 14'.36 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 309 - Aus 311 - Aus 312 - Aus 315**

**868(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Skirmish Point to Turner Point - Survey operations; tide gauges northwards**
*Former Notice* - 692(T)/2026 is cancelled
Cyan Renewables

Survey operations are in progress in an area bounded by the following positions:
12° 01'.0 S 134° 19'.0 E
11° 10'.0 S 134° 20'.0 E
11° 10'.0 S 133° 34'.0 E
11° 39'.0 S 133° 32'.0 E.

Tide gauges marked by light buoys, *Fl*, exist in the following positions:
11° 20'.0 S 133° 45'.5 E
11° 28'.3 S 134° 10'.8 E
11° 35'.3 S 133° 35'.8 E
11° 40'.6 S 133° 46'.7 E
11° 41'.5 S 134° 18'.2 E
11° 43'.7 S 133° 57'.6 E
11° 50'.6 S 134° 12'.5 E
11° 50'.7 S 134° 04'.9 E
11° 58'.4 S 134° 12'.2 E
11° 54'.6 S 134° 18'.2 E.

Mariners are advised to navigate with caution in the area. 0.5M clearance requested.

**Chart temporarily affected - Aus 17 - Aus 718 - Aus 719**

**914(T)/2026 AUSTRALIA - TIMOR SEA - Sahul Banks - Survey operations**
*Former Notice* - 596(T)/2026 is cancelled
EGS Survey Pty Ltd

Survey vessels MV *Shark 01*, USV *FM01* and USV *FM02* are conducting survey operations in an area bounded by the following positions:
11° 51'.20 S 125° 05'.00 E
11° 30'.83 S 126° 01'.00 E
12° 22'.00 S 126° 01'.00 E

12° 22'.00 S 125° 05'.00 E.

Tide gauges marked by special light buoys, *Fl.Y.1·5s*, exist in the following positions:
11° 46'.8 S 125° 48'.9 E
12° 08'.8 S 125° 23'.1 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 314 - Aus 315 - Aus 319**

**947(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Darwin - Survey operations**
Northern Territory Government Notice 94(T)/2026

Vessel *Wai Nawana*, with a 200m towed array, is conducting hydrographic and geophysical survey operations between the following positions:
12° 26'.45 S 130° 49.93 E
12° 26'.27 S 130° 47.09 E
12° 20'.46 S 130° 42.26 E
12° 19'.02 S 130° 40.30 E.

The vessel will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area and keep well clear.

**Chart temporarily affected - Aus 25 - Aus 26 - Aus 309**

**991(T)/2026 AUSTRALIA - NORTHERN TERRITORY - Hall Point - Wreck northeastwards**
Australian Hydrographic Office

A wreck with least depth, $12_6m$, exists in position 11° 38'.98 S 134° 02'.54 E.

**Chart temporarily affected - Aus 718**

## WESTERN AUSTRALIA

**1078(P)/2015 AUSTRALIA - WESTERN AUSTRALIA - East Holothuria Reef - Shoaling**
HMAS Mermaid

Depths less than 6m have been reported in the vicinity of position 13º 33'.6 S 126º 10'.8 E.

Mariners are advised to navigate with caution in the area.

**Chart which will be affected - Aus 318 - Aus 319 - Aus 727 - Aus 728**

**291(T)/2019 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Well abandonment works northwestwards**
Chevron Australia

Sixteen anchors and mooring lines have been installed around the well in position 20° 24'.49 S 114° 50'.95 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 328**

**212(T)/2020 AUSTRALIA - WESTERN AUSTRALIA - Rottnest Island - Scientific instruments northwestwards**
CSIRO

Subsurface scientific instruments exist as follows:

| *Position* | *Depth below surface* |
|---|---|
| 31° 38'.8 S 115° 11'.8 E | 24m |
| 31° 43'.7 S 115° 02'.5 E | 23m |
| 31° 45'.9 S 114° 57'.9 E | 496m |
| 31° 59'.0 S 115° 13'.7 E | 180m |
| 31° 59'.4 S 115° 23'.1 E | 22m |
| 32° 00'.0 S 115° 25'.0 E | 46m |

**Chart temporarily affected - Aus 754**

**1032(T)/2022 AUSTRALIA - WESTERN AUSTRALIA - Geographe Bay - Scientific instruments**
*Former Notice* - 800(T)/2022 is cancelled
Department of Transport WA Notice 2792/2022

Special light buoys, *Fl.Y.2·5s,* exist in the following positions:
33° 35'.49 S 115° 06'.99 E
33° 36'.01 S 115° 14'.99 E
33° 37'.62 S 115° 20'.28 E.

**Chart temporarily affected - Aus 755**

**1036(T)/2022 AUSTRALIA - WESTERN AUSTRALIA - Mullaloo - Scientific instruments**
Department of Transport WA Notice 5463/2022

Scientific instruments, 4m below the surface, exist in positions 31° 45'.82 S 115° 42'.64 E and 31° 47'.43 S 115° 42'.34 E.

**Chart temporarily affected - Aus 754**

**293(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipeligo - Legendre Island - Scientific instrument northwards**
*Former Notice* - 366(T)/2022 is cancelled
O2 Marine

A scientific instrument exists on the seabed in position 20° 17'.89 S 116° 51'.58 E.

**Chart temporarily affected - Aus 57 - Aus 327**

**367(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Gantheaume Bay - Scientific instrument northwestwards**
GHD

A subsurface scientific instrument, 0.5m above the seabed, exists in position 27° 26.89' S 113° 56.97' E.

**Chart temporarily affected - Aus 332**

**535(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Bonaparte Archipelago - Bernouilli Island - Obstruction**
Australian Maritime Safety Authority

An obstruction has been reported in position 14° 59'.56 S 124° 45'.49 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 730**

**630(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Torbay to King George Sound - Scientific instruments**
Department of Transport WA Notice 5742/2023

Scientific instruments marked by special light buoys, *Fl.Y.3s*, exist in the following positions:
35° 04'.92 S 117° 49'.18 E
35° 05'.38 S 117° 57'.75 E
35° 05'.45 S 117° 57'.76 E.

**Chart temporarily affected - Aus 118**

**767(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Carnarvon - Obstructions**
Department of Transport WA Notice 5769/2023

Pylons, 30cm below the surface, exist in the vicinity of position 24° 54'.35 S 113° 38'.61 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 73**

**774(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Rottnest Island - Thomson Bay - Rock**
Department of Transport WA Notice 5796/2023

A rock outcrop has been reported in position 31° 59'.82 S 115° 32'.64 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 112**

**820(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Browse Island - Light altered northwestwards**
Australian Maritime Safety Authority Auscoast Warning 213/2023

The light, *Mo(U)15s 15M* (13° 56'.37 S 123° 17'.87 E), has been temporarily altered to *Mo(U)15s 10M.*

**Chart temporarily affected - Aus 319 - Aus 320 - Aus 4603 (INT 603) - Aus 4722 (INT 722)**

**822(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Mermaid Sound - Scientific instrument**
Pilbara Ports Authority Notice D23(T)/2023

A special light buoy, *Fl(5)Y.20s*, exists in position 20° 30'.81 S 116° 45'.56 E.

**Chart temporarily affected - Aus 57**

**1065(T)/2023 AUSTRALIA - WESTERN AUSTRALIA - Fremantle - Arthur Head - Scientific instrument**
Department of Transport WA Notice 5895/2023

A subsurface scientific instrument, 5.5m below the surface, exists in positions 32° 03'.31 S 115° 44'.16 E.

**Chart temporarily affected - Aus 112 - Aus 117**

**25(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Brigadier Islands - Light buoy northwards**

MetOcean

A special light buoy, *Fl(5)Y.20s,* exists in position 20° 16'.78 S 116° 33'.71 E.

**Chart temporarily affected - Aus 327 - Aus 742**

**31(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Laurance Reef to Quinns Rocks - Scientific instruments**

Department of Transport WA Notice 5902/2023

Special light buoys, *Fl.Y.2·5s*, exist in the following positions:
31° 39'.60 S 115° 39'.88 E
31° 40'.63 S 115° 40'.24 E
31° 33'.28 S 115° 37'.30 E.

**Chart temporarily affected - Aus 754**

**33(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Norwegian Bay - Beacon obscured**

Department of Transport WA Notice 5805/2023

The rear leading beacon is obscured and currently not visible.

The recommended track may no longer indicate the best passage through the reef.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 745**

**70(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Cockburn Sound - Medina Channel - Light beacon destroyed**

Fremantle Ports Notice 15/2023

The port lateral light beacon, *Fl.R.2s C* (32° 09'.90 S 115° 45'.51 E), has been destroyed; a port lateral light buoy, *Fl.R.2s*, exists in situ.

**Chart temporarily affected - Aus 117**

**167(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Rottnest Island - Point Clune - Scientific instrument northwards**

MMA Offshore

A special light buoy, *Fl.Y,* exists in position 31° 57'.072 S 115° 31'.62 E.

**Chart temporarily affected - Aus 112 - Aus 754**

**223(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Bateman Bay to Bills Bay - Scientific instruments**

Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 23° 02'.58 S 113° 47'.45 E | 4.9 |
| 23° 02'.86 S 113° 47'.16 E | 14.6 |
| 23° 02'.88 S 113° 49'.06 E | 13 |
| 23° 02'.89 S 113° 47'.53 E | 17.2 |
| 23° 02'.89 S 113° 47'.91 E | 18.1 |
| 23° 02'.89 S 113° 48'.28 E | 14.2 |
| 23° 02'.89 S 113° 48'.67 E | 17.1 |
| 23° 05'.09 S 113° 48'.53 E | 8.7 |
| 23° 07'.27 S 113° 45'.09 E | 3 |
| 23° 07'.28 S 113° 45'.43 E | 7 |
| 23° 07'.42 S 113° 41'.37 E | 66 |
| 23° 07'.45 S 113° 41'.83 E | 66 |
| 23° 07'.48 S 113° 44'.95 E | 3 |
| 23° 07'.50 S 113° 42'.28 E | 64 |
| 23° 07'.57 S 113° 42'.72 E | 60 |
| 23° 07'.61 S 113° 43'.58 E | 42 |
| 23° 07'.62 S 113° 43'.15 E | 52 |

| | |
|---|---|
| 23° 07'.64 S 113° 44'.08 E | 30 |
| 23° 07'.64 S 113° 46'.13 E | 2 |
| 23° 08'.15 S 113° 45'.22 E | 8. |

**Chart temporarily affected - Aus 745 - Aus 746**

**224(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Cape Range - Tantabiddi - Scientific instruments**
Sydney Institute of Marine Science

Subsurface scientific instruments exist as follows:

| *Position* | *Metres below surface* |
|---|---|
| 21° 52'.83 S 113° 54'.33 E | 86 |
| 21° 53'.03 S 113° 54'.67 E | 84 |
| 21° 53'.31 S 113° 55'.03 E | 75 |
| 21° 53'.46 S 113° 55'.44 E | 57 |
| 21° 53'.71 S 113° 55'.79 E | 36. |

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 745**

**265(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island - Obstruction**
Chevron Australia

An obstruction, 15m below the surface, exists in position 21° 24'.17 S 115° 02'.81 E.

**Chart temporarily affected - Aus 64 - Aus 328 - Aus 743**

**297(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Cape Naturaliste - Scientific instrument northwestwards**
*Former Notice* - 821(T)/2023 is cancelled
JASCO Applied Sciences (Australia)

A subsurface scientific instrument, 5m above the seabed, exists in position 33° 20'.07 S 114° 46'.94 E.

**Chart temporarily affected - Aus 335**

**493(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Mooring buoy unlit northwards**
Vermilion Oil and Gas Australia

Lit mooring buoy, *Mo(U)Y.15s* (20° 06'.9 S 116° 26'.0 E), is unlit.

**Chart temporarily affected - Aus 327 - Aus 742**

**620(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Princess Royal Harbour - Marine farm; light buoys**
*Former Notice* - 111(T)/2023 is cancelled
Department of Transport WA Notice 6130/2024

A marine farm marked by special light buoys, *Fl.Y.4s*, exists in an area bounded by the following positions:
35° 04'.22 S 117° 54'.51 E
35° 04'.22 S 117° 54'.61 E
35° 04'.21 S 117° 54'.61 E
35° 04'.21 S 117° 55'.00 E
35° 04'.09 S 117° 55'.00 E
35° 04'.09 S 117° 55'.20 E
35° 04'.36 S 117° 55'.20 E
35° 04'.36 S 117° 55'.14 E
35° 04'.48 S 117° 55'.14 E
35° 04'.48 S 117° 54'.51 E.

**Chart temporarily affected - Aus 118**

**621(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Wilson Head - Scientific instruments**
*Former Notice* - 631(T)/2023 is cancelled
Department of Transport WA Notice 5793/2024

Two special light buoys, *Fl.Y.2·5s,* exist in the vicinity of position 35° 02'.93 S 117° 21'.82 E.

**Chart temporarily affected - Aus 336**

**918(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Light unlit; light established**
*Former Notice* - 655(T)/2024 is cancelled
Australian Maritime Safety Authority Auscoast Warning 216/2024, Preliminary ATH 22/2024

The light, *Fl.10s 129m 21M* (21° 48'.37 S 114° 09'.61 E), is unlit.

A temporary light, *Fl.10s 95m 19M (Obscd 172·5° - 202·5° (030°))*, exists in position 21° 49'.22 S 114° 06'.06 E.

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 744 - Aus 745 - Aus 4060 (INT 60) - Aus 4070 (INT 70) - Aus 4071 (INT 71) - Aus 4708 (INT 708) - Aus 4723 (INT 723)**

**988(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Fremantle - Deepwater Channel - Scientific instrument**
*Former Notice* - 1023(T)/2023 is cancelled
Department of Transport WA

A special light buoy, *Fl(5)Y.20s*, exists in position 31° 58'.78 S 115° 41'.38 E.

**Chart temporarily affected - Aus 112**

**990(T)/2024 AUSTRALIA - WESTERN AUSTRALIA - Houtman Abrolhos - Zeewijk Channel - Fish aggregating device**
Department of Primary Industries and Regional Development WA

A special light buoy, *Fl.Y.5s FAD (Oct-Apr)*, exists in position 28° 52'.74 S 113° 42'.37 E.

**Chart temporarily affected - Aus 332**

**999(P)/2024 AUSTRALIA - WESTERN AUSTRALIA - Port Walcott - Shoaling**
*Former Notice* - 789(P)/2024 is cancelled
Discovery Marine

Latest survey indicates shoaler depths than those charted may exist in an area bounded by the following positions:
20° 29'.89 S 117° 25'.65E
20° 29'.89 S 117° 27'.02E
20° 27'.96 S 117° 27'.02E
20° 27'.96 S 117° 25'.65E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 55 - Aus 326**

**55(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Rottnest Island - Phillip Rock - Entry prohibited**
Department of Transport WA Notice 6302/2025

Entry is prohibited within a 200m radius of position 31° 59'.83 S 115° 33'.78 E.

Only government vessels and those associated with a coordinated response on site are permitted to enter the area.

Mariners area advised to navigate with caution in the area.

**Chart temporarily affected - Aus 112**

**105(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Hilarys Boat Harbour - Scientific instrument westwards**
University of Western Australia

A special light buoy, *Fl.Y.2·5s*, exists in position 31° 50'.72 S 115° 38'.78 E.

**Chart temporarily affected - Aus 754**

**179(P)/2025 AUSTRALIA - WESTERN AUSTRALIA - Dampier - West Lewis Island - Obstruction**
Go Offshore

An obstruction on the sea floor has been reported in the vicinity of position 20° 36'.27 S 116° 35'.13 E.

Mariners should navigate with caution in the area.

**Chart which will be affected - Aus 57**

**181(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Exmouth - Scientific instruments**
*Former Notice* - 46(T)/2025 is cancelled
Department of Transport WA Notice 6268/2024

Scientific instruments, 5m below the surface, exist in the following positions:
21° 55'.56 S 114° 08'.88 E
21° 57'.66 S 114° 08'.82 E
21° 58'.02 S 114° 08'.76 E
21° 59'.04 S 114° 08'.46 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 744 - Aus 745**

**218(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Barracouta Shoal - Well plug and abandonment works eastwards**
Jadestone Energy

On or about 8 March 2025, a drill rig will be conducting well plug and abandonment works in the vicinity of position 12° 30'.08 S 124° 25'.12 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 314 - Aus 319 - Aus 4722 (INT 722)**

**222(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Eugene McDermott Shoal to Exmouth Plateau - Cable laying operations**
Gulf Agency Company (Australia)

Vessel *Ile de Brehat* is conducting cable laying operations between positions 13° 26'.46 S 124° 34'.93 E and 12° 58'.13 S 124° 26'.68 E; and in the vicinity of position 19° 53'.09 S 113° 14'.03 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 319 - Aus 4722 (INT 722) - Aus 4723 (INT 723)**

**229(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Rottnest Island - Scientific instruments northwestwards**
JASCO Applied Sciences (Australia)

Subsurface scientific instruments, 2m above seabed, exist in positions 31° 52'.91 S 114° 56'.07 E and 31° 52'.85 S 115° 01'.14 E.

Mariners are advised to keep a 100m radius clearance around the instruments and to navigate with caution in the area.

**Chart temporarily affected - Aus 754**

**264(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Hilarys Boat Harbour - Scientific instrument westwards**
University of Western Australia

A special light buoy, *Fl.Y.2·5s*, exists in position 31° 50'.72 S 115° 38'.78 E.

**Chart temporarily affected - Aus 754 - Aus 4060 (INT 60) - Aus 4070 (INT 70) - Aus 4708 (INT 708) - Aus 4709 (INT 709)**

**341(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island - Subsea operations**
Chevron Australia

Diving and mooring removal activities are in progress in the following positions:
21° 38'.17 S 114° 55'.43 E

21° 26'.42 S 115° 03'.24 E
21° 24'.00 S 115° 02'.55 E
21° 24'.33 S 115° 02'.79 E
21° 24'.35 S 115° 02'.82 E
21° 24'.36 S 115° 02'.94 E
21° 24'.15 S 115° 03'.07 E
21° 24'.06 S 115° 03'.00 E
21° 24'.05 S 115° 02'.97 E
21° 24'.27 S 115° 02'.97 E
21° 24'.00 S 115° 02'.86 E
21° 24'.13 S 115° 02'.62 E.

Vessels will display appropriate lights and shapes and will monitor VHF Ch 14 and Ch 16.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 64 - Aus 328 - Aus 743 - Aus 744**

**415(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Cape Range - Tantabiddi - Light**
Department of Transport WA Notice 6420/2025

The front lead (21° 53'.99 S 113° 59'.19 E) has collapsed and should not be relied upon to indicate recommended track.

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 745**

**459(P)/2025 AUSTRALIA - WESTERN AUSTRALIA - Varanus Island - Shoaling**
Precision Hydrographic Services

Latest survey indicates shoaler depths than those charted may exist in an area bounded by the following positions:
20° 37'.35 S 115° 32'.83 E
20° 37'.36 S 115° 33'.71 E
20° 38'.00 S 115° 34'.60 E
20° 39'.70 S 115° 36'.69 E
20° 39'.87 S 115° 36'.16 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 65 - Aus 742**

**498(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Subsea operations northwards**
Fugro

On or about 25 June 2025, subsea operations will be conducted in the vicinity of positions 21° 17'.70 S 114° 08'.00 E and 21° 26'.70 S 114° 01'.70 E.

Mariners are advised to navigate with caution in the area. 2.5NM clearance requested.

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 744**

**560(P)/2025 AUSTRALIA - WESTERN AUSTRALIA - Hopetoun - Mason Bay - Shoaling**
Department of Transport WA

Latest survey indicates shoaler depths than those charted may exist in the vicinity of the following positions:
33° 57'.51 S 120° 29'.84 E
33° 57'.77 S 120° 06'.91 E

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 116 - Aus 337**

**673(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Harbour works**
Pilbara Ports Authority Notice D15/2025

Harbour works are in progress in an area bounded by the following positions:
20° 37'.06 S 116° 44'.87 E
20° 36'.90 S 116° 44'.87 E
20° 36'.90 S 116° 44'.93 E
20° 37'.06 S 116° 44'.93 E.

Entry into the area is prohibited unless authorised by the primary contractor, Clough. Any arrivals or departures from the area must be reported to Dampier VTS along with confirmation that permission has been obtained.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 57 - Aus 59**

**676(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Scientific instrument northwestwards**
Fugro

A special light buoy, *Fl(5)Y.20s*, exists in position 19° 51'.33 S 114° 35'.48 E.

**Chart temporarily affected - Aus 328**

**678(P)/2025 AUSTRALIA - WESTERN AUSTRALIA - Roebuck Bay - Shoaling westwards**
Australian Hydrographic Office

Latest survey indicates shoaler depths than those charted may exist in an area bounded by the following positions:
18° 11'.04 S 121° 55'.21 E
18° 10'.67 S 121° 52'.15 E
18° 01'.61 S 121° 55'.81 E
18° 02'.48 S 121° 57'.98 E.

Mariners are advised to navigate with caution in the area.

Products will be updated in due course.

**Chart which will be affected - Aus 50 - Aus 324**

**679(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island - Light buoy altered**
Department of Transport and Major Infrastructure WA

The east cardinal light buoy, *Q(3)10s* (21° 26'.40 S 115° 03'.46 E), has been temporarily altered to *Fl(3)15s 5M*.

**Chart temporarily affected - Aus 64 - Aus 743**

**715(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Geraldton - Scientific instruments**
Mid West Ports Notice 11/2025

Subsurface scientific instruments exist on the seabed in positions 28° 45'.67 S 114° 36'.21 E and 28° 46'.23 S 114° 36'.30 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 81**

**789(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Bandy Creek Boat Harbour - Light beacon destroyed**
*Former Notice* - 670(T)/2025 is cancelled
Department of Transport WA

The light beacon, *Fl.G.5s No1* (33° 50'.01 S 121° 55'.95 E), has been destroyed; a starboard lateral light buoy, *Fl.G.5s*, exists in situ.

**Chart temporarily affected - Aus 119**

**790(P)/2025 AUSTRALIA - WESTERN AUSTRALIA - Bandy Creek Boat Harbour - Shoaling**
Department of Transport WA

Latest survey indicates shoaler depths than those charted may exist in the vicinity of position 33° 55'.09 S 121° 55'.95 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 119**

**792(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Subsea operations northwards**
Santos

Subsea operations associated with the cessation of production activities are in progress between positions 20° 01'.45 S 116° 18'.58 E and 20° 24'.64 S 116° 20'.14 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 57 - Aus 327 - Aus 742**

**836(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Double Island - Light unlit**
Chevron Australia Notice 7/2025

The light, *Fl.6s 17m 5M* (20° 44'.14 S 115° 29'.72 E), is unlit.

**Chart temporarily affected - Aus 65 - Aus 327 - Aus 328 - Aus 742**

**920(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Exmouth Plateau - Survey operations; obstructions**
Woodside Energy Ltd

A large number of concrete pads have been placed on the seabed in the vicinity of 19°48'.97S, 113°12'.00E, to facilitate gravity meter survey operations. They pose no threat to surface navigation but mariners should be aware when conducting any subsurface activities.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4723 (INT 723)**

**949(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Bonaparte Archipelago - Cassini Island - Wreck**
Cape Byron

A dangerous wreck exists in position 13° 56'.22 S 125° 38'.39 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 728**

**953(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Goeree Shoal - Mooring buoy**
McDermott Australia

A lit mooring buoy, *Fl,* exists in position 12° 57'.00 S 124° 25'.68 E.

**Chart temporarily affected - Aus 319**

**998(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Town Point - Light beacons unreliable; light beacon unlit**
Chevron Australia Notice 10/2025, 11/2025

The starboard lateral light beacon, *Q.G* (20° 50'.23 S 115° 32'.18 E), and the port lateral light beacon, *Fl.R.3s* (20° 50'.60 S 115° 31'.92 E), are unreliable.

The special light beacon, *Fl.Y.3s* (20° 48'.72 S 115° 29'.72 E), is unlit.

**Chart temporarily affected - Aus 65 - Aus 742 - Aus 743**

**1040(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Broome - Obstruction westwards**
Reach Subsea

An obstruction with depth 12m exists in position 17° 53'.28 S 122° 04'.11 E.

**Chart temporarily affected - Aus 50**

**1041(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Hampton Harbour - Wreck**
*Former Notice* - 1000(T)/2025 is cancelled
Pilbara Ports Authority Notice D25(T)/2025

A stranded wreck marked by an isolated danger light buoy, *Fl(2)*, exists in position 20° 39'.95 S 116° 41'.58 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 57 - Aus 60**

**1043(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Kingfisher Islands - Survey operations**
*Former Notice* - 921(T)/2025 is cancelled
Reach Subsea

Vessel *Warrego* and unmanned survey vessel (USV) *Orca 1* are conducting survey operations in an area bounded by the following positions:
15° 55'.1 S 124° 00'.6 E
15° 57'.2 S 124° 19'.9 E
16° 03'.6 S 124° 26'.1 E
16° 09'.5 S 124° 20'.4 E
16° 14'.1 S 124° 03'.4 E
16° 15'.2 S 123° 53'.4 E
16° 22'.5 S 123° 59'.3 E
16° 16'.7 S 123° 49'.7 E
16° 11'.4 S 123° 50'.2 E
16° 09'.8 S 123° 47'.9 E.

Tide gauges marked by special light buoys, *Fl.Y.5s*, exist in the following positions:
16° 21.4' S 123° 57.4' E
16° 19.1' S 123° 55.0' E
16° 15.9' S 123° 50.9' E
16° 10.9' S 123° 52.3' E
16° 09.4' S 123° 47.8' E
16° 02.9' S 123° 48.0' E
16° 04.8 S 123° 56.9' E
16° 09.2' S 124° 02.9' E
16° 01.5' S 124° 01.8' E
15° 55.7' S 123° 59.2' E
16° 02.4' S 124° 09.4' E
16° 02.1' S 124° 17.5' E
15° 57.2' S 124° 19.9' E
16° 03.6' S 124° 26.1' E
16° 07.3' S 124° 20.4' E
16° 09.5' S 124° 20.4' E
16° 11.3' S 124° 12.9' E
16° 13.1' S 124° 07.5' E
16° 12.3' S 123° 59.6' E
16° 05.9' S 123° 54.1' E
16° 12.3' S 124° 04.0' E
16° 02.3' S 124° 04.0' E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 40 - Aus 732 - Aus 733**

**1048(P)/2025 AUSTRALIA - WESTERN AUSTRALIA - Success Bank - Shoaling**
Department of Transport WA

Latest survey indicates shoaler depths than those charted may exist in an area bounded by the following positions:
32° 06'.75 S 115° 38'.75 E
32° 06'.75 S 115° 41'.44 E
32° 03'.77 S 115° 41'.44 E
32° 03'.77 S 115° 38'.75 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 112 - Aus 117**

**1080(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Exmouth Plateau - Subsea operations**
Woodside Energy Ltd

Vessels are conducting subsea operations in the vicinity of position 19° 49'.0 S 113° 11'.0 E.

A 500m exclusion zone exists around vessels.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4723 (INT 723)**

**1082(T)/2025 AUSTRALIA - WESTERN AUSTRALIA - Geraldton - Scientific instruments**
Mid West Ports Notice 17/2025

Scientific instruments marked by special light buoys, *Fl.Y.3s*, exist on the seabed in positions 28° 46'.36 S 114° 36'.32 E and 28° 46'.21 S 114° 36'.48 E.

Mariners are requested to avoid anchoring, fishing or trawling in the vicinity.

**Chart temporarily affected - Aus 81**

**161(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Indian Ocean - Perth to Melbourne - Perth to Christmas Island - Cable laying operations**
Subcom

Cable laying operations will be conducted between Perth and Melbourne and Perth and Christmas Island. Cable lay and post lay inspection activities will occur along the route shown in the diagram and mariners are advised to keep clear of vessel, *CS Resolute* during activities. Further advice on specific areas of activity will be issued through the AUSCOAST warning system.

*Note:* For e-notice users, please see full edition for map.





**Chart temporarily affected - Aus 4708 (INT 708) - Aus 4709 (INT 709) - Aus 4710 (INT 710)**

**163(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Subsea operations northwestwards**
Monson Offshore

On or about 1 March 2026, vessel *Saipem Constellation* and support vessels *Go Australis* and *Bigroll Bering* will begin subsea operations in positions 19° 48'.63 S 114° 36'.72 E and 19° 52'.73 S 114° 36'.48 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 328**

**210(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Coronation Beach to Drummond Cove - Scientific instruments**
Mid West Ports Notice 4/2026

Subsurface scientific instruments exist on the seabed in the following positions:
28° 33'.63 S 114° 32'.80 E
28° 33'.80 S 114° 32'.94 E
28° 38'.10 S 114° 34'.84 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 332**

**212(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Enderby Island - Mooring buoys northwards**
Saipem

Two red lit mooring buoys, *Fl.Y*, exist in positions 20° 30'.82 S 116° 26'.60 E and 20° 30'.94 S 116° 26'.72 E.

**Chart temporarily affected - Aus 57**

**215(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Lowendal Islands - Varanus Island - Subsea operations**
Santos

On or about 10 March 2026, vessel *Jetwave Lightning* will begin inspection and maintenance operations in the vicinity of positions 20° 42'.77 S 114° 58'.47 E and 20° 37'.78 S 115° 36'.54 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 65 - Aus 742**

**296(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Glomar Shoal - FPSO**
Woodside Energy Ltd

The lit FPSO *Okha Mo(U)15s* (19° 35'.36 S 116° 26'.78 E) is off station for maintenance; an unlit riser turret mooring remains in situ.

NOTE; FPSO is shown as *Wanaea* on Aus4723

**Chart temporarily affected - Aus 327 - Aus 4603 (INT 603) - Aus 4708 (INT 708) - Aus 4722 (INT 722) - Aus 4723 (INT 723)**

**302(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Scott Reef - Scientific instruments**
JASCO Applied Sciences (Australia)

Subsurface scientific instruments exist as follows:

| *Position* | *Remarks* |
|---|---|
| 13° 59'.09 S 121° 46'.42 E | 1.5m above seabed |
| 13° 59'.60 S 121° 58'.93 E | 1.5m above seabed |
| 14° 02'.07 S 122° 00'.98 E | 1.5m above seabed |
| 14° 02'.31 S 121° 58'.33 E | 20m below the surface |
| 14° 31'.15 S 121° 37'.64 E | 1.5m above seabed. |

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 322**

**337(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Hampton Harbour - Depths**
Revelare Hydrospatial

Latest survey indicates shoaler depths than those charted in the vicinity of the following positions:
20° 40'.25 S 116° 41'.68 E
20° 39'.72 S 116° 41'.98 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 60**

**338(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Platform unlit northwards**
Vermilion Oil and Gas Australia

The *Wandoo A* platform, *Mo(U)15s* (20° 08'.33 S 116° 25'.29 E), is unlit.

**Chart temporarily affected - Aus 327 - Aus 742 - Aus 4603 (INT 603) - Aus 4708 (INT 708) - Aus 4722 (INT 722) - Aus 4723 (INT 723)**

**339(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Mooring buoy unlit northwards**
Vermilion Oil and Gas Australia

The lit mooring buoy, *Mo(U)Y.15s* (20° 06'.94 S 116° 26'.10 E), is unlit.

**Chart temporarily affected - Aus 327 - Aus 742**

**342(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Joseph Bonaparte Gulf - Subsea operations**
Eni Australia Ltd

On or about 27 April 2026, vessels *Skandi Emerald* and *MMA Pinacle* will begin well intervention works in position 13° 53'.69 S 128° 29'.05 E.

**Chart temporarily affected - Aus 318**

**345(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Obstruction northwards**
*Former Notice* - 218(T)/2026 is cancelled
Santos

A direct turret mooring, with least depth 35m, exists in position 21° 24'.21 S 114° 05'.29 E.

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 744 - Aus 4723 (INT 723)**

**347(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island - Light buoy off station**
Pilbara Ports Authority Notice A8/2026

The special light buoy, *Fl.4s* (21° 24'.49 S 114° 52'.54 E), is off station.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 743 - Aus 744**

**380(P)/2026 AUSTRALIA - WESTERN AUSTRALIA - Buccaneer Archipelago - Mulgudna Island toTalbot Bay - Shoaling**
Reach Subsea

Latest survey indicates shoaler depths than those charted exist in an area bounded by the following positions:
16° 08'.17 S 123° 47'.55 E
16° 02'.69 S 123° 59'.17 E
16° 02'.99 S 124° 21'.22 E
16° 09'.95 S 124° 20'.73 E
16° 13'.22 S 123° 53'.40 E
16° 22'.75 S 123° 58'.36 E
16° 16'.72 S 123° 48'.86 E.

Mariners are advised to navigate with caution in the area.

**Chart which will be affected - Aus 40 - Aus 732 - Aus 733**

**382(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Carnarvon - Teggs Channel - Light buoy off station**
Department of Transport and Major Infrastructure WA Notice 6822/2026

The starboard lateral light buoy, *Fl.G.3s No5* (24° 54'.43 S 113° 38'.12 E), is off station.

**Chart temporarily affected - Aus 73**

**383(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Enderby Island - Fish aggregating device off station northwestwards**
NSW Department of Primary Industries and Regional Development

The special light buoy, *Fl.Y.5s FAD (Apr-Nov)* (20° 30'.05 S 116° 17'.64 E), is off station.

**Chart temporarily affected - Aus 57 - Aus 327 - Aus 742**

**386(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Glomar Shoal - Subsea operations northwards**
Santos , Vantris Energy Australia

On or about 12 May 2026, vessel *VE Constructor* and an ROV will begin conducting subsea operations associated with the decommissioning of the Mutineer, Exeter, Finucane and Fletcher fields in an area bounded by the following positions:
19° 19'.92 S 116° 30'.08 E
19° 19'.92 S 116° 50'.08 E

19° 09'.92 S 116° 50'.08 E
19° 09'.92 S 116° 30'.08 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 327 - Aus 4722 (INT 722) - Aus 4723 (INT 723)**

**387(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Lowendal Islands - Light unlit**
*Former Notice* - 900(T)/2023 is cancelled
Santos

The light, *Fl.3s* (20° 38'.04 S 115° 34'.34 E), is unlit.

**Chart temporarily affected - Aus 65 - Aus 742**

**393(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Passage Islands - Dredging**
Pilbara Ports Authority Notice CPW01/2026

Dredging operations have commenced at the Port of Cape Preston West for the transhipment channel to the BCI minerals Mardie Salt and Potash jetty in the vicinity of 21° 01'.48 S 115° 56'.40 E. Dredge materials will be disposed in the vicinity of 20° 50'.54 S 115° 51'.20 E.

Mariners should navigate with caution.

**Chart temporarily affected - Aus 742 - Aus 743**

**394(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Passage Islands - Scientific instruments**
Department of Transport and Major Infrastructure WA Notice 6807/2026

Special light buoys, *Fl.Y.4s*, exist in the following positions:
20° 49'.62 S 115° 51'.31 E
20° 49'.86 S 115° 52'.72 E
20° 50'.34 S 115° 50'.32 E
20° 50'.39 S 115° 51'.44 E
20° 50'.57 S 115° 50'.67 E
20° 50'.89 S 115° 50'.00 E
20° 51'.07 S 115° 48'.72 E
20° 51'.45 S 115° 49'.94 E
20° 58'.14 S 115° 58'.94 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 742 - Aus 743**

**443(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Port of Ashburton - Topmark destroyed**
Pilbara Ports Authority Notice A10/2026

The topmark on light beacon, *Fl.G.3s G02* (21° 32'.19 S 115° 02'.60 E), has been destroyed.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 64**

**447(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Two Rocks - Scientific instrument**
Department of Transport WA Notice 6859/2026

A special light buoy, *Fl.Y.2·5s*, exists in position 31° 29'.86 S 115° 34'.46 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 754**

**486(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Indian Ocean - Christmas Island - Cable laying operations**
Subcom

Cable laying operations are in progress between Perth and Christmas Island. Cable lay and post lay inspection activities will occur along the route shown in the diagram and mariners are advised to keep clear of vessel, *CS Resolute* during activities. Further advice on specific areas of activity will be issued through the AUSCOAST warning system.

*Note:* For e-notice users, please see full edition for map.





**Chart temporarily affected - Aus 400 - Aus 608 - Aus 4060 (INT 60) - Aus 4070 (INT 70) - Aus 4071 (INT 71) - Aus 4708 (INT 708)**

**487(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Kalbarri - Survey operations northwards**
Department of Transport WA Notice 6875/2026

MV *Inception II*, with a 130m towed array, is conducting survey operations in an area bounded by the coast and the following positions:
27° 18'.25 S 114° 00'.28 E
27° 20'.74 S 113° 54'.21 E
27° 27'.43 S 113° 57'.45 E
27° 25'.25 S 114° 03'.89 E.

The vessel will monitor VHF Ch 16.

Mariners are advised to navigate with caution in the area and keep well clear.

**Chart temporarily affected - Aus 332**

**492(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Rottnest Island - Thomson Bay - Harbour works; dredging operations**
Department of Transport WA Notice 6876/2026

Construction works and dredging operations associated with the Marine Logistics Hub are in progress in the vicinity of position 32° 00'.01 S 115° 33'.02 E.

An exclusion zone marked by special buoys exists around the works.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 112**

**527(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Kalbarri - Scientific instrument northwards**
RPS Group

A special light buoy, *Q(5)Y.20s*, exists in position 27° 22'.87 S 113° 59'.40 E.

**Chart temporarily affected - Aus 332**

**530(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Princess Royal Harbour - Light altered**
Department of Transport WA Notice 6882/2026

The light beacon, *F.Bu* (35° 03'.06 S 117° 52'.30 E), has been temporarily altered to *Fl.W.*

**Chart temporarily affected - Aus 118**

**565(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Carnarvon - Light beacons unlit**
Department of Transport WA Notice 6902/2026

The following light beacons are unlit:

| *Position* | *Remarks* |
|---|---|
| 24° 54'.30 S 113° 37'.94 E | *Q(2)R.5s No2* |
| 24° 54'.37 S 113° 38'.00 E | *Fl.G.3s No3* |
| 24° 54'.55 S 113° 38'.51 E | *Q.G.4M No7.* |

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 73**

**569(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Geraldton - Scientific instrument**
Mid West Ports Notice 10/2026

A scientific instrument marked by a special light buoy, *Fl.Y.4s*, exists on the seabed in position 28° 46'.10 S 114° 35'.55 E.

Mariners are requested to avoid anchoring, fishing or trawling in the vicinity.

**Chart temporarily affected - Aus 81**

**600(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Subsea operations northwestwards**
Woodside Energy Ltd

Vessel *Skandi Singapore* is conducting subsea structure recovery and survey operations in the vicinity of the following positions:
19° 27'.30 S 116° 29'.46 E
19° 35'.06 S 116° 06'.78 E
19° 37'.79 S 116° 23'.81 E
19° 39'.08 S 115° 55'.80 E
19° 40'.62 S 115° 53'.83 E
19° 41'.55 S 115° 50'.98 E
19° 41'.56 S 115° 53'.82 E
19° 44'.74 S 115° 44'.20 E
19° 46'.06 S 115° 53'.21 E
19° 47'.20 S 115° 46'.86 E
19° 50'.92 S 115° 47'.27 E
20° 04'.97 S 115° 10'.57 E
20° 09'.12 S 115° 03'.98 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 327 - Aus 328 - Aus 742**

**644(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Cockatoo Island - Restricted area**
Kimberley Ports Authority

A section of the old Terminal Jetty has collapsed in the vicinity of position 16° 06'.15 S 123° 36'.84 E.

A 25m radius restricted area exists around the jetty between positions 16° 06'.17 S 123° 36'.87 E and 16° 06'.15 S 123° 36'.83 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 40 - Aus 41 - Aus 323 - Aus 732 - Aus 733**

**693(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Survey operations northwards**
Santos

On or about 15 August 2026, survey vessel *Lightning* and an AUV will begin conducting survey operations along the pipeline between the following positions:
20° 32'.77 S 115° 16'.98 E
20° 39'.45 S 115° 31'.88 E;
and
20° 40'.45 S 115° 18'.68 E
20° 40'.29 S 115° 19'.53 E;
and
20° 39'.05 S 115° 27'.45 E
20° 39'.64 S 115° 30'.75 E.

A 500m safety exclusion zone exists around the vessels.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 65 - Aus 327 - Aus 328 - Aus 742**

**694(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Bowen - Port Denison - Light unlit**
Department of Transport WA Notice 6946/2026

The light, *Fl.R.3s* (29° 16'.35 S 114° 54'.91 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 84**

**695(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Cape Leeuwin - Scientific instrument southwards**
Department of Transport WA Notice 6935/2026

A special light buoy, *Fl.Y.2·5s*, exists in position 34° 32'.97 S 115° 09'.84 E.

**Chart temporarily affected - Aus 335 - Aus 336**

**697(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Pre-lay anchors northwestwards**
Woodside Energy Ltd

Pre-lay anchors exist in the vicinity of position 20° 03'.27 S 115° 10'.42 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 328**

**699(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Port Geographe - Dredging operations**
Department of Transport WA Notice 6952/2026

The dredge *Kingston* is conducting dredging operations in the entrance channel to the marina (33° 37'.74 S 115° 23'.38 E).

A floating and submerged pipeline marked by special light buoys exists from the dredge.

If mariners are unsure of where to safely pass the dredge contact can be made on VHF Ch 16 or Marine 27 MHz Ch 88.

The dredge will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 116**

**735(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Cable laying operations northwestwards**
Nexans

Vessel *Nexans Aurora* is conducting cable laying operations between positions 19° 52'.73 S 114° 36'.48 E and 20° 41'.50 S 115° 24'.97 E.

Mariners are advised to navigate with caution in the area. 1M clearance requested.

**Chart temporarily affected - Aus 65 - Aus 327 - Aus 328 - Aus 742**

**737(P)/2026 AUSTRALIA - WESTERN AUSTRALIA - Carnarvon - Shoaling**
*Former Notice* - 256(P)/2026 is cancelled
Department of Transport and Major Infrastructure WA

Latest survey indicates potential channel realignment and shoaler depths than those charted may exist in the vicinity of position 24° 54'.44 S 113° 38'.67 E. Shoaling is also extending northwards into the main channel in the vicinity of position 24° 54'.35 S 113° 37'.98 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 73**

**740(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Exmouth Gulf - Scientific instrument**
*Former Notice* - 525(T)/2026 is cancelled
Department of Transport WA Notice 6879(T)/2026

A special pillar light buoy, *Fl.Y.2·5s*, exists in position 22° 10'.01 S 114° 20'.24 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 744**

**780(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Bunbury - Koombana Bay - Shoaling; light beacon**
Department of Transport WA Notice 6967/2026

Due to shoaling, which extends approximately 15m east of Berth 1, a light beacon, *Fl.Y.3s*, has been established in position 33° 18'.35 S 115° 38'.77 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 115**

**781(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Exmouth Gulf - Observation Island - Scientific instrument**
Department of Transport WA Notice 6964(T)/2026

A special conical light buoy, *Fl.Y.2·5s*, exists in position 21° 41'.30 S 114° 35'.23 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 328 - Aus 744**

**782(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Garden Island - Scientific instruments**
Department of Transport WA

Subsurface scientific instruments, 0.6m above the seabed, exist in positions:
32° 13'.60 S 115° 42'.60 E

32° 14'.21 S 115° 41'.45 E
32° 15'.10 S 115° 39'.98 E
32° 14'.80 S 115° 42'.77 E
32° 14'.84 S 115° 41'.36 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 117**

**784(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Geraldton - Harbour works**
Mid West Ports Notice 14/2026

Works associated with the construction of a new breakwater, as part of the Tug Harbour Development Project, are in progress in an area bounded by the following positions:
28° 46'.27 S 114° 35'.64 E
28° 46'.29 S 114° 36'.00 E
28° 45'.81 S 114° 36'.00 E
28° 45'.81 S 114° 35'.88 E.

Mariners are advised to navigate with caution in the area and to maintain a safe distance.

**Chart temporarily affected - Aus 81**

**785(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Joseph Bonaparte Gulf - ROV operations northwards**
Eni Australia Ltd

Vessel *Lauri J* is conducting ROV operations in the vicinity of positions 12° 56'.04 S 128° 34'.25 E and 13° 16'.72 S 128° 07'.97 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 315 - Aus 318**

**786(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Leander Reef - Platform unlit; light buoys**
*Former Notice* - 742(T)/2026 is cancelled
Department of Transport and Major Infrastructure WA Notice WA979/2/2026

The *Cliff* platform, *Mo(U)15s* (29° 26'.99 S 114° 52'.18 E), is unlit.

4 special light buoys, *Fl.Y.5s*, exist surrounding the unlit platform.

**Chart temporarily affected - Aus 752 - Aus 4708 (INT 708)**

**787(P)/2026 AUSTRALIA - WESTERN AUSTRALIA - Mandurah - Shoaling southeastwards**
*Former Notice* - 743(P)/2026 is cancelled
Department of Transport and Major Infrastructure WA

Latest survey indicates shoaler depths than those charted may exist in the vicinity of position 32° 31'.37 S 115° 42'.66 E and in an area bounded by the following positions:
32° 31'.08 S 115° 42'.63 E
32° 30'.94 S 115° 42'.78 E
32° 31'.09 S 115° 43'.21 E
32° 31'.17 S 115° 43'.21 E
32° 31'.12 S 115° 42'.69 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 116 - Aus 755**

**825(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Town Point - Obstruction**
Department of Transport and Major Infrastructure WA

An obstruction exists on the seabed in position 20° 48'.79 S 115° 33'.32 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 65 - Aus 327 - Aus 742 - Aus 743**

**826(P)/2026 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Shoaling**
*Former Notice* - 779(P)/2026 is cancelled
Department of Transport WA

Latest survey indicates shoaler depths than those charted may exist within an area bounded by the following positions:
20° 36'.94 S 115° 37'.19 E
20° 45'.00 S 115° 37'.19 E
20° 54'.10 S 115° 27'.81 E
21° 00'.00 S 115° 18'.00 E
20° 58'.22 S 115° 15'.70 E
20° 50'.59 S 115° 16'.30 E
20° 36'.94 S 115° 22'.52 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 65 - Aus 327 - Aus 328 - Aus 742 - Aus 743**

**827(P)/2026 AUSTRALIA - WESTERN AUSTRALIA - Bremer Bay - Shoaling**
Department of Transport WA

Latest survey indicates shoaler depths than those charted exist within an area bounded by the following positions:
34° 25'.7 S 119° 23'.6 E
34° 25'.7 S 119° 24'.3 E
34° 25'.3 S 119° 24'.3 E
34° 25'.3 S 119° 23'.6 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 337**

**828(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Dampier Archipelago - Subsea operations northwestwards**
*Former Notice* - 567(T)/2026 is cancelled
Woodside Energy Ltd , Australian Maritime Safety Authority

Vessels are conducting subsea operations which includes the recovery of pre-laid mooring lines in the vicinity of the following positions:
19° 29'.00 S 116° 36'.62 E
19° 30'.63 S 116° 36'.32 E
19° 31'.30 S 116° 35'.22 E
19° 31'.20 S 116° 06'.65 E
19° 31'.45 S 116° 05'.90 E
19° 45'.73 S 115° 53'.40 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 327**

**829(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - King George Sound - Mooring buoy unlit**
Department of Transport and Major Infrastructure WA Notice 6998/2026

The lit mooring buoy, *Fl.Y.4s* (35° 02'.81 S 117° 55'.52 E), is unlit.

**Chart temporarily affected - Aus 118**

**869(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Cable laying operations northwestwards**
Subsea 7

Vessel *Seven Arctic* is conducting cable laying operations between the following positions:

19° 48'.57 S 114° 36'.50 E
19° 53'.95 S 114° 39'.43 E
20° 02'.90 S 114° 47'.34 E
20° 09'.38 S 114° 49'.66 E
20° 17'.07 S 114° 54'.94 E
20° 24'.52 S 114° 50'.87 E
20° 29'.05 S 114° 53'.84 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 328**

**871(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Browse Island - Light buoy unlit northwestwards**
INPEX

The special light buoy, *Fl(5)Y.20s* (13° 56'.21 S 123° 15'.86 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 319 - Aus 320**

**874(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Exmouth - Survey operations**
Department of Transport and Major Infrastructure WA Notice 7009/2026

On or about 14 October 2026, jack-up barge *Sea Lift 10* and support vessels *Jetfire*, *Optimus* and *Megatron* will begin conducting a geotechnical survey in an area bounded by the following positions:
21° 59'.28 S 114° 07'.68 E
21° 59'.34 S 114° 08'.94 E
21° 58'.92 S 114° 09'.00 E
21° 58'.86 S 114° 07'.86 E.

Vessels will display appropriate lights and shapes and will monitor VHF Ch 12 and Ch 16.

Mariners are advised to navigate with caution in the area. 50m clearance requested.

**Chart temporarily affected - Aus 744 - Aus 745**

**876(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Fremantle - Owen Anchorage - Scientific instrument**
Department of Transport and Major Infrastructure WA Notice 7016/2026

A subsurface scientific instrument, 0.5m above the seabed, exists in position 32° 07'.39 S 115° 45'.35 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 117**

**877(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - King George Sound - Seal Island - Wave energy converter**
Department of Transport WA Notice 6996/2026

On or about 5 October 2026, a wave energy converter will be deployed in position 35° 04'.64 S 117° 58'.68 E.

The device will be marked by a light, *Fl.5s*, and is not to be accessed by unauthorised personnel.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 118**

**880(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Subsea operations; survey operations northwestwards**
DOF Management

On or about 8 October 2026, vessel *Skandi Inventor* and an ROV will begin conducting subsea operations and survey operations in the vicinity of position 19° 52'.73 S 114° 36'.48 E.

Mariners are advised to navigate with caution in the area. 5M clearance requested.

**Chart temporarily affected - Aus 328**

**881(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Muiron Islands - FPSO off station northwestwards**
Woodside Energy Ltd

The lit FPSO *Pyrenees Venture* (21° 32'.47 S 114° 06'.98 E) is off station; a direct turret mooring, with least depth 20m, exists in situ marked by a special light buoy, *Fl.Y.5s.*

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 744 - Aus 4723 (INT 723)**

**882(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Ocean Reef Boat Harbour - Light unreliable**
Department of Transport and Major Infrastructure WA Notice 6896/2026

The leading light, *F.Bu.24m 5M & Iso.4s.13m 10M* (31° 45'.64 S 115° 43'.86 E), is reported as dim and not clearly visible from the required range.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 754**

**915(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Cape Leeuwin - Survey operations; tide gauges southwards**
Reach Subsea

USV *Reach Remote 2* and MV *Offshore Surveyor* are conducting survey operations in an area bounded by the following positions:
34° 39'.53 S 114° 56'.44 E
34° 24'.13 S 115° 14'.00 E
34° 36'.35 S 115° 39'.72 E
34° 53'.62 S 115° 20'.22 E.

Seabed mounted tide gauges exist in the following positions:
34° 39'.53 S 114° 56'.44 E
34° 31'.86 S 115° 05'.12 E
34° 24'.13 S 115° 14'.00 E
34° 36'.35 S 115° 39'.72 E
34° 45'.20 S 115° 29'.76 E
34° 53'.62 S 115° 20'.22 E
34° 46'.53 S 115° 08'.22 E
34° 30'.37 S 115° 27'.11 E
34° 38'.57 S 115° 17'.52 E.

A lit GNSS tide buoy will be positioned at each location for a period of up to 72 hours.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 116 - Aus 335 - Aus 336**

**917(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Muiron Islands - Subsea operations northwestwards**
Woodside Energy Ltd

On or about 20 October 2026, vessel *Skandi Hercules* will begin conducting subsea operations in the vicinity of positions 21° 29'.96 S 114° 07'.61 E and 21° 32'.47 S 114° 06'.98 E.

Mariners are advised to navigate with caution in the area. A 500m exclusion zone exists around the vessel.

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 744**

**948(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Rock installation; survey operations**
Van Oord

On or about 2 November 2026, vessel *Nordes* will begin conducting survey operations and rock installation along the cable within a 50m corridor between the following positions:
20° 15'.96 S 114° 53'.96 E
20° 33'.58 S 115° 06'.09 E
20° 41'.38 S 115° 24'.69 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 65 - Aus 327 - Aus 328 - Aus 742**

**949(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Cockburn Sound - Kwinana - Seagrass restoration trial**
Department of Transport and Major Infrastructure WA Notice 7028/2026

24 star pickets, 0.5m above the seabed, have been installed in the vicinity of position 32° 15'.05 S 115° 45'.06 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 117**

**950(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Cockburn Sound - Medina Channel - Wind turbine westwards**
*Former Notice* - 566(T)/2026 is cancelled
Department of Transport WA Notice 6901/2026

A floating vertical wind turbine, with a height of 26m, is moored in position 32° 10'.56 S 115° 44'.94 E.

The wind turbine is marked by 5 lights, *Fl.2s*.

The mooring buoy is lit, *Fl.Y.2s*.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 117**

**951(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Dampier - Parker Point - Topmark destroyed**
Pilbara Ports Authority Notice D22/2026

The topmark on light beacon, *Fl.R.3s 9E* (20° 37'.80 S 116° 41'.90 E), has been destroyed.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 60**

**952(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Dixon Island - Scientific instrument northwards**
Department of Transport and Major Infrastructure WA Notice 7035/2026

A special light buoy, *Fl.Y.2s*, exists in position 20° 34'.37 S 117° 04'.36 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 55**

**956(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Onslow - Hastings Shoal - Light buoy unlit**
Department of Transport and Major Infrastructure WA Notice 7050/2026

The starboard lateral light buoy, *Fl.G.3s* (21° 33'.62 S 115° 04'.15 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 64**

**957(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Port Walcott - Cape Lambert - Light unlit**
Department of Transport WA Notice 7048/2026

The rear leading light, *F.Bu (F Day)* (20° 35'.74 S 117° 10'.97 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 55**

**958(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Subsea operations eastwards**

Woodside Energy Ltd

Vessel *Seven Sisters* and an ROV will begin conducting subsea operations and survey operations associated with the decommissioning of the Echo Yodel field in the vicinity of positions 19° 39'.08 S 115° 55'.98 E and 19° 44'.74 S 115° 44'.20 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 327**

**959(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Rosily Islands to Paroo Shoal - Scientific instruments**
Department of Transport WA Notice 7046/2026

Scientific instruments, 5m below the surface, exist in the following positions:
21° 14'.76 S 114° 59'.57 E
21° 21'.99 S 115° 03'.06 E
21° 27'.28 S 114° 56'.19 E
21° 32'.70 S 114° 59'.56 E.

Mariners are advised to navigate with caution in the area and keep well clear.

**Chart temporarily affected - Aus 64 - Aus 743 - Aus 744**

**993(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Cockburn Sound - Scientific instruments**
Department of Transport and Major Infrastructure WA Notice 7058/2026

Special light buoys, *Fl.Y.2·5s,* exist in the following positions:
32° 06'.64 S 115° 43'.83 E
32° 11'.50 S 115° 44'.35 E
32° 11'.69 S 115° 45'.53 E
32° 11'.80 S 115° 45'.95 E
32° 15'.09 S 115° 43'.72 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 117**

**994(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - King Sound - Black Rocks - Light unlit**
Kimberley Ports Authority Notice 17/2026

The light, *LFl.12s.14m 12M* (17° 05'.25 S 123° 35'.41 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 45 - Aus 323 - Aus 733**

**995(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Madora Bay - Cable laying operations; rock installation southwestwards**
Department of Transport and Major Infrastructure WA Notice 7051/2026

On or about 15 November 2026, cable laying operations and rock installation will begin between positions 32° 28'.32 S 115° 44'.46 E and 32° 32'.14 S 115° 37'.18 E.

Vessels will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area. 1M clearance requested.

**Chart temporarily affected - Aus 116 - Aus 755**

**996(T)/2026 AUSTRALIA - WESTERN AUSTRALIA - Muiron Islands - Subsea operations northwestwards**
Santos

On or about 16 November 2026, vessel *Deep Ocean Southern Star* and support vessels will begin conducting subsea operations in the vicinity of position 21° 24'.55 S 114° 05'.29 E.

Mariners are advised to navigate with caution in the area. A 500m exclusion zone exists around the vessel.

**Chart temporarily affected - Aus 328 - Aus 329 - Aus 744**

## SOUTH AUSTRALIA

**81(T)/2021 AUSTRALIA - SOUTH AUSTRALIA - Gulf St Vincent - Rogues Point - Artificial reef**
Department of Planning, Transport and Infrastructure SA Notice 9/2017

An artificial reef is being developed in an area bounded by the following positions:
34° 30'.63 S 137° 53'.95 E
34° 30'.63 S 137° 54'.12 E
34° 30'.47 S 137° 54'.13 E
34° 30'.47 S 137° 53'.95 E.

A lit raft exists in position 34° 30'.59 S 137° 53'.99 E.

**Chart temporarily affected - Aus 781**

**291(T)/2021 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Shoaling**
Department for Transport, Energy and Infrastructure SA Notice 38/2007

Silting has resulted in width restrictions being imposed in the main channel of the Port Adelaide River between No 40 beacon (34° 47'.86 S 138° 30'.79 E) and No 41 beacon (34° 48'.52 S 138° 30'.77 E).

Mariners should avoid the western side of the main channel and navigate with caution in this part of the River as the available navigable channel is now only 90 metres wide measured from the eastern edge.

Mariners intending to transit this section should contact the Manager Marine Operations, Flinders Ports Pty Ltd on (08) 8447 0622 to confirm maximum widths.

**Chart temporarily affected - Aus 130**

**587(T)/2022 AUSTRALIA - SOUTH AUSTRALIA - Wallaroo - Point Hughes - Harbour works**
Department for Infrastructure and Transport SA Notice 18(T)/2022

Works associated with the construction of a new breakwater are in progress in the vicinity of position 33° 55'.88 S 137° 36'.29 E.

The works area is marked by special light buoys, *Fl.Y.4s*.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 777**

**724(T)/2023 AUSTRALIA - SOUTH AUSTRALIA - Port Lincoln - Boston Bay - Light beacon destroyed**
Department for Infrastructure and Transport SA Notice 44(T)/2023

The starboard lateral light beacon, *Fl.G.2s No3* (34° 41'.75 S 135° 52'.70 E), has been destroyed.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 134**

**1027(T)/2023 AUSTRALIA - SOUTH AUSTRALIA - Port Bonython - Scientific instrument**
Department for Infrastructure and Transport SA Notice 68(T)/2023

A subsurface scientific instrument, 1.5m above the seabed, exists in position 33° 00'.24 S 137° 47'.34 E.

**Chart temporarily affected - Aus 136**

**168(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Kangaroo Island - American River - Wreck**
Department for Infrastructure and Transport SA Notice 7(T)/2024

A stranded wreck marked by an isolated danger light buoy, *Fl(2)4s*, exists in position 35° 47'.22 S 137° 46'.51 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 780**

**337(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Denial Bay - Obstruction**
Department for Infrastructure and Transport SA Notice 23(T)/2024

A lost anchor exists in position 32° 14'.87 S 133° 30'.18 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 120 - Aus 341**

**459(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Yorke Peninsula - Sultana Point - Wreck**
Department for Infrastructure and Transport SA Notice 27(T)/2024

A stranded wreck marked by an isolated danger light buoy, *Fl(2)5s*, exists in position 35° 05'.95 S 137° 45'.00 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 780 - Aus 781**

**573(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Cape Hardy - Scientific instruments**
Department for Infrastructure and Transport SA Notice 37(T)/2024

Subsurface scientific instruments, 3m above the seabed, exist in the following positions:
34° 10'.03 S 136° 20'.90 E
34° 11'.05 S 136° 20'.47 E
34° 12'.01 S 136° 19'.80 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 777**

**574(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Spencer Gulf - Point Lowly - Scientific instruments**
*Former Notice* - 36(T)/2024 is cancelled
Department for Infrastructure and Transport SA Notice 33(T)/2024

Subsurface scientific instruments, 1.5m above the seabed, exist in positions 33° 00'.46 S 137° 47'.55 E and 32° 58'.76 S 137° 48'.02 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 136**

**622(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Light beacon destroyed**
Department for Infrastructure and Transport SA Notice 40(T)/2024

The light beacon, *Q.10M Entrance* (34° 46'.82 S 138° 22'.53 E), has been destroyed; a special virtual AIS exists in situ.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 130 - Aus 485 - Aus 781**

**757(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Gulf St Vincent - Port Gawler - Scientific instrument**
Department for Infrastructure and Transport SA Notice 55(T)/2024

A subsurface scientific instrument exists in position 34° 42'.67 S 138° 22'.58 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 130 - Aus 485 - Aus 781**

**921(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Scientific instruments**
Department for Infrastructure and Transport SA Notice 72(T)/2024

A subsurface scientific instrument, 0.5m above the seabed, exists in position 34° 44'.16 S 138° 20'.37 E.

Special light buoys, *Fl.Y.2s*, exist in positions 34° 40'.68 S 138° 25'.06 E and 34° 42'.56 S 138° 26'.80 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 130 - Aus 485 - Aus 781**

**1000(T)/2024 AUSTRALIA - SOUTH AUSTRALIA - Cape Hardy - Geotechnical operations**
Department for Infrastructure and Transport SA Notice 54(T)/2024

Geotechnical operations are in progress in the vicinity of position 34° 10'.97 S 136° 19'.83 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 777**

**59(T)/2025 AUSTRALIA - SOUTH AUSTRALIA - Gulf St Vincent - Port Gawler - Scientific instrument**
*Former Notice* - 305(T)/2024 is cancelled
Department for Infrastructure and Transport SA Notice 82(T)/2024

A subsurface scientific instrument exists on the seabed, with a minimum safe clearance of 2m, in position 34° 41'.89 S 138° 24'.83 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 781**

**147(T)/2025 AUSTRALIA - SOUTH AUSTRALIA - Cape Buffon - Light unlit**
*Former Notice* - 1026(T)/2023 is cancelled
Department for Infrastructure and Transport SA Notice 12(T)/2025

The light, *Fl.WR.2·5s 8/3M* (37° 33'.96 S 140° 06'.47 E), is unlit; a temporary light, *Fl.R.2·5s 2M*, exists in situ.

**Chart temporarily affected - Aus 348**

**502(T)/2025 AUSTRALIA - SOUTH AUSTRALIA - Island Point - Light beacons damaged and unlit**
Department for Infrastructure and Transport SA Notice 36(T)/2025

The west cardinal light beacon, *Q(9)15s* (34° 25'.99 S 137° 24'.80 E), is unlit and the topmark is missing.

The light beacon, *Fl.R.3s* (34° 26'.80 S 137° 23'.87 E), is unlit and the topmark is missing.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 776 - Aus 777**

**629(T)/2025 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Scientific instruments**
Department for Infrastructure and Transport SA Notice 46(T)/2025

Scientific instruments marked by a special buoys exist in positions 34° 47'.01 S 138° 28'.07 E and 34° 47'.12 S 138° 27'.74 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 130**

**801(T)/2025 AUSTRALIA - SOUTH AUSTRALIA - Gulf St Vincent - Brighton - Scientific instruments**
Department for Infrastructure and Transport SA Notice 54(T)/2025

Special light buoys, *Fl.Y.2·5s*, exist in positions 35° 01'.39 S 138° 27'.00 E and 35° 01'.45 S 138° 27'.24 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 781**

**923(P)/2025 AUSTRALIA - SOUTH AUSTRALIA - Cape Gantheaume - Shoaling southwards**
*Former Notice* - 887(P)/2025 is cancelled
Australian Hydrographic Office

Latest survey indicates shoaler depths than those charted, with a least depth of 19·6m, may exist in an area bounded by the following positions:
35° 54'.97 S 137° 42'.26 E
35° 58'.25 S 137° 52'.38 E
36° 07'.48 S 137° 43'.19 E
36° 22'.38 S 137° 21'.69 E
36° 11'.15 S 137° 24'.09 E
36° 01'.52 S 137° 37'.52 E

Mariners are advised to navigate with caution in the area.

Products will be updated in due course.

**Chart which will be affected - Aus 346**

**955(T)/2025 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Wonga Shoal - Light buoy off station; light buoy unlit**
Department for Infrastructure and Transport SA Notice 68(T)2025

The special light buoy, *Fl.Y.5s* (34° 49'.97 S 138° 26'.08 E), is unlit and off station. The current position of the light buoy is 34° 49'.84 S 138° 26'.52 E.

**Chart temporarily affected - Aus 130**

**1051(T)/2025 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Outer Harbor - Harbour works**
Department for Infrastructure and Transport SA Notice 71(T)/2025

Works associated with the remediation of a section of damaged breakwater are in progress in the vicinity of position 34° 45'.92 S 138° 29'.04 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 130**

**304(P)/2026 AUSTRALIA - SOUTH AUSTRALIA - Kangaroo Island - Shoaling**
Fugro

Latest surveys indicate shoaler depths than those charted exist in an area bounded by the following positions:
36° 07'.31 S 137° 22'.86 E
36° 21'.14 S 137° 22'.66 E
36° 20'.48 S 137° 14'.81 E
36° 07'.77 S 136° 43'.28 E
36° 03'.44 S 136° 45'.15 E

Mariners are advised to navigate with caution in the area.

ENC products have been updated, paper charts will be updated in due course.

**Chart which will be affected - Aus 346 - Aus 485 - Aus 4709 (INT 709)**

**449(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Port Lincoln - Billy Lights Point - Dredging operations; exclusion zone**
Department for Infrastructure and Transport SA Notice 31(T)/2026

Dredging operations are in progress in the vicinity of position 34° 44'.8 S 135° 54'.0 E.

A restricted area marked by special light buoys, *Fl.Y.5s*, exists around the dredging operations.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 134 - Aus 776**

**574(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Port Lincoln - Billy Lights Point - Scientific instruments**
Department for Infrastructure and Transport SA Notice 42(T)/2026

Special light buoys, *Fl.Y.3s*, exist in the following positions:
34° 44'.70 S 135° 54'.12 E
34° 45'.53 S 135° 53'.52 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 134 - Aus 776**

**606(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - Largs Bay to West Beach - Scientific instruments**
Department for Infrastructure and Transport SA Notice 47(T)/2026

Light buoys, *Fl.Y.2s*, exist in the following positions:
34° 46'.72 S 138° 27'.82 E
34° 47'.92 S 138° 28'.75 E
34° 49'.68 S 138° 28'.52 E
34° 51'.45 S 138° 27'.83 E
34° 53'.53 S 138° 28'.58 E
34° 55'.37 S 138° 29'.18 E
34° 56'.53 S 138° 29'.45 E
34° 57'.35 S 138° 29'.47 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 130 - Aus 781**

**608(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Spencer Gulf - Wallaroo - Moorings**
Department for Infrastructure and Transport SA Notice 49(T)/2026

Concrete anchors/mooring blocks, approximately 1m in height, exist on the seafloor in the vicinity of 33°55'.57 S, 137°32'.34 E.

Mariners should navigate with caution.

**Chart temporarily affected - Aus 777**

**700(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Louth Bay - Berlin Rock - Scientific instruments**
Department for Infrastructure and Transport SA Notice 54(T)/2026

Special light buoys, *Fl.Y.2·5s*, exist in positions 34° 34'.60 S 136° 02'.67 E and 34° 34'.57 S 136° 06'.33 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 776**

**794(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Port Lincoln - Billys Lights Point - Dredging operations; exclusion zone**
Department for Infrastructure and Transport SA Notice 61(T)/2026

An exclusion zone for dredging operations exists in an area bounded by the coast and the following:

| *Position* | *Remarks* |
|---|---|
| 34° 45'.16 S 135° 53'.09 E | |
| 34° 45'.40 S 135° 53'.25 E | marked by special light buoy, *Fl.5s* |
| 34° 45'.57 S 135° 53'.15 E | marked by special light buoy, *Fl.5s* |
| 34° 45'.73 S 135° 53'.05 E | marked by special light buoy, *Fl.5s* |
| 34° 46'.02 S 135° 52'.90 E | marked by special light buoy, *Fl.5s* |
| 34° 45'.90 S 135° 52'.60 E | marked by special light buoy, *Fl.5s* |
| 34° 45'.72 S 135° 52'.70 E | marked by special light buoy, *Fl.5s* |
| 34° 45'.17 S 135° 53'.05 E. | |

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 134**

**837(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Lucky Bay - Dredging operations**
Department for Infrastructure and Transport SA Notice 63(T)/2026

Dredging operations are in progress in an area bounded by the following positions:
33° 42'.48 S 137° 02'.18 E
33° 42'.63 S 137° 02'.38 E
33° 42'.60 S 137° 02'.42 E
33° 42'.45 S 137° 02'.22 E.

A submerged and floating pipeline exists in the area.

The dredge will monitor VHF Ch 16 and Ch 1.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 777**

**890(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Port Adelaide - North Haven - Dredging operations**
Department for Infrastructure and Transport SA Notice 72(T)/2026

Dredging operations are in progress in the marina channel and entrance (34° 47'.7 S 138° 28'.9 E).

The discharge area is marked by light buoys, *Fl.Y.3s*, and is bounded by the following positions:
34° 47'.62 S 138° 28'.77 E
34° 47'.45 S 138° 28'.33 E
34° 47'.35 S 138° 28'.40 E
34° 47'.50 S 138° 28'.82 E.

A submerged and floating pipeline exists 1200m from the dredge.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 130**

**920(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Cowleds Landing - Drilling operations southwards**
*Former Notice* - 168(T)/2026 is cancelled
Department for Infrastructure and Transport SA Notice 77(T)/2026

Drilling operations are in progress in the vicinity of position 33° 14'.43 S 137° 27'.16 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 778**

**997(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Great Australian Bight - Satellite re-entry**
*Former Notice* - 960(T)/2026 is cancelled
Southern Launch

Southern Launch will be conducting re-entry activities during the period 1100-1400 UTC 17-22 November 2026.

Satellite components may impact the waters within an area bounded by the following positions:
33° 10'.31 S 133° 12'.29 E
33° 06'.73 S 133° 35'.98 E
32° 10'.45 S 133° 28'.19 E
31° 59'.46 S 132° 50'.86 E.

Mariners are advised to be aware of floating debris hazards and to navigate with caution.

**Chart temporarily affected - Aus 120 - Aus 341**

**998(T)/2026 AUSTRALIA - SOUTH AUSTRALIA - Port Alfred - Black Point/Gudliwardi - Light beacon unlit**
Department for Infrastructure and Transport SA Notice 90(T)/2026

The port lateral light beacon, *Fl.R.3s* (34° 36'.13 S 137° 55'.40 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 781**

## VICTORIA

**350(T)/2021 AUSTRALIA - VICTORIA - Port Phillip - Corio Bay - Scientific instruments**
Victorian Regional Channels Authority Notice 93(T)2021

Scientific instruments exist on the seabed in the following positions:
38° 05'.17 S 144° 23'.31 E
38° 05'.35 S 144° 24'.20 E.

**Chart temporarily affected - Aus 153 - Aus 157**

**409(T)/2021 AUSTRALIA - VICTORIA - Port Phillip - Corio Bay - Scientific instrument**
Victorian Regional Channels Authority Notice 310(T)/2019

A scientific instrument marked by a special light buoy, *Fl.Y,* exists on the seabed in position 38° 05'.07 S 144° 23'.25 E.

**Chart temporarily affected - Aus 157**

**618(T)/2021 AUSTRALIA - VICTORIA - Port Phillip - Half Moon Bay - Obstructions**
Parks Victoria Notices 215(T), 218(T)/2021

The jetty (37° 58'.09 S 145° 00'.58 E) has been demolished. Shoaling and obstructions may exist in the area north of the jetty.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 155**

**664(T)/2021 AUSTRALIA - VICTORIA - Western Port - Stony Point to Sandy Point - Shoaling**
Victorian Regional Channels Authority Notice 199/2019

Shoaling exists in the vicinity of the following positions:

| *Position* | *Least depth* | *Remarks* |
|---|---|---|
| 38°25'.5 S 145° 13'.8 E | *13.6m* | Extending up to 100m into shipping channel |
| 38°22'.8 S 145° 14'.7 E | *13.2m* | Extending up to 50m into shipping channel |
| 38°21'.9 S 145° 14'.4 E | *13.5m* | Extending up to 40m into shipping channel |
| 38°22'.1 S 145° 14'.3 E | *13.8m* | Extending up to 10m into shipping channel |

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 151**

**859(T)/2021 AUSTRALIA - VICTORIA - Western Port - Crib Point - Exclusion zone**
Maritime Safety Victoria Notice 265(T)/2021

The Ex-HMAS OTAMA (Oberon class submarine) located 800 metres north of Crib Point jetty has been relocated to position 38° 20'.66 S 145° 13'.27 E, with a 200 metre exclusion zone.

A 200 metre exclusion zone remains at its previous location (38° 20'.48 S 145° 13'.45 E).

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 151**

**1033(T)/2021 AUSTRALIA - VICTORIA - Port Phillip - Beaumaris Bay - Buoy**
Parks Victoria Notice 353(T)/2021

A special buoy exists in position 37° 59'.50 S 145° 03'.56 E.

**Chart temporarily affected - Aus 155**

**294(T)/2022 AUSTRALIA - VICTORIA - Port Phillip - Point Wilson - Exclusion zone**
*Former Notice* - 1078(T)/2021 is cancelled

Victorian Regional Channels Authority  Notice 239/2020, Parks Victoria  Notice 104/2022

A 300m exclusion zone exists outwards from the centreline of Point Wilson Pier (38° 05'.54 S 144° 31'.48 E). It is marked by special light buoys, *Iso.2s*, in the following positions:
38° 05'.51 S 144° 30'.73 E
38° 05'.68 S 144° 31'.32 E
38° 05'.84 S 144° 31'.86 E
38° 05'.89 S 144° 32'.45 E
38° 05'.64 S 144° 32'.48 E
38° 05'.55 S 144° 32'.04 E
38° 05'.38 S 144° 31'.47 E
38° 05'.20 S 144° 30'.93 E.

Only vessels involved in the remediation works are permitted to enter the area.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 143 - Aus 157**

**630(T)/2022 AUSTRALIA - VICTORIA - Cape Duquesne - Scientific instruments**
Maritime Safety Victoria  Notice 165(T)/2019

Scientific instruments exist as follows:

| *Position* | *Remarks* |
|---|---|
| 38° 24'.52 S 141° 16'.26 E | 25m below surface |
| 38° 24'.24 S 141° 17'.48 E | 84m below surface |
| 38° 24'.10 S 141° 18'.04 E | 76m below surface |
| 38° 23'.97 S 141° 18'.60 E | 69m below surface |
| 38° 23'.83 S 141° 19'.16 E | 70m below surface |
| 38° 23'.69 S 141° 19'.73 E | 67m below surface |
| 38° 23'.56 S 141° 20'.25 E | 67m below surface |
| 38° 23'.44 S 141° 20'.73 E | 61m below surface |
| 38° 23'.34 S 141° 21'.18 E | 50m below surface |
| 38° 23'.24 S 141° 21'.57 E | 30m below surface |
| 38° 23'.15 S 141° 21'.91 E | 18m below surface. |

**Chart temporarily affected - Aus 140 - Aus 348 - Aus 349**

**747(T)/2022 AUSTRALIA - VICTORIA - Ninety Mile Beach - Traffic separation scheme southwestwards**
Australian Maritime Safety Authority

Decommissioning of oil and gas infrastructure will take place at Blackback Prod Well (38° 32'.42 S 148° 33'.24 E), Gudgeon Well (38° 30'.82 S 148° 28'.17 E) and Terakihi Well (38° 30'.27 S 148° 32'.89 E).

New temporary shipping fairways and a separation zone have been established to keep transiting ships away from decommissioning activities. The new shipping fairways and separation zone are bound by the following positions:

| | | |
|---|---|---|
| Northeast bound lane | 38° 36'.941 S | 148° 45'.842 E |
| | 38° 39'.507 S | 148° 48'.047 E |
| | 38° 44'.600 S | 148° 23'.000 E |
| | 38° 42'.034 S | 148° 20'.795 E. |
| Southwest bound lane | 38° 33'.407 S | 148° 42'.545 E |
| | 38° 35'.750 S | 148° 44'.746 E |
| | 38° 40'.844 S | 148° 19'.699 E |
| | 38° 38'.500 S | 148° 17'.500 E. |
| Separation zone | 38° 35'.750 S | 148° 44'.746 E |
| | 38° 36'.941 S | 148° 45'.842 E |
| | 38° 42'.034 S | 148° 20'.795 E |
| | 38° 40'.844 S | 148° 19'.699 E. |

The fairways and separation zone come into effect on 1 August 2022 at 0000 UTC and will remain in place until further notice.

Mariners should follow the appropriate traffic lane and navigate in the general direction of traffic flow for that lane. They should, as far as practicable, keep clear of the separation zone.

Due to an increased risk of collision, particularly with vessels that may be restricted in their ability to manoeuvre, mariners should keep a good look out and take early action to avoid collisions.

*Note:* For e-notice users, please see full edition for map.





**Chart temporarily affected - Aus 357 - Aus 487**

**754(T)/2022 AUSTRALIA - BASS STRAIT - Racon non operational**
Australian Maritime Safety Authority Auscoast Warning 171/2021

The racon at the *Flounder A* platform (38° 18'.65 S 148° 26'.36 E) is non operational.

**Chart temporarily affected - Aus 357 - Aus 487**

**465(T)/2023 AUSTRALIA - VICTORIA - Port Phillip Bay - Wreck**
Ports Victoria Notice 218(T)/2023

A wreck, least depth *11$_4$m*, exists in position 37° 55'.93 S 144° 56'.86 E.

**Chart temporarily affected - Aus 143 - Aus 155**

**340(T)/2024 AUSTRALIA - VICTORIA - Port Phillip - Sorrento - Harbour works**
Parks Victoria Notice 155(T)/2024

Construction works are in progress at Sorrento Ferry Terminal (38° 20'.16 S 144° 44'.75 E).

An exclusion zone exists in an area bounded by the coast and the following:

| *Position* | *Remarks* |
|---|---|
| 38° 20'.20 S 144° 44'.72 E | marked by buoy |
| 38° 20'.21 S 144° 44'.74 E | marked by buoy |
| 38° 20'.21 S 144° 44'.76 E | marked by buoy |
| 38° 20'.22 S 144° 44'.80 E | marked by buoy |
| 38° 20'.23 S 144° 44'.83 E | marked by buoy |
| 38° 20'.16 S 144° 44'.78 E. | |

Only vessels involved in the works, Searoad Ferries and Parks Victoria officers are permitted to enter the area.

All hazards to navigation will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 143**

**376(T)/2024 AUSTRALIA - VICTORIA - Ninety Mile Beach - Platform unlit eastwards**
Australian Maritime Safety Authority Auscoast Warning 24/2024

The *Kingfish B* platform, *Mo(U)15s* (38° 35'.82 S 148° 11'.28 E), is unlit.

**Chart temporarily affected - Aus 357 - Aus 487 - Aus 4601 (INT 601)**

**504(T)/2024 AUSTRALIA - VICTORIA - Port Phillip - Point Wilson Bank - Light buoy off station**
Ports Victoria Notice 248(T)/2024

The special light buoy, *Fl.Y.6s* (38° 06'.10 S 144° 31'.24 E), is off station.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 157**

**625(T)/2024 AUSTRALIA - VICTORIA - Western Port - North Arm - Scientific instrument**
Ports Victoria Notice 302(T)/2024

A subsurface scientific instrument, 1m above the seabed, exists in position 38° 19'.79 S 145° 13'.93 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 151**

**659(T)/2024 AUSTRALIA - VICTORIA - Corner Inlet - Scientific instruments eastwards**
*Former Notice* - 169(T)/2024 is cancelled
RPS Group

Subsurface scientific instruments, 20m below the surface, exist in the following positions:
38° 45.'19 S 147° 05'.63 E
38° 50'.96 S 147° 17'.54 E
38° 55'.81 S 146° 50'.01 E
39° 03'.61 S 147° 39'.05 E
39° 21'.71 S 146° 58'.05 E.

**Chart temporarily affected - Aus 357 - Aus 487 - Aus 802**

**933(P)/2024 AUSTRALIA - VICTORIA - Port Phillip - Popes Eye Bank - Shoaling southwards**
Port of Melbourne Operations

Latest survey indicates shoaler depths than those charted exist in the vicinity of position 38° 17'.0 S 144° 42'.2 E.

Mariners are advised to navigate with caution in the area.

Electronic Navigation Charts (ENCs) have been updated. Paper Charts will be updated in due course.

**Chart which will be affected - Aus 143 - Aus 144**

**934(T)/2024 AUSTRALIA - VICTORIA - Port Phillip - Exclusion zone**
Ports Victoria Notice 483(T)/2024

Due to debris on the sea floor, a 20m exclusion zone exists around No9 light beacon (37° 53'.19 S 144° 55'.75 E) extending to the north, east and south.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 155**

**67(T)/2025 AUSTRALIA - VICTORIA - Portland Bay to Childers Cove - Scientific instruments southwards**

RPS Group

Subsurface scientific instruments, 15m above seabed, exist in the following positions:
38° 30'.85 S 141° 49'.17 E
38° 33'.86 S 142° 18'.53 E
38° 40'.79 S 142° 02'.60 E
38° 50'.39 S 142° 35'.64 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 140 - Aus 349**

**152(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Platform unlit eastwards**
Australian Maritime Safety Authority Auscoast Warning 33/2025

The *Mackerel* platform, *Mo(U)15s* (38° 28'.73 S 148° 20'.56 E), is unlit.

**Chart temporarily affected - Aus 357 - Aus 487 - Aus 4060 (INT 60) - Aus 4601 (INT 601)**

**160(T)/2025 AUSTRALIA - BASS STRAIT - Kent Group - Scientific instruments northwards**
Bhagwan Marine

Subsurface scientific instruments, 1.5m above the seabed, exist in the following positions:
39° 04'.63 S 147° 59'.49 E
39° 07'.26 S 147° 16'.15 E
39° 16'.38 S 147° 31'.76 E
39° 21'.68 S 147° 04'.50 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 357 - Aus 487 - Aus 802**

**196(P)/2025 AUSTRALIA - VICTORIA - Port Phillip - Wreck**
Ports Victoria

Latest survey indicates a wreck, with least depth *21.5m*, exists in position 38° 08'.09 S 144° 56'.58 E.

Charts will be updated in due course.

**Chart which will be affected - Aus 143**

**231(T)/2025 AUSTRALIA - VICTORIA - Cape Otway - Artificial reef southwards**
Polaris Marine

Vessels *Constructor 3* and *Leaders Creek* are conducting works to establish an artificial reef in the vicinity of position 38° 58'.08 S 143° 31'.77 E.

Mariners are advised to navigate with caution in the area and keep well clear of the works.

**Chart temporarily affected - Aus 349 - Aus 487**

**235(T)/2025 AUSTRALIA - VICTORIA - Portland - Shoaling**
Port of Portland Notice 62(T)/2025

Shoaling extends approximately 90 metres to the west of the breakwater (38° 20'.65 S 141° 37'.37 E), with a least depth of *6.7m* at the channel toe line. Shoaling decreases as it extends west to a depth of *10m*.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 140**

**268(P)/2025 AUSTRALIA - VICTORIA - Kate Kearney Channel to McLoughlins Entrance - Shoaling**
*Former Notice* - 895(P)/2020 is cancelled
Gippsland Ports

Latest survey shows shoaling and channel realignment in the following channels:
Kate Kearney Channel (38° 41'.7 S 146° 43'.0 E)
Kate Kearney Entrance (38° 41'.5 S 146° 45'.1 E)
Tarra Channel (38° 40'.8 S 146° 45'.7 E)
Boat Harbour Channel (38° 40'.4 S 146° 48'.4 E)
Pelican Channel (38° 39'.3 S 146° 48'.7 E)
Manns Beach Channel (38° 38'.8 S 146° 47'.4 E)
Manns Channel (38° 40'.5 S 146° 49'.6 E)
Oyster Bed Channel (38° 38'.5 S 146° 51'.2 E)
McLoughlins Entrance (38° 37'.8 S 146° 53'.0 E).

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 181**

**271(T)/2025 AUSTRALIA - VICTORIA - Port Fairy - Scientific instrument southwards**
Deakin University

A special light buoy, *Fl.Y.2·5s*, exists in positions 38° 38'.55 S 142° 18'.69 E.

**Chart temporarily affected - Aus 349**

**313(T)/2025 AUSTRALIA - VICTORIA - Portland - Light unlit**
Parks Victoria Notice 158(T)/2025

The light (38° 20'.70 S 141° 37'.18 E), *F.G*, is unlit.

The light (38° 20'.70 S 141° 37'.18 E), *Oc.G.2·5s 19m,* is operating at reduced intensity.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 140**

**348(T)/2025 AUSTRALIA - VICTORIA - Port Phillip - Beaumaris Bay - Obstruction**
Parks Victoria

An above water obstruction exists in position 37° 59'.38 S 145° 02'.83 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 155**

**420(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Platform unlit eastwards**
Australian Maritime Safety Authority Auscoast Warning 142/2025

The *Dolphin* platform, *Mo(U)15s* (38° 29'.24 S 147° 22'.65 E), is unlit.

**Chart temporarily affected - Aus 357 - Aus 487 - Aus 4601 (INT 601)**

**505(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instrument southwards**
RPS Group

A special light buoy, *Q(5)Y.20s*, exists in position 38° 38'.58 S 147° 22'.98 E.

**Chart temporarily affected - Aus 357 - Aus 487**

**507(T)/2025 AUSTRALIA - VICTORIA - Port Campbell - Subsea operations southwards**
Delmar Systems

On or about 15 June 2025, pre-lay mooring operations will be conducted in the vicinity of position 39° 06'.68 S 142° 55'.72 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 349**

**579(T)/2025 AUSTRALIA - VICTORIA - Warrnambool - Scientific instrument southwards unlit**
*Former Notice* - 517(T)/2025 is cancelled
BMT

The special light buoy, *Fl.Y.4s* (38° 29'.27 S 142° 27'.43 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 349**

**634(T)/2025 AUSTRALIA - VICTORIA - Port Campbell - Well plug and abandonment works southwards**
*Former Notice* - 422(T)/2025 is cancelled
Woodside Energy Ltd

The Minerva wells have been plugged and abandoned. Anchors and rig moorings remain in the vicinity of the Minerva wells (38° 42'.38 S 142° 57'.55 E).

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 349**

**637(T)/2025 AUSTRALIA - VICTORIA - Port Phillip - Corio Bay - Scientific instrument**
Ports Victoria Notice 353(T)/2025

A special light buoy, *Fl.Y.3s*, exists in position 38° 05'.00 S 144° 23'.67 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 157**

**683(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instruments southwards**
*Former Notice* - 633(T)/2025 is cancelled
RPS Group

Special light buoys, *Q(5)Y.20s*, exist in positions 38° 33'.74 S 147° 12'.50 E and 38° 38'.63 S 147° 14'.62 E.

**Chart temporarily affected - Aus 357 - Aus 487**

**721(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instruments southwards**
ERM

Subsurface scientific instruments, 1.5m above seabed, exist in the following positions:
38° 41'.37 S 147° 12'.82 E
38° 28'.37 S 147° 18'.00 E
38° 47'.19 S 147° 25'.73 E
38° 38'.10 S 147° 30'.75 E
38° 41'.08 S 147° 48'.67 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 357 - Aus 487**

**891(T)/2025 AUSTRALIA - BASS STRAIT - Mooring buoys**
Delmar Systems , Australian Maritime Safety Authority Auscoast Warning 268/2025

8 lit yellow mooring buoys, *Fl.3s*, exist within 1M radius of 39° 14'.22 S 145° 15'.22 E. 2·5M clearance requested.

**Chart temporarily affected - Aus 487**

**956(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instruments southwards**
RPS Group

Subsurface scientific instruments, 2m above the seabed, exist in the following positions:
38° 52'.66 S 147° 48'.57 E
38° 56'.10 S 147° 52'.89 E
38° 56'.54 S 147° 38'.51 E
38° 56'.71 S 147° 48'.39 E
38° 58'.12 S 147° 42'.68 E
38° 58'.87 S 147° 57'.02 E
38° 59'.32 S 147° 48'.03 E
39° 00'.12 S 147° 53'.67 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 357 - Aus 487**

**957(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instruments southwards**
CSIRO

Subsurface scientific instruments, 4m above the seabed, exist in areas bounded by the following positions:
40° 47'.42 S 146° 18'.38 E
40° 46'.86 S 147° 26'.26 E
40° 21'.48 S 147° 25'.81 E
40° 21'.92 S 146° 17'.94 E;
and
39° 46'.00 S 146° 32'.15 E
39° 44'.33 S 146° 34'.84 E
39° 19'.71 S 146° 06'.65 E
39° 21'.37 S 146° 04'.17 E;
and
39° 37'.69 S 147° 47'.37 E
39° 36'.54 S 147° 50'.71 E
39° 03'.70 S 147° 25'.54 E
39° 04'.88 S 147° 22'.85 E;
and
38° 53'.41 S 147° 16'.12 E
38° 38'.13 S 147° 00'.68 E
38° 39'.78 S 146° 58'.22 E
38° 55'.05 S 147° 13'.40 E;
and
38° 39'.86 S 147° 52'.47 E
38° 14'.89 S 147° 29'.25 E
38° 16'.52 S 147° 26'.81 E
38° 41'.30 S 147° 49'.71 E;
and
37° 57'.67 S 148° 00'.32 E
38° 22'.94 S 148° 22'.51 E
38° 21'.20 S 148° 24'.92 E
37° 56'.13 S 148° 02'.78 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 357 - Aus 487 - Aus 798 - Aus 800 - Aus 802**

**962(T)/2025 AUSTRALIA - VICTORIA - Warrnambool - Scientific instruments southwards**
CSIRO

Subsurface scientific instruments, 4m above the seabed, exist in an area bounded by the following positions:
38° 39'.88 S 142° 28'.24 E
38° 41'.25 S 142° 35'.79 E
38° 35'.49 S 142° 37'.71 E
38° 31'.49 S 142° 33'.29 E
38° 27'.58 S 142° 23'.43 E
38° 29'.64 S 142° 09'.90 E
38° 35'.02 S 142° 12'.47 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 349**

**1055(T)/2025 AUSTRALIA - VICTORIA - Port Campbell - Mooring buoy southwards**
Delmar Systems

A lit yellow mooring buoy, *Fl.3s*, exists in position 39° 05'.71 S 142° 55'.22 E. 2·5M clearance requested.

**Chart temporarily affected - Aus 349**

**1085(T)/2025 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instrument southwards**
Ocean Winds

A light buoy, *Fl.Y.4s*, with AIS exists in position 38° 58'.42 S 147° 51'.54 E.

**Chart temporarily affected - Aus 357 - Aus 487**

**130(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Limeburners Point - Light beacon unlit**
Parks Victoria Notice 018(T)/2026

The light beacon, *Fl.R.3s* (38° 08'.57 S 144° 23'.14 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 157**

**177(T)/2026 AUSTRALIA - VICTORIA - Warratah Bay - Scientific instrument**
Deakin University

A special light buoy, *Fl.Y.2·5s*, exists in position 38° 51'.19 S 146° 00'.44 E.

**Chart temporarily affected - Aus 801 - Aus 802**

**349(T)/2026 AUSTRALIA - VICTORIA - Bass Strait - Cable laying operations**
Gulf Agency Company (Australia)

Cable laying operations will be conducted in Bass Strait as part of the Honomoana and Talaylink cable systems. Cable lay and post lay inspection activities will occur along the route shown in the diagram and mariners are advised to keep clear of vessel, *Resolute* during activities. Further advice on specific areas of activity will be issued through the AUSCOAST warning system.

*Note:* For e-notice users, please see full edition for map.





**Chart temporarily affected - Aus 349 - Aus 357 - Aus 487 - Aus 801 - Aus 802**

**402(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Wedge Spit - Scientific instrument**
Parks Victoria Notice 227(T)/2026

A special light buoy, *Fl.Y.4s*, exists in position 38° 02'.84 S 144° 38'.73 E.

**Chart temporarily affected - Aus 143 - Aus 157**

**498(T)/2026 AUSTRALIA - BASS STRAIT - Cable laying operations**
Gulf Agency Company (Australia)

Cable laying operations will be conducted in Bass Strait as part of the Talaylink cable system. Cable lay and post lay inspection activities will occur along the route shown in the diagram and mariners are advised to keep clear of vessel, *Dependable* during activities. Further advice on specific areas of activity will be issued through the AUSCOAST warning system.

*Note:* For e-notice users, please see full edition for map.




**Chart temporarily affected - Aus 349 - Aus 487 - Aus 4601 (INT 601) - Aus 4709 (INT 709)**

**537(T)/2026 AUSTRALIA - BASS STRAIT - Cable laying operations**
Gulf Agency Company (Australia)

Cable laying operations will be conducted in Bass Strait as part of the Honomoana cable system. Cable lay and post lay inspection activities will occur along the route shown in the diagram and mariners are advised to keep clear of vessel, *Responder* during activities. Further advice on specific areas of activity will be issued through the AUSCOAST warning system.

*Note:* For e-notice users, please see full edition for map.




**Chart temporarily affected - Aus 143 - Aus 349 - Aus 357 - Aus 487 - Aus 801 - Aus 802 - Aus 4601 (INT 601) - Aus 4709 (INT 709)**

**612(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Collins Bay - Buoy off station**
Parks Victoria Notice 320(T)/2026

The special buoy, (38° 19'.10 S 144° 43'.64 E), is off station.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 144**

**613(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Portsea - Light buoy unlit**
Parks Victoria Notice 321(T)/2026

The special light buoy, *Fl.Y.5s* (38° 18'.82 S 144° 42'.75 E), is unlit.

**Chart temporarily affected - Aus 143 - Aus 144**

**614(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Point Nepean - Light buoy unlit; light beacon unlit**
Parks Victoria Notice 322(T)/2026, 323(T)/2026

The special light buoy, *Fl.Y.5s* (38° 17'.95 S 144° 39'.14 E), is unlit.

The special light beacon, *Fl.Y.5s* (38° 18'.17 S 144° 39'.40 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 144**

**619(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Mordialloc - Buoy off station**
Parks Victoria Notice 319(T)/2026

The special buoy, (*3*8° 00'.26 S 145° 04'.60 E), is off station.

**Chart temporarily affected - Aus 143 - Aus 155**

**653(T)/2026 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instruments southwards**
RPS Group

Subsurface scientific instruments, 55m below the surface, exist in the following positions:
38° 48'.01 S 147° 41'.57 E
38° 52'.01 S 148° 09'.55 E
38° 58'.69 S 147° 43'.78 E
38° 59'.47 S 147° 56'.97 E.

**Chart temporarily affected - Aus 357 - Aus 487**

**655(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Scientific instruments**
*Former Notice* - 574(T)/2025 is cancelled
Parks Victoria Notice 333(T)/2025, 343/2026

Special light buoys, *Fl.Y.2·5s,* exist in the following positions:
37° 58'.72 S 144° 59'.73 E
38° 08'.16 S 144° 45'.18 E
38° 09'.73 S 145° 03'.26 E
38° 18'.09 S 144° 52'.36 E
38° 18'.95 S 144° 42'.74 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 143 - Aus 144 - Aus 155 - Aus 157**

**701(T)/2026 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instruments southwards**
*Former Notice* - 632(T)/2025 is cancelled
GHD

Subsurface scientific instruments, 2m above seabed, exist in the following positions:
38° 31'.61 S 147° 08'.96 E
38° 28'.08 S 147° 13'.55 E
38° 37'.24 S 147° 14'.53 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 357**

**702(T)/2026 AUSTRALIA - VICTORIA - Ninety Mile Beach - Scientific instruments**
Safe Transport Victoria Notice 373(T)/2026

Subsurface scientific instruments, 4m above seabed, exist in positions 38° 37'.53 S 146° 56'.68 E and 38° 13'.91 S 147° 25'.80 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 181 - Aus 357**

**704(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Mordialloc - Buoy off station**
Parks Victoria Notice 365(T)/2026

The special buoy (*38*° 00'.09 S 145° 04'.41 E) is off station.

**Chart temporarily affected - Aus 155**

**795(T)/2026 AUSTRALIA - VICTORIA - Corner Inlet - Scientific instruments**
Bhagwan Marine

Special light buoys, *Fl(5)Y.20s*, exist in positions 38° 52'.85 S 146° 42'.29 E and 38° 57'.65 S 146° 35'.50 E.

**Chart temporarily affected - Aus 181 - Aus 802**

**796(T)/2026 AUSTRALIA - VICTORIA - Ninety Mile Beach - Drill rig eastwards**
MODU *Valaris 107*

Drill rig *Valaris 107* is conducting drilling operations in position 38° 17'.79 S 147° 40'.57 E.

**Chart temporarily affected - Aus 357**

**801(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Carrum - Buoy off station**
Parks Victoria Notice 401(T)/2026

The special buoy, *No2* (38° 03'.09 S 145° 04'.43 E), is off station.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 143 - Aus 155**

**839(T)/2026 AUSTRALIA - VICTORIA - Port Fairy - Obstruction; buoy southwards**
J Cripps

A white buoy, marking fishing equipment on the seabed, exists in position 38° 57'.44 S 142° 15'.62 E.

Mariners area advised to navigate with caution in the area.

**Chart temporarily affected - Aus 349**

**895(T)/2026 AUSTRALIA - VICTORIA - Port Campbell - Scientific instruments southwestwards**
Amplitude Energy

Subsurface scientific instruments exist on the seabed in positions 38° 39'.54 S 142° 49'.35 E and 38° 39'.54 S 142° 49'.56 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 349**

**898(T)/2026 AUSTRALIA - BASS STRAIT - TASMANIA - Curtis Island to Bellbuoy Beach - Survey operations**
Gulf Agency Company (Australia)

On or about 12 October 2026, USV *Elite* will depart Melbourne to begin survey operations on or about 28 October 2026 between the following positions:
39° 36'.62 S 146° 39'.18 E
39° 53'.05 S 146° 52'.75 E
41° 00'.31 S 146° 49'.78 E
41° 02'.50 S 146° 50'.31 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 167 - Aus 487**

**962(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Hobsons Bay - Dredging operations**
Parks Victoria Notice 482(T)/2026

Dredging operations are in progress in vicinity of position 37° 51'.50 S 144° 56'.95 E.

A pipeline extends from the dredge to the beach and will be marked every 100m by special light buoys.

All hazards to navigation will be marked by flashing yellow lights.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 155**

**999(T)/2026 AUSTRALIA - VICTORIA - Cape Conran - Subsea operations southwestwards**
Amplitude Energy

Vessel *SEA1-Aquamarine* will begin inspection, maintenance and repair works in the vicinity of positions 38° 00'.26 S 148° 26'.65 E and 38° 01'.57 S 148° 27'.04 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 357**

**1000(T)/2026 AUSTRALIA - VICTORIA - Cape Conran - Survey operations southwestwards**
Emperor Energy Limited

On or about 23 November 2026, vessel *Bass Trek*, with a towed array, will begin geophysical survey operations in the vicinity of position 38° 09'.06 S 148° 33'.18 E.

Mariners are advised to navigate with caution in the area. 500m clearance requested.

**Chart temporarily affected - Aus 357**

**1001(T)/2026 AUSTRALIA - VICTORIA - Ninety Mile Beach - Decommissioning works**
Woodside Energy Ltd

Vessel *Fortitude* and support vessels are conducting decommissioning activities in an area bounded by the following positions:
38° 15'.27 S 148° 32'.13 E
38° 18'.91 S 148° 35'.08 E
38° 31'.91 S 148° 26'.08 E
38° 40'.91 S 148° 13'.28 E
38° 42'.25 S 148° 08'.25 E
38° 34'.98 S 147° 43'.92 E
38° 20'.61 S 147° 27'.93 E
38° 05'.39 S 147° 42'.26 E
38° 13'.54 S 148° 02'.66 E
38° 15'.47 S 148° 17'.15 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 357**

**1004(T)/2026 AUSTRALIA - VICTORIA - Port Phillip - Green Point - Buoy off station**

Parks Victoria  Notice 500(T)/2026

The special buoy (37° 56'.06 S 144° 59'.48 E) is off station.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 155**

**627(T)/2016 AUSTRALIA - TASMANIA - Pipe Clay Head to Pitt Water - Scientific instruments**
*Former Notice* - 309(T)/2014 is cancelled
University of Tasmania

Subsurface scientific instruments exist in the following positions:
42° 48'.25 S 147° 29'.91 E
42° 48'.29 S 147° 31'.42 E
42° 48'.43 S 147° 30'.02 E
42° 49'.18 S 147° 34'.71 E
42° 50'.70 S 147° 33'.57 E
42° 50'.74 S 147° 35'.11 E
42° 50'.90 S 147° 36'.91 E
42° 51'.05 S 147° 32'.08 E
42° 51'.33 S 147° 35'.89 E
42° 51'.69 S 147° 34'.85 E
42° 51'.82 S 147° 30'.92 E
42° 51'.82 S 147° 33'.36 E
42° 52'.35 S 147° 32'.10 E
42° 52'.70 S 147° 36'.29 E
42° 52'.94 S 147° 34'.16 E
42° 53'.24 S 147° 31'.16 E
42° 53'.79 S 147° 32'.67 E
42° 53'.88 S 147° 37'.33 E
42° 54'.20 S 147° 35'.44 E
42° 54'.37 S 147° 30'.53 E
42° 54'.47 S 147° 40'.80 E
42° 54'.67 S 147° 33'.87 E
42° 54'.92 S 147° 40'.78 E
42° 55'.13 S 147° 31'.80 E
42° 55'.36 S 147° 40'.76 E
42° 55'.81 S 147° 40'.74 E
42° 56'.99 S 147° 39'.68 E
42° 57'.04 S 147° 38'.01 E
42° 57'.15 S 147° 39'.22 E
42° 57'.15 S 147° 37'.41 E
42° 57'.28 S 147° 36'.79 E
42° 57'.40 S 147° 36'.20 E
42° 57'.51 S 147° 35'.59 E
42° 57'.62 S 147° 34'.99 E
42° 57'.73 S 147° 34'.44 E
42° 57'.86 S 147° 33'.85 E
42° 57'.96 S 147° 33'.30 E.

**Chart temporarily affected - Aus 171 - Aus 796**

**263(T)/2018 AUSTRALIA - TASMANIA - Devonport - Shoaling**
HydroSurvey Australia

Shoaling exists in the Mersey River between positions 41° 11'.20 S 146° 21'.98 E and 41° 11'.48 S 146° 22'.10 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 164**

**522(T)/2020 AUSTRALIA - TASMANIA - D'Entrecasteaux Channel - Tower Bay - Harbour works; light buoys**
Marine and Safety Tasmania Notice M98/2020

Mooring works are in progress, marked by special light buoys as follows:

| *Position* | *Remarks* |
|---|---|
| 43° 23'.38 S 147° 02'.34 E | *Fl.Y.4s* |
| 43° 23'.46 S 147° 02'.27 E | *Fl.Y.4s* |
| 43° 23'.36 S 147° 01'.98 E | |
| 43° 23'.28 S 147° 02'.05 E | |

**Chart temporarily affected - Aus 173**

**673(T)/2021 AUSTRALIA - TASMANIA - Maria Island - Scientific instruments**
Marine and Safety Tasmania

Subsurface scientific instruments exist on the seabed in the following positions:
42° 40'.08 S 147° 58'.04 E
42° 39'.99 S 147° 58'.60 E
42° 39'.91 S 147° 59'.16 E
42° 39'.82 S 147° 59'.72 E
42° 39'.74 S 148° 00'.28 E
42° 39'.08 S 148° 10'.40 E
42° 39'.28 S 148° 10'.92 E
42° 39'.48 S 148° 11'.44 E
42° 39'.68 S 148° 11'.96 E
42° 39'.88 S 148° 12'.49 E
42° 40'.08 S 148° 13'.01 E
42° 40'.28 S 148° 13'.53 E
42° 40'.48 S 148° 14'.05 E
42° 40'.68 S 148° 14'.57 E
42° 40'.88 S 148° 15'.10 E
42° 41'.08 S 148° 15'.62 E
42° 41'.28 S 148° 16'.14 E
42° 41'.48 S 148° 16'.66 E
42° 41'.68 S 148° 17'.18 E
42° 41'.88 S 148° 17'.71 E
42° 42'.08 S 148° 18'.23 E
42° 42'.28 S 148° 18'.75 E
42° 42'.48 S 148° 19'.27 E
42° 42'.68 S 148° 19'.79 E
42° 42'.87 S 148° 20'.32 E
42° 43'.07 S 148° 20'.84 E
42° 43'.26 S 148° 21'.26 E.

**Chart temporarily affected - Aus 766 - Aus 797**

**677(T)/2021 AUSTRALIA - TASMANIA - North West Bay - Mooring area**
Marine and Safety Tasmania Notice M106/2021

A mooring area, marked by special light buoys, exists in an area bounded by the following positions:
43° 02'.75 S 147° 17'.91 E
43° 02'.66 S 147° 18'.04 E
43° 02'.74 S 147° 18'.15 E
43° 02'.82 S 147° 18'.00 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 171**

**722(T)/2021 AUSTRALIA - TASMANIA - Port Dalrymple - Bell Bay - Harbour works**
Marine and Safety Tasmania Notice M207/2021

Remediation works are in progress at Bell Bay Berth 6 (41° 08'.39 S 146° 51'.14 E).

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 167**

**916(T)/2022 AUSTRALIA - TASMANIA - Devonport - Virtual AIS**
Marine and Safety Tasmania Notice M373(T)/2022

A reduced width of the channel is marked by virtual AIS as follows:

| *Position* | *Remarks* |
|---|---|
| 41° 10'.43 S 146° 21'.85 E | starboard lateral AIS |
| 41° 10'.45 S 146° 21'.93 E | port lateral AIS |
| 41° 10'.45 S 146° 21'.84 E | starboard lateral AIS |
| 41° 10'.50 S 146° 21'.82 E | starboard lateral AIS |
| 41° 10'.51 S 146° 21'.91 E | port lateral AIS |
| 41° 10'.57 S 146° 21'.89 E | port lateral AIS. |

**Chart temporarily affected - Aus 164**

**83(T)/2023 AUSTRALIA - TASMANIA - Devonport - Harbour works**
Marine and Safety Tasmania Notice M10(T)/2023

Demolition works are in progress in the vicinity of berth 3E in an area bounded by the coast and the following positions:
41° 11'.30 S 146° 22'.14 E
41° 11'.32 S 146° 22'.09 E
41° 11'.15 S 146° 21'.97 E
41° 11'.11 S 146° 21'.97 E
41° 11'.07 S 146° 21'.99 E
41° 10'.94 S 146° 21'.98 E
41° 10'.94 S 146° 22'.00 E.

Vessels will display appropriate lights and shapes and will monitor VHF Ch 14.

Mariners are advised not to enter the works area unless they are required to utilise the swing basin. These vessels must obtain approval from Devonport VTS prior to arrival and departure.

**Chart temporarily affected - Aus 164**

**375(T)/2023 AUSTRALIA - TASMANIA - Devonport - Mersey River - Berth**
Marine and Safety Tasmania Notice M175/2023

Three piles exist in the vicinity of position 41° 11'.44 S 146° 22'.01 E for the temporary berth, Devonport Berth 6 West.

**Chart temporarily affected - Aus 164**

**639(T)/2023 AUSTRALIA - TASMANIA - River Derwent - Flowerpot Point - Kelp longlines; light buoys**
*Former Notice* - 513(T)/2023 is cancelled
Marine and Safety Tasmania Notice M214(T)/2023, M266(T)/2023

Subsurface kelp longlines exist in an area, marked by light buoys, bounded by the following positions:
43° 01'.24 S 147° 20'.24 E
43° 01'.24 S 147° 20'.31 E
43° 01'.04 S 147° 20'.31 E
43° 01'.04 S 147° 20'.24 E.

Vessels not directly involved in the research activities are prohibited from entering the area.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 171 - Aus 173**

**876(T)/2023 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instruments**
Marine and Safety Tasmania Notice M338(T)/2023

Scientific instruments, 10m below the surface, exist in positions 42° 18'.49 S 145° 23'.01 E and 42° 20'.80 S 145° 25'.22 E.

**Chart temporarily affected - Aus 177 - Aus 792**

**85(T)/2024 AUSTRALIA - TASMANIA - Macquarie Harbour - Lit barge**
Marine and Safety Tasmania Notice M10/2024

The barge *Wombat* which is marked by a light, *F*, exists in position 42° 17'.55 S 145° 22'.18 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 177**

**133(T)/2024 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instrument**
Marine and Safety Tasmania Notice M36/2024

A scientific instrument, 10m below the surface, exists in position 42° 22'.79 S 145° 28'.84 E.

**Chart temporarily affected - Aus 177 - Aus 792**

**134(T)/2024 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instruments**
Marine and Safety Tasmania Notice M37/2024

Scientific instruments marked by special buoys exist in the following positions:
42° 16'.92 S 145° 17'.62 E
42° 17'.06 S 145° 19'.03 E
42° 17'.16 S 145° 16'.00 E
42° 19'.38 S 145° 19'.27 E
42° 21'.72 S 145° 32'.22 E
42° 22'.08 S 145° 24'.46 E
42° 24'.24 S 145° 27'.62 E
42° 26'.04 S 145° 26'.91 E.

**Chart temporarily affected - Aus 177 - Aus 792**

**343(T)/2024 AUSTRALIA - TASMANIA - Franklin Sound - Lady Barron - Wreck**
Marine and Safety Tasmania Notice M159(T)/2024

A wreck marked by an isolated danger light buoy, *Q(2)5s*, exists in position 40° 12'.85 S 148° 14'.74 E.

**Chart temporarily affected - Aus 179**

**69(T)/2025 AUSTRALIA - TASMANIA - Macquarie Harbour - Table Head - Scientific instrument**
Marine and Safety Tasmania Notice M430(T)/2024

A scientific instrument marked by a special buoy exists in position 42° 16'.86 S 145° 16'.84 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 177**

**113(T)/2025 AUSTRALIA - TASMANIA - River Derwent - Limekiln Point - Light beacon destroyed**
*Former Notice* - 74(T)/2025 is cancelled
Marine and Safety Tasmania Notice M028(T)/2025

The starboard lateral light beacon, *Fl.G.2s* (42° 50'.80 S 147° 20'.22 E), has been destroyed, a starboard lateral light buoy, *Fl.G.2s*, exist in situ.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 171 - Aus 796**

**424(T)/2025 AUSTRALIA - TASMANIA - Burnie - Aquaculture trial and research area northwards**
*Former Notice* - 384(T)/2024 is cancelled
Marine and Safety Tasmania Notice M208(T)/2025, M209(T)/2025

An aquaculture trial and research area marked by special light buoy, *Fl.Y.3s*, exists in an area bounded by the following positions:
40° 56'.68 S 145° 56'.03 E
40° 56'.39 S 145° 56'.59 E
40° 55'.90 S 145° 56'.15 E
40° 56'.18 S 145° 55'.59 E.

All vessels not directly involved in activities with the research project are prohibited from entering the area.

**Chart temporarily affected - Aus 163**

**685(T)/2025 AUSTRALIA - TASMANIA - Port Dalrymple - Barrel Rock - Beacon destroyed**
Marine and Safety Tasmania Notice M256(T)/2025

The port lateral beacon (41° 03'.99 S 146° 47'.48 E) has been destroyed; a special buoy exists in situ.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 167**

**687(T)/2025 AUSTRALIA - TASMANIA - Spring Bay - Paddys Point to Alginate Bay - Pipe laying operations**
Marine and Safety Tasmania Notice M261(T)/2025

Works are in progress to install a pipeline between Paddys Point (42° 32'.31 S 147° 55'.51 E) and Alginate Bay (42° 32'.50 S 147° 54'.85 E).

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 797**

**724(T)/2025 AUSTRALIA - TASMANIA - Ansons Bay - Beacon destroyed**
Marine and Safety Tasmania Notice M264(T)/2025

The beacon (41° 03'.75 S 148° 17'.91 E) has been destroyed.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 767**

**1009(T)/2025 AUSTRALIA - TASMANIA - Low Head - Obstruction northwestwards**
Marine and Safety Tasmania Notice M348(T)/2025

A lost anchor chain exists in the vicinity of position 40° 57'.05 S 146° 44'.77 E.

Mariners are advised to navigate with caution and to avoid anchoring or trawling in the area.

**Chart temporarily affected - Aus 487**

**1011(T)/2025 AUSTRALIA - TASMANIA - River Derwent - Tasman Bridge - Harbour works**
Marine and Safety Tasmania Notice M352(T)/2025

Maintenance works on the western side of the bridge (42° 51'.91 S 147° 20'.45 E) are in progress.

A gantry will be installed under the bridge, resulting in reduced clearance.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 171**

**1058(T)/2025 AUSTRALIA - TASMANIA - Mercury Passage - Scientific instrument**
*Former Notice* - 111(T)/2025 is cancelled
Marine and Safety Tasmania Notice M360(T)/2025

A special light buoy, *Fl.Y.3s*, exists in position 42° 31'.83 S 148° 01'.69 E.

**Chart temporarily affected - Aus 766 - Aus 797**

**1092(T)/2025 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instruments**
Marine and Safety Tasmania Notice M362/2025

111 subsurface receiver buoys, 4m below the surface, will be deployed throughout Macquarie Harbour.

Individual locations of each buoy can be found in AHO ENC products.

Mariners should navigate with caution and avoid anchoring or trawling in the vicinity.

**Chart temporarily affected - Aus 177**

**80(T)/2026 AUSTRALIA - TASMANIA - River Derwent - Storm Bay - Frederick Henry Bay - Sea trials**
MAST M015/2026

INCAT vessel *China Zorrilla* will be conducting sea trials in the Storm Bay, Frederick Henry Bay and River Derwent areas. A 300 meter clearance is requested at all times, due to speed and possible sudden deviations of course, along with high volumes of water movement from the vessels jet propulsion.

Mariners are advised to navigate with caution in the vicinity of the craft.

**Chart temporarily affected - Aus 171 - Aus 173 - Aus 795 - Aus 796**

**311(T)/2026 AUSTRALIA - TASMANIA - Great Oyster Bay - Fish aggregating device removed**
Marine and Safety Tasmania Notice M106(T)/2026

The special light buoy, *Fl.Y.3s FAD* (42° 10'.40 S 148° 10'.72 E), has been temporarily removed.

**Chart temporarily affected - Aus 766**

**500(T)/2026 AUSTRALIA - TASMANIA - Cape Sorell - Light buoy off station westwards**
Marine and Safety Tasmania Notice M186(T)/2026

The light buoy, *Fl(5)Y.20s* (42° 11'.94 S 145° 03'.29 E), is off station.

**Chart temporarily affected - Aus 792**

**622(T)/2026 AUSTRALIA - TASMANIA - Tasman Island - Scientific instrument eastwards**
Australian Antarctic Division

Subsurface scientific instrument exists on the seabed at position 43° 12'.01 S 148° 12'.31 E.

**Chart temporarily affected - Aus 796 - Aus 797**

**927(T)/2026 AUSTRALIA - TASMANIA - Flinders Island - Survey operations; tide gauges**
*Former Notice* - 841(T)/2026 is cancelled
Ocean Infinity

Vessel *Ocean Dynasty* is conducting survey operations in an area bounded by the following positions:
39° 30'.41 S 147° 27'.39 E
39° 42'.34 S 147° 50'.56 E
39° 42'.34 S 147° 50'.56 E
39° 37'.30 S 148° 02'.23 E
39° 15'.66 S 147° 56'.36 E
39° 22'.21 S 147° 27'.42 E.

Tide gauges exist on the seabed in the following positions:
39° 31'.49 S 147° 27'.52 E
39° 21'.86 S 147° 26'.84 E
39° 19'.16 S 147° 37'.21 E
39° 16'.74 S 147° 46'.86 E
39° 15'.14 S 147° 56'.90 E
39° 22'.89 S 147° 58'.95 E
39° 30'.75 S 148° 00'.91 E
39° 39'.74 S 148° 03'.12 E
39° 43'.34 S 147° 51'.32 E
39° 38'.38 S 147° 43'.79 E
39° 33'.91 S 147° 33'.49 E.

Orange spherical floats exist in the following positions;
39° 30'.75 S 148° 00'.91 E
39° 39'.74 S 148° 03'.12 E

Special light buoys, *Fl.Y.3·2s*, may be deployed in the vicinity of the above positions.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 357 - Aus 487 - Aus 800**

## PAPUA NEW GUINEA and SOUTH PACIFIC

**789(T)/2018 PAPUA NEW GUINEA - Bismarck Sea - Fish aggregating devices**
National Maritime Safety Authority PNG Warning 9/2018

17 fish aggregating devices exist in an area bounded by the following positions:
4° 30'.0 S 149° 55'.0 E
4° 40'.0 S 149° 55'.0 E
4° 40'.0 S 150° 45'.0 E
4° 30'.0 S 150° 45'.0 E.

Mariners are advised to navigate with caution.

**Chart temporarily affected - Aus 4622 (INT 622)**

**286(P)/2019 PAPUA NEW GUINEA - Madang Harbour - Shoaling**
LADS Flight

Latest survey shows shoaler depths than those charted may exist in an area bounded by the following positions:
05° 04'.51 S 145° 48'.06 E
05° 11'.75 S 145° 47'.82 E
05° 11'.91 S 145° 49'.61 E
05° 10'.14 S 145° 50'.36 E
05° 04'.14 S 145° 48'.99 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - PNG 646**

**346(T)/2019 PAPUA NEW GUINEA - Huon Gulf - Light buoy off station**
National Maritime Safety Authority PNG Notice 9(T)/2017

The isolated danger light buoy, *Q(2)5s* (6° 48'.38 S 146° 58'.28 E), is off station.

**Chart temporarily affected - PNG 643**

**1110(T)/2019 PAPUA NEW GUINEA - Oreore Channel - Light buoy off station**
National Maritime Safety Authority PNG Coastal Navigation Warning 39/2019

The port lateral light buoy, *Q.R* (10° 13'.68 S 150° 52'.78 E), is off station.

**Chart temporarily affected - PNG 628**

**668(T)/2020 PAPUA NEW GUINEA - Dauan Island - Light altered**
HMAS *Mermaid*

The light, *Fl.R.6s* (9° 25'.38 S 142° 32'.07 E), has been temporarily altered to *F.R*.

**Chart temporarily affected - Aus 841**

**826(P)/2020 PAPUA NEW GUINEA - Batumata Point - Shoaling**
LADS Flight

Latest survey shows shoaler depths than those charted may exist in and around the islands and reefs in the area between Galovi (Howard) Reef (10° 11'.1 S 148° 08'.7 E) and Eunoro Island (10° 23'.6 S 149° 27.3 E).

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - PNG 506 - PNG 507 - PNG 623**

**118(T)/2021 PAPUA NEW GUINEA - Madehas Island - Light unlit**
National Maritime Safety Authority PNG

The light, *Fl.10s 137m 16M* (5° 27'.63 S 154° 38'.06 E), is unlit.

**Chart temporarily affected - Aus 399 - Aus 4604 (INT 604) - Aus 4622 (INT 622) - PNG 397 - PNG 684**

**985(T)/2021 PAPUA NEW GUINEA - Saibai Island - Shoaling**
*Former Notice* - 201(T)/2021 is cancelled
HMAS *Paluma* , HMAS *Mermaid*

Latest survey indicates shoaler depths than those charted exist in an area bounded by the following positions:
9° 20'.66 S 142° 36'.94 E
9° 20'.15 S 142° 39'.81 E
9° 17'.86 S 142° 48'.32 E
9° 21'.86 S 142° 47'.07 E
9° 21'.01 S 142° 40'.60 E
9° 21'.80 S 142° 37'.67 E
9° 22'.75 S 142° 37'.04 E
9° 22'.72 S 142° 35'.37 E
9° 22'.46 S 142° 34'.10 E
9° 21'.74 S 142° 34'.60 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart temporarily affected - Aus 840 - Aus 841**

**327(T)/2022 PAPUA NEW GUINEA - Bonvouloir Islands - Aulelowa (Hastings) Island - Light unlit**
National Maritime Safety Authority PNG Coastal Navigation Warning 8/2022

The light, *Fl(2)6s 8m 10M* (10° 20'.48 S 151° 52'.07 E), is unlit.

**Chart temporarily affected - PNG 509 - PNG 512**

**785(T)/2022 PACIFIC OCEAN - Scientific instruments**
UKHO

Grey pillar buoys exist in the following positions:
5° 02'.3 N 164° 49'.9 E
0° 00'.8 N 164° 59'.8 E
1° 59'.9 S 164° 58'.6 E
5° 01'.0 S 165° 10'.0 E
8° 02'.2 S 164° 46'.4 E.

**Chart temporarily affected - Aus 4604 (INT 604)**

**794(T)/2022 PAPUA NEW GUINEA - Huon Gulf - Fish aggregating devices**
National Maritime Safety Authority PNG Coastal Navigation Warning 8/2018

23 fish aggregating devices exist in an area bounded by the following positions:
7° 00'.0 S 147° 40'.0 E
7° 55'.0 S 147° 40'.0 E
7° 55'.0 S 148° 50'.0 E
7° 00'.0 S 148° 50'.0 E.

Mariners are advised to navigate with caution.

**Chart temporarily affected - Aus 4622 (INT 622) - PNG 386 - PNG 521 - PNG 522 - PNG 523**

**829(T)/2022 PAPUA NEW GUINEA - Dekatuwe (Bright) Island - Light beacon unlit**
*Former Notice* - 500(T)/2022 is cancelled
National Maritime Safety Authority PNG Notice 10/2022, 14/2022

The light beacon, *Fl.2·5s 16m 10M* (10° 31'.89 S 151° 12'.74 E), is unlit.

**Chart temporarily affected - PNG 509**

**830(T)/2022 PAPUA NEW GUINEA - Kanaweya (Shortland) Reefs to Nuakata Passage - Light beacons unlit**
National Maritime Safety Authority PNG Notice 15/2022, 16/2022

The light beacons, *Fl(3)12s 11m 10M* (10° 30'.70 S 151° 08'.13 E) and *Fl(2)10s 7m 6M* (10° 23'.60 S 151° 00'.77 E), are unlit.

**Chart temporarily affected - PNG 508 - PNG 509 - PNG 628**

**831(T)/2022 PAPUA NEW GUINEA - Wadei Island - Light beacon unlit**
National Maritime Safety Authority PNG Notice 17/2022

The starboard lateral light beacon, *Fl(2)G.8s 7m 3M* (2° 39'.45 S 150° 37'.68 E), is unlit.

**Chart temporarily affected - PNG 543 - PNG 666**

**278(T)/2023 PAPUA NEW GUINEA - Boli Point - Trobriand Islands - Light unlit**
National Maritime Safety Authority PNG

The light, *Fl.G.5s* (08° 33'.77 S 151° 01'.10 E) is unlit.

**Chart temporarily affected - PNG 516 - PNG 637**

**279(T)/2023 PAPUA NEW GUINEA - Bomatu Point - Trobriand Islands - Light unlit**
National Maritime Safety Authority PNG

The light, *Fl(3)15s 31m 10M* (08° 24'.09 S 151° 07'.20 E) is unlit.

**Chart temporarily affected - PNG 516 - PNG 637**

**282(T)/2023 PAPUA NEW GUINEA - Galogalohi (Gallows) Reef - Goschen Strait - Light unlit**
National Maritime Safety Authority PNG

The light, *Fl.5s 7m 10M* (10° 15'.44 S 151° 10'.39 E), is unlit.

**Chart temporarily affected - PNG 509 - PNG 513**

**283(T)/2023 PAPUA NEW GUINEA - Kitava Island - Trobriand Islands - Light unlit**
National Maritime Safety Authority PNG

The light, *Q* (08° 37'.70 S 151° 18'.34 E) is unlit.

**Chart temporarily affected - PNG 515 - PNG 516 - PNG 637**

**285(T)/2023 PAPUA NEW GUINEA - Tamiaris Reef - Laughlan Islands - Light unlit**
National Maritime Safety Authority PNG

The light, *Fl(2)8s* (09° 16'.84 S 153° 39'.38 E), is unlit.

**Chart temporarily affected - PNG 514**

**974(T)/2023 PAPUA NEW GUINEA - Buka Passage - Light beacon unlit**
National Maritime Safety Authority PNG Coastal Navigation Warning 23/2023

The light beacon, *Fl.2·5s 7m 10M* (5° 24'.39 S 154° 42'.69 E), is unlit.

**Chart temporarily affected - Aus 399 - Aus 4622 (INT 622) - PNG 397 - PNG 684**

**289(T)/2024 PAPUA NEW GUINEA - Queen Carola Harbour - Light beacon unlit**

National Maritime Safety Authority PNG  Coastal Navigation Warning 7/2024

The light beacon, *Fl.R.6s* (5° 08'.18 S 154° 32'.92 E), is unlit.

**Chart temporarily affected - PNG 684**

**290(T)/2024 PAPUA NEW GUINEA - Redscar Head - Light unlit**
National Maritime Safety Authority PNG  Coastal Navigation Warning 5/2024

The light, *Fl.10s 77m 10M* (9° 15'.91 S 146° 54'.03 E), is unlit.

**Chart temporarily affected - PNG 379 - PNG 647**

**746(P)/2024 PAPUA NEW GUINEA - Rabaul - Coastline**
Australian Hydrographic Office

The coastline between Karavia Bay (4° 16'.84 S 152° 09'.83 E) and Nodup (4° 11'.66 S 152° 12'.32 E) may differ to what is currently charted.

Mariners are advised to navigate with caution in the area.

Charts will updated in due course.

**Chart which will be affected - PNG 545 - PNG 554 - PNG 680**

**445(T)/2025 PAPUA NEW GUINEA - Kitumala (Fortification) Point - Light unlit**
National Maritime Safety Authority PNG  Coastal Navigation Warning 4/2025

The light, *Fl(2)8s 27m 8M* (6° 19'.16 S 147° 48'.35 E), is unlit.

**Chart temporarily affected - Aus 4622 (INT 622) - PNG 386 - PNG 387**

**832(T)/2025 PAPUA NEW GUINEA - Loa Islet - Light unlit**
National Maritime Safety Authority PNG  Coastal Navigation Warning 19/2025

The light, *Fl.8s 43m 10M* (11° 26'.96 S 154° 23'.90 E), is unlit.

**Chart temporarily affected - Aus 4060 (INT 60) - Aus 4604 (INT 604) - PNG 511**

**911(T)/2025 PAPUA NEW GUINEA - Dawapia (The Beehives) - light beacon unlit**
National Maritime Safety Authority

The light beacon, *Fl(2)R.6s4M* (04° 14'.2 S 152° 10'.1 E), is unlit.

**Chart temporarily affected - PNG 545 - PNG 554 - PNG 680**

**912(T)/2025 PAPUA NEW GUINEA - Ward Hunt Strait - Ipoteto Island - Light unlit**
National Maritime Safety Authority PNG

The light, *Fl(2)8s 23m 10M* (9° 37'.78 S 150° 01'.36 E), is unlit.

**Chart temporarily affected - Aus 4060 (INT 60) - Aus 4604 (INT 604) - PNG 518 - PNG 519**

**947(T)/2025 PAPUA NEW GUINEA - Malendok Island - Light beacon unlit**
National Maritime Safety Authority PNG  Coastal Navigation Warning 24/2025

The west cardinal light beacon, *Q(9)15s* (3° 27'.25 S 153° 10'.42 E), is unlit.

**Chart temporarily affected - PNG 539**

**251(T)/2026 PAPUA NEW GUINEA - Cape Gerhards - Light unlit**
National Maritime Safety Authority PNG  Coastal Navigation Warning 2/2026

The light, *Fl(3)12s 22m 10M* (6° 44'.70 S 147° 34'.56 E), is unlit.

**Chart temporarily affected - Aus 4622 (INT 622) - PNG 523**

**252(T)/2026 PAPUA NEW GUINEA - Caution Bay - Light buoy off station**
National Maritime Safety Authority PNG Coastal Navigation Warning 1/2026

The east cardinal light buoy, *Q(3)10s TB1* (9° 20'.44 S 146° 58'.59 E), is off station.

**Chart temporarily affected - PNG 647 - PNG 648**

**729(T)/2026 PAPUA NEW GUINEA - Admiralty Islands - Nauna Island - Light unlit**
National Maritime Safety Authority PNG Coastal Navigation Warning 6/2026

The light, *Fl.5s 54m 14M* (2° 13'.19 S 148° 11'.78 E), is unlit.

**Chart temporarily affected - Aus 4603 (INT 603) - Aus 4604 (INT 604) - Aus 4622 (INT 622) - PNG 391 - PNG 392**

**730(T)/2026 PAPUA NEW GUINEA - Nessup Island - Light beacon unlit**
National Maritime Safety Authority PNG

The light beacon, *Fl.8s 7m 10M* (5° 54'.95 S 148° 07'.82 E), is unlit.

**Chart temporarily affected - PNG 386 - PNG 387 - PNG 673**

**731(T)/2026 PAPUA NEW GUINEA - Nussing Island - Light unlit**
National Maritime Safety Authority PNG Coastal Navigation Warning 8/2026

The light, *Fl.6s 20m 10M* (6° 39'.37 S 147° 51'.79 E), is unlit.

**Chart temporarily affected - Aus 4622 (INT 622) - PNG 386 - PNG 523 - PNG 653**

**822(T)/2026 PAPUA NEW GUINEA - Raymonde Shoal to Eve Shoal - Lights unlit**
National Maritime Safety Authority PNG Coastal Navigation Warning 11/2026; 12/2026

The light, *Fl.5s 16m 10M* (8° 13'.22 S 148° 17'.39 E), is unlit.

The light beacon, *Fl(2) 8s 16m 10M* (8° 31'.17 S 148° 25'.39 E), is unlit.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4622 (INT 622) - PNG 521**

**823(T)/2026 PAPUA NEW GUINEA - Veale Reef to Greaves Reef - Lights unlit**
National Maritime Safety Authority PNG Coastal Navigation Warning 9/2026, 10/2026

The light, *Fl.2·5s 9m 10M* (9° 11'.93 S 149° 28'.70 E), is unlit.

The light, *Fl(3)12s 11m 10M* (9° 10'.83 S 149° 27'.05 E), is unlit.

**Chart temporarily affected - PNG 519 - PNG 520**

## EAST TIMOR

NIL

## MISCELLANEOUS

**678(T)/2017 SOLOMON ISLANDS - Lungga Point - Light beacon unlit**
Australian Hydrographic Service

The light beacon, *Fl(3)20s 10m 5M* (9° 24'.26 S 160° 01'.66 E), is unlit.

**Chart temporarily affected - SLB 101 - SLB 201**

**91(P)/2018 SOLOMON ISLANDS - Ghizo Island - Shoaling**
Secretariat of the Pacific Community

Latest survey shows shoaler depths than those charted may exist in and around the islands and reefs in the area between Naru Island (8° 08'.3 S 156° 55'.1 E) and Sepo Island (8° 03'.2 S 156° 49.5 E).

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - SLB 102 - SLB 301 - SLB 302**

**987(T)/2018 TIMOR-LESTE - Dili - Light unlit**
HMAS *Paluma*

The light, *Fl.R.4s* (8° 33'.20 S 125° 34'.70 E), is unlit.

**Chart temporarily affected - Aus 901**

**406(P)/2020 SOLOMON ISLANDS - Port Noro to Kuri Point - Shoaling**
*Former Notice* - 184(P)/2020 is cancelled
Australian Hydrographic Office , HMAS *Leeuwin*

Latest survey shows shoaler depths than those charted may exist in areas bounded by the following positions:
8° 15'.07 S 157° 11'.77 E
8° 15'.43 S 157° 11'.52 E
8° 15'.78 S 157° 11'.47 E
8° 15'.78 S 157° 12'.00 E
8° 15'.07 S 157° 11'.89 E;
and
8° 19'.68 S 157° 11'.83 E
8° 21'.27 S 157° 12'.62 E
8° 21'.09 S 157° 13'.14 E
8° 19'.05 S 157° 12'.30 E
8° 19'.17 S 157° 11'.76 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - SLB 102**

**80(P)/2022 SOUTHERN OCEAN - Antarctica - Mawson - Shoaling**
Australian Antarctic Division

Latest survey indicates shoaling in the approach to Mawson in the following locations

67° 25'.00 S 062° 46'.20 E
67° 29'.58 S 062° 52'.92 E
67° 30'.08 S 062° 50'.45 E
67° 30'.70 S 062° 53'.35 E
67° 30'.45 S 062° 51'.56 E
67° 35'.00 S 062° 52'.25 E

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 600 (INT 9036)**

**228(T)/2024 SOUTHERN OCEAN - Macquarie Island - Scientific instrument southwestwards**
CSIRO

A subsurface scientific instrument, 90m below the surface, exists in the position 55° 47'.62 S 152° 43'.56 E.

**Chart temporarily affected - Aus 4074 (INT 74)**

**387(T)/2024 SOLOMON ISLANDS - Maru Sound - Nort East Entrance - Light buoys off station**
Solomon Islands Maritime Authority

The port lateral light buoy, *Fl.R.3s* (9° 46'.81 S 160° 51'.08 E), and the starboard lateral light buoy, *Fl.G.3s* (9° 46'.54 S 160° 50'.48 E), are off station.

**Chart temporarily affected - SLB 101**

**506(T)/2024 SOLOMON ISLANDS - Lengo Channel - Taivu Point - Light beacon unlit**
Solomon Islands Maritime Safety Administration

The light beacon, *LFl(2)20s 10m 5M* (9° 24'.54 S 160° 21'.02 E), is unlit.

**Chart temporarily affected - SLB 201 - SLB 304**

**768(P)/2024 SOLOMON ISLANDS - Diamond Narrows to Munda Bar - Shoaling**
Aero Asahi Corporation

Latest survey indicates shoaler depths than those charted may exist between Diamond Narrows (8° 15'.62 S 157° 11'.69 E) and Munda Bar (8° 20'.94 S 157° 12'.72 E).

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - SLB 102 - SLB 302**

**938(P)/2024 SOLOMON ISLANDS - Blackett Strait - Shoaling**
Aero Asahi Corporation

Latest survey indicates shoaler depths than those charted may exist in Blackett Strait in an area between longitudes 157° 06'.68 E and 157° 09'.94 E.

Drying coral exists in position 8° 07'.94 S 157° 09'.74 E.

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - SLB 102**

**940(T)/2024 SOLOMON ISLANDS - Honiara - Kua Bay - Light buoy unlit**
Solomon Islands Maritime Authority Notice 12/2024

The isolated danger light buoy, *Fl(2)10s* (9° 25'.89 S 159° 57'.76 E), is unlit.

**Chart temporarily affected - SLB 101**

**631(P)/2025 SOUTHERN OCEAN - Shoaling**
Department of Foreign Affairs and Trade

Latest survey indicates shoaler depths than those charted may exist as follows:

| *Position* | *Depth* |
|---|---|

40° 31'.22 S 165° 46'.17 E *2922m*
40° 33'.83 S 162° 09'.41 E *2738m*
40° 54'.61 S 154° 09'.96 E *2343m*
40° 53'.57 S 153° 14'.58 E *2476m*
40° 24'.25 S 151° 36'.45 E *2423m*
38° 59'.70 S 132° 31'.94 E *1621m*
38° 53'.74 S 126° 37'.73 E *2729m*
38° 50'.15 S 122° 35'.56 E *2485m*
38° 47'.20 S 119° 25'.55 E *566m*
38° 27'.28 S 116° 50'.88 E *630m*
38° 44'.94 S 117° 00'.04 E *2855m.*

Mariners are advised to navigate with caution in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 4060 (INT 60) - Aus 4074 (INT 74) - Aus 4601 (INT 601) - Aus 4708 (INT 708) - Aus 4709 (INT 709) - Aus 4710 (INT 710)**

**892(T)/2025 SOLOMON ISLANDS - Honiara - Point Cruz - Light buoy removed**
Solomon Islands Maritime Authority

The special light buoy, *Fl.Y.10s* (9° 25'.45 S 159° 57'.53 E), has been temporarily removed.

**Chart temporarily affected - SLB 101**

**1093(T)/2025 NEW ZEALAND - Australia - Tasman Sea - Submarine cable removal**
Mertech Marine

On or about the 16 December 2025, Mertech Marine will be conducting cable recovery of the Tasman 2 Cable between Auckland and Sydney between the following positions:
36° 50'.8 S 174° 08'.8 E
37° 00'.6 S 173° 00'.3 E
36° 46'.9 S 164° 32'.0 E
35° 56'.1 S 160° 21'.3 E
36° 04'.1 S 159° 48'.5 E
35° 30'.8 S 156° 07'.5 E
34° 53'.1 S 154° 23'.1 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 489 - Aus 4060 (INT 60) - Aus 4601 (INT 601) - Aus 4602 (INT 602)**

**83(T)/2026 SOLOMON ISLANDS - Nusatupe Island - Light beacon relit; topmark destroyed**
*Former Notice* - 805(T)/2025 is cancelled
Solomon Islands Maritime Authority Notice 20/2025

The topmark on light beacon, *Fl(3)R.10s 11m 5M* (8° 05'.55 S 156° 51'.82 E), has been destroyed.

**Chart temporarily affected - SLB 102 - SLB 301 - SLB 302**

**123(P)/2026 SOUTHERN OCEAN - Heard Island - Shoaling**
Australian Antarctic Division

Latest survey indicates shoaler depths than those charted exist in an area bounded by the following positions:
53° 02'.19 S 73° 37'.27E
53° 01'.53 S 73° 38'.24E
53° 03'.13 S 73° 40'.89E
53° 03'.78 S 73° 40'.37E.

Mariners are advised to avoid navigating in the area.

Charts will be updated in due course.

**Chart which will be affected - Aus 605**

**266(T)/2026 SOLOMON ISLANDS - Guadalcanal Island - Geotechnical and geophysical operations northwards**
Solomon Islands Maritime Authority Notice 4/2026

Vessel *Ocean Surveyor* is conducting geotechnical and geophysical survey operations between the following positions:
9° 25'.61 S 160° 00'.00 E
8° 51'.91 S 159° 54'.43 E
8° 23'.47 S 160° 28'.68 E
7° 10'.30 S 159° 53'.15 E
5° 16'.84 S 160° 23'.89 E.

The vessel will monitor VHF Ch 13 and Ch 16.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4604 (INT 604) - SLB 101 - SLB 201 - SLB 303 - SLB 304**

**408(T)/2026 SOLOMON ISLANDS - Honiara - Light unlit**
Solomon Islands Maritime Authority Notice 7/2026

The leading light, *Fl.G.5s 6M* (9° 25'.81 S 159° 57'.31 E), is unlit;

**Chart temporarily affected - SLB 101**

**659(T)/2026 SOLOMON ISLANDS - Tulaghi Island - Wreck**
UKHO

A dangerous wreck exists in position 9° 05'.73 S 160° 08'.83 E.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - SLB 103 - SLB 201 - SLB 304**

**891(T)/2026 SOUTHERN OCEAN - USV operations**
CSIRO

The USV *Saildrone* is approximately 7m long and 4m tall, painted orange with a white all-around light on top, and marked "SAILDRONE."

The vehicle will be operating in the Southern Ocean, broadcasting AIS and travelling at speeds up to 3 knots.

Mariners are advised to navigate with caution in the area.

**Chart temporarily affected - Aus 4074 (INT 74) - Aus 4601 (INT 601) - Aus 4709 (INT 709) - Aus 4710 (INT 710)**