



Australian Notices to Mariners are the authority for correcting Australian Charts

AUSTRALIAN NOTICES TO MARINERS

© Commonwealth of Australia 2005 - Copyright restrictions apply to Notices to Mariners

 Notices 189 - 230

Published fortnightly by the Australian Hydrographic Service

R NAIRN,
Hydrographer of Australia

- SECTIONS.**
- I. **Australian Notices to Mariners, including blocks and notes.**
 - II. **Amendments to Admiralty List of Lights and Fog Signals, Vol K**
 - III. **Navigational Warnings.**
 - IV. **Hydrographic Reports.**
 - V. **Amendments to Admiralty List of Radio Signals (NP 281(2), 282, 283(2), 285, 286(4))**
 - VI. **Amendments to Admiralty Sailing Directions (NP 9, 13, 14, 15, 17, 33, 34, 35, 36, 39, 44, 51, 60, 61, 62, 100, 136)**

[British Admiralty Notices to Mariners](#)
[New Zealand Notices to Mariners](#)

The substance of these notices should be inserted on the charts affected.

Bearings are referred to the true compass and are reckoned clockwise from 000° (North) to 359°; those relating to lights are given as seen by an observer from seaward. Positions quoted in permanent notices relate to the horizontal datum for the chart(s). When preliminary or temporary notices affect multiple charts, positions will be provided in relation to only one horizontal datum and that datum will be specified. When the multiple charts do not have a common horizontal datum, mariners will be required to adjust the position(s) for those charts not on the specified datum. The range quoted for a light is its nominal range. Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices. A star () adjacent to the number of a notice indicates that the notice is based on original information.*

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 Wollongong, NSW 2500 (Fax 02-4221 8599, e-mail Hydro.NTM@defence.gov.au or, alternatively by filling in and submitting the [Hydrographic Notes](#) forms located on the web site – www.hydro.gov.au), immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).

Copies of these notices can be obtained from the AUSTRALIAN HYDROGRAPHIC OFFICE, 8 Station Street, Wollongong; Distributors for the sale of Australian Navigational Products; AHS website www.hydro.gov.au or register for eNotices at www.hydro.gov.au/enotices/enotices.htm.

The Notices may be copied for the purpose of inserting their substance on official charts and other publications. However, any copies of the notices may not be sold for profit.

IMPORTANT NOTICE

This edition of Notices to Mariners includes all significant information affecting AHS products which the AHS has become aware of since the last edition. All reasonable efforts have been made to ensure the accuracy and completeness of the information, including third party information, on which these updates are based. The AHS regards third parties from which it receives information as reliable, however the AHS cannot verify all such information and errors may therefore exist. The AHS does not accept liability for errors in third party information.

This work is copyright. Apart from any use permitted under the Copyright Act 1968, no part may be reproduced by any process, adapted, communicated or commercially exploited without prior written permission from The Commonwealth represented by the Australian Hydrographic Service. Copyright in some of the material in this publication may be owned by another party and permission for the reproduction of that material must be obtained from the owner.

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 5

4 March 2005

Notices	Aus Chart, INT Chart, BA Pubs
189.....	AZ 60000, NP 51, 282
190.....	Aus 139, 143, 144, 158, 200, 209, 219, 243, 260, 366, 371, 444, 715, 726, 788, 817, 4601, 4727, INT 601, 727
191.....	Aus 209
192.....	Aus 219
193.....	Aus 235, 236
194.....	Aus 236
195.....	Aus 241
196.....	Aus 819
197.....	Aus 820
198.....	Aus 270
199.....	Aus 312
200.....	Aus 333, 753
201.....	Aus 112, AX 63112
202.....	Aus 334, 754
203.....	Aus 777, 778
204.....	Aus 791
205.....	Aus 143, 144, 148
206.....	Aus 357A, 358, 423
207.....	Aus 358, 359, 423
208.....	Aus 358, 359, 423
209.....	Aus 806
210(T).....	Aus 197, 806, 807, 808, 809, 810, 811, 812, 813, AX 70197, 70808
211(T).....	Aus 199
212(T).....	Aus 236
213(T).....	Aus 236
214(T).....	Aus 241, 817
215(T).....	Aus 242
216(T).....	Aus 260, 367, 370, 822, AX 60260
217(T).....	Aus 268, AU421148
218(T).....	Aus 381, 567, 625, 629
219(T).....	Aus 303, 304
220(T).....	Aus 20, 720, 722, AX 70722
221(T).....	Aus 29, 308, 309, 310, 315, 316, 318, 721, 722, AX 70308, 70309, 70721, 70722
222(T).....	Aus 754
223(T).....	Aus 777
224(T).....	Aus 141
225(P).....	Aus 349
226(T).....	Aus 355
227(T).....	Aus 356
228(T).....	Aus 150, 151
229(T).....	Aus 150, 151
230(T).....	Aus 357A, 358

189 AUSTRALIA - Products.

AHO (A128039), British Admiralty (A127552 & A128244).

Miscellaneous chart

Chart	Published	Title	Scale	Remarks
AZ 60000	18/2/2005	Northern Australia Exercise Area - 10 Metre Contour Interval GOP	1:1 000 000	Fleet use only

Admiralty publication

NP No	Title	Date	Remarks
NP 51	New Zealand Pilot (Sixteenth Edition 2004)	2/9/2004	New Zealand Pilot (Fifteenth Edition 2001) is cancelled. This volume contains a CD ROM version.
NP 282	Admiralty List of Radio Signals. Radio Aids to Navigation, Satellite Navigation Systems, Legal Time, Radio Time Signals and Electronic Position Fixing System. Edition 2005/06	10/2/2005	The 2004/05 edition of NP 282 is cancelled.

190* AUSTRALIA - Miscellaneous correction.

AHO (A121281, A126664, A128050, A128220 & A128273).

Aus 139 (plan, Ardrossan Harbor Approaches) [169/2004]

Substitute	accompanying legend for ZOC CATEGORIES	34° 23'.4 S	137° 54'.0 E
	accompanying note for Historic Wreck note outside N border		

Aus 143 [113/2005]

Substitute	accompanying note for Entrance Depths note	37° 56'.0 S	144° 35'.0 E
	legend, <i>ENTRANCE DEPTHS - PORT PHILLIP</i> (see Note), for legend	38° 20'.0 S	144° 37'.3 E

Aus 144 [113/2005]

Substitute	accompanying note for Entrance Depths note	38° 16'.0 S	144° 35'.5 E
	legend, <i>ENTRANCE DEPTHS - PORT PHILLIP</i> (see Note), for legend	38° 19'.8 S	144° 35'.0 E

Aus 158 [62/2005]

Substitute	accompanying legend for ZOC CATEGORIES	38° 21'.9 S	145° 01'.0 E
	accompanying note for Historic Wreck note	38° 22'.6 S	144° 53'.3 E
	accompanying note for ESSA note	38° 22'.2 S	144° 53'.3 E
	accompanying note for Entrance Depths note	38° 22'.3 S	144° 56'.4 E
	legend, <i>ENTRANCE DEPTHS - PORT PHILLIP</i> (see Note), for legend	38° 19'.8 S	144° 37'.0 E

Aus 200 [915/2004]

Substitute	accompanying note for Historic Wreck note	33° 53'.3 S	151° 08'.5 E
------------	---	-------------	--------------

Aus 209 [158/2005]

Substitute	accompanying legend for ZOC CATEGORIES	32° 46'.0 S	152° 03'.2 E
------------	--	-------------	--------------

Aus 219 (plan, Hastings River) [972/2004]

Substitute	accompanying legend for ZOC CATEGORIES	31° 25'.4 S	152° 51'.1 E
	accompanying note for Historic Wreck note	31° 25'.3 S	152° 50'.9 E

Aus 243 [38/2005]			
Insert	magenta legend, <i>Military Exercise Area (see note)</i> accompanying Military Exercise Areas note	24° 35'.7 S 24° 56'.2 S	152° 34'.7 E 152° 27'.0 E
Aus 260 [90/2005]			
Insert	green legend, <i>Particularly Sensitive Sea Area (see Note)</i>	22° 20'.0 S	150° 47'.5 E
	magenta legend, <i>Designated Shipping Area (see Note)</i>	22° 21'.5 S	150° 47'.5 E
	accompanying PSSA note	22° 20'.0 S	150° 08'.7 E
	accompanying DSA note	22° 22'.0 S	150° 08'.7 E
Aus 366 [117/2005]			
Insert	magenta legend, <i>Military Exercise Area (see note)</i> accompanying Military Exercise Areas note	24° 35'.0 S 24° 25'.0 S	152° 34'.0 E 151° 00'.0 E
Aus 371 [45/2005]			
Substitute	accompanying note for PSSA note	20° 22'.0 S	146° 55'.0 E
	accompanying note for DSA note	20° 02'.0 S	146° 55'.0 E
	accompanying note for Historic Wreck note	20° 22'.5 S	146° 42'.5 E
	accompanying AMJ note for TSA note	20° 09'.0 S	146° 55'.0 E
	accompanying note for SRS note	20° 13'.0 S	147° 06'.0 E
	accompanying note for Compulsory Pilotage note	20° 09'.0 S	147° 06'.0 E
Aus 444 [167/2005]			
Substitute	accompanying AMJ note for TSA note	33° 00'.5 S	136° 07'.5 E
Aus 715 [103/2004]			
Substitute	accompanying legend for ZOC CATEGORIES	12° 17'.0 S	136° 21'.0 E
Aus 726 [274/2004]			
Substitute	accompanying note for AMJ note	14° 45'.0 S	127° 43'.5 E
	accompanying legend for ZOC CATEGORIES	14° 50'.5 S	127° 53'.3 E
Aus 788 [482/2004]			
Substitute	accompanying note for Historic Wreck note	38° 26'.0 S	143° 44'.5 E
Amend	legend to <i>See Aus 143</i>	38° 16'.8 S	144° 02'.6 E
Delete	Note	38° 24'.6 S	143° 57'.2 E
Aus 817 [975/2004]			
Insert	magenta legend, <i>Military Exercise Area (see Note)</i> accompanying Military Exercise Areas note	24° 35'.0 S 25° 42'.5 S	152° 34'.0 E 152° 43'.5 E
Substitute	accompanying note for PSSA note	25° 47'.5 S	152° 38'.0 E
	accompanying note for DSA note	25° 44'.0 S	152° 38'.0 E
	accompanying note for Historic Wreck note	25° 45'.8 S	152° 32'.5 E
Aus 4601 (INT 601) [1009/2004]			
Substitute	accompanying note for AMJ note	35° 40'.0 S	148° 05'.0 E
	accompanying note for EEZ note	34° 30'.0 S	148° 05'.0 E
Aus 4727 (INT 727) [167/2005]			
Substitute	accompanying note for Historic Wreck note	32° 32'.0 S	124° 04'.0 E

191* AUSTRALIA - NEW SOUTH WALES - Port Stephens - Corlette Point to Lemon Tree Passage - Nav aids.

List of Lights Vol K/2005 - 2772.57, 2772.58, 2775.8

NSW Maritime Authority Notice HI0413 & HI0506 (A119825, A126340 & A128134).

Aus 209 [190/2005]

Insert	north cardinal cylindrical light buoy, Q, with topmark	32° 43'.460 S	152° 02'.577 E
Amend	light to <i>Fl. R.</i> 3s	32° 42'.99 S	152° 06'.27 E
	light to Q	32° 42'.98 S	152° 06'.24 E
Substitute	port lateral light beacon, <i>Fl. R.</i> 3s, without topmark, for special light beacon	32° 43'.58 S	152° 02'.49 E
	starboard lateral conical buoy without topmark, for beacon	32° 43'.64 S	152° 02'.42 E
Delete	depth 0 ₃ m	32° 43'.62 S	152° 02'.46 E
	beacon	32° 43'.60 S	152° 02'.46 E

192* AUSTRALIA - NEW SOUTH WALES - Cape Hawke Harbour - Lights altered.

List of Lights Vol K/2205 - 2782.4, 2782.41

NSW Maritime Authority (A128096).

Aus 219 (plan, Cape Hawke Harbour) [190/2005]

Amend	light to <i>F. Bu</i>	32° 10'.41 S	152° 30'.57 E
		32° 10'.45 S	152° 30'.36 E

193* AUSTRALIA - QUEENSLAND - Flinders Reef - Light buoy altered in position.

Maritime Safety Queensland Notice 68/2005 (A128132)

Aus 235 [867/2004]

Move	north cardinal light buoy to	26° 58'.4 S	153° 29'.3 E
		26° 58'.36 S	153° 29'.37 E

Aus 236 [160/2005]

Move	north cardinal light buoy to	26° 58'.4 S	153° 29'.3 E
		26° 58'.36 S	153° 29'.37 E

194* AUSTRALIA - QUEENSLAND - Moreton Bay - Customs and quarantine relocated.

Maritime Safety Queensland Notice 48/2005 (A126663).

Aus 236 [193/2005]

Insert	customs office	27° 27'.75 S	153° 11'.22 E
	quarantine office	27° 27'.68 S	153° 11'.10 E

Delete	customs office	27° 11'.9 S	153° 06'.6 E
	quarantine office	27° 11'.9 S	153° 06'.5 E

Aus 236 (plan, Manly Boat Harbour)

Insert	customs office	27° 27'.770 S	153° 11'.300 E
	quarantine office	27° 27'.727 S	153° 11'.300 E

195* AUSTRALIA - QUEENSLAND - Dayman Point - Harbour works.

AHO (A128240).

Aus 241 [772/2004]

Insert	accompanying block	25° 17'.5 S	152° 55'.0 E
--------	------------------------------------	-------------	--------------

196* AUSTRALIA - QUEENSLAND - Boulton Reef - Depth.
AHO (A126753).

Aus 819 [161/2005]

Insert	50m contour between	23° 44'.23 S	152° 18'.03 E
		23° 43'.78 S	152° 17'.44 E

Delete	50m contour between	23° 44'.23 S	152° 18'.03 E
		23° 43'.78 S	152° 17'.91 E
	depth 8m and enclosing contour	23° 43'.78 S	152° 17'.44 E
		23° 43'.9 S	152° 17'.8 E

197* AUSTRALIA - QUEENSLAND - Goodwin Shoal - Depth.
AHO (A128057).

Aus 820 [88/2005]

Substitute	depth, 7 ₈ m, for depth 6 ₃ m	22° 54'.5 S	151° 43'.6 E
------------	---	-------------	--------------

198* AUSTRALIA - QUEENSLAND - Pipon Islets - Rock.
AHO V5/272 (A128040).

Aus 270 (plan, Cape Melville and Pipon Islets) [738/2004]

Insert	rock which covers and uncovers, semi-enclosed by danger line to E	14° 07'.144 S	144° 32'.043 E
--------	---	---------------	----------------

199* AUSTRALIA - TIMOR SEA - Bayu-Undan - Buoys.
ConcoPhillips Australia (A128016 & A128215).

Aus 312 [38/2005]

Insert	mooring buoy	11° 05'.22 S	126° 39'.07 E
		11° 05'.21 S	126° 40'.58 E
		11° 05'.27 S	126° 37'.29 E

200* WESTERN AUSTRALIA - Jurien Bay - Scientific instrument.
DPI WA (A128042).

Aus 333 [987/2004]

Insert	special spherical light buoy, <i>Fl(5)</i> Y. 20s, without topmark	30° 17'.57 S	114° 54'.79 E
--------	--	--------------	---------------

Aus 753 [131/2005]

Insert	special spherical light buoy, <i>Fl(5)</i> Y. 20s, without topmark	30° 17'.57 S	114° 54'.79 E
--------	--	--------------	---------------

201* WESTERN AUSTRALIA - Cottesloe - Scientific instrument.
DPI WA (A128042).

Aus 112 [132/2005]

Insert	special spherical light buoy, <i>Fl(5)</i> Y. 20s, without topmark	31° 58'.66 S	115° 41'.20 E
--------	--	--------------	---------------

Delete	depth 11 ₉ m	31° 58'.7 S	115° 41'.2 E
--------	-------------------------	-------------	--------------

AX 63112 [132/2005]

Insert	special spherical light buoy, <i>Fl(5)</i> Y. 20s, without topmark	31° 58'.66 S	115° 41'.20 E
--------	--	--------------	---------------

Delete	depth 11 ₉ m	31° 58'.7 S	115° 41'.2 E
--------	-------------------------	-------------	--------------

202* WESTERN AUSTRALIA - Rottnest Island - Scientific instrument.

Former Notice - 952(T)/2004 is cancelled

DPI WA (A126333).

Aus 334 [539/2004]

Insert special spherical light buoy, *Fl(5)* Y. 20s, without topmark 32° 05'.73 S 115° 24'.48 E

Aus 754 [132/2005]

Insert special spherical light buoy, *Fl(5)* Y. 20s, without topmark 32° 05'.73 S 115° 24'.48 E

203* SOUTH AUSTRALIA - Spencer Gulf - Depths.

AMSA (A126197), AHO (A126196).

Aus 777 [790/2004]

Insert accompanying block 34° 00'.0 S 137° 15'.0 E
accompanying block 33° 45'.0 S 137° 27'.0 E

Delete pecked line between 34° 09'.18 S 137° 09'.22 E
34° 08'.28 S 137° 09'.93 E

Aus 778 [1024/2004]

Insert accompanying plan, *Yarraville Shoal* 32° 35'.0 S 138° 00'.0 E
accompanying block 33° 15'.0 S 137° 33'.0 E
accompanying block 33° 45'.0 S 137° 27'.0 E

204* AUSTRALIA - TASMANIA - Hally Bayley Shoal - Symbol southwestwards.

UKHO (A126339).

Aus 791 [NC 12/11/2004]

Delete symbol 40° 50'.2 S 144° 14'.6 E

205* AUSTRALIA - VICTORIA - Port Phillip - Scientific instruments.

Former Notices – 956(T)/2004 and 968(T)/2004 are cancelled

Victorian Notices 7 & 19/2005 (A128110 & A128115).

Aus 143 [190/2005]

Insert special spherical light buoy, *Fl.* Y. 5s, without topmark 38° 21'.64 S 144° 41'.49 E

Aus 144 [190/2005]

Insert special spherical light buoy, *Fl(4)* Y. 10s, without topmark 38° 21'.62 S 144° 41'.36 E
special spherical light buoy, *Fl.* Y. 3s, without topmark 38° 21'.62 S 144° 41'.61 E
special spherical light buoy, *Fl.* Y. 5s, without topmark 38° 21'.64 S 144° 41'.49 E

Aus 158 [190/2005]

Insert special spherical light buoy, *Fl(4)* Y. 10s, without topmark 38° 21'.62 S 144° 41'.36 E
special spherical light buoy, *Fl.* Y. 3s, without topmark 38° 21'.62 S 144° 41'.61 E
special spherical light buoy, *Fl.* Y. 5s, without topmark 38° 21'.64 S 144° 41'.49 E

206* AUSTRALIA - VICTORIA - Cape Conran - Light range altered.

List of Lights Vol K/2005 - 2555

MARSYS (A127608).

Aus 357A [66/2005]

Amend light range to 10M

37° 48'.9 S

148° 43'.7 E

Aus 358 [66/2005]

Amend light range to 10M

37° 48'.9 S

148° 43'.7 E

Aus 423 [157/2005]

Amend light range to 10M

37° 48'.9 S

148° 43'.7 E

207* AUSTRALIA - VICTORIA - Wingan Point - Light range altered.

List of Lights Vol K/2005 - 2557

MARSYS (A127608).

Aus 358 [206/2005]

Amend light range to 6M

37° 44'.9 S

149° 30'.9 E

Aus 359 [88/2005]

Amend light range to 6M

37° 44'.9 S

149° 30'.9 E

Aus 423 [206/2005]

Amend light range to 6M

37° 44'.9 S

149° 30'.9 E

208* AUSTRALIA - VICTORIA - Little Rame Head - Light range altered.

List of Lights Vol K/2005 - 2557.5

AMSA AN357-01 (A128048).

Aus 358 [207/2005]

Amend light range to 18M

37° 41'.1 S

149° 40'.2 E

Aus 359 [207/2005]

Amend light range to 18M

37° 41'.1 S

149° 40'.2 E

Aus 423 [207/2005]

Amend light range to 18M

37° 41'.1 S

149° 40'.2 E

209* AUSTRALIA - VICTORIA - Mallacoota - Light range altered.

List of Lights Vol K/2005 - 2561

MARSYS (A127608).

Aus 806 [863/2004]

Amend light range to 6M

37° 33'.6 S

149° 45'.6 E

210(T)/2005 AUSTRALIA - NEW SOUTH WALES - Green Cape to Lennox Head - Scientific instruments.

Former Notice - 879(T)/2004 is cancelled

NSW Department of Commerce (A127984 & A127985).

Scientific instruments, marked by special light buoys *Fl(5) Y. 20s*, exist as follows:

<i>Location</i>	<i>Position (WGS 84 datum)</i>	<i>Chart Affected</i>
Green Cape	37° 18'.1 S 150° 11'.1 E	Aus 806
Batemans Bay	35° 42'.4 S 150° 20'.9 E	Aus 807
Port Kembla	34° 28'.5 S 151° 01'.6 E	Aus 808, AX 70808
Deewhy Head	33° 46'.8 S 151° 25'.3 E	Aus 197, Aus 809, AX 70197
Crowdy Head	31° 49'.5 S 152° 51'.6 E	Aus 810, Aus 811
Coffs Harbour	30° 21'.6 S 153° 16'.4 E	Aus 812
* Lennox Head	28° 49'.6 S 153° 39'.8 E	Aus 813

* Indicates revised entry.

Mariners are not to use the buoys as moorings.

Chart temporarily affected - Aus 197 - Aus 806 - Aus 807 - Aus 808 - Aus 809 - Aus 810 - Aus 811 - Aus 812 - Aus 813 - AX 70197 - AX 70808.

211(T)/2005 AUSTRALIA - NEW SOUTH WALES - Botany Bay - Dolls Point to Monterey - Dredging; silt curtain.

Date - Until 30 June 2005

NSW Maritime Authority Notice SU0502 (A128657).

A dredge, displaying appropriate day shapes and navigation lights, is operating in position 33° 59'.36 S 151° 09'.12 E.

A silt curtain, marked by east cardinal buoys, exists between positions 33° 58'.273 S 151° 09'.315 E and 33° 58'.273 S 151° 09'.239 E.

Chart temporarily affected - Aus 199.

212(T)/2005 AUSTRALIA - QUEENSLAND - Moreton Bay - Green Island - Light beacon destroyed; light buoy.

Maritime Safety Queensland Notice 62(T)/2005 (A128680).

The port lateral light beacon (27° 24'.96 S 153° 14'.51 E) has been destroyed; a port lateral light buoy, *Q. R.*, exists in situ.

Chart temporarily affected - Aus 236.

213(T)/2005 AUSTRALIA - QUEENSLAND - Moreton Bay - North Stradbroke Island - Harbour works.

Date - Until 31 July 2005

Maritime Safety Queensland Notice 59(T)/2005 (A128681).

The jetty head (27° 30'.33 S 153° 24.00 E) is closed for maintenance.

Chart temporarily affected - Aus 236.

214(T)/2005 AUSTRALIA - QUEENSLAND - Great Sandy Strait - Light buoys.

Former Notice - 171(T)/2005 is cancelled

Maritime Safety Queensland Notices 36(T)/2005 & 53(T)/2005 (A125183 & A127601).

Light buoys exist as follows:

<i>Position (WGS 84 datum)</i>	<i>Remarks</i>
25° 09'.123 S 152° 50'.508 E	starboard lateral <i>Fl. G. 2.5s</i>
25° 08'.939 S 152° 50'.502 E	port lateral <i>Fl. R. 2.5s</i>
25° 20'.180 S 153° 01'.400 E	starboard lateral <i>Fl. G. 3s</i>
* 25° 12'.689 S 152° 54'.744 E	starboard lateral <i>Fl. G. 3s S 3</i>

* Indicates new entry.

Chart temporarily affected - Aus 241 - Aus 817.

215(T)/2005 AUSTRALIA - QUEENSLAND - Bundaberg - Burnett River - Dredging operations.

Former Notice - 1035(T)/2004 is cancelled

Maritime Safety Queensland Notice 75(T)/2005 (A128775).

Dredge *John G Francis* is operating between 24° 46'.34 S 152° 22'.91 E and 24° 46'.41 S 152° 22'.93 E.
The dredge may be contacted on VHF Ch 16 or 12.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 242.

216(T)/2005 AUSTRALIA - QUEENSLAND - Shoalwater Bay – Military exercise.

Date - Until 22 April 2005

Maritime Safety Queensland Notice 63(T)/2005 (A128682).

A prohibited area, including all waters contained within a 3M radius of position 22° 22'.0 S 150° 30'.5 E (WGS 84 datum), is declared from 11 April 2005 to 22 April 2005.

Chart temporarily affected - Aus 260 - Aus 367 - Aus 370 - Aus 822 - AX 60260.

217(T)/2005 AUSTRALIA - QUEENSLAND - Gloucester Passage - Light beacon destroyed; light buoy.

Maritime Safety Queensland Notice 62(T)/2005 (A128687).

The No 3 west cardinal light beacon (20° 03'.49 S 148° 26'.54 E) is destroyed and the remains are submerged at low water; a light buoy Q(9) 15s exists in situ.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 268 - AU421148.

218(T)/2005 PAPUA NEW GUINEA - Weka Una to Isulailai Point - Light beacons destroyed.

Department of Transport PNG (A128045).

The following lights are unlit:

<i>Name</i>	<i>Position (WGS 84 datum)</i>	<i>Volume K</i>
Weka Una	10° 36'.2 S 150° 36'.6 E	3455
Kaba Eru Eru	10° 34'.5 S 150° 42'.1 E	3453
Isulailai Point	10° 33'.7 S 150° 41'.7 E	3452

Chart temporarily affected - Aus 381 - Aus 567 - Aus 625 - Aus 629.

219(T)/2005 AUSTRALIA - QUEENSLAND - Gulf of Carpentaria - Mornington Island - Scientific instruments northwestward.

Date - Until 8 April 2005

Geoscience Australia (A129084).

Scientific instruments marked by special buoys, exist as follows:

16° 05'.7 S 139° 02'.4 E
16° 42'.0 S 138° 52'.0 E

Mariners are not to use the buoys as moorings.

Chart temporarily affected - Aus 303 - Aus 304.

220(T)/2005 AUSTRALIA - NORTHERN TERRITORY - Rooper Rock - Light buoy off station.

List of Lights Vol K/2005 - 3315.5

RCC (A128878).

The port lateral light buoy (12° 04'.30' S 131° 10'.71 E (WGS 84 datum)) is off station.

Chart temporarily affected - Aus 20 - Aus 720 - Aus 722 - AX 70722.

221(T)/2005 AUSTRALIA - NORTHERN TERRITORY - Darwin - Military exercise.

Date - Until 11 March 2005

DRN (A129125).

Air to air missile firing is programmed daily from 0730 to 1300 LT (2200z - 0330z) in the Darwin Air Weapons Ranges R202 A-D and/or R230 B-C.

For details see Australian Notice to Mariners No 9.

Chart temporarily affected - Aus 29 - Aus 308 - Aus 309 - Aus 310 - Aus 315 - Aus 316 - Aus 318 - Aus 721 - Aus 722 - AX 70308 - AX 70309 - AX 70721 - AX 70722.

222(T)/2005 WESTERN AUSTRALIA – Rottnest Island - Scientific instrument.

DPI WA (A1128042).

A lit waverider buoy *FI(5) Y. 20s*, exists in position 32° 06'.50 S 115° 24'.11 E (GDA 94 datum).

Mariners are not to use the buoy as a mooring.

Chart temporarily affected - Aus 754.

223(T)/2005 SOUTH AUSTRALIA - Arno Bay - Light beacon destroyed.

List of Lights Vol K/2005 - 1898

Transport SA Notice 02/2005 (A128691).

The isolated danger light beacon (33° 55'.0 S 136° 35'.13 E) is destroyed.

Chart temporarily affected - Aus 777.

224(T)/2005 AUSTRALIA - VICTORIA - Port Fairy - Light buoy off station.

Victorian Notice 17(T)/2005 (A128114).

The port lateral light buoy (38° 23'.03 S 142° 15'.25 E) is reported to be in position 38° 22'.88 S 142° 15'.44 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 141.

225(P)/2005 AUSTRALIA - VICTORIA - Port Campbell - Wells southwestward.

Date - On or about 31 March 2005 to 5 June 2005

Santos Ltd (A128984).

Drill rig Ocean Patriot will undertake drilling operations to establish the Casino gas field.

Casino 4 well will be established in position 38° 47'.306 S 142° 41'.829 E.

Casino 5 well will be established in position 38° 47'.819 S 142° 44'.662 E.

Mariners are advised to navigate with caution in the area.

Chart which will be affected - Aus 349.

226(T)/2005 AUSTRALIA - TASMANIA - Wineglass Bay - Wreck.

Marine and Safety Tasmania Notice M16-05 (A128954). Wreck is a yacht.

A wreck exists in position 42° 10'.22 S 148° 19'.03 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 355.

227(T)/2005 AUSTRALIA - TASMANIA - Georges Bay - Dredging.

Date - Until 2 April 2005

Marine and Safety Tasmania Notice M09-05 (A127544).

Dredge *Stay Calm* is operating in approx position 41° 16'.0 S 148° 20'.3 E.

Dredging is restricted to the ebb tide and vessels wishing to transit the barway should contact the dredge on VHF Ch 16.

Buoys established for dredging purposes are not to be used for navigation and mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 356.

228(T)/2005 AUSTRALIA - VICTORIA - Western Port - Shoreham - Beacon destroyed.

Victorian Notice 15(T)/2005 (A128112).

The special beacon (38° 26'.430 S 145° 02'.974 E) is destroyed.

Chart temporarily affected - Aus 150 - Aus 151.

229(T)/2005 AUSTRALIA - VICTORIA - Western Port - Watsons Inlet - Beacon destroyed.

Victorian Notice 20(T)/2005 (A128779).

The starboard lateral beacon (38° 15'.651 S 145° 15'.758 E) is destroyed.

Chart temporarily affected - Aus 150 - Aus 151.

230(T)/2005 AUSTRALIA - BASS STRAIT - Light buoy replaced in position.

Former Notice - 729(T)/2004 is cancelled

Tamboritha Consultants (A128795).

Cancel this notice on receipt.

Chart formerly affected - Aus 357A - Aus 358.

II

AMENDMENTS TO ADMIRALTY LIST OF LIGHT AND FOG SIGNALS VOLUME K 2005/06

Edition No 5 dated 4 March 2005.

Last Amendment: Edition No 4 dated 18 February 2005

0839	- Pulau Batumakele. Ldg Lts 186°. Front	0 03-3 98 17-6	Fl W 3s	13	10	Beacon	12	<i>fl 0-3. Ra refl. Destroyed (T) 2005</i>
								*
0839-1	--- Rear	0 03-67 98 17-60	Fl W 5s	19	8	Beacon	18	<i>fl 0-5. Destroyed (T) 2005</i>
								*
0839-4	- Pulau Tello	0 03-1 98 16-8	Fl W 4s	8	6	White framework tower	16	<i>fl 0-5. Destroyed (T) 2005</i>
								*
1524	Karang Takarewataya. SW edge	6 04-87 118 54-03	Fl W 10s	25	22	White 8-sided metal tower, 3 galleries, red stripes	23	<i>fl 1. Racon. Reported TR 2004</i>
		*						*
1623	-- Halong (Tg Galala)	3 39-63 128 11-78	Fl G 5s	8	6	Green beacon	5	<i>fl 0-5. TE 2005</i>
								*
1687-9	- FPSO	19 16-56 116 36-76	Mo(U) WR 15s	...	W 10 R 5			
*	*	*	*	*	*	*	*	*
2547-5	- Entrance. N Arm. No 7	37 52-81 147 58-33	Q G	△ on green beacon		
*	*	*	*	*	*	*	*	*
2547-52	--- No 11	37 52-78 147 58-43	Fl G 3s	△ on green beacon		
*	*	*	*	*	*	*	*	*
2547-54	--- No 13	37 52-74 47 58-61	Fl(2) G 5s	△ on green beacon		
*	*	*	*	*	*	*	*	*
2547-56	--- No 8	37 52-71 147 58-79	Q R	□ on red beacon		
*	*	*	*	*	*	*	*	*
2547-58	--- No 10	37 52-60 147 59-08	Fl(2) R 5s	□ on red beacon		
*	*	*	*	*	*	*	*	*
2547-6	--	37 52-89 147 58-72	F R					
*	*	*	*	*	*	*	*	*
2818	- Clarence Head. Common rear. Ldg Lts 237°30' (COM)	29 26-05 153 21-78	Fl(3) W 15s	41	16	White concrete tower and lantern	17	<i>(fl 0-1, ec 2-4) x 2, fl 0-1, ec 9-9. Vis 171°-shore. Rear to K2819. R and G Ldg Lts are shown at Maclean, Lawrence, Elizabeth Island and Ulmarra. F R on radio mast at Lawrence</i>
	--- Ldg Lts 131-5°	...	F Bu	Same structure		Rear to K2822
	*	*						
2863-545	--	27 01-09 153 05-76	Fl G 2-5s	△ on green beacon		Destroyed; starboard lateral light buoy in situ (T) 2005
*	*	*	*	*	*	*	*	*

Volume K *continued*

2869-298	Fisherman Islands	27 21-42 153 12-05	Q(3) W 10s	◇ on black beacon, yellow band	
*	*	*	*	*	*	*	*
2885-25	<i>Remove from List</i>						
2902-14	- N of Potts Point	27 34-39 153 21-65	Fl G 2-5s	Green △ on beacon	Destroyed; starboard lateral light buoy in situ (T) 2005
		*					*
2997-7	- off S end	23 10-26 150 55-28	Lit	Observation Platform	
*	*	*	*	*	*	*	*
3183	- S2	16 56-55 145 46-61	Fl R 2-5s	...	3	Beacon	Removed (T) 2005
							*
3207-2	Dawson Reef	15 29-99 145 19-25	Q(9) W 15s	∇ on yellow beacon, black band	
*	*	*	*	*	*	*	*
3265-2	- Prince of Wales Channel. Nardana Patches	10 30-29 142 14-63	Fl(4) R 12s	5	7	White hut on white pile 8	<i>(fl 0-5, ec 1-5) x 3, fl 0-5, ec 5-5. R250°-086°(196°) but only partially obscured to the N. Helicopter platform. Totally obscured sector 086°-250°(164°) to be introduced (P) June/July 2005</i>
							*
3463-4	Haidana Island. Reef	9 27-2 147 01-5	Fl R 5s	6	4	White pile	<i>fl 0-5</i>
							*
3463-8	Boera Head	9 23-5 147 00-8	Fl W 2-5s	33	14	White hut 2	
							*
3464	Idi Island	9 25-6 146 52-9	Fl(2) W 5s	23	10	Framework tower	
	*	*					*
3464-4	Redscar Head	9 16-4 146 54-0	Fl W 10s	77	10	White hut 3	<i>fl 0-5</i>
							*
4744	- SAVUSAVU BAY. Lesiaceva Point. Point Reef	16 49-8 179 16-2	Fl W 3s	8	10	White 6-sided concrete tower 9	<i>fl 0-3. Obscured by land when bearing less than 250°. TE 2005</i>
							*
4970-5	-- Pointe Tonoï. SSE side	16 44-3 151 25-9	Iso R 3s	5	4	Red □ on red beacon 6	Synchronized with K4970-7
							*

III

NAVIGATION WARNINGS

The following radio messages have been received during the period to 18 February 2005. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNING

- 040 NW Coast. Drill rig *Atwood Eagle* in position 19° 54'.6 S 113° 03'.1 E. 2.5M clearance requested.
- 041 NE Coast. Fairway Channel/Lads Passage new aid to navigation temporary light, *Fl(3) G. 6s 20m 3M*, established in position 13° 54'.0 S 144° 14'.3 E. Structure is four white piles with white hexagonal tower.
- 042 NE Coast. Isolated danger buoy K3090.1 (19° 18'.3 S 147° 37'.2 E) off station.
- 043 NW Coast. Drill rig *Sedco 703* in position 20° 55'.0 S 114° 53'.1 E. 2.5M clearance requested.
- 044 NW Coast. Drill rig *Ocean Bounty* in position 11° 56'.0 S 125° 00'.0 E. 2.5M clearance requested.
- 045 Cancelled.
- 046 Cancelled.
- 047 N Coast. Rooper Rock light buoy K3315.5 (12° 04'.4 S 131° 10'.6 E) off station.
- 048 NE Coast. South Creech Reef Lads Passage temporary light *Fl(3) R. 6s 3M* established in position 13° 39'.7 S 144° 06' E.
- 049 Cancelled.
- 050 SE Coast. SPV *Argo II* conducting underwater operations in area bounded by 39° 06' S to 39° 13' S and 146° 54' E to 146° 57' E.
- 051 SE Coast. Cape Schank DGPS ALRS 3156 (38° 29'.5 S 144° 53'.2 E) reduced power.
- 052 Cancelled.
- 053 NW Coast. Seismic SV *Geco Eagle* towing eight 4M cables in area bounded by 19° 00' S to 21° 00' S and 115° 00' E to 116° 00' E. 5M clearance requested.
- 054 Cancelled.
- 055 Cancelled.
- 056 NE Coast. White Tip Reef racon ALRS 88080 (19° 55'.5 S 150° 16'.0 E) temporarily discontinued.
- 057 NE Coast. Wideawake Shoals NW buoy K3233.47 (13° 17'.48 S 143° 50'.66 E) unreliable.
- 058 SE Coast. Seismic SV *Western Trident* towing eight 3.5M cables in area bounded by 38° 08' S to 38° 22' S and 148° 44' E to 149° 18' E. Chase vessels *Lady Roula* and *Pioneer* in attendance. Monitoring VHF Ch 16 and 73. 5M clearance requested.
- 059 Cancelled.
- 060 Cancelled.
- 061 SW Coast. Drill rig *Ensco 56* in position 29° 28'.2 S 114° 52'.7 E. 2.5M clearance requested.

NAVAREA X WARNINGS

Nil issued.

Navigational warnings in force as at 170001UTC FEB 05.

Auscoast

2004

341 365 366.

2005

001 002 006 021 027 029 032 034 040 041 042 043 044 047 048 050 051 053 056 057 058 061.

Navarea X

2004

007.

Summary of mobile drilling rigs as at 170001UTC FEB 05.

Name	Position
Ensco 104	11° 04'.2 S 126° 36'.8 E
Ocean Bounty	11° 56'.0 S 125° 00'.0 E
Ocean Epoch	19° 19'.0 S 116° 30'.6 E
Atwood Eagle	19° 54'.6 S 113° 03'.1 E
Sedco 703	20° 55'.0 S 114° 53'.1 E
Jack Bates	21° 38'.0 S 113° 26'.6 E
Ensco 56	29° 28'.2 S 114° 52'.7 E
Ensco 102	38° 09'.0 S 147° 58'.7 E
Ocean Patriot	38° 34'.5 S 148° 59'.3 E

III

NAVAREA XIV WARNINGS

- 010 South Pacific. Scientific instruments. Yellow buoy with scientific instruments (74° 00' S 175° 05' E) missing. Sighting or recovery reports to Italian Antarctic Program Ph +39 06304 84939, fax +39 06304 84893 or email direzione@consorzio.pnra.it.
- 011 Cancelled.
- 012 Cancelled.

Navarea XIV warnings in force as at 170001UTC FEB 05.

2004

087.

2005

005 007 008 010.

HYDROGRAPHIC REPORTS

Locality	Report	Ship/Authority	Observer
PRODUCTS Annual Notice	Typo		RJ Hardstaff
QLD- Darnley Island Cumberland Passage Hibernia Passage	Depths Reef Reef	<i>MV Malu Baizam</i>	
TAS- Bass Strait	Racon	<i>MV Bass Trader</i>	J Lewis
NT- Darwin	Feature	<i>MV Fourcroy</i>	M Bresman

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS 2005

Edition No 5 dated 4 March 2005

VOLUME 1, PART 2, NP 281(2), 2004/05

Published BA Wk 28/04

(Last Amendments: Edition No 4 dated 18 February 2005)

COAST RADIO STATIONS

Pages 188 & 189, **PANAMA**, PANAMÁ INTEL MAR (HPP) [2890], wef 17 February 2005, delete station

Cable & Wireless Panama Ad5/05

Page 220, **SOLOMON ISLANDS**, HONIARA delete station and replace by:

HONIARA (H4H)		9°26'S 160°04'E	
TELEPHONE	+677 30027, 30362 & 30885		
FAX	+677 30886		
E-MAIL	martin.horika@telekom.com.sb		
NOTE	Station accepts reports from vessels participating in the Solomon Islands Ship Reporting System on 6215.5 kHz		
	Transmits	Receives	Hours of Watch
RT (MF)			
	2167	2167	
	2182	2182	H24
RT (HF)			
	6215.5	6215.5	2100-0530
	6227	6227	
TRAFFIC LISTS:	2203-2230		
POSITION ROUTING:	2103-2130		
	0403-0430		
VHF			
	Ch 16 26		H24

Honiara Radio Ad5/05

Page 254, **VANUATU**, PORT-VILA (YJM), delete WT (MF) and WT (HF) tables

RCC Nadi Ad6/05

Page 254, **VENEZUELA**, LA GUAIRA (YVG), delete and replace by:

LA GUAIRA (YWMO)		10°35'N 67°04'W	
	Transmits	Receives	Hours of Watch
RT (MF)			
	2182	2182	H24
VHF			
	Ch 16		H24

FCO Ad6/05

VOLUME 2, NP 282, 2004/05

Published BA Wk 11/04

(Last Amendments: Edition No 4 dated 18 February 2005)

**THE 2005/06 EDITION OF THIS VOLUME HAS NOW BEEN PUBLISHED
THE 2004/05 EDITION IS CANCELLED**

VOLUME 2, NP 282, 2005/06

Published BA Wk 6/05

*Notices accrued while this volume was in the press, from BA Week 49/04 to BA Week 5/05, are herewith re-issued along with new information***Page iii, DIRECTIONS FOR UPDATING THIS VOLUME***below,*

RECORD OF AMENDMENTS
Weekly Notices to Mariners (Section VI)

*insert:***This edition was published in BA week 6/05. First Weekly Notice to Mariners issued in BA week 6/05.**

UKHO Ad6/05

RADAR BEACONS**Page 32, NETHERLANDS** *section***54950 Westgat Schiermonnikoog Lt Buoy WG***Delete position 53°32'·56N 6°10'·71E and replace by: 53°32'·35N 6°11'·38E*

Netherlands Notice 46/536/04 Ad6/05

Page 58, TURKEY (Marmara Denizi) *section, insert:***İzmit Körfezi, Dil Burnu Lt Racon** **40°44'·45N 29°30'·86E 71470**
T

Turkish Notice 2/5/05 Ad6/05

Page 69, UNITED ARAB EMIRATES (Persian Gulf Coast) *section,***76960 Dubayy, Approach Lt Buoy***Delete position 25°21'·11N 55°14'·07E and replace by: 25°18'·50N 55°10'·00E*

Marine Advisers Office, Dubai Ad6/05

Page 74, INDIA *section, delete entry:***79020 Mormugao (Mormagao), Sig Stn**

Indian Correction to List of Radio Signals Edition 1/05 Ad6/05

*Page 75, insert:***Rāmāpatnam Lt Racon**
(3 & 10 cm)**15°02'·73N 80°03'·02E 79170**
K

NAVAREA VIII WARNING 009/05 Ad6/05

Page 81, CHINA *section, delete entry:***81340 Huizhou FPSO HZ-21-1**

Chinese Chart 15010 Ad6/05

*Page 82, insert:***Xiamen Gang Lt Buoy, Xia 3 Racon****24°24'·22N 118°06'·25E 81465**
Y

Chinese Notice 44/903/04 Ad6/05

*Page 82, delete entry:***81470 Muqian Jiao Lt Bn**

Chinese Notice 44/894/04 Ad6/05

*Page 82, delete entry:***81495 Haicang Bridge Lt**

Chinese Chart 14291 Ad6/05

Page 83, insert:

Min Jiang Ldg Lt Racon 26°08'·02N 119°38'·30E **81565**

M

Chinese Notice 47/988/04 Ad6/05

Page 84, insert:

Yangxiaomao Dao Lt Racon 29°53'·88N 122°09'·00E **81671**

C

Chinese Notice 40/836/04 Ad6/05

Page 84, insert:

Zhoushan Qundao Lt Bn Racon 30°37'·88N 122°16'·33E **81771**

G

Chinese Notice 44/892/04 Ad6/05

Page 85, insert:

Changjiang Kou, Racon 30°51'·67N 122°40'·34E **81805**
Huaniaoshan Lt

Y

Chinese Notice 40/838/04 Ad6/05

Page 85, delete entry:

81830 Jiudian Sha Lt

MV Royal Princess Ad6/05

Page 85, delete entry:

81880 Beicaozhong Lt

MV Royal Princess Ad6/05

Page 85, insert:

Changjiang Kou, Racon 31°41'·60N 121°52'·78E **81945**
Beijiao

Q

Chinese Notice 38/791/04 Ad6/05

Page 87, insert:

Bohai Wan, Huanghua Gang Lt Racon 38°20'·34N 117°55'·45E **82115**

X

Chinese Chart 11770 Ad6/05

Page 87, insert:

Bohai Wan, SPM Racon 38°46'·32N 118°42'·25E **82140**

D

Chinese Notice 40/835/04 Ad6/05

Page 87, insert:

Dalian Gang, Lt Buoy X1 Racon 38°56'·00N 121°53'·95E **82245**

X

Chinese Notice 43/872/04 Ad6/05

Page 89, **KOREA, SOUTH** section, insert:

Maemulto Lt Racon 34°31'·35N 125°41'·10E **82560**
(3 & 10cm) 360° 10 n miles **M**

Korean Notice 52/756/04 Ad6/05

Page 90,

82630 Cheju Hang, West Breakwater Lt

Delete position 33°31'·93N 126°32'·43E and replace by: 33°31'·98N 126°32'·47E

Korean Notice 52/753/04 Ad6/05

Page 90, insert:

Cheju Do, Ch'agwi Do Lt Racon 33°18'·41N 126°09'·19E **82635**
(3 & 10cm) 10 n miles **O**

Korean Notice 43/589/04 Ad6/05

Page 91, delete entry:

82760 Kwangyang Hang, Lt Buoy No 3

Korean Notice 47/645/04 Ad6/05

Page 91, delete entry:

82770 Kwangyang Hang, Lt Buoy No 8

Korean Notice 47/645/04 Ad6/05

Page 91, delete entry:

82780 Kwangyang Hang, Lt Buoy No 11

Korean Notice 47/645/04 Ad6/05

Page 105, **AUSTRALIA** section

87420 Port of Dampier, Sea Lt Buoy

Delete position 20°25'·50S 116°42'·90E and replace by: 20°25'·45S 116°42'·91E

Australian Notice 22/966/04 Ad6/05

Page 111, **UNITED STATES (Pacific Coast)** section

Delete entry:

90310 Astoria

US Notice 12/18521/04 Ad6/05

Page 111, delete entry:

90320 Longview Bridge, Slaughters Turn and Channel

US Notice 4/18524/05 Ad6/05

Page 114, **ECUADOR** section,

91730 Esmeraldas Lt Buoy

Delete morse ident. T and replace by: Q

Ecuador Notice 10/15/05 Ad6/05

Page 114, **PERU** section, insert

Paíta, Pta Telégrafo Lt Racon 5°04'·21S 81°07'·50W **91815**
(3 & 10cm) 360° M

Peru Amendments to List of Lights-Cambio 02/04 Ad6/05

Page 114, insert

Port of Salaverry, Morro Carretas Lt Racon 8°13'·65S 78°58'·70W **91825**
(3 & 10cm) 360° 10 - 25 n miles T

Peru Notice 06/61/04 Ad6/05

Page 114, insert

Pta Coles Lt Racon 17°42'·23S 71°22'·75W **91885**
(3 & 10cm) 360° D

Peru Amendments to List of Lights-Cambio 02/04 Ad6/05

Page 121, **PANAMA (Caribbean Coast)** section

95080 Panama Canal, E Breakwater Lt

Delete morse ident C and replace by: U

MV Peninsular Bay Ad6/05

Page 124, **UNITED STATES (Gulf Coast)** section, insert:

Galveston Bay, Platform Racon 28°06'·80N 93°02'·30W **95945**
X

US Notice 3/11340/05 Ad6/05

DIFFERENTIAL GPS (DGPS)

BEACONS TRANSMITTING DGPS CORRECTIONS

Page 182, **PORTUGAL** section, Horta, delete station and replace by:

Horta	38°32'N 28°37'W	308		484 485	342	295		On trial	
-------	--------------------	-----	--	---------	-----	-----	--	----------	--

Portugese Notice 24/315(T)/04 Ad6/05

VOLUME 3, PART 2, NP 283(2), 2004/05

Published BA Wk 14/04

(Last Amendments: Edition No 4 dated 18 February 2005)

RADIO WEATHER SERVICES AND NAVIGATIONAL WARNINGSPage 187, **PAPUA NEW GUINEA, PORT MORESBY (P2M)**, frequency table, delete and replace by:

	4405 (417)	RT (HF)	2100-1200
	6510 (604)		

Port Moresby Radio Ad6/05

VOLUME 5, NP 285, 2004/05

Published BA Wk 24/04

(Last Amendments: Edition No 1 dated 7 January 2005)

Page 52, **Chapter 3: COMMUNICATIONS SYSTEMS FOR USE IN THE GLOBAL SYSTEM, POINTS OF CONTACT FOR COSPAS-SARSAT 406 MHz BEACON REGISTRATION** table, after Argentina insert:

Aruba	Dienst Telecommunicatiezaken Cayo G.F. Betico Croes 149 Oranjestad Aruba	+297 5826069		+297 5825307
		dirtelza@setarnet.aw www.dtz.aw		

RCC CURAÇAO Ad6/05

Page 55, after Netherlands insert:

Netherlands Antilles	Bureau Telecommunicatie en Post Groot Davelaar 139-140 Curaçao Netherlands Antilles	+599 9 4631700		+599 9 4635265

RCC CURAÇAO Ad6/05

Page 56, **Poland** delete section and replace by:

Poland	MRCC Gdynia Hryniewickiego 10 81-340 Gdynia	+48 58 6615222		+48 58 6205338
		office@sar.gov.pl		
	Ministerstwo Infrastruktury ul. T Chałubińskiego 4/6 00-928 Warszawa	+48 22 6301570		+48 22 6308515
		info.ma@mi.gov.pl		

Polish Notice WŻ3/2005 Ad6/05

Page 225, **Chapter 14: MARITIME SAFETY INFORMATION (MSI) UNDER THE GMDSS, NAVAREA CO-ORDINATORS, NAVAREA IV (United States), National Co-ordinators** table, row 18, **Nederlandse Ant.**, delete entry and replace by:

Nederlandse Ant.	+599 9 4637700			kw.rcc@czmcarib.an
-------------------------	----------------	--	--	--------------------

RCC CURAÇAO Ad6/05

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS 2005

Nil Amendments