

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2010/11. Weekly Edition No. 9, Dated 04 March 2010.

Last Amendment: Weekly Edition No. 8, dated 25 February 2010.

| | | | | | | | | |
|-------------------|---|---------------------------------------|--------------------------|----------------|----------------|---|--|---|
| K1690-35 | - Sea Buoy (AMSA) -- -- | 20 25-46 S 116 42-95 E | Q(4)Y 6s Racon AIS | | | Yellow conical buoy | Withdrawn; special pillar light buoy Q Y in situ (T) 2010 ALRS Vol 2 Station 87420. TD 2010 TD 2010 | * |
| | | | | | | | | |
| K1691-415 | Remove from list | | | | | | | |
| K1691-8945 | - Withnell Bay Terminal. Channel Beacon. No 13C ----- | 20 34-49 S 116 45-46 E .. | Fl Y 3s F WR | | | | R339-7°-345-4°(5-7°), W345-4°-355-9°(10-5°), R355-9°-003-1°(7-2°) | * |
| * | * | * | * | * | * | * | | * |
| | | | | | | | | |
| K2313 | Remove from list | | | | | | | |
| K2343-5 | - Williamstown | 37 51-95 S 144 54-76 E | F RG | 23 | .. | .. | F G233-17°-236-17°(3°). F R236-17°-239-17°(3°) | * |
| | | | | | | | | |
| K2426-2 | - | 38 28-00 S 145 03-20 E | Fl Y 5s | .. | .. | Beacon | | |
| * | * | * | * | * | * | * | | * |
| | | | | | | | | |
| K2441-55 | - Crib Point Oil Terminal | 38 20-89 S 145 13-30 E | Fl Y 4s | .. | .. | Beacon | | |
| * | * | * | * | * | * | * | | * |
| | | | | | | | | |
| K2997-3 | - Half Tide Rock | 23 09-20 S 150 56-30 E | Fl(2)W 6s | .. | .. | Black \oslash on black beacon, red band | Destroyed (T) 2010 | * |
| | | | | | | | | |
| K3023-6 | - Coral Point. Castrades Inlet | 21 22-08 S 149 18-76 E | Fl G 2-5s | .. | .. | Green \triangle on green beacon | Destroyed; starboard lateral light buoy Fl G 3s in situ (T) 2010 | * |
| | | | | | | | | |
| K4760-1 | - Passe Honikulu. Ldg Lts 032-3°. Rear. 2-7M from front * | 13 20-53 S 176 11-17 W | Iso W 4s | 98 | 9 | Grey wall 7 | | * |
| | | | | | | | | |
| K4761-5 | - Mouillage de Mata Utu. No 22 | 13 18-13 S 176 09-57 W | Q(3)W 10s | 3 | 4 | ∇ on black beacon, yellow band 4 | TE 2008 | * |

VOLUME 2, NP 282, 2009/10

Published Wk 10/09
(Last Amendments: Weekly Edition No. 8 dated 25 February 2010)

A New Edition of this volume is in the press and will be published shortly.
This New Edition will include a worldwide listing of known Automatic Identification System Aids to Navigation (AIS AtoN).
Please note Satellite Navigation Systems and Horizontal Datums on Charts have been transferred to The Mariner's Handbook NP 100.

RADAR BEACONS

PAGE 129, UNITED STATES (Gulf Coast).
95640 Brazos Santiago Pass Lt Buoy BS.
Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\) 9/10](#)

PAGE 129, UNITED STATES (Gulf Coast).
95650 Aransas Pass Fairway Lt Buoy AP.
Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\) 9/10](#)

PAGE 129, UNITED STATES (Gulf Coast).
95660 Matagorda Ship Channel Lt Buoy MSC.
Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\) 9/10](#)

PAGE 129, UNITED STATES (Gulf Coast).
95690 Freeport Fairway Lt Buoy FP.
Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\) 9/10](#)

PAGE 131, UNITED STATES (Gulf Coast).
96230 Gulfport Fairway Lt Buoy GP.
Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\) 9/10](#)

PAGE 131, UNITED STATES (Gulf Coast).
96240 Mobile Bay Approach Lt Buoy M.
Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\) 9/10](#)

VOLUME 5, NP 285, 2009/10

Published Wk 23/09
(Last Amendments: Weekly Edition No. 7 dated 18 February 2010)

CHAPTER 9: VHF DSC, LIST OF COAST STATIONS FOR SEA AREA A1

PAGE 119, Mauritius.
Delete entry and replace by:

Mauritius

| | | | | |
|-----------------|-----------|-----------------|----|---------------------------------------|
| Mauritius Radio | 006452700 | 20°11'S 57°28'E | 20 | Operational (<i>MRCC Mauritius</i>) |
|-----------------|-----------|-----------------|----|---------------------------------------|

[Mauritius Radio/3BM \(RSDRA2010000020990\) 9/10](#)

CHAPTER 10: MF DSC, LIST OF COAST STATIONS FOR SEA AREA A2

PAGE 143, Mauritius.
Delete entry and replace by:

Mauritius

| | | | | |
|-----------------|-----------|-----------------|-----|---------------------------------------|
| Mauritius Radio | 006452700 | 20°11'S 57°28'E | 200 | Operational (<i>MRCC Mauritius</i>) |
|-----------------|-----------|-----------------|-----|---------------------------------------|

[Mauritius Radio/3BM \(RSDRA2010000020990\) 9/10](#)

PAGE 164, diagram R12-A, INDIAN OCEAN - WEST, Digital Selective Calling (DSC), Limits of Sea Areas.
Delete diagram and replace by diagram on page 6.5

[Mauritius Radio/3BM \(RSDRA2010000020990\) 9/10](#)

CHAPTER 11: HF DSC, LIST OF COAST STATIONS FOR SEA AREAS A3 AND A4

PAGE 179, After Korea, South (Republic of).

Insert new entry:

Mauritius

Mauritius Radio 006452700 4, 6, 8, 12, 16 MHz Operational (*MRCC Mauritius*)

Mauritius Radio/3BM (RSDRA2010000020990) 9/10

PAGE 181, Figure 13 - Operational HF DSC Stations with MMSI numbers for Sea Areas A3 and A4.

Insert in approximate position 20°11'N 57°28'E:

- Mauritius 006452700

Mauritius Radio/3BM (RSDRA2010000020990) 9/10

CHAPTER 16: DISTRESS, SEARCH AND RESCUE

PAGE 321, CYPRUS, wef 1 April 2010.

Delete and replace by:


| | | | |
|---|----------------------------------|-----------------|---|
| <p>National SAR Agency: Department of Merchant Shipping of Ministry of Communications and Works. Address: P.O. Box 56193, CY-3305 Lemesos Tel: +357 25848100 Fax: +357 25848200 E-mail: maritimeadmin@dms.mew.gov.cy</p> | | | |
| <p>The Search and Rescue Coordination Centre for Cyprus is based at Larnaca International Airport and is manned 24 hours a day. All communications concerning Search and Rescue should be directed to JRCC LARNACA. The Search and Rescue Coordination Centre for the British Sovereign Base Area is based at RAF Akrotiri, is manned 24 hours a day and is known as RCC AKROTIRI. Cyprus operates a maritime radio service which maintains a continuous listening watch on international distress frequencies.</p> | | | |
| <p>TeleMedical Service: Provided by Emergency Department, Nicosia General Hospital. Contact through Cyprus Radio MMSI 002091000 on VHF, MF, HF DSC or JRCC LARNACA. Possible consultation languages: Greek and English.</p> | | | |
| | Telephone +357 | Fax +357 | Others |
| JRCC LARNACA (Cospas-Sarsat SPOC) | 24304723 24304737 24643005 | 24643254 | AFTN LCLKYCYX Inmarsat B 321099990 (Tel) 321099991 (Fax) 321099992 (Tlx) Inmarsat C 421099999 E-mail jrcc_cyp@cytanet.com.cy & rescuecy@gmail.com |
| RCC AKROTIRI | 25276664 | 25276914 | |

RCC Episkopi (RSDRA2010000026003) 9/10


PAGE 384, diagram R12, INDIAN OCEAN - WEST, Maritime Search and Rescue Regions (SRR).

Delete diagram and replace by diagram on page 6.6

Mauritius Radio/3BM (RSDRA2010000020990) 9/10



R12-A



AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

NP44 Malacca Strait and West coast of Sumatera Pilot (2008 Edition)

Malacca Strait - Tanjung Laboh — Light

76

Paragraph 2.125 2 lines 3-5 *Replace by:*

SW of Tanjung Laboh (24 miles NW), from where Kuala Sungai Ayam Light (red square on white column, pile platform, 12 m in height) (1°44'76N 102°55'67E) is exhibited, and where the routes either side of Permatang Alur Mudah combine into one.

Malaysian Notice 04/2010
(SDD 2010000 020391)

[09/10]

Thailand - Ao Krabi - Khlong Si Bo Ya — Directions; buoyed channel; leading lights; marine farms

149

Paragraph 5.114 1 lines 3-5 *Delete*

Paragraph 5.115 including heading *Replace by:*

Chart 3941, Thai Charts 308, 340 (see 1.18)

Khlong Si Bo Ya **5.115**

- 1 **Description.** Khlong Si Bo Ya passes between Laem Hin (7°55'8N 98°55'3E) and Ko Si Bo Ya (4 cables S), continues E and SE passing N of Ko Si Bo Ya, and NE and E Ko Nok Khuam (7°54'8N 99°00'3E). Thence it continues SW, passing between Ko Nok Khuam and Ko Hang (1 mile S), and S, passing between the S part of Ko Si Bo Ya and Ko Hang, thence between Ko To Lang (7°49'7N 98°59'8E) and Ko Klang (1½ miles ESE), and returns to the open sea S of Ko Pu (7°47'3N 98°59'0E).
- 2 **Directions.** Khlong Si Bo Ya is best approached from W from seaward through a channel with a least depth of 2.3 m, marked by lateral buoys, the outer end of which is marked by a buoy (safe water), 5 miles WSW of Laem Hin.

- 3 The alignment (075½°) of leading lights on Ko To Lam leads through the buoyed channel:
Front light (white beacon) (7°56'02N 98°59'62E).
Rear light (white beacon) (6½ cables from front light).

- 4 At the inward end of the buoyed channel, S of Laem Hin, the S limit of the channel is marked by buoys (N cardinal). Thence it continues E, passing S of Ko To Lam and off the leading line between two pairs of buoys (special).

The channel continues SE, passing NE of Ko Nok Khuam, where the deepest water lies in mid-channel, and then S, remaining clear of a rock awash which lies 1¾ cables NE of the SW shore, and a 2 m patch 2 cables off the E shore.

- 5 S of Ko Nok Khuam, the channel, which is unmarked, continues SW and S, with a least depth of 2.8 m. It is considerably constrained by drying banks on both sides, passing between the S part of Ko Si Bo Ya and Ko Hang, between Ko To Lang, Ko Cham (7°47'9N 99°00'0E) and other islands E of Ko Pu to W and Ko Klang to E, and thence to the open sea S of Ko Pu, passing, with positions relative to Ko Lola (7°46'6N 98°58'9E):

- 6 Clear of a 1.2 m patch (1¼ miles E), thence:
Clear of Hin Lola (1¼ miles SW), a rock awash, thence:
Clear of Hin Ba Seng (2½ miles SE) (5.109).

Note. Mariners are advised that marine farms exist in the vicinity of the S exit to Khlong Si Bo Ya the exact positions of which are not charted and whose positions may change frequently. They may or may not be marked.

BA Chart 3941; Thai Charts 308; 340; Thai Notice 23/2553
(SDD 2010000 025887) [09/10]

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2010/11. Weekly Edition No. 10, Dated 11 March 2010.

Last Amendment: Weekly Edition No. 9, dated 04 March 2010.

| | | | | | | | |
|-------------------|---|---------------------------|---------------------|-----|---|---|---|
| K1157 | Ujung Pangkah (I) | 6 50-43 S 112 32-90 E | Fl W 6s | 30 | 16 White beacon | <i>fl 0-4</i> | |
| | * | | * | | | | * |
| K1366-3 | - Atapupu (I) | 8 59-70 S 124 51-57 E | Fl W 3s | 11 | 8 White metal framework structure 20 | <i>fl 0-5.</i> TE 2010 | |
| | * | * | * | * | * | | * |
| K1382 | - Larat. Ritabel. Pier. Head (I) | 7 08-93 S 131 43-26 E | Fl W 3s | 14 | 12 White metal framework tower 9 | <i>fl 0-5.</i> Shown when vessels are expected or departing | |
| | | | * | | | | |
| K1382-7 | Remove from list | | | | | | |
| K1412 | Remove from list | | | | | | |
| K1412-3 | Remove from list | | | | | | |
| K1430 | - Pulau Kunyit | 4 05-21 S 116 02-41 E | Fl W 5s | 135 | 18 White metal framework tower 13 | <i>fl 0-5.</i> Vis 237°-177°(300°) | |
| | | | | | * | | |
| K1432 | - Tg Petang (I) | 3 36-48 S 115 58-01 E | Fl W 5s | 19 | 13 White metal framework tower 19 | <i>fl 0-5.</i> Partially obscured 219°-223°(4°) | |
| | | | | | * | | |
| K1438-2 | - Tg Pemancingan (I) | 3 13-88 S 116 16-80 E | Q W | 10 | 4 Δ on yellow beacon black top | | |
| | * | * | * | * | * | | * |
| K1438-22 | - Tg Pemancingan (I) | 3 13-60 S 116 16-92 E | Q(6) + LFl W 15s | 10 | 4 ∇ on black beacon, yellow top | | |
| | * | * | * | * | * | | * |
| K1498 | - Majene. Pier. Head (I) | 3 33-10 S 118 57-80 E | F W | 7 | 4 White metal framework tower 6 | Shown until 2300 | |
| | | | * | | | | * |
| K1532 | Bulukumba. Tg Papanambeya (I) | 5 33-96 S 120 11-57 E | Fl W 5s | 42 | 18 White metal framework tower 24 | Vis 270°-051°(141°) | |
| | | * | * | * | * | | |
| K1564 | - Tg Matube (I) | 1 57-00 S 121 32-50 E | Fl G 4s | 16 | 11 Green Δ on beacon | <i>fl 0-5</i> | |
| | | | * | | | | * |
| K1609-5 | Remove from list | | | | | | |
| K1622 | - (I) | 3 41-74 S 128 09-71 E | Fl W 3s | 25 | 12 White mast 3 | <i>fl 0-8</i> | |
| | | * | * | * | * | | |
| K1685-3015 | - <i>No15</i> | 20 28-70 S 117 16-80 E | Fl(3)G 6s | .. | .. Green pillar buoy | | |
| | * | * | * | * | * | | * |
| K1685-3016 | - <i>No16</i> | 20 29-11 S 117 16-61 E | Q R 1s | .. | .. Red pillar buoy | | |
| | * | * | * | * | * | | * |
| K1687-73 | - Pluto A (AMSA) | 19 59-78 S 115 22-09 E | Mo(U)W 30s | .. | 10 Platform | On opposite corners | |
| | -- | .. | Mo(U)R 30s | .. | 3 .. | On opposite corners | |
| | -- | .. | AIS | .. | | MMSI No 503565000 | |
| | * | * | * | * | * | | * |
| K3338 | - S side (I) | 8 30-11 S 140 22-38 E | Fl(4)W 20s | 44 | 27 White metal framework tower 40 | <i>(fl 1, ec 3) x 3, fl 1, ec 7</i> | |
| | | | | | * | | |
| K3393-3 | - Sorido Laguno. Inner Ldg Lts 295°. Front (I) | 1 11-13 S 136 04-45 E | Iso W 8s | 17 | 15 White Δ on white mast 10 | | |
| | | | * | | | | |

| | | | | | | |
|-----------------|---|--------------------------------|----------|----|--|---------------|
| K3393-31 | - Sorido Laguno . Inner Ldg Lts 295°. Rear. 240m from front (1) | 1 11-03 S 136 04-23 E | Iso W 8s | 17 | 15 White ▽ on white mast 15 | <i>fl 0-3</i> |
| | | | * | * | * | |
| K4139-2 | Remove from list, replaced by light buoy | | | | | |
| K4316 | - Akaroa Harbour. Green Point. On reef | 43 48-91 S 172 56-80 E * | Fl G 5s | 4 | 2 White wooden post 5 | * |

VOLUME 2, NP 282, 2009/10

Published Wk 10/09
(Last Amendments: Weekly Edition No. 9 dated 4 March 2010)

THE 2010/11 EDITION OF THIS VOLUME HAS NOW BEEN PUBLISHED
THE 2009/10 EDITION IS CANCELLED

VOLUME 2, NP 282, 2010/11

Published Wk 10/10
Notices accrued from Week 53/09 to Week 10/10, are re-issued along with new information.

This New Edition includes a worldwide listing of known Automatic Identification System Aids to Navigation (AIS AtoN).
Please note Satellite Navigation Systems and Horizontal Datums on Charts have been transferred to The Mariner's Handbook NP 100.

RECORD OF AMENDMENTS

PAGE ii, NEW EDITION, First Amendments.

Insert:

This edition was published in week 10/10.

The first Weekly Notice to Mariners was issued in week 10/10.

UKHO 10/10

RADAR BEACONS

PAGE 25, NETHERLANDS.

54947 WG Lt Buoy.

Delete morse identification **Z** and replace by: **N**

Netherlands Notice 2/63/10 (RSDRA201000009790) 10/10

PAGE 26, GERMANY (North Sea Coast).

Insert:

Borkumriffgrund Platform L 1-2 Racon 53°53'·71N 6°15'·56E 55450
D

German Notice 2/87/10 (RSDRA2010000012944) 10/10

PAGE 31, LATVIA.

57870 Daugavgrīvas Lt.

Delete sector 265°-035° and replace by: 035°-265°

Latvian Notice 2/014/10 (RSDRA2010000026174) 10/10

PAGE 39, SWEDEN.

Insert:

North Cardinal Lt Buoy Racon¹ 55°14'·57N 12°48'·05E 63070
D

(1) Withdrawn during the winter

Swedish Notice 290/6104(T)/10 (RSDRA2010000015173) 10/10

PAGE 72, INDIA.

79128 Cuddalore Chemplast Sanmar MT.

Delete morse identification **C** and replace by: **O**

Indian Notice 4/70/10 (RSDRA2010000028503) 10/10

PAGE 74, MALAYSIA (West Coast).

Insert:

One Fathom Bank North Lt Bn Racon 3°00'·91N 100°51'·89E 79860
T

Malaysian Notice 70/09 (RSDRA2009000185958) 10/10

PAGE 77, CHINA.

Insert:

Qinzhou Gang East Channel Racon 21°25'·21N 108°38'·25E 80918
Lt Buoy No 0
O

Chinese Notice 52/1949/09 (RSDRA2010000004283)
and Chinese List of Lights (RSDRA2010000004302) 10/10

PAGE 77, CHINA.

Insert:

Qinzhou Gang East Channel Racon 21°37'·45N 108°40'·44E 80919
Lt Buoy No 19
G

Chinese Notice 52/1949/09 (RSDRA2010000004283)
and Chinese List of Lights (RSDRA2010000004302) 10/10

PAGE 82, CHINA.

81515 Bai Yu Lt Bn.

Delete position and replace by: 25°18'·99N 119°33'·48E

Chinese Notice 2/71/10 (RSDRA2010000009688) 10/10

PAGE 85, CHINA.

81663 Xiangshan Gang Lt Buoy No 1.

Delete position and replace by: 29°40'·14N 121°57'·72E

Chinese Notice 6/256/10 (RSDRA2010000028140) 10/10

**PAGE 89, CHINA.
81850 Jiudian Lt Vessel.**

Delete position and replace by: 31°05'·47N 121°59'·68E

Chinese Notice 2/69/10 (RSDRA201000009686) 10/10

**PAGE 89, CHINA.
81883 Changjiang Kou Lt Buoy D25.**

Delete entry and replace by:

Beicao Shuidao Lt Buoy D25 Racon 31°13'·95N 122°05'·74E 81883
Q

Chinese Notice 6/253/10 (RSDRA2010000028134) 10/10

**PAGE 89, CHINA.
81905 Beigang Shuidao Platform.**

Delete entry

Chinese Notice 49/1829/09 (RSDRA2009000185641) 10/10

PAGE 89, CHINA.

Insert:

Changjiang Daqiao Opening Lt No 25 Racon 31°26'·06N 121°44'·65E 81906
X

Chinese Notice 49/1830/09 (RSDRA2009000185642) 10/10

**PAGE 90, CHINA.
81930 Wusong Kou Rear Ldg Lt.**

Delete entry

Chinese List of Lights G102 (RSDRA2009000166152) 10/10

**PAGE 90, CHINA.
81935 Changjiang Kou Lt Buoy No 74.**

Delete position and replace by: 31°28'·34N 121°26'·86E

Chinese Notice 49/1827/09 (RSDRA2009000185639) 10/10

**PAGE 93, CHINA.
82103 Quezuijianzi Lt Bn.**

Delete position and replace by: 37°54'·87N 120°43'·31E

Chinese Notice 51/1879/09 (RSDRA2009000194866) 10/10

**PAGE 93, CHINA.
82135 Tianjin Gang Lt Buoy D2.**

Delete position and replace by: 38°58'·25N 117°48'·15E

Chinese Notice 52/1919/09 (RSDRA2010000004244) 10/10

**PAGE 96, KOREA, SOUTH.
82301 Inch'ön Hang Lt Buoy No 1.**

Delete entry

Korean Notice 49/738/09 (RSDRA2009000183898) 10/10

PAGE 96, KOREA, SOUTH.

Insert:

Inch'ön Hang Lt Buoy Racon 37°24'·68N 126°34'·19E 82303
(3 & 10 cm) 10 n miles T

Korean Notice 49/740/09 (RSDRA2009000183900)
and Korean List of Lights 53/09 10/10

PAGE 96, KOREA, SOUTH.

Insert:

Inch'ön Hang Lt Buoy Racon 37°24'·97N 126°33'·78E 82304
(3 & 10 cm) 10 n miles B

Korean Notice 49/740/09 (RSDRA2009000183900)
and Korean List of Lights 53/09 10/10

PAGE 99, KOREA, SOUTH.

Insert:

Wando Hang Lt Buoy Racon 34°15'·20N 126°48'·50E 82647
(3 & 10 cm) 10 n miles X

Korean Notice 53/814/09 (RSDRA2010000001859) 10/10

**PAGE 100, KOREA, SOUTH.
82830 Pusan New Port Lt Buoy C.**

Delete position and replace by: 35°01'·42N 128°47'·67E

Delete morse identification Q and replace by: N

Korean Notice 3/69(T)/10 (RSDRA2010000017504) 10/10

PAGE 101, KOREA, SOUTH.

Insert:

Cheongdo Lt Bn Racon 37°30'·23N 130°55'·12E 82943
(3 & 10 cm) G

Korean Notice 3/54/10 (RSDRA2010000017485) 10/10

PAGE 117, UNITED STATES (Pacific Coast).

Insert:

Rosario Strait Lt Buoy R Racon 48°16'·42N 123°06'·58W 90200
T

Canadian Notice 1/112/10 (RSDRA2010000017241) 10/10

PAGE 127, VENEZUELA.

Insert:

Isla Puerto Real Lt Racon 11°11'·72N 63°44'·22W 94627
K

MV Ocean Village (RSDRA2009000194091)
& MV Logos Hope (RSDRA2009000190232) 10/10

**PAGE 130, UNITED STATES (Gulf Coast).
95640 Brazos Santiago Pass Entrance Lt Buoy BS.**

Delete entry

USCG Light List Volume IV corrections 7/10 (RSDRA2010000024288) 10/10

**PAGE 130, UNITED STATES (Gulf Coast).
95650 Aransas Pass Entrance Lt Buoy AP.**

Delete entry

USCG Light List Volume IV corrections 7/10 (RSDRA2010000024288) 10/10

**PAGE 130, UNITED STATES (Gulf Coast).
95660 Matagorda Ship Channel Approach Lt Buoy MSC.**

Delete entry

USCG Light List Volume IV corrections 7/10 (RSDRA2010000024288) 10/10

**PAGE 130, UNITED STATES (Gulf Coast).
95690 Freeport Entrance Lt Buoy FP.**

Delete entry

USCG Light List Volume IV corrections 7/10 (RSDRA2010000024288) 10/10

PAGE 131, UNITED STATES (Gulf Coast).
95805 Galveston Bay Entrance Lt Buoy GB.
 Delete entry

[USCG Light List Volume IV corrections 5/10 \(RSDRA2010000013349\)](#) 10/10

PAGE 132, UNITED STATES (Gulf Coast).
96230 Gulfport Ship Channel Lt Buoy GP.
 Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\)](#) 10/10

PAGE 132, UNITED STATES (Gulf Coast).
 Insert:

ATP- 111-2 Platform Racon 28°02'·01N 89°06'·04W **96125**
(ATP TITAN-MC-941-A)
 (3 & 10 cm) **A**

[USCG District 8 Local Notice 3/10 \(RSDRA2010000012820\)](#) 10/10

PAGE 132, UNITED STATES (Gulf Coast).
96240 Mobile Entrance Lt Buoy M.
 Delete entry

[USCG Light List Volume IV corrections 7/10 \(RSDRA2010000024288\)](#) 10/10

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 149, AUSTRALIA, after Ningaloo Vision FPSO entry.
 Insert:

| | | | | | |
|-------------------------|------------------------|-----------|--|-------------|--|
| Pluto A Platform | 19°59'·78S 115°22'·09E | 503565000 | | Operational | |
|-------------------------|------------------------|-----------|--|-------------|--|

[Pluto LNG Project, Woodside Energy Ltd. \(RSDRA2010000026065\)](#) 10/10

PAGE 151, CHILE, after Roca Anson Lt Buoy entry.
 Insert:

| | | | | | |
|-------------------|-----------------------|--|--|-------------|--|
| Valparaíso | 33°02'·33S 71°37'·70W | | | Operational | |
|-------------------|-----------------------|--|--|-------------|--|

[Chilean Chart 4320 \(RSDRA2009000052136\)](#) 10/10

PAGE 151, CHINA, before Banyang Jiao entry.
 Insert:

| | | | | | |
|---------------------|------------------------|-----------|----------------------------|-------------|--|
| Bai Yu Lt Bn | 25°18'·99N 119°33'·48E | 999412532 | Broadcasts every 3 minutes | Operational | |
|---------------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 2/71/10 \(RSDRA2010000009688\)](#) and [Chinese List of Lights G102 \(RSDRA2010000009712\)](#) 10/10

PAGE 151, CHINA, before Beicao Shuidao Lt Buoy D24.
 Insert:

| | | | | | |
|-----------------------------------|------------------------|-----------|----------------------------|-----------|--|
| Beicao Shuidao Lt Buoy D19 | 31°10'·35N 122°11'·51E | 999413282 | Broadcasts every 3 minutes | Temporary | |
| Beicao Shuidao Lt Buoy D23 | 31°12'·80N 122°07'·36E | 999413283 | Broadcasts every 3 minutes | Temporary | |

[Chinese Notice 3/T155/10 \(RSDRA2010000014546\)](#) 10/10

PAGE 151, CHINA.
Beicao Shuidao Lt Buoy D24, column 2.
 Delete position and replace by: 31°13'·26N 122°06'·31E

[Chinese Notice 6/253/10 \(RSDRA2010000028134\)](#) 10/10

PAGE 151, CHINA.
Beicao Shuidao Lt Buoy D25, column 2.
 Delete position and replace by: 31°13'·95N 122°05'·74E

[Chinese Notice 6/253/10 \(RSDRA2010000028134\)](#) 10/10

PAGE 151, CHINA.
Beicao Shuidao Lt Buoy D26, column 2.
 Delete position and replace by: 31°13'·84N 122°04'·75E

[Chinese Notice 6/253/10 \(RSDRA2010000028134\)](#) 10/10

PAGE 151, CHINA, Changhai 226 Wreck.

Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 153, CHINA, before Changjiang Kou Lt Buoy A29A entry.

Insert:

| | | | | | |
|------------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Changjiang Kou Lt Buoy A25A | 31°06'·12N 122°00'·10E | 999412234 | Broadcasts every 3 minutes | Operational | |
|------------------------------------|------------------------|-----------|----------------------------|-------------|--|

Chinese Notice 2/68/10 (RSDRA2010000009685) and Chinese List of Lights G102 (RSDRA2010000009712) 10/10

PAGE 153, CHINA.

Changjiang Kou Lt Buoy No 74, column 2.

Delete position and replace by: 31°28'·34N 121°26'·86E

Chinese Notice 49/1827/09 (RSDRA2009000185639) 10/10

PAGE 153, CHINA, Changjiang Kou Lt Buoy S17.

Delete entry

Chinese List of Lights G102 (RSDRA2010000006083) 10/10

PAGE 153, CHINA, after Dafeng Gang entry.

Insert:

| | | | | | |
|----------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Dafeng Gang Lt Bn | 33°17'·10N 120°48'·61E | 999412106 | Broadcasts every 3 minutes | Operational | |
| Dafeng Gang Lt Buoy No 1 | 33°33'·16N 120°45'·53E | 999412104 | Broadcasts every 3 minutes | Operational | |
| Dafeng Gang Lt Buoy No 19 | 33°20'·22N 120°50'·25E | 999412105 | Broadcasts every 3 minutes | Operational | |
| Dafeng Gang Superbuoy | 33°35'·57N 120°47'·71E | 999412103 | Broadcasts every 3 minutes | Operational | |

Chinese Notice 49/1824/09 (RSDRA2009000185636), Chinese Notice 49/1825/09 (RSDRA2009000185637), Chinese Notice 51/1885/09 (RSDR2009000194872) and Chinese List of Lights G102 (RSDRA2009000185651 and RSDRA2009000194889) 10/10

PAGE 153, CHINA, Dayu Wan Wreck.

Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 155, CHINA, before Dongdu Hangdao Lt Buoy No 42 entry.

Insert:

| | | | | | |
|--------------------------------------|------------------------|-----------|----------------------------|-----------|--|
| Dongdu Hangdao Lt Buoy No 41A | 24°29'·01N 118°03'·76E | 999413285 | Broadcasts every 3 minutes | Temporary | |
| Dongdu Hangdao Lt Buoy No 41B | 24°29'·45N 118°04'·08E | 999413286 | Broadcasts every 3 minutes | Temporary | |

Chinese Notice 4/T182/10 (RSDRA2010000023169) 10/10

PAGE 155, CHINA, Dong Lin 1.

Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 155, CHINA, Dong Lin 4.

Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 155, CHINA, after Dongying Gang entry.

Insert:

| | | | | | |
|-------------|------------------------|-----------|----------------------------|-------------|--|
| Gu Yu Lt Bn | 25°40'·57N 119°37'·50E | 999412571 | Broadcasts every 3 minutes | Operational | |
|-------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 2/71/10 \(RSDRA201000009688\)](#) and [Chinese List of Lights G102 \(RSDRA201000009712\)](#) 10/10

PAGE 155, CHINA, before Hao Deng Fu Lt Buoy No 11 entry.

Insert:

| | | | | | |
|--------------------------|------------------------|-----------|----------------------------|-------------|--|
| Hao Deng Fu Lt Buoy No 1 | 24°13'·75N 118°13'·86E | 999412699 | Broadcasts every 3 minutes | Operational | |
| Hao Deng Fu Lt Buoy No 6 | 24°15'·26N 118°10'·88E | 999412607 | Broadcasts every 3 minutes | Operational | |

[Chinese Notice 4/164/10 \(RSDRA2010000023154\)](#) and [Chinese List of Lights G102 \(RSDRA2010000020631\)](#) 10/10

PAGE 155, CHINA, after Hengsha Tongdao Lt Buoy No 600 entry.

Insert:

| | | | | | |
|-----------------------|------------------------|-----------|----------------------------|-------------|--|
| Houzhou Lt Buoy No 1 | 24°46'·17N 118°49'·80E | 999412611 | Broadcasts every 3 minutes | Operational | |
| Houzhou Lt Buoy No 3 | 24°48'·55N 118°46'·31E | 999412613 | Broadcasts every 3 minutes | Operational | |
| Houzhou Lt Buoy No 8 | 24°49'·61N 118°42'·67E | 999412612 | Broadcasts every 3 minutes | Operational | |
| Houzhou Lt Buoy No 11 | 24°51'·80N 118°41'·56E | 999412610 | Broadcasts every 3 minutes | Operational | |

[Chinese Notices 1/5/10 \(RSDRA2010000006750\)](#), [3/120/10 \(RSDRA2010000014538\)](#), [6/262/10 \(RSDRA2010000028152\)](#) and [Chinese List of Lights G102 \(RSDRA2010000006782 and RSDRA2010000014549\)](#) 10/10

PAGE 155, CHINA, after Hu Tou Yu Wreck entry.

Insert:

| | | | | | |
|-----------------------|------------------------|-----------|----------------------------|-------------|--|
| Jiannang Jiao Lt Buoy | 25°19'·15N 119°38'·05E | 999412531 | Broadcasts every 3 minutes | Operational | |
|-----------------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 2/71/10 \(RSDRA201000009688\)](#) and [Chinese List of Lights G102 \(RSDRA201000009712\)](#) 10/10

PAGE 155, CHINA, Ji Li Lai 886 Wreck.

Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 155, CHINA, Jin Ma 328 Wreck.

Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 157, CHINA, Jin Peng Wreck.

Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 157, CHINA, after Jintang Daqiao Lt Buoy No 109 entry.

Insert:

| | | | | | |
|----------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Jintang Daqiao Opening Lt No 123 | 30°03'·65N 121°48'·28E | 999412398 | Broadcasts every 3 minutes | Operational | |
|----------------------------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 51/1889/09 \(RSDRA2009000194876\)](#) and [Chinese List of Lights G102 \(RSDRA2009000194889\)](#) 10/10

PAGE 157, CHINA, Jin Zhen Zhou Wreck.

Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 157, CHINA.

Jiudian Lt Vessel, column 2.

Delete position and replace by: 31°05'·47N 121°59'·68E

Chinese Notice 2/69/10 (RSDRA201000009686) 10/10

PAGE 157, CHINA, Lianyungang Gang Lt Buoy No 7.

Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 157, CHINA, Lianyungang Gang Lt Buoy No 11.

Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 157, CHINA, after Luyou Jiao Lt Bn entry.

Insert:

| | | | | | |
|---------------------------------|------------------------|--|--|-------------|--|
| Mayou Shi Jiao Lt Vessel | 22°16'·59N 113°48'·32E | | | Operational | |
|---------------------------------|------------------------|--|--|-------------|--|

Chinese Chart 15300 (2009 Edition) (RSDRA2009000139835) 10/10

PAGE 157, CHINA, before Meizhou Wan Pipe LNG No 2 entry.

Insert:

| | | | | | |
|----------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Meizhou Wan Lt Buoy No 5 | 24°57'·25N 119°04'·21E | 999412614 | Broadcasts every 3 minutes | Operational | |
| Meizhou Wan Lt Buoy No 14 | 25°02'·76N 119°02'·52E | 999412615 | Broadcasts every 3 minutes | Operational | |
| Meizhou Wan Lt Buoy No 24 | 25°05'·48N 119°00'·43E | 999412616 | Broadcasts every 3 minutes | Operational | |
| Meizhou Wan Lt Buoy No 39 | 25°11'·22N 119°00'·52E | 999412617 | Broadcasts every 3 minutes | Operational | |

Chinese Notice 1/4/10 (RSDRA2010000006749), Chinese List of Lights G102 (RSDRA2010000006782) and Chinese Notice 4/160/10 (RSDRA2010000023149) 10/10

PAGE 159, CHINA, Nan Tai 17 Wreck.

Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 159, CHINA, after Ou Jiang Lt Buoy No 11 entry.

Insert:

| | | | | | |
|-------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Ou Jiang Lt Buoy No 13 | 27°56'·50N 121°00'·61E | 999412410 | Broadcasts every 3 minutes | Operational | |
| Ou Jiang Lt Buoy No 17 | 27°57'·85N 120°57'·54E | 999412411 | Broadcasts every 3 minutes | Operational | |
| Ou Jiang Lt Buoy No 30 | 27°58'·83N 120°49'·52E | 999412412 | Broadcasts every 3 minutes | Operational | |

Chinese Notice 48/1810/09 (RSDRA2009000185279) and Chinese List of Lights G102 (RSDRA2009000185316) 10/10

PAGE 159, CHINA, after Qinhuangdao Jiao entry.

Insert:

| | | | | | |
|------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Quanjin Lt Buoy No 15 | 24°33'·65N 118°29'·17E | 999412609 | Broadcasts every 3 minutes | Operational | |
| Quanjin Lt Buoy No 17 | 24°36'·13N 118°26'·15E | 999412608 | Broadcasts every 3 minutes | Operational | |

Chinese Notice 2/73/10 (RSDRA2010000009690) and Chinese List of Lights G102 (RSDRA2010000009712) 10/10

PAGE 159, CHINA, before Rizhao Gang Lt entry.

Insert:

| | | | | | |
|--------------------|------------------------|-----------|--|-----------|--|
| Quan Xing 98 Wreck | 29°55'·10N 122°33'·95E | 999413284 | Isolated Danger Mark Broadcasts every 3 minutes | Temporary | |
|--------------------|------------------------|-----------|--|-----------|--|

[Chinese Notice 51/T1907/09 \(RSDRA2009000194886\)](#) 10/10

PAGE 159, CHINA, Sea Bee Wreck.

Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 159, CHINA, before Songyu entry.

Insert:

| | | | | | |
|---------------------------|------------------------|-----------|----------------------------|-------------|--|
| Songxia Gang Lt Buoy No 1 | 25°43'·40N 119°39'·50E | 999412524 | Broadcasts every 3 minutes | Operational | |
| Songxia Gang Lt Buoy No 2 | 25°44'·25N 119°39'·23E | 999412525 | Broadcasts every 3 minutes | Operational | |
| Songxia Gang Lt Buoy No 3 | 25°42'·11N 119°38'·24E | 999412526 | Broadcasts every 3 minutes | Operational | |
| Songxia Gang Lt Buoy No 4 | 25°41'·13N 119°36'·17E | 999412527 | Broadcasts every 3 minutes | Operational | |

[Chinese Notice 2/71/10 \(RSDRA2010000009688\)](#) and [Chinese List of Lights G102 \(RSDRA2010000009712\)](#) 10/10

PAGE 159, CHINA, after Songyu entry.

Insert:

| | | | | | |
|-----------------|------------------------|-----------|----------------------------|-------------|--|
| Su'ao N Lt Buoy | 25°37'·63N 119°42'·16E | 999412528 | Broadcasts every 3 minutes | Operational | |
|-----------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 2/71/10 \(RSDRA2010000009688\)](#) and [Chinese List of Lights G102 \(RSDRA2010000009712\)](#) 10/10

PAGE 159, CHINA, after Taizi Shan Lt entry.

Insert:

| | | | | | |
|-------------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Taoyaomen Daqiao Opening Lt No 3 | 30°06'·01N 121°57'·57E | 999412397 | Broadcasts every 3 minutes | Operational | |
|-------------------------------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 52/1924/09 \(RSDRA2010000004252\)](#) and [Chinese List of Lights G102 \(RSDRA2010000004302\)](#) 10/10

PAGE 159, CHINA, Wuqiu Yu Dong Nan.

Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 159, CHINA, Wuwei Gong 92 Wreck.

Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 161, CHINA, before Xiamen Gang Lt Buoy No 29 entry.

Insert:

| | | | | | |
|---------------------------|------------------------|-----------|----------------------------|-------------|--|
| Xiamen Gang Lt Buoy No 15 | 24°22'·16N 118°08'·38E | 999412606 | Broadcasts every 3 minutes | Operational | |
|---------------------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 2/74/10 \(RSDRA2010000009691\)](#) and [Chinese List of Lights G102 \(RSDRA2010000009712\)](#) 10/10

PAGE 161, CHINA, after Xiamen Gang Lt Buoy No 29 entry.

Insert:

| | | | | | |
|----------------------------|------------------------|-----------|----------------------------|-------------|--|
| Xiamen Gang Lt Buoy No 601 | 24°26'·17N 118°02'·51E | 999412618 | Broadcasts every 3 minutes | Operational | |
|----------------------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 2/74/10 \(RSDRA2010000009691\)](#) and [Chinese List of Lights G102 \(RSDRA2010000024508\)](#) 10/10

PAGE 161, CHINA, Xian Feng Hai 1 Hao Wreck.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 161, CHINA, Xian Feng 68 Wreck.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 161, CHINA, Xiangshan Gang Bridge Lt Buoy No 1.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 161, CHINA, Xiangshan Gang Bridge Lt Buoy No 8.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 161, CHINA, before Xiaoji Shan Lt Bn entry.
Insert:

| | | | | | |
|--------------------|------------------------|-----------|-----------------------------|-------------|--|
| Xianqian Lt Vessel | 31°27'·16N 121°29'·66E | 999412219 | Broadcasts every 10 minutes | Operational | |
|--------------------|------------------------|-----------|-----------------------------|-------------|--|

[Chinese Notice 50/1848/09 \(RSDRA2009000194286\)](#) and [Chinese List of Lights G102 \(RSDRA2009000194315\)](#) 10/10

PAGE 161, CHINA, after Xiazhi Men Lt Bn entry.
Insert:

| | | | | | |
|---------------------------------|------------------------|-----------|----------------------------|-------------|--|
| Xihoumen Daqiao Opening Lt No 3 | 30°03'·86N 121°55'·11E | 999412399 | Broadcasts every 3 minutes | Operational | |
|---------------------------------|------------------------|-----------|----------------------------|-------------|--|

[Chinese Notice 51/1887/09 \(RSDRA2009000194874\)](#) and [Chinese List of Lights G102 \(RSDRA2009000194889\)](#) 10/10

PAGE 161, CHINA, after Xing Bi Hai 58 Wreck entry.
Insert:

| | | | | | |
|----------------------|------------------------|-----------|----------------------------|-------------|--|
| Xinghua Lt Buoy No 1 | 25°15'·60N 119°41'·33E | 999412529 | Broadcasts every 3 minutes | Operational | |
| Xinghua Lt Buoy No 5 | 25°19'·15N 119°30'·57E | 999412530 | Broadcasts every 3 minutes | Operational | |

[Chinese Notice 2/71/10 \(RSDRA2010000009688\)](#) and [Chinese List of Lights G102 \(RSDRA2010000009712\)](#) 10/10

PAGE 163, CHINA, Yangshan Gangqu Lt Buoy Y6.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 163, CHINA, Yan Ting Wreck.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 163, CHINA, Zhe Ding 58226 Wreck.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 163, CHINA, Zhe Lin Ji 576 Wreck.
Delete entry

[Chinese Temporary Notices in Force 4/10 \(RSDRA2010000023171\)](#) 10/10

PAGE 163, CHINA, Zhe Ping Ji 225 Wreck.
Delete entry

Chinese Temporary Notices in Force 4/10 (RSDRA2010000023171) 10/10

PAGE 165, DENMARK.
Langelandsbælt North Lt DW 40, column 5.
Delete Planned and replace by: Operational

Danish Notice 4/180/10 (RSDRA2010000021345) 10/10

PAGE 165, DENMARK.
Østerrenden North Lt W26, column 5.
Delete Planned and replace by: Operational

Danish Notice 4/180/10 (RSDRA2010000021345) 10/10

PAGE 165, DENMARK.
Romsø Tue Lt No 24, column 5.
Delete Planned and replace by: Operational

Danish Notice 4/180/10 (RSDRA2010000021345) 10/10

PAGE 167, DENMARK.
Vengeancegrund Lt No 31, column 5.
Delete Planned and replace by: Operational

Danish Notice 4/180/10 (RSDRA2010000021345) 10/10

PAGE 169, GERMANY (North Sea Coast), before Fino 1 Platform entry.
Insert:

| | | | | | |
|---------------------------------------|----------------------|--|--|-------------|--|
| Borkumriffgrund Platform L 1-2 | 53°53'-71N 6°15'-56E | | | Operational | |
|---------------------------------------|----------------------|--|--|-------------|--|

German Notice 2/87/10 (RSDRA2010000012944) 10/10

PAGE 177, before UNITED KINGDOM.
Insert:

| | | | | | |
|--|-----------------------|-----------|--|-------------|--|
| UNITED ARAB EMIRATES (Persian Gulf Coast) | | | | | |
| DYNA 1 Lt Bn | 24°58'-85N 52°23'-36E | 994701034 | | Operational | |

United Arab Emirates Boundary Affairs Council (RSDRA2009000190646) 10/10

PAGE 179, UNITED KINGDOM (Northern Ireland).
Altacarry Head Lt, columns 4 and 5.
Column 4, insert: AIS Base Station

Column 5, delete On trial and replace by: Planned

Commissioners of Irish Lights (RSDRA2010000010701) 10/10

DIFFERENTIAL GPS (DGPS)

PAGE 184, After EUROFIX section.
Insert:

CAUTION: GPS gaps have been reported in the following areas:

- BAHRAIN – Approaches to Mīnā Salmān
- CROATIA – Entrance to Rijeka
- FRANCE (Atlantic Coast) – Approaches to S. Malo
- FRANCE (Mediterranean Coast) – Golfe du Lion (Gulf of Lions)
- ITALY – Golfo di Genova (Gulf of Genoa) and Golfo di Napoli (Bay of Naples)
- UNITED KINGDOM – NW Entrance to the Menai Strait
- UNITED STATES (Atlantic Coast) – Chesapeake Bay

UKHO 10/10

LEGAL TIME

PAGE 222, diagram, STANDARD TIME ZONE CHART OF THE WORLD.

Delete -7h in position 25°00'N 90°00'E and replace by: -6h

OAG Worldwide Limited (RSDRA2010000003044) 10/10

PAGE 224, Bangladesh.

Delete entry and replace by:

| | | | | |
|------------|----|----|--------------------------|----------------------------|
| Bangladesh | -6 | -7 | 31 March each year 2300h | 31 October each year 2400h |
|------------|----|----|--------------------------|----------------------------|

OAG Worldwide Limited (RSDRA2010000003044) 10/10

PAGE 231, Samoa (USA).

Delete entry and replace by:

| | | | | |
|-------|-----|-----|-------------------------|--------------------|
| Samoa | +11 | +10 | 26 September 2010 0000h | 2 April 2011 2400h |
|-------|-----|-----|-------------------------|--------------------|

MV Queen Victoria (RSDRA2010000014374) and OAG Worldwide Ltd (RSDRA2010000018097) 10/10

UNIVERSAL TIME

PAGE 237, LEAP SECONDS, IMPLEMENTATION DATES, TABLE 2.

Insert:

| | | | |
|---------|---------------|-------------|------|
| 0 hours | 11 March 2010 | 0-0 seconds | 8/10 |
|---------|---------------|-------------|------|

International Earth Rotation Service (IERS) Bulletin D 105 (RSDRA2010000023727) 10/10

ELECTRONIC POSITION FIXING SYSTEM

PAGE 280, Loran-C: Chains in Operation.

NORTHWEST PACIFIC CHAIN, row 3

Delete Minami-Tori Shima entry

Japanese Notice 51/2144/09(RSDRA2009000186572) 10/10

PAGE 285, LORAN-C CHAIN COVERAGE, PACIFIC OCEAN CHAIN DESIGNATORS diagram.

Delete Minami-Tori Shima slave station in position 24°17'N 153°59'E together with line and legend 8930-X

Japanese Notice 51/2144/09(RSDRA2009000186572) 10/10

VOLUME 6, PART 4, NP 286(4), 2009/10

Published Wk 30/09

(Last Amendments: Weekly Edition No. 7 dated 18 February 2010)

PAGE 105, FIJI, FIJI - SHIP REPORTING SYSTEM, Fiji Ship Reporting System, CONTACT DETAILS, MSC Fiji, Fax.

Delete and replace by:

Fax: +679 3306295

MSC Fiji, (RSDRA2010000004346), 10/10

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

NP44 Malacca Strait and West coast of Sumatera Pilot (2008 Edition)

Thailand - Ko Muk and Ko Talibong — Submarine cables

149

Paragraph 5.125 *1* lines 4-5 *Replace by:*

...beach on its SE side. A submarine power cable is laid across the channel from SE coast of Ko Muk ESE to the mainland. It is buoyed at each end. Hin Khai Muk, a rocky shoal, lies 1½ miles S of the island.

After Paragraph 5.125 *1* line 11 *Insert:*

A submarine power cable is laid from the N point of Ko Talibong NE to the mainland shore. It is buoyed at each end.

Thai Notice 25/2533
(SDD 2010000 029150)

[10/10]

NP100 The Mariner's Handbook (2009 Edition)

Navigational Warnings — Different types

60

Paragraph 4.6 *5* lines 4-6 *Delete* Navigational *to* local warnings.

UKHO

(HH. 073/200/06)

[10/10]

IALA Maritime Buoyage System - Lateral Marks - Region B - Preferred channels — characteristics of buoys

315

Existing Section IV Notice Week 07/10 Diagram C.16.2
Lateral Marks - Region B PREFERRED
CHANNELS *Left column* Preferred channel to
starboard line 2 *Replace by:*

Shape: Can, pillar or spar.

UKHO; MY *Queen K*

(HH. 073/200/06)

[10/10]

