

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2010/11. Weekly Edition No. 11, Dated 18 March 2010.

Last Amendment: Weekly Edition No. 10, dated 11 March 2010.

K1034	- Gosong Mampango (I)	3 34-71 S 109 10-16 E	Fl W 5s	13	12	Red and white framework structure 20	<i>fl 0-5.</i> Obs 052°-135°(83°). Ra refl. PA. TE 2010 ALRS Vol 2 Station 85940. TD 2010
--	--	--	Racon	--	--	--	--
						*	*
K1144-48	Juana Channel (I)	6 39-96 S 111 11-26 E	Fl W 2s	10	12	White pipe beacon 7	<i>fl 0-5</i>
*	*	*	*	*	*	*	*
K1144-65	Pulau Gedeh (I)	6 39-04 S 111 17-46 E	Fl W 4s	10	12	White pipe beacon 7	<i>fl 0-5</i>
*	*	*	*	*	*	*	*
K1144-68	Karang Seliro (I)	6 41-35 S 111 19-26 E	Fl W 4s	8	12	White pipe beacon 7	<i>fl 1</i>
*	*	*	*	*	*	*	*
K1197	- Karang Manila (I)	7 21-53 S 113 10-18 E	Fl(2)W 12s	12	12	Black \odot on black beacon, red band	<i>fl 0-5, ec 1, fl 0-5, ec 10</i>
*	*	*	*	*	*	*	*
K2613	- Eastern Basin. Ldg Lts 358°. Front	34 27-06 S 150 53-70 E	F Bu	--	2		
*	*	*	*	*	*	*	*
K2613-01	- Eastern Basin. Ldg Lts 358°. Rear. 258m from front	34 26-92 S 150 53-69 E	F Bu	--	2		
*	*	*	*	*	*	*	*
K2812-51	Arrawarra. Ldg Lts 175-9°. Front	30 03-61 S 153 12-05 E	Fl Bu 3s	--	3		
			*				
K2812-511	Arrawarra. Ldg Lts 175-9°. Rear	30 03-61 S 153 12-05 E	Fl Bu 3s	--	3		
			*				
K3304-2	- Entrance Channel Ldg Lts 119°03'. Front	17 26-82 S 140 45-52 E	Q W	--	7	White \triangle on metal pile with platform	Vis 116-05°-122-05°(6°)
	---	--	Fl(2)W 6s	--	4	--	<i>fl 0-5, ec 1, fl 0-5, ec 4.</i> Vis 122-05°-116-05°(354°)
*	---	--	By day F W	--	--	--	Occas
	*	*	*	*	*	*	*
K3304-21	- Entrance Channel Ldg Lts 119°03'. Rear	17 27-17 S 140 46-18 E	Iso W 2s	--	8	White ∇ on metal framework tower on metal pile	Vis 116-05°-122-05°(6°)
	---	--	Fl(2)W 8s	--	4	--	<i>fl 0-5, ec 1, fl 0-5, ec 6.</i> Vis 122-05°-116-05°(354°)
*	---	--	By day F W	--	--	--	Occas
	*	*	*	*	*	*	*
K3536-4	- Island Breakwater. SE end (AMSA)	41 03-08 S 145 55-28 E	F G	16	6	Metal tower 8	Neon
			*			*	*
K3536-6	- Island Breakwater. NW end (AMSA)	41 02-91 S 145 55-01 E	F W	16	6	Metal tower 8	Neon
			*			*	*
K4967-5	- Reiono Island (F)	17 03-20 S 149 32-70 W	Fl(2)W 10s	15	15	White pylon, red top 15	TE 2010
							*
K5000-254	- Passe Otugi. Motu Tavake Roa (F)	15 51-90 S 145 57-70 W	Fl R 4s	5	5	Red \square on red beacon 5	<i>fl 1.</i> TE 2010
							*
K5000-255	- Passe Otugi. Motu Tavake Roa (F)	15 51-20 S 145 58-30 W	Fl G 4s	4	5	Green \triangle on green beacon 5	<i>fl 1.</i> TE 2010
							*
K5000-256	- Passe Otugi. Motu Tavake Roa (F)	15 50-10 S 145 59-50 W	Q G	4	5	Green \triangle on green beacon 4	TE 2010
							*
K5035	- Baie d' Ha'urei. Ldg Lts 280-1°. Front (F)	27 36-90 S 144 18-60 W	Iso R 4s	6	6	White metal column, red bands 6	TE 2010
							*

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 11 dated 18 March 2010

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from the UKHO website. To obtain a colour version of these diagrams go to: www.ukho.gov.uk – select **PRODUCTS AND SERVICES** – select **Maritime Safety Info** – select **Visit NMs page and Download NMs** – select **Weekly** – select **Year** – select **Week** – go to **Selected Week Content** – select **File** (for example: NP286(3)-WK01-10-PAGE149_Week01_2010.pdf)

VOLUME 2, NP 282, 2010/11

Published Wk 10/09

(Last Amendments: Weekly Edition No. 10 dated 11 March 2010)

RADAR BEACONS

PAGE 24, BELGIUM.

54200 Antwerp, Plaats van Boomke, Lt Buoy No 112.

Delete entry and replace by:

Westerschelde Lt Buoy No 112 Racon 51°14'·59N 4°20'·54E **54200**
(3 & 10 cm) 360° 2.5 n miles **D**

[Flemish Hydrography, Belgium \(RSDRA2010000031005\)](#) 11/10

PAGE 24, BELGIUM.

Insert:

Westerschelde Lt Buoy No 124 Racon 51°07'·52N 4°18'·64E **54210**
(3 & 10 cm) 360° 2.5 n miles **T**

[Flemish Hydrography, Belgium \(RSDRA2010000031005\)](#) 11/10

PAGE 25, NETHERLANDS.

54725 SB Lt Buoy.

Delete entry

[Netherlands Notice 8/123/10 \(RSDRA2010000033901\)](#) 11/10

PAGE 25, NETHERLANDS.

Insert:

SB-M Lt Buoy Racon 52°00'·08N 3°53'·18E **54730**
(3 & 10 cm) 360° 10 n miles **Z**

[Netherlands Notice 8/123/10 \(RSDRA2010000033901\)](#) 11/10

PAGE 54, EGYPT (Mediterranean Coast).

71600 Rosetta 1 Platform.

Add note:

Note: Reported inoperative

[MV Costa Pacifica \(RSDRA2010000027484\)](#) 11/10

PAGE 54, EGYPT (Mediterranean Coast).

71605 Rosetta 2 Platform.

Add note:

Note: Reported emitting morse identification Q

[MV Costa Pacifica \(RSDRA2010000027484\)](#) 11/10

PAGE 100, KOREA, SOUTH.

82830 Pusan New Port Lt Buoy C.

Delete position and replace by: 35°01'·41N 128°47'·54E

(former amendment 10/10)

[Korean Notice 3/69\(T\)/10 \(RSDRA2010000017504\)](#) 11/10

PAGE 107, INDONESIA (Kalimantan).

85940 Gosong Mampango Lt.

Delete entry

[Hydro-Oceanographic Office, Indonesian Navy \(RSDRA2010000029434\)](#) 11/10

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 173, NETHERLANDS, after Ellemeet entry.

Insert:

Geulhaven	51°53'·39N 4°18'·85E			Operational	
Hoek van Holland	51°58'·86N 4°06'·75E			Operational	
Lekhaven	51°54'·25N 4°25'·79E			Operational	

[Netherlands Charts 207 \(2010 Edition\) and 208 \(2010 Edition\)](#) 11/10

PAGE 173, NETHERLANDS, Rabsbank Lt Buoy.

Delete entry

[Netherlands Notices 8/125/10 \(RSDRA2010000033905\)](#) 11/10

PAGE 173, NIGERIA, Lagos Fairway Lt Buoy.

Delete entry and replace by:

Lagos Fairway Lt Buoy	6°21'·96N 3°24'·77E			Operational	
-----------------------	---------------------	--	--	-------------	--

Nigerian Ports Authority (RSDRA2010000000067) 11/10

PAGE 179, UNITED KINGDOM, before Lowestoft Lt entry.

Insert:

Innimore Bay Lt Buoy	56°30'·37N 5°43'·47W	992351062	North Cardinal Mark Broadcasts every 10 minutes	Operational	21
----------------------	----------------------	-----------	--	-------------	----

Northern Lighthouse Board Notice 6/10 (RSDRA2010000029626) 11/10

LEGAL TIME**PAGE 232, Tunisia.**

Delete entry and replace by:

Tunisia	-1	*		
---------	----	---	--	--

OAG Worldwide Limited (RSDRA2010000033089) 11/10

VOLUME 3, PART 2, NP 283(2), 2010

Published Wk 4/10

(Last Amendments: Weekly Edition No. 4 dated 28 January 2010)

RADIO WEATHER SERVICES AND NAVIGATIONAL WARNINGS**PAGE 249, URUGUAY, after CARMELO PREFECTURA RADIO (CWC 22).**

Insert new entry:

CERRITO RADIO (CWA)			34°51'·10S 56°10'·80W		
	421.5	WT (MF)			
	4346	WT (HF)			
	8602				
	12750				
	17230				
DIAGRAM: page 249					
Weather Bulletins					
1100 1600 2100	Weather bulletins.				
Navigational Warnings					
1100 1600 2100	Navigational warnings.				

Uruguay Annual Notice to Mariners 2010 (RSDRA2010000032697) 11/10

PAGE 249, URUGUAY, COLONIA PREFECTURA RADIO (CWC 23).

Delete entry and replace by:

COLONIA PREFECTURA RADIO (CWC 23)			34°28'·20S 57°51'·10W		
	Ch 15	VHF			
DIAGRAM: page 249					
Weather Bulletins					
0003 1033 1803	Weather bulletins.				
Navigational Warnings					
0003 1033 1803	Navigational warnings.				

Uruguay Annual Notice to Mariners 2010 (RSDRA2010000032697) 11/10

PAGE 250, URUGUAY, LA PALOMA RADIO (CWC 30).

Delete entry and replace by:

LA PALOMA RADIO (CWC 30) (CWS 27)			34°39'·50S 54°08'·50W	
	Ch 15	VHF		
	2722-1	RT (MF)		
	4146	RT (HF)		
DIAGRAM: page 249				
Weather Bulletins				
0000 0300 1200 1533 2300	Weather bulletins.			
Navigational Warnings				
0000 0300 1200 1533 2300	Navigational warnings.			

Uruguay Annual Notice to Mariners 2010 (RSDRA2010000032697) 11/10

PAGE 250, URUGUAY, MONTEVIDEO CONTROL PREFECTURA RADIO (CWC 39).

Delete entry and replace by:

MONTEVIDEO CENTRO DE RADIO CONTROL PREFECTURA (CWC 39)			34°54'·30S 56°12'·70W	
	Ch 15	VHF		
DIAGRAM: page 249				
Weather Bulletins				
0833 1603 2203	Weather bulletins.			
Navigational Warnings				
0833 1603 2203	Navigational warnings.			

Uruguay Annual Notice to Mariners 2010 (RSDRA2010000032697) 11/10

PAGE 250, URUGUAY, MONTEVIDEO TROUVILLE RADIO (CWC 39).

Delete entry and replace by:

MONTEVIDEO TROUVILLE RADIO (CWC 39)			34°52'·00S 56°18'·66W	
	2722-1	RT (MF)		
	4146	RT (HF)		
DIAGRAM: page 249				
Weather Bulletins				
0833 1603 2203	Weather bulletins.			
Navigational Warnings				
0833 1603 2203	Navigational warnings.			

Uruguay Annual Notice to Mariners 2010 (RSDRA2010000032697) 11/10

VOLUME 5, NP 285, 2009/10

Published Wk 23/09

(Last Amendments: Weekly Edition No. 9 dated 4 March 2010)

CHAPTER 16: DISTRESS, SEARCH AND RESCUE**PAGE 324, ESTONIA, contacts table, row 1, JRCC TALLINN.**

Delete and replace by:

JRCC TALLINN (Cospas-Sarsat SPOC)	6 191224 6 191226 6 922500 5 5260511	6 922501	Inmarsat C 492480040 E-mail jrcc@politsei.ee
--------------------------------------	---	----------	---

(former amendment 32/09)
JRCC Tallinn (RSDRA2010000032841) 11/10

PAGE 333, INDIA, Andaman & Nicobar Region, contacts table, row 1, MRCC PORT BLAIR.

Delete and replace by:

MRCC PORT BLAIR	3192 245530 3192 246081	3192 242948	Inmarsat C 441922666 Inmarsat F77 764902560 (voice) 764902561 (fax) E-mail commanderbb@dataone.in pblmrccpb@sancharnet.in
-----------------	----------------------------	-------------	--

(former amendment 45/09)

MRCC Port Blair (RSDRA2010000033634) 11/10

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

**NP44 Malacca Strait and West coast of Sumatera
Pilot (2008 Edition)**

Malacca Strait — Directions; buoyage

76

Paragraph 2.125 5 lines 4-5 *Delete* marked *To* (isolated danger),

Peninsular Malaysian Notice 09/2010
(SDD 2010000 035122)

[11/10]

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2010/11, Weekly Edition No. 12, Dated 25 March 2010.

Last Amendment: Weekly Edition No. 11, dated 18 March 2010.

K1052-9	Remove from list							
K1053-26	Remove from list							
K1262-84	Tanjung Kowang (I)	8 13-97 S 111 04-63 E	Fl R 5s	17	13 Red □ on red GRP beacon 10	<i>fl 0.5</i>		
*	*	*	*	*	*	*	*	*
K1262-85	Pacitan Harbour (I)	8 13-53 S 111 04-48 E	Fl W 10s	22	14 White metal framework structure 20	<i>fl 1.5</i>		
*	*	*	*	*	*	*	*	*

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 12 dated 25 March 2010

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from the UKHO website. To obtain a colour version of these diagrams go to: www.ukho.gov.uk - select **PRODUCTS AND SERVICES** - select **Maritime Safety Info** - select **Visit NMs page and Download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-10-PAGE149_Week01_2010.pdf)

VOLUME 2, NP 282, 2010/11

Published Wk 10/10

(Last Amendments: Weekly Edition No. 11 dated 18 March 2010)

RADAR BEACONS

**PAGE 66, OMAN (Strait of Hormuz Coast).
76710 West Bukha Oil Field.**

Delete morse identification **W** and replace by: **B**

[Oman Notices to Mariners 2/10 \(RSDRA2010000039613\) 12/10](#)

PAGE 76, TAIWAN.

Insert:

Kao-hsiung Second Entrance Lt Buoy Racon 22°32'·25N 120°13'·92E **80810**
(3 & 10 cm) 10 n miles **S**

[Taiwan Notice 30/30/10 \(RSDRA2010000036514\) 12/10](#)

PAGE 70, INDIA.

Insert:

Tapti Oil Field Platform STD Racon 20°32'·74N 71°58'·67E **78983**
C

[Indian Notice 5/77/10 \(RSDRA2010000036840\) 12/10](#)

PAGE 76, TAIWAN.

Insert:

Kao-hsiung First Entrance Lt Buoy Racon 22°37'·87N 120°12'·32E **80825**
(3 & 10 cm) 10 n miles **Z**

[Taiwan Notice 30/30/10 \(RSDRA2010000036514\) 12/10](#)

LEGAL TIME

PAGE 227, Fiji.

Delete entry and replace by:

Fiji	-12	-13	29 November 2009 0200h	28 March 2010 0300h
------	-----	-----	------------------------	---------------------

[OAG Worldwide Limited \(RSDRA2010000037859\) 12/10](#)

PAGE 230, Paraguay.

Delete entry and replace by:

Paraguay	+4	+3	18 October 2009 0000h 3 October 2010 0000h 2 October 2011 0000h	10 April 2010 2400h 9 April 2011 2400h 7 April 2012 2400h
----------	----	----	---	---

[OAG Worldwide Limited \(RSDRA2010000037000\) 12/10](#)

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

NP36 Indonesia Pilot Volume 1 (2009 Edition)

Java Sea - Gosong Mampango — Light; racon

85

Paragraph 4.45 2 lines 3-4 *Delete* from *to* displayed

86

Paragraph 4.54 1 line 8 *Delete* from *to* displayed

159

Paragraph 8.20 1 line 2 *Delete*

Paragraph 8.21 1 lines 6-7 *Delete* from *to* exhibited,

Hydro-Oceanographic Office, Indonesian Navy
(SDD 2010000 029434) [12/10]

NP44 Malacca Strait and West coast of Sumatera Pilot (2008 Edition)

Malaysia - Johor Strait - South-eastern part - Tanjung Pengelih southward - Malang Berendam — Light beacon

314

Paragraph 9.188 1 line 8 *Replace* by:

...a small drying reef, marked by a light beacon
(white column on platform) (1°21'48N
104° 05'35E).

Peninsular Malaysian Notice 12/2010
(SDD 2010000 036488) [12/10]

NP60 Pacific Islands Pilot Volume 1 (2007 Edition)

Solomon Islands - New Georgia Island - Hathorn Sound — Lights

158

Paragraph 4.80 3 lines 4-8 *Replace* by:

The track then continues SW to a position 2 miles NNW of Tanguivili Point (21 miles SW), from where a light (white column, 11 m in height) (8°11'4S 157°12'9E) (see Chart 1735) is exhibited, on the alignment (190°) of the leading lights for Hathorn Sound (4.92).

159

Paragraph 4.92 1 lines 2-5 *Replace* by:

Front light (white column, 9 m in height) (8°15'3S 157°11'4E).

Rear light (similar structure, 11 m in height) (200 m from front light).

Nawae Construction Ltd
(SDD 2010000 000144) [12/10]