

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2011/12. Weekly Edition No. 28, Dated 14 July 2011.

Last Amendment: Weekly Edition No. 27, dated 07 July 2011.

K1687-85	DAMPIER ARCHIPELAGO. NORTHWESTWARDS - FPSO Cossack Pioneer	19 35-33 S 116 26-80 E	Mo(U)W 15s	..	..	Storage tanker	Off station; Mo(U)15s riser turret mooring in situ (T) 2011
						*	*
K1691-861	DAMPIER ARCHIPELAGO. PORT OF DAMPIER. MERMAID SOUND - Pluto LNG Channel. P5	20 32-91 S 116 42-65 E	Fl G 6s	17	6	△ on beacon	
*	---	..	Oc(2)Bu 6s	17	7		*
		*	*	*	*	*	
K1691-862	- Pluto LNG Channel. PR1	20 33-23 S 116 42-56 E	Fl 6s	28	7	▽ on beacon	
*	---	..	Oc(2)Bu 6s	28	7		*
		*	*	*	*	*	
K1691-863	- Pluto LNG Channel. P7	20 33-49 S 116 42-78 E	Fl G 6s	17	6	△ on beacon	
*	---	..	Oc(2)Bu 6s	17	7		*
		*	*	*	*	*	
K1691-865	- Pluto LNG Channel. P21	20 36-40 S 116 45-30 E	Q Bu	17	8	△ on beacon	
				*	*		
K1691-8651	- Pluto LNG Channel. P22	20 36-52 S 116 45-41 E	Iso Bu 4s	26	8	▽ on beacon	
				*	*		
K1708	NORTH WEST CAPE. VAN GOGH FIELD - FPSO Ningaloo Vision	21 24-21 S 114 05-31 E	Mo(U)W 15s	..	..	..	PA. Off station; a riser mooring buoy exists in situ 40m below the sea surface (T) 2011
	--	..	AIS				*
		*					
K3117	GREAT BARRIER REEF (COASTAL WATERS). HALIFAX BAY - West Channel. Bay Rock	19 07-03 S 146 45-23 E	Fl(2)W 8s				*
K4293	PEGASUS BAY. LYTTTELTON HARBOUR/WHAKARAUPU - Sticking Point. Breakwater. Head	43 36-62 S 172 44-01 E	Fl(2)G 5s	8	5	White pile	TE 2011
		*					*
K4367-1	OTAGO HARBOUR - Harington Point	45 47-00 S 170 43-39 E	F Y	3	4	Red metal beacon	Vis 177°-182°(5°)
	--	..	Oc R 10s	..	2	..	<i>ec 1</i>
			*		*	*	*
K4445	DUSKY SOUND Remove from list; replaced by unlit Isolated danger mark.						
K4445-5	Remove from list; replaced by unlit W Cardinal mark.						
K4676 FJ, F201, 4676	VITI LEVU ISLAND. SOUTH COAST. SUVA HARBOUR - W Reef. SE end	18 08-56 S 178 23-56 E	Fl R 3s	9	5	White round tower on red and white base	<i>fl 0-3.</i> Ra refl. TE 2011
					10		*
K4733 FJ, F201, 4733	VITI LEVU ISLAND. EAST COAST - Cakau Momo. W side	17 38-69 S 179 15-55 E	Fl W 2s	6	9	White concrete tower, red top	<i>fl 0-3.</i> Ra refl. TE 2011
					6		*

K4746-5 FJ, F201, 4746-5	VANUA LEVU ISLAND. NORTH COAST. KIA ISLAND - Kia Island . N end	16 13-41 S 179 05-77 E	Fl W 5s	70	15	Metal tower 8	Vis 109°-008°(259°). TE 2011	*
K4998-7 FR, KB, 70100	ATOLL DE MANIHI - Passe Tairapa	14 27-50 S 146 03-60 W	Fl G 2-5s	6	5	Green Δ on green beacon 6	<i>fl 0-5.</i> TE 2011	*
K5000-6 FR, KB, 71510	ATOLL DE FAKARAVA - Passe Garuae. W side (FR)	16 05-10 S 145 43-21 W	Fl G 2-5s	7	5	Green Δ on green beacon 9	<i>fl 0-5.</i> TE 2011	*
K5000-7 FR, KB, 71520	- Récif Pufana (FR)	16 04-90 S 145 41-60 W	Fl R 2-5s	5	5	Red $\square$ on red beacon 8	<i>fl 0-5.</i> TE 2011	*
K5000-8 FR, KB, 71530	- Récif Togamaitu-i-Tai (FR)	16 04-70 S 145 39-10 W	Fl G 4s	5	5	Green Δ on green beacon 6	<i>fl 1.</i> TE 2011	*
K5001-1 FR, KB, 71550	- Récif Tatapiri. Shoal SE (FR)	16 03-50 S 145 37-50 W	Fl R 2-5s	5	4	Red $\square$ on red beacon 10	<i>fl 0-5.</i> TE 2011	*
K5001-2 FR, KB, 71560	- Récif Kopuapiro (FR)	16 03-70 S 145 37-30 W	Q W	4	3	Δ on yellow beacon, black top 4	TE 2011	*

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 28 dated 14 July 2011

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from the UKHO website. To obtain a colour version of these diagrams go to: www.ukho.gov.uk - select **PRODUCTS AND SERVICES** - select **Maritime Safety Info** - select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-10-PAGE149_Week01_2010.pdf)

VOLUME 2, NP 282, 2011/12

Published Wk 11/11
(Last Amendments: Weekly Edition No. 27 dated 7 July 2011)

RADAR BEACONS

PAGE 89, CHINA.

Insert:

Qingdao Gang Lt Buoy W1 Racon 35°59'·30N 120°31'·72E **82007**
Z

Chinese Notice 24/827/11 (RSDRA2011000113371) 28/11

VOLUME 6, PART 4, NP 286(4), 2010/11

Published Wk 27/10

(Last Amendments: Weekly Edition No. 25 dated 23 June 2011)

PAGE 41, AUSTRALIA, GREAT BARRIER REEF AND TORRES STRAIT (REEFVTS), above Pilots section.

Delete diagram links and replace by:

See diagram (1) GREAT BARRIER REEF AND TORRES STRAIT - VESSEL TRAFFIC SERVICE (VTS) - REEFVTS.

See diagram (2) GREAT BARRIER REEF AND TORRES STRAIT - VESSEL TRAFFIC SERVICE (VTS) - REEFVTS.

See diagram (3) GREAT BARRIER REEF AND TORRES STRAIT - VESSEL TRAFFIC SERVICE (VTS) - REEFVTS.

See diagram Summary of Reporting Requirements.

See diagram Summary of REEFVTS Reports.

(former amendment 22/11)

Australian Notice 12/608(P)/11, (RSDRA2011000113799), 28/11

PAGE 41, AUSTRALIA, GREAT BARRIER REEF AND TORRES STRAIT (REEFVTS), Vessel Traffic Service, CONTACT DETAILS.

Delete and replace by:

CONTACT DETAILS:

Telephone: +61(0)7 47263428

+61 1300 721293 (Australia only)

Fax: +61(0)7 47210633

E-mail: reefvts@vtm.qld.gov.au

(former amendment 22/11)

Great Barrier Reef and Torres Strait Vessel Traffic Service (REEFVTS) User Guide, July 2011, (RSDRA2011000118366), 28/11

PAGE 42, AUSTRALIA, GREAT BARRIER REEF AND TORRES STRAIT (REEFVTS), diagram (1) TORRES STRAIT AND GREAT BARRIER REEF VESSEL TRAFFIC SERVICE (VTS) - REEFVTS.

Delete and replace by diagram (1) GREAT BARRIER REEF AND TORRES STRAIT VESSEL TRAFFIC SERVICE (VTS) - REEFVTS, on page 6.4

Australian Notice 12/608(P)/11, (RSDRA2011000113799), 28/11

PAGE 43, AUSTRALIA, GREAT BARRIER REEF AND TORRES STRAIT (REEFVTS), diagram (2) TORRES STRAIT AND GREAT BARRIER REEF VESSEL TRAFFIC SERVICE (VTS) - REEFVTS.

Delete and replace by diagram (2) GREAT BARRIER REEF AND TORRES STRAIT VESSEL TRAFFIC SERVICE (VTS) - REEFVTS on page 6.5

Australian Notice 12/608(P)/11, (RSDRA2011000113799), 28/11

AFTER PAGE 43, AUSTRALIA, GREAT BARRIER REEF AND TORRES STRAIT (REEFVTS).

Insert new diagram (3) GREAT BARRIER REEF AND TORRES STRAIT VESSEL TRAFFIC SERVICE (VTS) - REEFVTS on page 6.6

Australian Notice 12/608(P)/11, (RSDRA2011000113799), 28/11

PAGE 47, AUSTRALIA, GREAT BARRIER REEF AND TORRES STRAIT (REEFVTS), Vessel Traffic Service, INTRODUCTION, section (5) REEFVTS Area.

Delete and replace by:

(5) **REEFVTS Area:** The area is defined as:

- (a) The Torres Strait between longitude 141°45'00E and 144°00'00E, including the Endeavour Strait and the Great North East Channel;
- (b) The waters of the Great Barrier Reef between the Australian Coast and:
- (c) The outer edge of the Great Barrier Reef, as bounded by a line:
 - (i) Starting from the outer edge of the Reef at 10°40'00S 144°00'00E
 - (ii) Then running SE to 21°00'00S 152°40'00E
 - (iii) Then running E to 21°00'00S 152°55'00E
 - (iv) Then running SSE to 23°42'00S 153°45'00E
 - (v) Then running SSW to 24°30'00S 153°35'00E, and
 - (vi) Then running W to the intersection of latitude 24°30'00S with the Australian Coast at the low water line

(former amendment 22/11)

Australian Notice 12/608(P)/11, (RSDRA2011000113799), 28/11


PAGES 49 & 50, AUSTRALIA, GREAT BARRIER REEF AND TORRES STRAIT (REEFVTS), Vessel Traffic Service, COMMUNICATION WITH REEFVTS, section (4) VHF Communications.


Delete and replace by:


(4) **VHF Communications:**

- (a) A VHF radio network is employed along the Queensland Coast and on islands in the Torres Strait to allow mariners to communicate with REEFVTS. REEFVTS maintains a listening watch at all times on the working VHF Channels listed below. The relationship between VHF Channels and associated Mandatory Reporting Points are dependant on a ship's position in relation to the area of that Reporting Point (see table).

Name of Reporting Point and Aus chart designation	VHF Working Channel	Name of Reporting Point and Aus chart designation	VHF Working Channel
Bramble (A)	14	Bowling North (S)	14
Daru (B)	14	Townsville (N) (S1)	14
Twin (C)	14	Townsville (S) (S2)	14
Booby (D)	14	Bowling South (T)	14
Thursday Island (D1)	14	Abbot Point (T1)	14
Endeavour (E)	14	Blossom (U)	14
Alpha North (F)	14	Molle (southbound) (V)	11
Alpha South (G)	14	Cid Harbour (V1)	11
Shortland (H)	14	Shaw (northbound) (W)	11
Hannibal (I)	14	Edward (X)	11
Inset (J)	14	Creal (Y)	11
Heath (K)	11/14	Mackay (Y1)	11
Pipon (L)	11	Hay Point (NE) (Y3)	11
Two Isles (M)	11	Hay Point (S) (Y4)	11
Cape Flattery (M1)	11	High Peak (Z)	11
Gubbins East (N)	11	Swain (Z1)	11
Gubbins West (O)	11	Archer (Z2)	14
Grafton Passage (P)	11	Sandy Cape (Z3)	14
Cairns (P1)	11	Port Alma (Z4)	14
Barnard (Q)	11	Gladstone (N) (Z5)	14
Mourilyan (Q1)	11	Gladstone (E) (Z6)	14
Palm Passage (R)	14	Bundaberg (W) (Z7)	14
Lucinda (R1)	14	Bundaberg (E) (Z8)	14







- (b) Mariners are reminded of the duty, only if practical, under the Safety of Life at Sea (SOLAS) Convention provisions to maintain a continuous listening watch on VHF Ch 16 while at sea and for a radio watch to be maintained for broadcasts of MSI on the appropriate frequency or frequencies on which such information is broadcast for the area in which they are navigating.

(former amendment 22/11)
Australian Notice 12/608(P)/11, (RSDRA2011000113799), 28/11

PAGE 343, UNITED ARAB EMIRATES, FUJAIRAH (FUJAYRAH).

Delete entry and replace by:

FUJAIRAH (FUJAYRAH)

25° 12'N 56° 22'E

UNCTAD LOCODE: AE FJR

Pilots and Port

CONTACT DETAILS:

Pilots

VHF Frequency: Ch 12
E-mail: mar_pilots@fujairahport.ae

Port Control

Call: Fujairah Port Control
VHF Frequency: Ch 16; 08 10
Telephone: +971(0)9 2228777
Fax: +971(0)9 2228022
E-mail: ct_pof@fujairahport.ae (AOH)
mo_pof@fujairahport.ae (Office hours)

Port Engineering

VHF Frequency: Ch 11

Hr Mr

Telephone: +971(0)9 2228877
Fax: +971(0)9 2228022
E-mail: hm_pof@fujairahport.ae

Port Authority

Telephone: +971(0)9 2228800
Fax: +971(0)9 2228811
E-mail: info@fujairahport.ae
Website: www.fujairahport.ae

Vopak (VHFL) Terminal

Telephone: +971(0)9 2281800
+971(0)9 2281642 (Control Room)
Fax: +971(0)9 2281358
Website: www.vopakhorizonfujairah.com

Dibā Port

Telephone: +971(0)9 2442300

Tugs

VHF Frequency: Ch 08

Patrol Vessels

VHF Frequency: Ch 08

Pollution Control

VHF Frequency: Ch 12

HOURS: H24

PROCEDURE:

- (1) **Pilotage is compulsory** for all vessels except the following:
- (a) UAE Coastguard or Defence Vessels
 - (b) MENAS vessels
 - (c) Vessels holding exemption licences

- (2) **Notice of ETA:** Vessels should send ETA 72h before arrival confirming 48h, 24h and 12h in advance through the agent, stating:

(a) ETA

(b) Arrival draught

- (3) Tankers visiting the oil terminal must send a Tanker Pre-arrival Information Form via the agent, at least 72h in advance of ETA.

- (4) Vessels should contact Fujairah Port Control on VHF Ch 16, 08 or 10 when within VHF range.

- (5) In addition, vessels intending to enter the harbours or to anchor in Fujairah waters, should establish direct contact as soon as possible on VHF Ch 16 before entering within 4 n miles of the coast, and request anchoring instructions. They should also maintain a listening watch on VHF Ch 16.

- (6) **Notice of ETD:** Vessels should give notice of ETD immediately upon completion of loading arm disconnection. Requests for Pilots should also be forwarded at this time.

- (7) **Pilot boards** in position 25°08'·80N 56°24'·00E.

(former amendment 25/11)
Port of Fujairah Notice 148/11, (RSDRA2011000113414), 28/11

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

NP15 Australia Pilot Volume 3 (2009 Edition)

Australia - Queensland - Ship reporting systems — Torres Strait and Great Barrier Reef ship reporting system

13

Paragraph 1.94 2 line 3 *For* 22°00'S *Read* 24°30'·00S.

Australian Notice 12/608(P)/11
(AA539200)

[28/11]

AMENDMENTS TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2011/12. Weekly Edition No. 29, Dated 21 July 2011.

Last Amendment: Weekly Edition No. 28, dated 14 July 2011.

K0839-1 ID, , 2780	PULAU-PULAU BATU. PULAU BATUMAKELE - Ldg Lts 186°. Rear (ID)	0 03-67 S 98 17-60 E	Fl W 5s	18	10	White beacon 18	<i>fl 0-5.</i> TE 2011	*
K1558-37 ID, , 5612-4	PULAU BUTUNG. E COAST - Teluk Kali Susu. Teluk Koro (ID)	4 47-61 S 123 08-00 E	Fl G 4s	7	6	Green △ on green pipe beacon 6	<i>fl 0-5</i>	*
K1558-371 ID, , 5612-5	- Teluk Kali Susu. Teluk Koro (ID)	4 47-76 S 123 07-50 E	Fl R 4s	7	6	Red □ on red pipe beacon 6	<i>fl 0-5</i>	*
K1558-372 ID, , 5612-6	- Teluk Kali Susu. Teluk Koro (ID)	4 46-99 S 123 08-78 E	Fl G 4s	7	6	Green △ on green pipe beacon 6	<i>fl 0-5</i>	*
K1643	BUCCANEER ARCHIPELAGO. TANNER ISLAND - Tanner Island (AU:AMSA)	16 05-69 S 123 31-81 E	Fl(2)W 10s	23	12	White concrete tower and lantern 6	<i>fl 1, ec 2, fl 1, ec 6.</i> TE 2011	*
K1838-9	DENIAL BAY. THEVENARD -	32 08-55 S 133 38-38 E	Fl G 2-5s	..	2	Green △ on green beacon	Destroyed; starboard lateral light buoy Fl G 2-5s in situ (T) 2011	*
K2193	Barwon River. Ldg Lts 296-4°. Front	38 17-09 S 144 29-90 E	Fl W 3s	3	1	.. 3	TE 2011	*
K2863-52	MORETON BAY. BRIBIE ISLAND - Pumicestone Channel	27 04-12 S 153 08-62 E	Fl R 2-5s	..	..	Red □ on beacon	TE; Destroyed; Port lateral buoy, Fl R 2-5s in situ (T) 2011	*
K3609-6	MERCURY PASSAGE. MARIA ISLAND. ILE DU NORD - Ile du Nord (AU:AMSA)	42 33-69 S 148 04-21 E *	Fl(3)W 12s	23	8	White GRP hut 4	<i>(fl 0-5, ec 1-5) x 2, fl 0-5, ec 7-5.</i> Vis 027-5°-302°(274-5°) *	*
K4666 FJ, F201, 4666	VITI LEVU ISLAND. SOUTH COAST. KADAVU ISLAND - North Astrolabe Reef. Solo	18 38-13 S 178 31-64 E *	LFl W 30s	29	10	Red metal tower, white bands 32	<i>fl 3.</i> TE 2011	*
K4676 FJ, F201, 4676	VITI LEVU ISLAND. SOUTH COAST. SUVA HARBOUR - W Reef. SE end	18 08-56 S 178 23-56 E	Fl R 3s	9	5	White round tower on red and white base 10	<i>fl 0-3.</i> Ra refl	*
K4701 FJ, , 4701	VITI LEVU ISLAND. SOUTH COAST. NAVO ISLAND - Navo Island	18 06-87 S 177 19-17 E	Fl(2)W 12s	14	12	Red tripod tower 8		*
K4885	BOUGAINVILLE ISLAND. EAST COAST - Anewa Bay. Kerekerina Point	6 11-30 S 155 33-56 E	Fl R 8s	8	2	Beacon	TE 2011	*

K4887	BOUGAINVILLE ISLAND. BOUGAINVILLE STRAIT. RANTAN ISLAND						
	- Rantan Island. E side	6 40-89 S 155 58-96 E	Fl(3)W 12s	27	14	White framework tower 9	(fl 0.5, ec 1.5) x 2, fl 0.5, ec 7.5. Vis 134°-022°(248°)
		*					*
K5004-78	ATOLL DE RAROŌA						
	- Récif Neketaotao (FR)	16 02-25 S 142 28-12 W	VQ(3)W 5s	4	4	⬤ on black beacon, yellow band 4	TE 2011
FR, KB, 73380							*

AMENDMENTS TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 29 dated 21 July 2011

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from the UKHO website. To obtain a colour version of these diagrams go to: www.ukho.gov.uk - select **PRODUCTS AND SERVICES** - select **Maritime Safety Info** - select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-10-PAGE149_Week01_2010.pdf)

VOLUME 2, NP 282, 2011/12

Published Wk 11/11

(Last Amendments: Weekly Edition No. 28 dated 14 July 2011)

RADAR BEACONS

PAGE 18, UNITED KINGDOM.

Insert:

Bassurelle Lt Buoy Racon 50°32'·75N 0°57'·70E **52360**
(3 & 10 cm) 360° 5-8 n miles **B**

[UKHO 29/11](#)

PAGE 18, UNITED KINGDOM.

52800 East Channel Lt Buoy (English Channel).

Delete entry

[UKHO 29/11](#)

PAGE 42, FRANCE (English Channel).

66880 Vergoyer Lt Buoy N.

Delete entry and replace by:

Vergoyer Nord Lt Buoy Racon 50°39'·66N 1°22'·21E **66880**
(3 & 10 cm) 360° 5-8 n miles **C**

[UKHO 29/11](#)

PAGE 43, FRANCE (English Channel).

66920 Bassurelle Lt Buoy.

Delete entry

[UKHO 29/11](#)

PAGE 43, FRANCE (English Channel).

Insert:

East Channel Lt Buoy Racon 49°58'·67N 2°29'·01W **67100**
(3 & 10 cm) 360° 10 n miles **T**

[UKHO 29/11](#)

PAGE 124, CUBA.

94400 Cayo Bretón Lt.

Delete entry

[Cuban Notice 5/48/11 \(RSDRA2011000120820\) 29/11](#)

PAGE 124, CUBA.

94520 Punta Maisí Lt.

Delete entry

[Cuban Notice 5/47/11 \(RSDRA2011000120819\) 29/11](#)

PAGE 124, CUBA.

94530 Punta Lucrecia Lt.

Delete entry

[Cuban Notice 5/46/11 \(RSDRA2011000120818\) 29/11](#)

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 161, FRANCE (English Channel), before ZC2 Lt Buoy entry.

Insert:

Vergoyer Nord Lt Buoy	50°39'·66N 1°22'·21E	992271103		Real	
------------------------------	----------------------	-----------	--	------	--

[French Notice 26/11/11 \(RSDRA2011000122768\) 29/11](#)

Insert:

Bassurelle Lt Buoy	50°32'·75N 0°57'·70E	992271105		Real	
--------------------	----------------------	-----------	--	------	--

French Notice 26/11/11 (RSDRA2011000122768) 29/11

VOLUME 5, NP 285, 2011/12

Published Wk 27/11

(Last Amendments: Weekly Edition No. 27 dated 7 July 2011)

CHAPTER 13: MARITIME SAFETY INFORMATION (MSI) UNDER THE GMDSS**PAGE 208, NAVAREA III (Spain).**

Delete entry and replace by:

NAVAREA III (Spain)

Mares Mediterráneo y Negro
Head of the Navigational Area
Instituto Hidrográfico de la Marina
Plaza San Severiano No 3
11007 CÁDIZ

Spain

Telephone: +34 956 599409 H24

+34 956 599414 H24

Fax: +34 956 599396

email: ihmesp@fn.mde.es

Website: <http://www.armada.mde.es/ihm>**National Coordinators**

COUNTRY	TELEPHONE	FACSIMILE	EMAIL	OTHER
Albania	+355 260995 +355 68 4039350	+355 260243	silvanboni@yahoo.com	
Algeria	+213 21864999	+213 21861182	shfn@mdn.dz	
Bulgaria	+359 52 552036	+359 52 603259	bma@marad.bg radio@navbul.com mrcc_vn@marad.bg mrcc.varna@gmail.com	TELEX: +67 77385 www.marad.bg
Croatia	+385 21 308845	+385 21 347208	naut@hhi.hr office@hhi.hr	TELEX: +599 26270 HIRH www.hhi.hr
Cyprus	+357 24304723	+357 24643254	cyprus.radio@cya.com.cy	TELEX: +605 7888
Egypt	+20 3 4802299	+20 3 4875633		
France	+33 2 98221559	+33 2 98221432	coord.navarea2@shom.fr	www.shom.fr
Georgia	+995 222 73913	+995 222 73905	magheadof@fsc.gov.ge hidrograpia@list.ru	
Greece	+30 210 6551750	+30 210 6517811	nasf@hnhs.gr info@hnhs.gr	www.hnhs.gr
Israel	+972 4 8632080	+972 4 8632118	techni@mot.gov.il magidh@mot.gov.il bennyr@mot.gov.il	TELEX: +606 46632 SAPAN IL www.mot.gov.il
Italy	+39 06 59084527 +39 06 59084946	+39 06 59084793 +39 06 59084440	guardiacostiera@guardiacostiera.it navtex@guardiacostiera.it	
Lebanon	+961 1 371644 +961 1 371645 +961 3371647	+961 1 371647	ministry@transportation.gov.lb	
Malta	+356 22 494202 +356 22 494206	+356 21 809860	opsroom.afm@gov.mt	TELEX: +406 1489
Morocco	+212 5 37625877 +212 5 37625897	+212 5 37625017	mrcc.rabat@mpn.gov.ma mrccrabat@gmail.com	
Romania	+40 241 651040	+40 241 513065	horia.popa@radionav.ro	www.constantia-radio.ro
Russia	+7 812 7175900	+7 812 7175900	navarea13@gunio.ru	
Serbia and Montenegro	+381 82 72531	+381 82 72531	hirm@cg.yu iho-serbia@plovput.co.yu	
Slovenia	+386 5 6632100	+386 5 6632102	ursp.box@gov.si	www.up.gov.si
Syria	+963 41 473876	+963 41 475805	danco@net.sy	TELEX +492 45121 MWANI
Tunisia		+216 72 510777	sho@email.ati.tn	www.defense.tn
Turkey	+90 212 4259728	+90 212 5410338	ttelsiz@ttmail.com	
Ukraine	+380 44 2966040 +380 44 2926444	+380 44 2921217 +380 44 2926444	office@hydro.gov.ua office@charts.gov.ua	www.hydrography.com.ua

CHAPTER 14: SAFETYNET

PAGE 229, Diagram, SafetyNET NAV/METAREA I - AOR-E & AOR-W, UNITED KINGDOM.
Delete 65° at approximate position 75°N 35°W and replace by 75°N.

(former amendment 27/11)
UKHO 29/11

CHAPTER 15: NAVTEX

PAGE 283, Diagram X1, NAVTEX - MSI BROADCASTS North Atlantic and Arctic
Delete diagram and replace by diagram on page 6.5

UKHO 29/11

AMENDMENTS TO ADMIRALTY SAILING DIRECTIONS

NP14 Australia Pilot Volume 2 (2010 Edition)

New South Wales - Port Kembla — Anchorages

312

Paragraph 12.35 1 lines 1-4 *Replace by:*

- 1 There are no recommended anchorages. Vessels have reported the loss of anchors and cables whilst anchoring off Port Kembla and the adjacent coastline, particularly within the area bounded by the following coordinates:

34°22'·00S	150°57'·00E
34°22'·00S	150°59'·40E
34°25'·70S	150°55'·20E
34°25'·70S	150°59'·40E

Masters are advised to exercise extreme caution when anchoring in these waters. However at the Master's discretion vessels may anchor more than 3 miles off the coast, outside Port Kembla port limits and not on or near entry leading lines.

Paragraph Paragraph 12.35 3 4 *Replace by:*
...weigh anchor and proceed to sea without waiting to receive instructions from Port Kembla Vessel Traffic Information Centre.

Australian Notice 17/918(T)/2010
(AA540714)

[29/11]

NP15 Australia Pilot Volume 3 (2009 Edition)

Australia – New South Wales – Newcastle — Outer Anchorages

102

Paragraph 3.92 3 lines 1-3 *Replace by:*

- 3 **Caution.** Lost anchors and cables exist in the area bounded by:

32°56'·50S	151°48'·00E
32°56'·50S	151°56'·50E
33°15'·00S	151°47'·00E
33°15'·00S	151°38'·00E

Vessels are advised to take appropriate precautions when anchoring.

Australian Notice 17/919(T)/10
(AA354885)

[29/11]

NP 36 Indonesia Pilot Volume 1 (2009 Edition)

N coast of Java - Tanjung Leran — Power station and pier

119

After Paragraph 5.102 3 line 11 Insert:

Leran power station 5.102a

- 1 **Leran power station** (6°38'·31S 111°28'·30E) has been established 5 cables NE of Tanjung Leran. A pier extends 7 cables NW from the shore terminating in a coal unloading berth oriented NE/SW, served by an unloading gantry. A light buoy (safe water) (6°34'·20S 111°26'·40E) marks the approach with light buoys (lateral) marking the channel. The station features a conspicuous chimney.

Useful marks:

Tanjung Bendoh Light (6°37'·41S 111°29'·44E) (5.100).

Light beacons on the unloading berth (6°37'·53S 111°27'·79E).

BA Chart 3731
(HH. 036/200/01)

[29/11]

