

4 November 2011 Edition 22

Australian Notices to Mariners are the authority for correcting Australian Charts and Publications

AUSTRALIAN NOTICES TO MARINERS

Notices 1111 – 1173 투

Published fortnightly by the Australian Hydrographic Service

Commodore R. NAIRN RAN Hydrographer of Australia

SECTIONS.

- I. Australian Notices to Mariners, including blocks and notes.
- II. Hydrographic Reports.
- **III.** Navigational Warnings.

SUPPLEMENTS.

- I. Tracings
- II. Cumulative List of Australian Notices to Mariners.
- III. Temporary and Preliminary Notices in force.
- IV. Amendments to Admiralty List of Lights and Fog Signals (Vol K), Radio Signals (NP 281(2), 282, 283(2), 285, 286(4)) and Sailing Directions (NP 9, 13, 14, 15, 33, 34, 35, 36, 39, 44, 51, 60, 61, 62, 100, 136).

© Commonwealth of Australia 2011

This work is copyright. Apart from any use permitted under the Copyright Act 1968, no part may be reproduced by any process, adapted, communicated or commercially exploited without prior written permission from The Commonwealth represented by the Australian Hydrographic Service.

IMPORTANT NOTICE

This edition of Notices to Mariners includes all significant information affecting AHS products which the AHS has become aware of since the last edition. All reasonable efforts have been made to ensure the accuracy and completeness of the information, including third party information, on which these updates are based. The AHS regards third parties from which it receives information as reliable, however the AHS cannot verify all such information and errors may therefore exist. The AHS does not accept liability for errors in third party information.

GENERAL INSTRUCTIONS

The substance of these notices should be inserted on the charts affected.

Bearings are referred to the true compass and are reckoned clockwise from North; those relating to lights are given as seen by an observer from seaward. Positions quoted in permanent notices relate to the horizontal datum for the chart(s). When preliminary or temporary notices affect multiple charts, positions will be provided in relation to only one horizontal datum and that datum will be specified. When the multiple charts do not have a common horizontal datum, mariners will be required to adjust the position(s) for those charts not on the specified datum. The range quoted for a light is its nominal range. Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices. A star (*) adjacent to the number of a notice indicates that the notice is based on original information.

REPORTING OF DANGERS

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 Wollongong, NSW 2500 (Fax 02-4223 6599, e-mail Hydro.NTM@defence.gov.au or, alternatively by filling in and submitting the Hydrographic Notes forms located on the web site – www.hydro.gov.au), immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).

AUTHORISED USE

Copies of Australian notices are available free of charge from the Australian Hydrographic Service (AHS) website (www.hydro.gov.au) and through the eNotices (email) service (www.hydro.gov.au/enotices/enotices.htm).

Individual Notices may be copied for the purpose of inserting Notice substance on official charts and publications. Paper copies may be printed by chart agents and distributed to customers on a cost recovery basis. Participating chart agents are listed on the AHS website as providing a 'Paper Notices to Mariners' service (www.hydro.gov.au/prodserv/distributors/distributors.htm). Copies of the notices may not be sold for profit without prior written agreement.

NUMERICAL INDEX OF NOTICES TO MARINERS

Edition No 22

Notices	Aus Chart, INT Chart, AHP
1111	
1112	Amendment to Australian Seafarers Handbook AHP20
1113	
1114	Aus 198, 199
1115	Aus 200, 202, AX 6202F
1116	
1117	
1118	
1119	· · · · · · · · · · · · · · · · · · ·
1120	
1121	
1122	
1123	
1124	
1125	
1126 1127	
1128	
1129	
1130	, ,
1131	
1132	
1133	
1134	
1135	
1136	
1137	Aus 155
1138(T)	
1139(T)	
1140(T)	
1141(P)	
1142(T)	
1143(T)	
1144(T)	
1145(T)	
1146(T) 1147(T)	
1147(T)	
1149(T)	
1150(T)	
1151(T)	
1152(T)	
1153(T)	
1154(T)	
1155(P)	
1156(T)	Aus 293, 299
1157(T)	
1158(T)	
1159(T)	
1160(T)	
1161(T)	
1162(T)	
1163(T)	
1164(T)	
1165(T) 1166(T)	
1167(T)	
1168(T)	
1169(T)	
1170(T)	
1171(T)	
1172(T)	
1173(T)	
• •	

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 22

Aus Chart	Notices	Aus Chart	Notices
Aus 4	()	Aus 400	1128
Aus 24	- ()	Aus 462	1111
Aus 26		Aus 489	1138(T)
Aus 28	1161(T), 1162(T), 1163(T)	Aus 502	1158(T)
Aus 55	1111	Aus 547	1123
Aus 57		Aus 608	1128
Aus 58		Aus 610	1116
Aus 59	1130	Aus 683	1159(T)
Aus 62	_	Aus 700	1124
Aus 64	- ()	Aus 741	1129
Aus 84		Aus 742	1131
Aus 114	()	Aus 743	1131, 1167(T)
Aus 117		Aus 744	1132
Aus 121	1111	Aus 777	1134
Aus 134	1133	Aus 780	1155(P)
Aus 139		Aus 781	1135
Aus 143	1173(T)	Aus 814	1143(T), 1144(T)
Aus 144	1171(T)	Aus 815	1144(T), 1147(T)
Aus 155	1137, 1172(T)	Aus 820	1149(T)
Aus 158	1171(T), 1173(T)	Aus 822	1149(T), 1150(T)
Aus 167		Aus 823	1150(T)
Aus 168		Aus 829	1153(T)
Aus 198	1114, 1139(T)	Aus 831	1119 ′
Aus 199		Aus 839	1155(P)
Aus 200	* *	Aus 4060	1127`´
Aus 202	1115	Aus 4071	1127
Aus 207	1140(T), 1141(P)	Aus 4603	1125, 1127
Aus 208		Aus 4622	1123, 1159(T)
Aus 230		Aus 4643	1138(T)
Aus 235		Aus 4708	1127`´
Aus 236		Aus 4720	1125
Aus 237		Aus 4721	1164(T)
Aus 238		Aus 4727	1170(T)
Aus 244		AX 0249E	1151(T)
Aus 245		AX 0310F	1164(T)
Aus 249		AX 0311F	1164(T)
Aus 250		AX 0312F	1126`´
Aus 256		AX 0367E	1149(T)
Aus 257	1152(T)	AX 0820E	1149(T)
Aus 264		AX 0822E	1149(T), 1150(T)
Aus 267		AX 0823E	1150(T)
Aus 270		AX 4603F	1125, 1127
Aus 292		AX 4708F	1127
Aus 293		AX 4720F	1125
Aus 296		AX 4721F	1164(T)
Aus 299		AX 6027S	1119`´
Aus 310		AX 6202F	1115
Aus 311	` '	AX 70117	1169(T)
Aus 312		AX 72026	1161(T), 1162(T), 1163(T)
Aus 324		, 5 () = 5 = 5	,,=(.,,=(.,
Aus 327	. ,	INT Chart	Notices
Aus 328		INT 60	1127
Aus 329		INT 71	1127
Aus 346		INT 603	1127
Aus 346		INT 622	
			1123, 1159(T)
Aus 376	, ()	INT 643 INT 708	1138(T)
Aus 378	\		1127
Aus 379		INT 720	1125
Aus 391		INT 721	1164(T)
Aus 399	1159(T)	NT 727	1170(T)

1111 AUSTRALIA - Product

Australian Hydrographic Service (AA564145)

New Chart

Chart Published Title and description of amendments Scale Index Chart Price
Aus 391 4/11/2011 Papua New Guinea - Admiralty Islands - Nauna Island to 1:300 000 Aus 5000 \$35.00

Manus Island

1° 44'.5 S - 3° 31'.5 S 145° 43'.0 E - 148° 31'.5 E

New chart with amended limits to provide improved coverage of Circular and Sherburne Reefs and includes the

latest surveys.

New Chart to be published shortly

Chart	Title	Scale	Expected Publication Date
Aus 55	Australia - North West Coast - Western Australia - Approaches to Port	1:50 000	18 November 2011
	Walcott		
Aus 293	Australian - North Coast - Torres Strait - Prince of Wales Channel	1:37 500	18 November 2011
Aus 296	Australian - North Coast - Torres Strait - Goods Island to Proudfoot Shoal	1:75 000	18 November 2011
Aus 346	Australia - South Coast - South Australia - Kangaroo Island (South Coast)	1:300 000	18 November 2011

New Edition to be published shortly

INCW EGIL	ion to be published shortly		
Chart	Title	Scale	Expected Publication Date
Aus 121	Plans in South Australia - South West Coast		18 November 2011
	Plans:		
	Streaky Bay	1:75 000	
	Coffin Bay	1:75 000	
	Port Eyre	1:50 000	
	Blanche Port	1:37 500	
	Venus Bay	1:37 500	
	Waterloo Bay	1:25 000	

Chart permanently withdrawn

Chart On publication of new chart

Aus 391 Aus 391

Chart permanently withdrawn without replacement

Chart On publication of new chart

Aus 462 Aus 391

For further details refer to the AHS website at www.hydro.gov.au for new edition and new chart stock arrival information.

When placing orders with a chart agent, mariners should advise whether their order pertains to the current edition or the new edition.

1112 AUSTRALIA - Amendment to Australian Seafarers Handbook AHP20

Australian Hydrographic Service (AA564388)

Chapter 13 - Charts and Publications - AHS Product Name Changes (all references)

Seafarer Tides change to AusTides

Seafarer RNC change to AusRNC (effective from Jan 2012)

1113 **AUSTRALIA - Product - Amendment to Australian National Tide Tables 2012**

Australian Hydrographic Service (AA561575)

Page xxxii

Amend Dampier To Chart Datum AUS 59 NC 9 SEP 2011 0.0

Page xxxiii

Amend Goods Island To Chart Datum AUS 299 NE 22 APR 2011 0.0

Page xxxvi

Pt Phillip Hds. To Chart Datum AUS 158 NC 12 AUG 2011 0.0 Amend

Page xxxvii

Thursday Island To Chart Datum AUS 299 NE 22 APR 2011 0.0 Amend

Page 374

Noosa Head To Chart Datum to 0.0 Amend

Amend Nerang River (Bundall) To Chart Datum to 0.0

Page 400

Amend Point Murat To Chart Datum to 0.0

1114* AUSTRALIA - NEW SOUTH WALES - Botany Bay - Navaids; navlines

Sydney Ports Corporation (AA560242 - AA560246)

Aus 198	[286/2011]
Incort	light E Or 26r

Aus 130 [20	0/2011]		
Insert	light, F.Or.26m	33° 57′.176 S	151º 11'.720 E
	light, <i>F.Or.19m</i>	33º 57'.311 S	151º 11'.755 E
	a dashed line in a direction 167.8° for a distance of		
	2250m, with legend 347.8°, emanating from light	33° 57′.176 S	151° 11′.720 E
	light, F.Bu.26m	33° 57′.206 S	151º 11'.765 E
	light, F.Bu.19m	33º 57'.335 S	151º 11'.798 E
	a dashed line in a direction 167.8° for a distance of		
	2170m, with legend 347.8°, emanating from light	33º 57'.206 S	151º 11'.765 E
Aus 199 [28	6/2011]		
Insert	light, F.Or.26m	33º 57'.176 S	151º 11'.720 E
	light, F.Or.19m	33º 57'.311 S	151º 11'.755 E
	a dashed line in a direction 167.8° for a distance of		
	2250m, with legend 347.8°, emanating from light	33º 57'.176 S	151º 11'.720 E
	light, F.Bu.26m	33° 57′.206 S	151º 11'.765 E
	light, F.Bu.19m	33º 57'.335 S	151º 11'.798 E
	a dashed line in a direction 167.8° for a distance of		
	2170m, with legend 347.8°, emanating from light	33º 57',206 S	151º 11'.765 E
	special spherical light buoy, <i>Fl(5)Y.20s</i> , without		
	topmark	33º 57'.855 S	151º 11'.642 E
		55 57 1000 0	

4 November 2011 6

	STRALIA - NEW SOUTH WALES - Port Jackson - Chart s Corporation (AA559932, AA559933)	notes; legend	
Aus 200 [95 Delete	3/2011] legend, PORT OPERATIONS CENTRE	33º 51'.41 S	151º 12'.10 E
Aus 202 [95	3/2011]		
Amend	text to readdecreases the above clearances by 3.3 metres.	33º 52'.20 S	151º 09'.87 E
Delete	legend, HARBOUR CONTROL CENTRE	33º 51'.42 S	151º 12'.10 E
AV SOODE IO	- 052/2014]		
AX 6202F [9 Amend	text to readdecreases the above clearances by 3.3 metres.	33º 52'.20 S	151º 09'.87 E
Delete	legend, HARBOUR CONTROL CENTRE	33º 51'.42 S	151º 12'.10 E
Geoscience	STRALIA - TASMAN SEA - Lord Howe Island - Depths Australia (DHDB 1708775)		
Aus 610 [95 Insert	4/2011] accompanying block	31º 33'.0 S	159° 05'.0 E
Maritime Saf Aus 256 [10 Amend	STRALIA - QUEENSLAND - Magnetic Island - Nelly Bay fety Queensland Notice 1044/2011 (AA563476) 61/2011] light beacon to Fl.G.1.5s an, Magnetic Harbour) light beacon to Fl.G.1.5s No1 light beacon to Fl.R.1.5s No2 light beacon to Fl.G.1.5s No3 light beacon to Fl.R.1.5s No4 light beacon to Fl.R.1.5s No5 light beacon to Fl.R.1.5s No5 light beacon to Fl.R.1.5s No6	19° 09'.75 S 19° 09'.75 S 19° 09'.75 S 19° 09'.75 S 19° 09'.69 S 19° 09'.63 S 19° 09'.63 S	146° 51'.37 E 146° 51'.37 E 146° 51'.34 E 146° 51'.37 E 146° 51'.34 E 146° 51'.37 E 146° 51'.34 E
Maritime Saf	STRALIA - QUEENSLAND - Lucinda - Light ety Queensland Notice 1042/2011 (AA563354)	19- 09-03-3	140° 31'.34 E
Aus 267 [10 Amend	<i>48/2010</i>] light to <i>Fl.G.2⋅5</i> s	18º 31'.30 S	146º 19'.87 E
	STRALIA - QUEENSLAND - Linden Bank - Depth naid (DHDB 1882853)		
Aus 831 [67 Insert	9/2011] depth 17₅m, enclosed by contour	16º 19'.35 S	145º 59'.27 E
Delete	depth, 21 ₇ m	16º 19'.2 S	145º 58'.9 E
AX 6027S [8	392/2011] depth 17₅m, enclosed by contour	16º 19'.35 S	145º 59'.27 E
	·		
Delete	depth, 21 ₇ m	16º 19'.2 S	145º 58'.9 E

1120* AUSTRALIA - QUEENSLAND - Cooktown - Light buoys

Former Notice - 1136(T)/2009 is cancelled

Maritime Safety Queensland (AA562996, AA561781 - AA561784)

) <i>11</i> 1
J

port lateral cylindrical light buoy, Fl.R.2.5s No2,	450 071 000 0	4.450.451.070.5
without topmark	15° 27′.226 S	145º 15'.372 E
light buoy	15º 27'.16 S	145º 15'.35 E
to	15º 27'.208 S	145º 15'.335 E
special cylindrical light buoy, Fl. Y.3s, without topmark		
for light beacon	15º 27'.71 S	145º 14'.78 E
light beacon	15º 27'.24 S	145º 15'.36 E
	port lateral cylindrical light buoy, Fl.R.2.5s No2, without topmark light buoy to special cylindrical light buoy, Fl.Y.3s, without topmark for light beacon	without topmark 15° 27'.226 S light buoy 15° 27'.16 S to 15° 27'.208 S special cylindrical light buoy, <i>Fl.Y.3s</i> , without topmark for light beacon 15° 27'.71 S

1121* AUSTRALIA - QUEENSLAND - Ellis Channel - Wilkie Bank - Light buoy

Former Notice - 1040(T)/2011 is cancelled

Maritime Safety Queensland Notice 975(T)/2011 (AA561070)

Aus 299	[1007/2011]
Move	light hugy

Move	light buoy	10º 35'.27 S	142º 14'.02 E
	to	10º 35'.349 S	142º 13'.937 E
Delete	denth 4-m	10º 35' 36 S	142º 13' 94 F

1122* PAPUA NEW GUINEA - Redscar Bay - Depths

HMAS Mermaid, HMAS Paluma (DHDB 1812533)

Aus 3	79 [198/2	201	1]
-------	------	-------	-----	----

Insert	depth, 8_2m , enclosed by contour	9º 08'.27 S	146º 41'.47 E
Substitute	depth, 7 ₃ m, enclosed by contour for depth, 13₁m	9º 10'.0 S	146º 40'.5 E

1123* PAPUA NEW GUINEA - Kimbe Island - Light

Former Notice - 406(T)/2008 is cancelled

National Maritime Safety Authority PNG Notice 43/2011 (AA561789)

Aus 547 [140/2011] light to FI(3)10s 110m 8M

Amend

4 4000 (INIT 000) [4005/004/1		
Aus 4622 (INT 622) [1065/2011]		

light to *FI(3) 8M* Amend

5º 12'.3 S 150° 22'.6 E

1124* AUSTRALIA - TORRES STRAIT - Cook Reef - Depth

Australian Hydrographic Service (AA561654)

Aus 376 [792/2011]

Substitute depth, 6_5m , for depth, 7_3m 10º 17'.6 S 141º 40'.8 E

Aus 700 [896/2011]

depth, 65m, for depth, 73m 10º 17'.6 S 141º 40'.8 E Substitute

4 November 2011 8

5º 12'.3 S

150° 22'.6 E

1125* INDONESIA - Arafura Sea - Merauke - Wreck Australian Hydrographic Service (AA563294, AA563298)

Aus 4603 (IN Insert	NT 603) [1009/2011] safe clearance depth, 15m, enclosed by danger circle with legend, Wk danger circle to enclose depth, 6m	9º 18'.0 S 8º 53'.0 S	139° 45'.0 E 139° 37'.0 E
Aus 4720 (IN Insert	NT 720) [632/2011] safe clearance depth, 15m, enclosed by danger circle with legend, Wk PA danger circle to enclose depth, 6 ₄ m	9º 18'.0 S 8º 53'.0 S	139° 45'.0 E 139° 37'.0 E
AX 4603F [9 Insert	safe clearance depth, 15m, enclosed by danger circle with legend, <i>Wk</i> danger circle to enclose depth, 6m	9º 18'.0 S 8º 53'.0 S	139° 45'.0 E 139° 37'.0 E
AX 4720F [6 Insert	s32/2011] safe clearance depth, 15m, enclosed by danger circle with legend, Wk PA danger circle to enclose depth, 6 ₄ m	9º 18'.0 S 8º 53'.0 S	139° 45'.0 E 139° 37'.0 E
Former Notic	STRALIA - TIMOR SEA - Sahul Banks - Light buoy ce - 476(T)/2006 is cancelled ngineers (AA561014)		
Aus 312 [10 Insert	67/2011] special spherical light buoy, <i>FI(5)Y.20s,</i> without topmark	11º 04'.95 S	126° 35'.90 E
AX 0312F [<i>1</i> Insert	067/2011] special spherical light buoy, <i>FI(5)Y.20s,</i> without topmark	11º 04'.95 S	126º 35'.90 E
1127* INDONESIA - Java Sea - Gosong Sibbalds - Light Dishidros, BA 3011 (AA560567)			
Aus 4060 (IN Delete	NT 60) [853/2 <i>011</i>] light	5º 45'.0 S	117º 07'.0 E
Aus 4071 (IN Delete	NT 71) [853/2 <i>011</i>] light	5° 45′.0 S	117º 07'.0 E
Aus 4603 (IN Substitute	NT 603) [<i>1125/2011</i>] depth, <i>8m,</i> for light	5° 45′.0 S	117º 07'.0 E
Aus 4708 (IN Substitute	NT 708) [<i>900/2011</i>] depth, <i>8m,</i> for light	5º 45'.0 S	117º 07'.0 E
AX 4603F [1 Substitute	125/2011] depth, 8m, for light	5° 45′.0 S	117º 07'.0 E
AX 4708F [9 Substitute	00/2011] depth, 8m, for light	5º 45'.0 S	117º 07'.0 E

9 4 November 2011

1128* INDIAN OCEAN - Christmas Island - Rocky Point to McPherson Point - Depths HMAS Leeuwin (DHDB 1897090), HMAS Melville (DHDB 1898120)

Aus 400 [85	[3/2011]		
Insert	approximate contour, between	10° 27′.22 S	105° 35′.14 E
	,	10° 26′.00 S	105º 33'.76 E
Delete	depth, 289m	10º 26'.3 S	105º 34'.5 E
20.0.0	contour, between	10° 27'.2 S	105° 35'.1 E
	contour, between	10° 27′.2 S	105° 34'.9 E
		10° 26′.0 S	105° 33′.8 E
	depth, 91m, and enclosing contour with legend, ED	10º 22'.4 S	105º 39'.4 E
Aus 608 [85	53/2011]		
Delete	depth, 563m, and enclosing contour with legend, ED	10º 26'.2 S	105° 35′.4 E
	depth, 289m, and enclosing contour with legend, ED	10º 26'.3 S	105º 34'.5 E
	depth, 91m, and enclosing contour with legend, ED	10º 22'.4 S	105° 39'.4 E
	dopan, o min, and onoloomy contour war logona, 25	10 22.10	100 00.4 E
4400* 411	OTD 4114 W/FOTEDN 4110TD 4114 D 4 1		
	STRALIA - WESTERN AUSTRALIA - Dampier Archipela	igo - Light buoys n	orthwards
	ce - 1270(T)/2010 is cancelled		
MetOcean E	ngineers (AA561014)		
Aus 327 [10	071/2011]		
Insert	special spherical light buoy, FI(5)Y.20s, without		
	topmark	18º 45'.51 S	117º 01'.86 E
		10 40.010	117 01.00 L
	special spherical light buoy, FI(5)Y.20s, without	400 041 00 0	4.470.001.40.5
	topmark	19º 31'.30 S	117º 03'.12 E
Aus 741 [90	00/2011]		
Insert	special spherical light buoy, FI(5)Y.20s, without		
	topmark	19º 31'.30 S	117º 03',12 E
1130* AU	STRALIA - WESTERN AUSTRALIA - Dampier - King Ba	v - Light heacon	
	ydrographic Service (AA433964)	y Light beacon	
Australian	ydiographic Service (AA433904)		
A F7 [000	0/0.0441		
Aus 57 [638			
Amend	light beacon to <i>LFI.10</i> s	20º 37'.7 S	116º 44'.1 E
Aus 58 [960	/2011]		
Amend	light beacon to LFI.10s 5M Fairway	20º 37'.69 S	116º 44'.08 E
	3		
Aus 59 [NC	9/9/2011]		
	light beacon to <i>LFI.10s 5M Fairway No1</i>	20º 37'.69 S	116º 44'.08 E
Amena	light beacon to Li i. los ow i all way No i	20 31.093	110 44.00 L
	STRALIA - WESTERN AUSTRALIA - Barrow Island - To	wn Point - Light bu	loy
Department	of Transport WA Notice 138/2011 (AA562666)		
Aus 62 [961	/2011]		
Move	light buoy	20º 48'.56 S	115° 29'.69 E
	to	20° 49′.174 S	115° 30'.284 E
	i.	20 43.1143	110 JU.Z04 E
A 740 [40	140/00441		
Aus 742 [10		000 401 0 0	4450 001 7 5
Move	light buoy	20º 48'.6 S	115º 29'.7 E
	to	20° 49′.17 S	115º 30'.28 E
Aug 742 [40			
Aus 143 10	010/2011]		
Move	010/2011] light buoy	20º 48'.6 S	115º 29'.7 E

4 November 2011 10

20° 49′.17 S

115º 30'.28 E

1132* AUSTRALIA - WESTERN AUSTRALIA - North West Cape - Light buoy northwards

Former Notice - 176(T)/2011 is cancelled

MetOcean Engineers (AA561014)

Aus 328 [1071/2011]

Insert special spherical light buoy, FI(5)Y.20s, without

topmark 21° 31′.02 S 114° 01′.20 E

Aus 329 [1310/2010]

Insert special spherical light buoy, FI(5)Y.20s, without

topmark 21° 31′.02 S 114° 01′.20 E

Aus 744 [902/2011]

Insert special spherical light buoy, FI(5)Y.20s, without

topmark 21° 31'.02 S 114° 01'.20 E

1133* AUSTRALIA - SOUTH AUSTRALIA - Port Lincoln - Magnetic variation

A ODonnell, Boat Books Melbourne (AA563238)

Aus 134 [356/2011]

Amend magnetic variation to 6°55′E 2014 (1′E) 34° 39′.2 S 136° 00′.1 E magnetic variation to 7°00′E 2014 (1′E) 34° 54′.8 S 135° 57′.1 E

1134* AUSTRALIA - SOUTH AUSTRALIA - Franklin Harbor - Beacons

Department for Transport, Energy and Infrastructure SA (AA561580 - AA561583)

Aus 777 [690/2011]

Move	to	33° 42'.3 S 33° 42'.55 S	136° 55'.6 E 136° 55'.54 E
Delete	beacon	33º 42'.9 S	136º 55'.3 E

Aus 777 (plan, Franklin Harbor)

 Insert
 beacon with port lateral topmark beacon with port lateral topmark
 33° 43′.997 S
 136° 57′.478 E

 Move
 beacon
 33° 42′.553 S
 136° 55′.538 E

 33° 42′.31 S
 136° 55′.64 E

to 33° 41'.867 S 136° 55'.989 E

Delete depth, 0₄m 33° 42'.47 S 136° 55'.58 E

1135* AUSTRALIA - SOUTH AUSTRALIA - Port Alfred - Black Point - Light beacon

Department for Transport, Energy and Infrastructure SA (AA561609, AA561610)

Aus 139 (plan, Ardrossan Harbor Approaches) [598/2011]

Insert	light beacon, Fl.R.3s, with port lateral topmark	34º 36'.125 S	137º 55'.400 E
Delete	beacon	34º 36'.07 S	137º 55'.57 E
Aus 781 [8 Insert	60/2011] light beacon, <i>Fl.R.3</i> s, with port lateral topmark	34º 36'.13 S	137º 55'.40 E
Delete	beacon	34º 36'.1 S	137º 55'.6 E

1136* AUSTRALIA - TASMANIA - River Tamar - Dotterel Point to Point Rapid - Depths HydroSurvey Australia (DHDB 1380090)

Aus 167 [1	079/2011]		
Insert	depth, 11 ₄ m	41º 07'.879 S	146° 49′.012 E
	depth, 32m, and extend contour NW to enclose	41º 04'.144 S	146º 47'.514 E
Delete	depth, 13₀m	41º 07'.88 S	146º 49'.02 E
	depth, 4 ₂ m	41º 04'.17 S	146º 47'.54 E
Aus 167 (p	lan, Bell Bay)		
Insert	depth, 11 ₄ m	41º 07'.879 S	146° 49'.012 E
Delete	depth, 13 ₉ m	41º 07'.88 S	146º 49'.02 E
Aus 168 [1	002/2010]		
Insert	depth, 45m, enclosed by contour	41º 10'.294 S	146° 55′.667 E
	depth, 46m, enclosed by contour	41º 10'.333 S	146° 55′.822 E

1137* AUSTRALIA - VICTORIA - Port Phillip - Hobsons Bay - Light

Victorian Notice 123/2011 (AA563406)

Aus 155 [602/2011] Amend light to *Fl.G.10s* 37º 51'.06 S 144º 56'.99 E

4 November 2011 12

1138(T)/2011 AUSTRALIA - NEW SOUTH WALES - Bega to Port Jackson - Ship to ship transfer completed

Former Notice - 1018(T)/2011 is cancelled Caltex Australia Petroleum Pty Ltd (AA559166)

Cancel this notice on receipt.

Chart formerly affected – Aus 489 – Aus 4643 (INT 643)

1139(T)/2011 AUSTRALIA - NEW SOUTH WALES - Botany Bay - Harbour works

Date - Until 30 November 2012

Sydney Ports Corporation (AA562429)

Harbour works associated with the construction of Bulk Liquids berth 2 are in progress in an area bounded by the HWL and special light buoys, *Fl.Y.5s*, in the following positions:

33° 58'.84 S 151° 12'.57 E 33° 58'.83 S 151° 12'.53 E 33° 58'.79 S 151° 12'.53 E 33° 58'.75 S 151° 12'.52 E 33° 58'.70 S 151° 12'.53 E 33° 58'.67 S 151° 12'.55 E 33° 58'.62 S 151° 12'.55 E 33° 58'.58 S 151° 12'.55 E 33° 58'.54 S 151° 12'.59 E 33° 58'.52 S 151° 12'.61 E 33° 58'.50 S 151° 12'.67 E.

The area is restricted and only vessels involved in the works are authorised access.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected – Aus 198 – Aus 199

1140(T)/2011 AUSTRALIA - NEW SOUTH WALES - Newcastle - Depth information Former Notice - 968(T)/2011 is cancelled Newcastle Port Corporation (AA564167)

Available depths as at 21 October 2011:	
Berth	Metres
Western Basin 3	11.6
Western Basin 4	11.6
Eastern Basin 1	11.6
Eastern Basin 2 North of Ch 450	11.6
Eastern Basin 2 South of Ch 450	11.0
Channel Berth	8.3
Dyke 1	12.5
,	12.8
Dyke 2	
Dyke 4	16.3
Dyke 5	16.3
Dyke 6	6.3
Mayfield 4 Ch 27 to 266	12.6
BHP Wharf 6 to Ch 1050	7.9
Kooragang 2	11.4
Kooragang 2 North Dolphin Ch 182 to 228	11.1
Kooragang 2 South Dolphin Ch -92 to 00	10.9
Kooragang 3	13.0
* Kooragang 4	16.4
Kooragang 5	16.5
Kooragang 6	16.5
Kooragang 8	16.5
Kooragang 9	16.5
Kooragang Ship Receival KSR	7.5
Throsby 1	8.4
Carrington Wharf	To be sounded as and when required
Foreshore Park Berth	5.9
Elgo Wharf	To be sounded as and when required
Channels	
Entrance Approach	17.7
Entrance Channel (18.0m)	18.0
Entrance Channel (17.4m)	17.4
Entrance Channel (16.8m)	16.8
Entrance Channel (16.2m)	16.2
Entrance Channel to Horseshoe	15.2
Horseshoe	15.0
Steelworks Channel to Swinging Basin	15.0
Swinging Basin	15.0
Swinging Basin to Mayfield 4	12.8
* Hunter River South Arm (Kooragang 6 to Kooragang 9)	15.2
Basin Cutting	12.8
Basin Area to Eastern & Western Basin Berths	12.3
Basin Area to 1 Throsby	10.0
Stockton Crossing	3.6
* Indicates revised entry.	5.5
maioacoo romood omiy.	

Chart temporarily affected - Aus 207 - Aus 208

4 November 2011 14

1141(P)/2011 AUSTRALIA - NEW SOUTH WALES - Newcastle - Infrastructure; navaids

Former Notice - 515(T)/2011 is cancelled

Newcastle Port Corporation (AA562730, AA562731)

The new channel widening into Kooragang berths 8 and 9 has been completed. The channel is marked by the following navaids:

-	Position	Characteristic
3	32° 52'.500 S 151° 44'.311 E	F.G 19m 13M
3	32° 52'.228 S 151° 43'.831 E	F.G 33m 13M
3	32° 52'.491 S 151° 44'.318 E	F.R 19m 13M
3	32° 52'.219 S 151° 43'.838 E	F.R 33m 13M
3	32° 53′.690 S 151° 46′.412 E	F.G 30m 13M
3	32° 53'.869 S 151° 46'.728 E	F.G 38m 13M
3	32° 53'.829 S 151° 46'.203 E	FI.R.3s No8
3	32° 53′.698 S 151° 46′.132 E	FI.R.3s No10
3	32° 53'.436 S 151° 45'.860 E	FI.R.3s No12
3	32° 53'.273 S 151° 45'.573 E	Fl.R.3s No14
3	32° 53'.103 S 151° 45'.272 E	Fl.R.3s No16
3	32° 52'.965 S 151° 45'.120 E	Fl.R.3s No18.

The light Dir WRG (32° 53'.77 S 151° 46'.41 E) has been discontinued.

An accompanying diagram showing the changes is attached. New editions of Aus 208 and ENC Cell AU5XX208 will be published shortly.

Chart which will be affected - Aus 207 - Aus 208

1142(T)/2011 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Shoaling

Former Notice - 910(T)/2011 is cancelled

Maritime Safety Queensland Notice 1070(T)/2011 (AA565511)

Available depths as at 24 October 2011:

Metres

Centre line leads (255°) 4.8 Southern approach leads (291°) 3.9

A shoal area, with a least depth of 3.9m, is drifting northwards immediately east of the southern break wall towards the centreline leads.

Mariners are advised to navigate with caution when using the southern approach leads as breaking waves may be experienced when seas rise above 1.5m.

Chart temporarily affected - Aus 230

1143(T)/2011 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Dredging operations

Former Notice - 909(T)/2011 is cancelled

Date - Until 28 February 2012

Maritime Safety Queensland Notice 1072(T)/2011 (AA565512)

The dredge Port Frederick is conducting dredging operations at the entrance to the Gold Coast Seaway (27° 56'.0 S 153° 26'.0 E).

The dredge will be operating between the entrance and Surfers Paradise beach (28° 00′.0 S 153° 26′.0 E) during the operations.

The dredge will monitor VHF Ch 16 and Ch 67.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 230 - Aus 814

1144(T)/2011 AUSTRALIA - QUEENSLAND - Moreton Bay - Brisbane River - Depth information Former Notice - 1081(T)/2011 is cancelled Brisbane Port Corporation (AA565406)

Available depths and under keet elegrances (LIK)	2) of 2 N	ovember 2011:
Available depths and under keel clearances (UKO Berth		Remarks
* Fisherman Islands No10	13.9	Remarks
Fisherman Islands No9	14.0	
Fisherman Islands No8	14.0	
Fisherman Islands No7	14.0	
* Fisherman Islands No6	13.8	
* Fisherman Islands No5	14.0	
Fisherman Islands No4	14.0	
Fisherman Islands No3	14.0	
* Fisherman Islands No2	14.0	
* Fisherman Islands No1	13.8	
Fisherman Islands Grain and Woodchip	13.0	
Caltex Fisherman Islands	14.5	
Fisherman Islands Coal	14.1	
Fisherman Islands General Purpose	11.5	
* BP Luggage Point	14.3	
Caltex Products	9.8	
Cement Australia Co Wharf	9.8	
BP Products	10.9	
Shell	10.9	
Pacific Terminals	10.8	
Incited North	10.0	
* Incited South	10.3	
Pinkenba 1	10.4	
Pinkenba 2	10.4	
Riverside Marina	-	
* Sugar Terminal	9.7	
Cairncross Fitting Out Wharf	8.0	
Cairncross Breasting Wharf	6.5	
Brisbane Naval Wharf	-	
Maritime No3	5.6	(not maintained)
* Maritime No2	8.8	(not maintained)
Maritime No1	9.0	
Hamilton No4	10.3	
* Hamilton No1	8.8	
Brisbane Cruise Ship Terminal	9.3	
Briddane Graide Griip Terminai	0.0	
	Metres	UKC/Remarks
Moreton Bay :		
North East Channel	5.5	1.5
North West Channel	14.9	2.3 (280m width)
North West Bypass Channel	9.2	1.6
Spitfire Channel	15.0	1.5 (600m width)
East Knoll Bypass Channel	6.9	1.4
East Channel	15.0	1.5 (300m width from western side)
Main Channel (M8 - M9)	10.0	1.8
Entrance Channel (E5 - EBCN)	14.7	1.5
Brisbane River:		
Entrance Beacons and Bar Cutting	14.0	1.46
Fisherman Islands Swing Basin	14.0	1.3
Pelican Banks Reach to Hamilton Reach	9.0	0.6 / 0.9 (draft/tide)
Cement Australia Swing Basin	9.0	0.6 / 0.9 (draft/tide)
Pinkenba Swing Basin	9.0	0.6 / 0.9 (draft/tide)
Hamilton Swing Basin	8.8	0.6 / 0.9 (draft/tide)
* Indicates new or revised entry.		

Chart temporarily affected - Aus 235 - Aus 236 - Aus 237 - Aus 238 - Aus 814 - Aus 815

4 November 2011 16

1145(T)/2011 AUSTRALIA - QUEENSLAND - Brisbane River - Petrie Bight - Harbour works

Former Notice - 203(T)/2011 is cancelled

Date - Until 16 December 2011

Maritime Safety Queensland Notice 1024(T)/2011 (AA562438)

Remediation works on Howard Smith Wharves (27° 27'.75 S 153° 02'.13 E) are in progress.

A barge and support vessels are on site and will display appropriate lights and shapes. The barge has deployed three anchors, marked by special light buoys. The support vessel will monitor VHF Ch 13.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 238

1146(T)/2011 AUSTRALIA - QUEENSLAND - Moreton Bay - Deception Bay - Scientific instruments recovered

Former Notice - 204(T)/2011 is cancelled Maritime Safety Queensland (AA565517)

Cancel this notice on receipt.

Chart formerly affected - Aus 236

1147(T)/2011 AUSTRALIA - QUEENSLAND - Point Arkwright - Scientific instruments recovered

Former Notice - 972(T)/2011 is cancelled

Maritime Safety Queensland Notice 872(T)/2011 (AA556309)

Cancel this notice on receipt.

Chart formerly affected - Aus 815

1148(T)/2011 AUSTRALIA - QUEENSLAND - Gladstone - Pipelines

Former Notice - 1088(T)/2011 is cancelled

Date - Until 31 December 2012

Maritime Safety Queensland Notices 877(T)/2011, 994(T)/2011, 1017(T)/2011, 1071(T)/2011, 1080(T)/2011 (AA556928, AA561056, AA562067, AA565645, AA565737)

Submarine pipelines, marked by unlit orange buoys and lit special buoys, exist between;

23° 46'.56 S 151° 10'.03 E 23° 46'.65 S 151° 10'.71 E 23° 46'.87 S 151° 11'.52 E and 23° 46'.56 S 151° 10'.03 E 23° 46'.56 S 151° 11'.12 E 23° 46'.38 S 151° 11'.38 E and 23° 46'.18 S 151° 09'.95 E 23° 45'.49 S 151° 10'.34 E 23° 45'.49 S 151° 10'.55 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 244 - Aus 245

1149(T)/2011 AUSTRALIA - QUEENSLAND - Shoalwater Bay - Live firing

Date - Until 23 November 2011

Maritime Safety Queensland Notice 830(T)/2011 (AA553615)

Live firing activities will be conducted in the Shoalwater Bay training area during the period 11 to 22 November 2011.

A marine danger area extends to all internal waters bounded by the following positions:

22° 29′.51 S	150° 24′.40 E
22° 30′.20 S	150° 33'.89 E
22° 33′.13 S	150° 42′.40 E
22° 40′.00 S	150° 38'.00 E
22° 35′.87 S	150° 28'.80 E
22° 29'.51 S	150° 24'.40 E.

All waters, creeks, beaches and other areas within the declared marine danger area are not available for access.

Mariners are advised to keep clear of this area throughout the above times.

Chart temporarily affected - Aus 367 - Aus 820 - Aus 822 - AX 0367E - AX 0820E - AX 0822E

1150(T)/2011 AUSTRALIA - QUEENSLAND - Percy Isles - South Island - Wreck

Maritime Safety Queensland Notice 1074(T)/2011 (AA565504)

A wreck exists in position 21° 48'.18 S 150° 23'.70 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 822 - Aus 823 - AX 0822E - AX 0823E

1151(T)/2011 AUSTRALIA - QUEENSLAND - Hay Point - Depth information

Former Notice - 1090(T)/2011 is cancelled

Maritime Safety Queensland Notice 1055(T)/2011 (AA564549)

Available depths as at 27 October 2011:

	Wetres
* HPS Berth No 1	16.0
HPS Berth No 2	16.4
DBCT Berth No 1	17.8
DBCT Berth No 2	17.6
DBCT Berth No 3	18.1
DBCT Berth No 4	17.5
* Indicates revised entry.	

Chart temporarily affected - Aus 249 - Aus 250 - AX 0249E

1152(T)/2011 AUSTRALIA - QUEENSLAND - Townsville - Dredging operations

Date - Until 28 November 2011

Maritime Safety Queensland Notice 1043(T)/2011 (AA564684)

The dredge *Brisbane* is conducting dredging operations in the Sea Channel (19° 10'.0 S 146° 52'.7 E), Platypus Channel (19° 13'.5 S 146° 50'.7 E), outer harbour (19° 14'.4 S 146° 50'.3 E) and inner harbour (19° 14'.9 S 146° 50'.0 E).

Further information can be obtained by contacting Townsville VTS on VHF Ch 12 and Ch 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 256 - Aus 257

1153(T)/2011 AUSTRALIA - QUEENSLAND - Rocky Point - Light beacon re-established

Former Notice - 170(T)/2009 is cancelled Maritime Safety Queensland (AA564067)

Cancel this notice on receipt.

Chart formerly affected - Aus 829

1154(T)/2011 AUSTRALIA - QUEENSLAND - Cairns - Trinity Inlet - Smiths Creek - Wreck

Maritime Safety Queensland Notice 1021(T)/2011 (AA562436)

A wreck marked by a special light buoy, Fl. Y.2.5s, exists in position 16° 57'.51 S 145° 46'.26 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 264

1155(P)/2011 AUSTRALIA - TORRES STRAIT - East Strait Island to Gannet Passage - Two-way route amendment; light buoy to be established; light buoys to be repositioned

Former Notice - 1039(P)/2011 is cancelled

Date - Until 18 November 2011

Australian Maritime Safety Authority Preliminary ATH 11/2011, 12/2011, 13/2011, 14/2011 (AA559150, AA559151, AA564092, AA564095 - AA564097)

The two-way route is to be amended to define the route north of Alert Patches that is used as an alternate route by medium draught vessels using the Great North East Channel. Vessels using this route should be cognisant of the ZOC B category of this area and plan accordingly. The ZOC category will be upgraded following re-survey.

The two-way route is to be amended to define the route south of Herald Patches that is used as an alternative route by shallow draught vessels using the inner route of the Great Barrier Reef.

The extant two-way route at the western end of Prince of Wales Channel is top be extended to Varzin and Gannet Passages.

A north cardinal light buoy, Q, with topmark will be established in position 10° 28'.43 S 142° 22'.61 E.

The light buoys will be repositioned as follows:

Current position	New position	Remarks
10° 32'.47 S 141° 52'.20 E	10° 32'.40 S 141° 52'.17 E	C1
10° 32'.11 S 141° 52'.03 E	10° 32'.17 S 141° 51'.95 E	C2
10° 35'.40 S 141° 52'.48 E	10° 35'.49 S 141° 52'.41 E	south cardinal

New charts Aus 293 and Aus 296, scheduled for publication on 18 November 2011, will refer. Charts Aus 292, Aus 301, Aus 376, Aus 700 and Aus 839 will be updated by NTM block correction.

Chart which will be affected - Aus 292 - Aus 293 - Aus 296 - Aus 376 - Aus 780 - Aus 839

1156(T)/2011 AUSTRALIA - QUEENSLAND - Thursday Island - Light beacon destroyed Maritime Safety Queensland Notice 1026(T)/2011 (AA565110)

The light beacon, Fl.Y.2.5s (10° 34'.88 S 142° 11'.91 E (WGS84 datum)), has been destroyed.

Chart temporarily affected - Aus 293 - Aus 299

1157(T)/2011 AUSTRALIA - QUEENSLAND - Thursday Island - Light buoy re-established

Former Notice - 570(T)/2011 is cancelled Maritime Safety Queensland (AA563272)

Cancel this notice on receipt.

Chart formerly affected - Aus 292 - Aus 293 - Aus 299

1158(T)/2011 PAPUA NEW GUINEA - Gulf of Papua - Works

Date - Until 31 December 2011

National Maritime Safety Authority PNG Notice 44/2011 (AA565256)

DPB Lewek Champion and support vessels are conducting construction works and pipelay operations in an area within a 5M radius of Kumul production platform (8° 03'-86 S 144° 33'-64 E). An exclusion zone exists within the area of the works and pipelay operations.

Chart temporarily affected - Aus 378 - Aus 502

1159(T)/2011 PAPUA NEW GUINEA - Bougainville Island - Lights unlit

Former Notice - 660(T)/2011 is cancelled

National Maritime Safety Authority PNG Notices 22/2011, 46/2011 (AA535709, AA565338)

The following lights are unlit:

ine renering ngine are armi	
Location	Position
Takanupei Island (K4884.4)	6° 08'.86 S 155° 34'.31 E
Dokome Point (K4885.2)	6° 10'.91 S 155° 32'.94 E
Kerekerina Point (K4885)	6° 11'.30 S 155° 33'.56 E
Arawa Bay (K4884.6)	6° 13'.74 S 155° 34'.37 E
Banaru Reef (K4885.7)	6° 08'.30 S 155° 39'.03 E
Moto Reef (K4885.8)	6° 08'.77 S 155° 39'.52 E
Wogoromodo Reef (K4885.6)	6° 10'.12 S 155° 39'.03 E

Chart temporarily affected - Aus 399 - Aus 683 - Aus 4622 (INT 622)

1160(T)/2011 AUSTRALIA - QUEENSLAND - Weipa - Dredging operations completed

Former Notice - 1041(T)/2011 is cancelled

Maritime Safety Queensland Notice 926(T)/2011 (AA559261)

Cancel this notice on receipt.

Chart formerly affected - Aus 4

1161(T)/2011 AUSTRALIA - NORTHERN TERRITORY - Darwin - Frances Bay - Mooring buoy

Former Notice - 939(T)/2011 is cancelled

Date - Until 30 November 2011

Darwin Port Corporation Notice 84(T)/2011 (AA565562)

A lit yellow cylindrical mooring buoy, Q. Y, exists in position 12° 28′.35 S 130° 51′.47 E.

Chart temporarily affected - Aus 24 - Aus 26 - Aus 28 - AX 72026

1162(T)/2011 AUSTRALIA - NORTHERN TERRITORY - Darwin - East Arm - Mooring buoys withdrawn

Former Notice - 713(T)/2011 is cancelled

Darwin Port Corporation Notice 86/2011 (AA565644)

Cancel this notice on receipt.

Chart formerly affected - Aus 26 - Aus 28 - AX 72026

1163(T)/2011 AUSTRALIA - NORTHERN TERRITORY - Darwin - Hudson Creek - Light beacon removed; light buoy established

Darwin Port Corporation Notice 83(T)/2011 (AA565102)

The light beacon, Q.G.2m 2M, has been temporarily removed; a yellow light buoy, Q.G, exists in situ.

Chart temporarily affected - Aus 26 - Aus 28 - AX 72026

1164(T)/2011 AUSTRALIA - TIMOR SEA - Melville Island - Seismic survey northwestwards

Date - Until 23 December 2011

Eni Australia (AA564956)

MV Veritas Viking II, towing eight 4800m cables, and support vessels are conducting a survey in an area bounded by the following positions:

10° 13'.26 S 128° 52'.82 E

10° 03'.71 S 128° 49'.44 E

10° 00'.02 S 129° 02'.39 E

10° 00'.01 S 129° 15'.00 E

10° 04'.22 S 129° 16'.38 E

10° 13'.26 S 128° 52'.82 E.

Chart temporarily affected - Aus 310 - Aus 311 - Aus 4721 (INT 721) - AX 0310F - AX 0311F - AX 4721F

1165(T)/2011 AUSTRALIA - WESTERN AUSTRALIA - Coulomb Point to Cape Boileau - Scientific instruments

Former Notice - 1204(T)/2010 is cancelled

Date - Until 31 December 2012

Woodside Energy Ltd (AA565081, AA565082)

Scientific instruments marked by buoys exist in positions:

17° 20'.69 S 122° 04'.90 E

17° 23'.33 S 122° 07'.52 E

17° 25'.04 S 122° 06'.42 E

17° 27'.95 S 122° 07'.80 E

17° 29'.46 S 122° 07'.86 E

17° 30'.11 S 122° 06'.06 E

17° 31'.39 S 122° 07'.72 E

17° 32'.95 S 122° 08'.29 E

17° 33'.94 S 122° 06'.34 E 17° 34'.95 S 122° 07'.28 E

17° 35'.24 S 122° 09'.03 E

17° 41'.59 S 122° 10'.04 E.

Chart temporarily affected - Aus 324

1166(T)/2011 AUSTRALIA - WESTERN AUSTRALIA - Exmouth Plateau - Mooring buoys

Date - Until 29 February 2012

Auscoast Warnings 268/2011, 269/2011 (AA564572, AA564674), Hess Exploration Australia Pty Ltd (AA565581)

Four lit mooring buoys exist in each of the following positions 20° 04'.57 S 113° 49'.55 E and 20° 28'.79 S 113° 54'.35 E.

Chart temporarily affected - Aus 328 - Aus 329

1167(T)/2011 AUSTRALIA - WESTERN AUSTRALIA - Thevenard Island - Scientific instruments

Former Notice - 1277(T)/2010 is cancelled

Date - Until 30 November 2012 MetOcean Engineers (AA565533)

Scientific instruments marked by special light buoys, FI(5)Y.20s, exist in the following positions:

21° 03'.65 S 115° 08'.26 E 21° 18'.98 S 115° 13'.73 E 21° 28'.41 S 115° 08'.41 E 21° 28'.43 S 115° 08'.51 E 21° 31'.75 S 115° 01'.41 E 21° 31'.75 S 115° 01'.82 E 21° 35'.00 S 115° 01'.28 E 21° 39'.29 S 115° 00'.09 E.

Chart temporarily affected - Aus 64 - Aus 328 - Aus 743

1168(T)/2011 AUSTRALIA - WESTERN AUSTRALIA - Jurien Bay - Harbour works

Date - Until 13 December 2011

Department of Transport WA Notice 137/2011 (AA565369)

Harbour works associated with the construction of two additional boat ramps are in progress in the vicinity of position 30° 17'.41 S 115° 02'.74 E. The area of the works is marked by two special light buoys, Q.Y. Unlit piles exist within the work area. The barge *Gunna* and support vessels will install a pontoon in the area and will monitor VHF Ch 4.

All vessels involved in the works will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 84

1169(T)/2011 AUSTRALIA - WESTERN AUSTRALIA - Cockburn Sound - Jervoise Bay - Dredging operations

Date - Until 9 December 2011

Fremantle Ports Notice 18(P)/2011 (AA565592)

The dredge *Baldur*, barges *Chun Hing* and *LLM006* and support vessels are conducting dredging operations in the vicinity of position 32° 09'.61 S 115° 45'.80 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 114 - Aus 117 - AX 70117

1170(T)/2011 AUSTRALIA - SOUTH AUSTRALIA - Great Australian Bight - Ceduna Terrace - Seismic survey

Date - Until 6 May 2012

NT Shipping Agencies (AA565074, AA565075)

MV Ramform Sterling, and support vessels, Ocean Dynasty and Unlimited, are conducting a survey in the area bounded by the following positions:

33° 30'.0 S 129° 23'.5 E 33° 30'.0 S 131° 52'.0 E 35° 30'.0 S 131° 52'.0 E 35° 30'.0 S 129° 23'.5 E.

Chart temporarily affected - Aus 4727 (INT 727)

1171(T)/2011 AUSTRALIA - VICTORIA - Port Phillip - South Channel - Shoaling

Victorian Notice 127(T)/2011, 128(T)/2011 (AA565638, AA565639)

South cardinal light buoys, VQ(6)+LFI.10s, exist in positions 38° 18'.22 S 144° 44'.36 E and 38° 19'.09 S 144° 48'.71 E. Shoaling with a least depth of 14.9m exists north of a line joining the positions and a least depth of 15.2m to the south.

A south cardinal light buoy, VQ(6)+LFI.10s, exists in position 38° 18'.27 S 144° 45'.65 E. Shoaling with least depth 13.4 exists to the north of the position.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 144 - Aus 158

1172(T)/2011 AUSTRALIA - VICTORIA - Port Phillip - Altona - Dredging operations completed

Former Notice - 1056(T)/2011 is cancelled Victorian Notice 116(T)/2011 (AA559331)

Cancel this notice on receipt.

Chart formerly affected - Aus 155

1173(T)/2011 AUSTRALIA - VICTORIA - Port Phillip - Sorrento - Harbour works completed

Former Notice - 724(T)/2011 is cancelled Victorian Notice 65(T)/2011 (AA543562)

Cancel this notice on receipt.

Chart formerly affected - Aus 143 - Aus 158

HYDROGRAPHIC REPORTS

Locality	Report	Ship/Authority	Observer
WA – Exmouth Plateau	Mooring buoys	MV Maersk Searcher	

NAVIGATION WARNINGS

The following radio messages have been received during the period to 4 November 2011. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNING

	7,00007,01 117,11,111,10
261	Cancelled.
262	Special purpose vessel <i>Sapura 3000</i> conducting underwater operations in position 12° 39'.6 S 124° 32'.7 S. 2.5M clearance requested.
263	Drill rig Ocean Patriot in position 12° 07'.67 S 124° 59'.78 E. 2.5M clearance requested.
264	Four yellow lit white flashing mooring buoys in the vicinity of position 20° 18'·70 S 114° 23'·9 E. 2·0M clearance requested.
265	Cancelled.
266	Cancelled.
267	Special purpose vessel <i>Greatship Mamta</i> conducting subsea survey in an area bounded by 20° 03'.0 S to 20° 05'.0 S and 115° 10'.0 S to 115° 12'.0 S. 2.5M clearance requested.
268	Four lit mooring buoys in position 20° 04'.57 S 113° 49'.55 E. 2.0M clearance requested.
269	Four lit mooring buoys in position 20° 28'·79 S 113° 54'·35 E. 2·0M clearance requested.
270	Special purpose vessel <i>Seisquest</i> conducting seismic survey, towing eight 6600m cables, in an area bounded by 18° 46'.0 S to 19° 15'.0 S and 115° 25'.0 E to 115° 44'.0 S. 5.0M clearance requested.
271	Cancelled.
272	Special purpose vessel Viking Vision conducting seismic survey in an area bounded by 19° 00'.00 S to 21° 00'.00 S

NAVAREA X WARNINGS

- 021 Cancelled.
- 022 Naval training operations underway 011300 to 040100 UTC in area bounded by 22° 41'.0 S 169° 06'.5 E and 24° 44'.0 S 170° 10'.0 E.

Navigational warnings in force as at 040001UTC NOV 11.

Auscoast

2011 206 221 228 243 246 255 258 259 260 262 263 264 267 268 269 270 272

and 111º 27'.00 E to 114º 06'.00 S. 5.0M clearance requested.

Navarea X 2011 018 022


Summary of mobile drilling rigs as at 040001UTC NOV 11.

Name	Position
Ocean Patriot	12° 07'.67 S 124° 59'.78 E
Transocean Legend	20° 31'.70 S 116° 40'.60 E
Ensco 109	20° 31'.99 S 116° 40'.14 E
Nan Hai 6	19° 28'-00 S 116° 38'-00 E
Atwood Eagle	20° 23'.23 S 111° 49'.84 E
Atwood Osprey	20° 31'-12 S 114° 49'-26 E
Ocean America	21° 30'-51 S 113° 50'-32 E
Maersk Discoverer	19° 54'-75 S 111° 36'-90 E

NAVARFA XIV WARNINGS

		NAVAREA AIV WARNINGS
101 102 103 104 105 106	Cancelled. Cancelled. Cancelled. Cancelled. Cancelled. Cancelled.	
107 108 109	Cancelled. Cancelled. Cancelled.	
2011	096	Navarea XIV warnings in force as at 040001UTC NOV 11.

To accompany Australian Notice to Mariners 1116/2011



Block for Aus 610 © Commonwealth of Australia 2011 (90.2 x 121.1mm)

