

13 March 2015 Edition 5

Australian Notices to Mariners are the authority for correcting Australian Charts and Publications

AUSTRALIAN NOTICES TO MARINERS

Notices 266 - 334



Published fortnightly by the Australian Hydrographic Service

Commodore B.K. BRACE RAN Hydrographer of Australia

SECTIONS.

- I. Australian Notices to Mariners, including blocks and notes.
- II. Hydrographic Reports.
- III. Navigational Warnings.

SUPPLEMENTS.

- I. Tracings
- II. Cumulative List of Australian Notices to Mariners.
- III. Cumulative List of Temporary and Preliminary Australian Notices to Mariners.
- IV. Temporary and Preliminary Notices in force.
- V. Amendments to Admiralty List of Lights and Fog Signals (Vol K), Radio Signals (NP 281(2), 282, 283(2), 285, 286(4)) and Sailing Directions (NP 9, 13, 14, 15, 33, 34, 35, 36, 39, 44, 51, 60, 61, 62, 100, 136).

© Commonwealth of Australia 2015

This work is copyright. Apart from any use permitted under the Copyright Act 1968, no part may be reproduced by any process, adapted, communicated or commercially exploited without prior written permission from The Commonwealth represented by the Australian Hydrographic Service.

IMPORTANT NOTICE

This edition of Notices to Mariners includes all significant information affecting AHS products which the AHS has become aware of since the last edition. All reasonable efforts have been made to ensure the accuracy and completeness of the information, including third party information, on which these updates are based. The AHS regards third parties from which it receives information as reliable, however the AHS cannot verify all such information and errors may therefore exist. The AHS does not accept liability for errors in third party information.

GENERAL INSTRUCTIONS

The substance of these notices should be inserted on the charts affected.

Bearings are referred to the true compass and are reckoned clockwise from North; those relating to lights are given as seen by an observer from seaward. Positions quoted in permanent notices relate to the horizontal datum for the chart(s). When preliminary or temporary notices affect multiple charts, positions will be provided in relation to only one horizontal datum and that datum will be specified. When the multiple charts do not have a common horizontal datum, mariners will be required to adjust the position(s) for those charts not on the specified datum. The range quoted for a light is its nominal range. Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices. A star (*) adjacent to the number of a notice indicates that the notice is based on original information.

REPORTING OF DANGERS

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 Wollongong, NSW 2500 (Fax 02-4223 6599, e-mail Hydro.NTM@defence.gov.au or, alternatively by filling in and submitting the Hydrographic Notes forms located on the web site – www.hydro.gov.au), immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).

AUTHORISED USE

Copies of Australian notices are available free of charge from the Australian Hydrographic Service (AHS) website (www.hydro.gov.au) and through the eNotices (email) service (www.hydro.gov.au/enotices/enotices.htm).

Individual Notices may be copied for the purpose of inserting Notice substance on official charts and publications. Paper copies may be printed by chart agents and distributed to customers on a cost recovery basis. Participating chart agents are listed on the AHS website as providing a 'Paper Notices to Mariners' service (www.hydro.gov.au/prodserv/distributors/distributors.htm). Copies of the notices may not be sold for profit without prior written agreement.

ı

NUMERICAL INDEX OF NOTICES TO MARINERS

Edition No 5

Notices	Aus Chart, INT Chart, ENC Cell, AHP, BA Pubs
266	Amendment to Australian Notice to Mariners No 2
267	Aus 489, 808, AX 00808S
268	Aus 244, 245
269	Aus 827, 828
270	Aus 830, AXA 0830T
271	Aus 367, 490, 822, 4620, 4621, 4635, INT 620, 621, 635, AX 00367S, 00822S, 04620U
272	Aus 367, 822, 823, 4620, 4621, 4635, INT 620, 621, 635, AX 00367S, 00822S, 00823S, 04620U, 04621U
273	Aus 293, 299
274	Aus 257
275	Aus 614
276	Aus 24, 26, 28, AX 00026T
277	Aus 740
278	Aus 776, AX 00776S
279	Aus 125
280	Aus 127, 347, 4728, INT 728
281	Aus 776, AX 00776S
282	Aus 181, 182
283	Aus 171
284(T)	Aus 207, 208
285(T)	Aus 200, 201, AX 00200T, 00201T
286(T)	Aus 222, 812, 813
287(T)	Aus 242, 243
288(T)	Aus 245, 246, 819
289(T)	Aus 230, 814
290(T)	Aus 250
291(T)	Aus 367, 490, 822, 4060, 4602, 4620, 4621, 4635, INT 60, 602, 620, 621, 635, AX 00367S, 00822S,
000(T)	04620U, 04621U
292(T)	Aus 833
293(T)	Aus 6, 303
294(T)	Aus 376, 377, 837, 839, 841
295(T)	Aus 236
296(T)	Aus 235, 236, 814, 815
297(T)	Aus 235, 236, 237, 814, 815
298(T)	Aus 235, 236, 237, 238, 814, 815
299(T)	Aus 367, 822, 823, 4060, 4602, 4620, 4621, 4635, INT 60, 602, 620, 621, 635, AX 00367S, 00822S,
300(T)	00823S, 04620U, 04621U Aus 265
301(T)	Aus 247, 265
302(T)	Aus 247, 200
303(T)	Aus 248, 367, 490, 820, 822, AX 00367S, 00820S, 00822S
304(T)	Aus 260, 261, 367, 490, 822, AX 00260T, 00260S, 00022S
305(T)	Aus 386, 387, 4622, INT 622
306(P)	Aus 520
307(T)	Aus 519, 520, 644
308(T)	Aus 64, 328, 743, 744
309(T)	Aus 64, 328, 743, 744
310(T)	Aus 327, 328
311(T)	Aus 62, 66
312(T)	Aus 52, 53, 739
313(T)	Aus 329, 331, 332, 745, 746, 748, 749, 4723, 4725, INT 723, 725, AX 04723U
314(T)	Aus 52, 54
315(T)	Aus 52, 54
316(T)	Aus 53, 739, 740
317(T)	Aus 740
318(T)	Aus 127, 347
319(T)	Aus 132
320(T)	Aus 143, 158
321(T)	Aus 357, 4644, INT 644
322(T)	Aus 143
323(T)	Aus 143, 155
324(T)	Aus 154
325(T)	Aus 150, 151, 152
	Aug 100, 101, 102
326(T)	Aus 173, 795
326(T) 327(T) 328(T)	

Notices	Aus Chart, INT Chart, ENC Cell, AHP, BA Pubs
329(T)	Aus 177
330(T)	Aus 177, 792
331(T)	Aus 171
332(T)	Aus 767
333(T)	Aus 171, 172
334(T)	Aus 168

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 5

Aus Chart	Notices	Aus Chart	Notices
Aus 6	293(T)	Aus 329	313(T)
Aus 24	276	Aus 331	313(T)
Aus 26	276	Aus 332	313(T)
Aus 28	276	Aus 347	280, 318(T)
Aus 52	312(T), 314(T), 315(T)	Aus 357	321(T)
Aus 53	312(T), 316(T)	Aus 367	271, 272, 291(T), 299(T), 303(T),
			304(T)
Aus 54	314(T), 315(T)	Aus 376	294(T)
Aus 62	311(T)	Aus 377	294(T)
Aus 64	308(T), 309(T)	Aus 386	305(T)
Aus 66	311(T)	Aus 387	305(T)
Aus 125	279	Aus 489	267
Aus 127	280, 318(T)	Aus 490	271, 291(T), 303(T), 304(T)
Aus 132	319(T)	Aus 519	307(T)
Aus 143	320(T), 322(T), 323(T)	Aus 520	306(P), 307(T)
Aus 150	325(T)	Aus 614	275
Aus 151	325(T)	Aus 644	307(T)
Aus 152	325(T)	Aus 739	312(T), 316(T)
Aus 154	324(T)	Aus 740	277, 316(T), 317(T)
Aus 155	323(T)	Aus 743	308(T), 309(T)
Aus 158	320(T)	Aus 744	308(T), 309(T)
Aus 168	334(T)	Aus 745	313(T)
Aus 171	283, 331(T), 333(T)	Aus 746	313(T)
Aus 172	327(T), 333(T)	Aus 748	313(T)
Aus 173	326(T)	Aus 749	313(T)
Aus 177	328(T), 329(T), 330(T)	Aus 767	332(T)
Aus 181	282	Aus 776	278, 281
Aus 182	282	Aus 792	328(T), 330(T)
Aus 200	285(T)	Aus 795	326(T)
Aus 201	285(T)	Aus 808	267
Aus 207	284(T)	Aus 812	286(T)
Aus 208	284(T)	Aus 813	286(T)
Aus 222	286(T)	Aus 814	289(T), 296(T), 297(T), 298(T)
Aus 230	289(T)	Aus 815	296(T), 297(T), 298(T)
Aus 235	296(T), 297(T), 298(T)	Aus 819	288(T)
Aus 236	295(T), 296(T), 297(T), 298(T)	Aus 820	303(T)
Aus 237	297(T), 298(T)	Aus 822	271, 272, 291(T), 299(T), 303(T),
7100 207	207(1), 200(1)	7100 022	304(T)
Aus 238	298(T)	Aus 823	272, 299(T)
Aus 242	287(T)	Aus 827	269
Aus 243	287(T) 287(T)	Aus 828	269
Aus 244	268	Aus 830	270
Aus 245	268, 288(T)	Aus 833	292(T)
Aus 246	288(T)	Aus 837	294(T)
Aus 247	301(T), 302(T)	Aus 839	294(T)
Aus 248	303(T)	Aus 841	294(T)
Aus 250	290(T)	Aus 4060	291(T), 299(T)
Aus 257	274	Aus 4602	291(T), 299(T)
Aus 260	304(T)	Aus 4620	271, 272, 291(T), 299(T)
Aus 261	304(T) 304(T)	Aus 4621	271, 272, 291(T), 299(T) 271, 272, 291(T), 299(T)
Aus 265	300(T), 301(T)	Aus 4622	305(T)
Aus 203 Aus 293	273	Aus 4635	271, 272, 291(T), 299(T)
Aus 293 Aus 299	273	Aus 4644	
Aus 299 Aus 303	273 293(T)	Aus 4723	321(T) 313(T)
Aus 327 Aus 328	310(T) 308(T) 300(T) 310(T)	Aus 4725	313(T) 280
AUS 320	308(T), 309(T), 310(T)	Aus 4728	200

-	
Aus Chart	Notices
AX 00026T	276
AX 00200T	285(T)
AX 00201T	285(T)
AX 00260S	304(T)
AX 00260T	304(T)
AX 00367S	271, 272, 291(T), 299(T), 303(T),
	304(T)
AX 00776S	278, 281
AX 00808S	267
AX 00820S	303(T)
AX 00822S	271, 272, 291(T), 299(T), 303(T),
	304(T)
AX 00823S	272, 299(T)
AX 04620U	271, 272, 291(T), 299(T)
AX 04621U	272, 291(T), 299(T)
AX 04723U	313(T)
AXA 0830T	270

INT Chart	Notices
INT 60	291(T), 299(T)
INT 602	291(T), 299(T)
INT 620	271, 272, 291(T), 299(T)
INT 621	271, 272, 291(T), 299(T)
INT 622	305(T)
INT 635	271, 272, 291(T), 299(T)
INT 644	321(T)
INT 723	313(T)
INT 725	313(T)
INT 728	280

266 **AUSTRALIA - Product - Amendment to Australian Notice to Mariners No 2**

Australian Hydrographic Service (AA795889)

Page 12

Insert new China chart agent:

Bogerd Marint (Tianjin) Marine Equipment Co Ltd Telephone +86 (22) 2576 2721 С

No 3.6 Mi Xinggang No 1 Road Fax +86 (22) 2576 2722 Binhai New Area, Tanggu Email charts-tj@martincn.com Tianjin 300456 Website www.martin.be

267* AUSTRALIA - NEW SOUTH WALES - Shoalhaven Bight - Fish haven

NSW Department of Primary Industries (AA793047)

A	400	[675/2013]	
Aus	409	10/5/20131	

Insert	fish haven with minimum depth 22 ₄ m, centred on	34° 50′.96 S	150° 47'.73 E
Delete	depth 24 ₁	34° 51'.0 S	150° 47'.0 E
Aus 808 Insert	$[994/2014]$ fish haven with minimum depth 22_4 m, centred on	34° 50′.96 S	150° 47'.73 E

AX 00808S [994/2014]

Insert fish haven with minimum depth 22₄m, centred on 34° 50'.96 S 150° 47'.73 E

AUSTRALIA - QUEENSLAND - Gladstone - Barney Point - Topmarks

Maritime Safety Queensland (AA794736)

topmark

Aus 244 [220/2015]

Delete	topmark	23° 50'.26 S	151° 16'.28 E
	topmark	23° 50'.16 S	151° 16'.13 E
Aus 245 [<i>1</i>	62/2015]	23° 50' 26 S	151° 16' 28 F

151° 16'.13 E

23° 50'.16 S

269* AUSTRALIA - QUEENSLAND - Great Palm Island - Light, navline, light beacon

Maritime Safety Queensland (AA793297), Palm Island Aboriginal Shire Council (AA793298)

Aus 827 [1052/2014]

Insert	light, 2F.Bu a dashed line in a direction 272·9° for a distance of 0·33M, thence a continuous line for 1·73M, with legend 092·9°, emanating from light	18° 44'.14 S 18° 44'.14 S	146° 34'.69 E 146° 34'.69 E
Delete	light beacon	18° 44'.1 S	146° 34'.4 E
Aus 828 [1 Insert	107/2014] light, 2F.Bu a dashed line in a direction 272·9° for a distance of 0·33M, thence a continuous line for 1·73M, with legend 092·9°, emanating from light	18° 44'.14 S 18° 44'.14 S	146° 34'.69 E 146° 34'.69 E
Delete	light beacon	18° 44'.1 S	146° 34'.4 E

AUSTRALIA - QUEENSLAND - Haycock Island - Light buoy

Maritime Safety Queensland Notice 057/2015 (AA795635)

Aus 830 [1107/2014]

Move	light buoy	16° 43'.82 S	145° 42'.91 E
	to	16° 44'.02 S	145° 42'.60 E
AXA 0830	T [1107/2014]		

light buoy Move

16° 43'.82 S 145° 42'.91 E 16° 44'.02 S 145° 42'.60 E

271* AUSTRALIA - QUEENSLAND - High Peak island - Light altered AMSA AUSCOAST 062/2015, ATH 04/2015 (AA796494, AA796299)

Aus 367 [1220/2014] Amend legend to FI.5s 70m 15M	21° 57'.1 S	150° 42'.1 E
Aus 490 [1220/2014] Amend legend to <i>Fl.5s 15M</i>	21° 57'.1 S	150° 42'.1 E
Aus 822 [1112/2014] Amend legend to Fl.5s 70m 15M	21° 57'.1 S	150° 42'.1 E
Aus 4620 (INT 620) [222/2015] Amend legend to <i>Fl. 15M</i>	21° 57'.1 S	150° 42'.1 E
Aus 4621 (INT 621) [222/2015] Amend legend to <i>Fl. 15M</i>	21° 57'.1 S	150° 42'.1 E
Aus 4635 (INT 635) [1220/2014] Amend legend to Fl. 15M	21° 57'.1 S	150° 42'.1 E
AX 00367S [<i>NE 19/12/2014</i>] Amend legend to <i>Fl.5s 70m 15M</i>	21° 57'.1 S	150° 42'.1 E
AX 00822S [1112/2014] Amend legend to <i>Fl.5s 70m 15M</i>	21° 57'.1 S	150° 42'.1 E
AX 04620U [222/2015] Amend legend to <i>Fl. 15M</i>	21° 57'.1 S	150° 42'.1 E
272* AUSTRALIA - QUEENSLAND - Pine Islets - Light altered	_, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	.00 .2 2
AMSA AUSCOAST 056/2015, ATH 3/2015 (AA794792, AA796495)		
Aus 367 [271/2015] Amend legend to FI.10s 10M	21° 39'.4 S	150° 13'.0 E
Aus 822 [271/2015] Amend legend to <i>Fl.10s 67m 10M</i>	21° 39'.4 S	150° 13'.0 E
Aus 823 [1213/2014] Amend legend to FI.10s 67m 10M	21° 39'.4 S	150° 13'.0 E
Aus 4620 (INT 620) [271/2015] Amend legend to <i>Fl. 10M</i>	21° 39'.4 S	150° 13'.0 E
Aus 4621 (INT 621) [271/2015] Amend legend to Fl. 10M	21° 39'.4 S	150° 13'.0 E
Aus 4635 (INT 635) [271/2015] Amend legend to Fl. 10M	21° 39'.4 S	150° 13'.0 E
AX 00367S [271/2015] Amend legend to <i>Fl.10s 10M</i>	21° 39'.4 S	150° 13'.0 E
AX 00822S [271/2015] Amend legend to Fl.10s 67m 10M	21° 39'.4 S	150° 13'.0 E
AX 00823S [1213/2014]		
Amend legend to FI.10s 67m 10M	21° 39'.4 S	150° 13'.0 E
AX 04620U [271/2015] Amend legend to Fl. 10M	21° 39'.4 S	150° 13'.0 E
AX 04621U [<i>222/2015</i>] Amend legend to <i>FI. 10M</i>	21° 39'.4 S	150° 13'.0 E

273* AUSTRALIA - QUEENSLAND - Thursday Island - Light

Maritime Safety Queensland Notice 067/2015 (AA795946, AA796902)

Aug 200 02/2010	Aus 293	[32/2015]
------------------	---------	-----------

Amend light to FI(2)7s 10° 35'.04 S 142° 13'.67 E

Aus 299 [NE 26/9/2014]

light to FI(2)7s 10° 35'.04 S 142° 13'.67 E

274* AUSTRALIA - QUEENSLAND - Townsville - Ross River - Light beacon

Maritime Safety Queensland Notice 53/2015 (AA793749)

Aus 257 [125/2015]

19° 16'.691 S Insert light beacon, Fl.R.2s No18, with port lateral topmark 146° 49'.816 E

AUSTRALIA - CORAL SEA - Central Diamond Islet - Depths

LADS Flight (AA796455, AA796456)

Aus 614 [NE 2/7/2010]

depth, 13_3^{-} m, enclosed by contour 17° 27'.75 S 151° 02'.02 E depth, 135m, enclosed by contour 150° 55'.04 E 17° 31′.52 S 17° 28'.0 S Delete depth, 31m 151° 02'.2 E

AUSTRALIA - NORTHERN TERRITORY - Port Darwin - East Arm - Light buoys

Darwin Port Corporation Notices 34/2015, 35/2015, 38/20015, 40/2015 (AA794538, AA794539, AA794778, AA794779)

12° 28'.960 S

130° 51'.530 E

Aus 24 [2	224/2015]
Insert	starboard lateral pillar light buoy, Iso. G. 2s No15, with topmark

msert	isolated danger pillar light buoy, <i>Fl(2)5s</i> , with topmark port lateral pillar light buoy, <i>Iso.R.2s No8</i> , with topmark with AIS	12° 28'.035 S 12° 28'.078 S	130° 49'.465 E 130° 49'.247 E
Delete	light buoy with AIS light buoy with AIS	12° 28'.79 S 12° 28'.03 S	130° 51'.32 E 130° 49'.47 E
Aus 26 [22 Insert	24/2015] starboard lateral pillar light buoy, <i>Iso.G.2s,</i> with topmark isolated danger pillar light buoy, <i>FI(2)5s,</i> with topmark port lateral pillar light buoy, <i>Iso.R.2s,</i> with topmark with AIS	12° 28'.96 S 12° 28'.04 S 12° 28'.08 S	130° 51'.53 E 130° 49'.47 E 130° 49'.25 E
Delete	light buoy with AIS light buoy with AIS depth, 15 ₁ m	12° 28'.8 S 12° 28'.0 S 12° 28'.1 S	130° 51'.3 E 130° 49'.5 E 130° 49'.2 E
Aus 28 [22 Insert	24/2015] starboard lateral pillar light buoy, <i>Iso.G.2s No15</i> , with topmark	12° 28'.960 S	130° 51'.530 E
Delete	light buoy with AIS	12° 28'.79 S	130° 51'.32 E
AX 000261 Insert	[224/2015] starboard lateral pillar light buoy, <i>Iso.G.2s</i> , with topmark isolated danger pillar light buoy, <i>Fl(2)5s</i> , with topmark port lateral pillar light buoy, <i>Iso.R.2s</i> , with topmark with AIS	12° 28'.96 S 12° 28'.04 S 12° 28'.08 S	130° 51'.53 E 130° 49'.47 E 130° 49'.25 E
Delete	light buoy with AIS light buoy with AIS depth, 15 ₁ m	12° 28'.8 S 12° 28'.0 S 12° 28'.1 S	130° 51'.3 E 130° 49'.5 E 130° 49'.2 E

AUSTRALIA - WESTERN AUSTRALIA - Port Hedland to Port Walcott - Tidal panel

277*

Australian Hydrographic Service (AA795310, AA795311, AA795330) Aus 740 [228/2015] accompanying block 20° 45'.0 S 117° 45'.0 E Insert Amend tidal stream to B 20° 34'.9 S 117° 12'.8 E 278* AUSTRALIA - SOUTH AUSTRALIA - Boston Bay - Light beacon UKHO (AA795818) Aus 776 [NE 16/1/2015] light to Q.WG 34° 39'.8 S Amend 135° 54'.4 E **AX 00776S** [175/2015] Amend light to Q.WG 34° 39'.8 S 135° 54'.4 E 279* AUSTRALIA - SOUTH AUSTRALIA - Cape Jervis - Signal station Australian Hydrographic Service (AA795607) Aus 125 (plan, Cape Jervis) [174/2015] Substitute signal station with legend (traffic), for light 35° 36'.38 S 138° 05'.61 E 280* AUSTRALIA - SOUTH AUSTRALIA - Robe - Racon discontinued Former Notice - 154(P)/2015 is cancelled Australian Maritime Safety Authority AUSCOAST 060/15, ATH 331/2015 (AA796299, AA796374) Aus 127 (plan, Port Caroline to Robe) [1228/2014] Delete magenta circle, with magenta legend Racon (G) 37° 09'.9 S 139° 44′.7 E Aus 347 [229/2015] Delete magenta circle, with magenta legend Racon (G) 37° 09'.9 S 139° 44'.7 E Aus 4728 (INT 728) [229/2015] Delete magenta circle, with magenta legend Racon (G) 37° 09'.9 S 139° 44'.7 E AUSTRALIA - SOUTH AUSTRALIA - Yorke Peninsula - The Pines - Light beacon Department of Planning, Transport and Infrastructure SA Notice 10/2015 (AA795781) Aus 776 [278/2015] port lateral light beacon, Fl.R.2s, with topmark 34° 54'.60 S 137° 09'.73 E Insert AX 00776S [278/2015] port lateral light beacon, Fl.R.2s, with topmark 34° 54'.60 S 137° 09'.73 E Insert AUSTRALIA - VICTORIA - Corner Inlet - Franklin Channel to Port Welshpool - Light buoys 282* Gippsland Ports Notice 97/2014, 53/2015 (AA793874, AA795892) Aus 181 [39/2015] starboard lateral pillar light buoy, FI(3)G.8s PS1, with topmark 146° 24'.80 E Insert 38° 45'.40 S 146° 22'.61 E 146° 25'.30 E starboard lateral pillar light buoy, FI(2)G.6s PS3, with topmark 38° 45'.50 S port lateral pillar light buoy, FI(3)R.8s PS2, with topmark 38° 45'.70 S 146° 22'.80 E port lateral pillar light buoy, FI(2)R.6s PS4, with topmark 38° 46'.00 S Amend light to FI(2)R.6s 38° 42'.2 S 146° 28'.0 E Delete depth 7₃m 38° 45'.7 S 146° 25'.4 F Aus 182 (plan, Lewis Channel) [777/2014] Amend light to FI(2)R.6s 38° 42' 18 S 146° 27'.96 F Aus 182 (plan, Port Welshpool) [777/2014] 146° 27'.96 E 38° 42' 18 S Amend light to FI(2)R.6s 5m 2M

283* AUSTRALIA - TASMANIA - River Derwent - Crayfish Point - Fish haven

MAST Notice M36/2015 (AA793594)

Aus 171 [1175/2014]

Insert fish haven with minimum depth 11m, centred on 42° 57'.50 S 147° 21'.28 E

284(T)/2015 AUSTRALIA - NEW SOUTH WALES - Newcastle - Depth information

Former Notice - 240(T)/2015 is cancelled Newcastle Port Corporation (AA795429)

Available depths as at 27 February 2015:		
Berth	Metres	Remarks
Eastern Basin 1	11.5	Remarks
Eastern Basin 2 North of Ch 450	11.6	
Eastern Basin 2 South of Ch 450	11.3	
Western Basin 3	11.6	
Western Basin 4	11.6	
Channel Berth	9.7	
Dyke 1	12.8	
Dyke 2	12.8	
* Dyke 4	16.5	
Dyke 5	16.5	
Dyke 6	5.3	
Mayfield 4 Ch 27 to 266	12.8	
BHP Wharf 6 to Ch 1050	7.3	
Kooragang 2	11.6	
Kooragang 2 North Dolphin Ch 182 to 243	11.6	
Kooragang 2 South Dolphin Ch -92 to 00	11.4	
Kooragang 3 Ch -40 to 00	13.1	
Kooragang 3 Ch 00 to 220	13.3	
Kooragang 4	16.2	
Kooragang 5	16.5	
* Kooragang 6	16.5	
Kooragang 7	16.5	
Kooragang 8	16.4	
Kooragang 9	16.4	
Kooragang 10	16.4	
Throsby 1 Ch 850 to 1030	8.9	
Carrington Wharf	0.0	To be sounded as and when required
Foreshore Park Berth	5.9	ro bo ocanaca ao ana mion roquita
Elgo Wharf	0.0	To be sounded as and when required
Channels		To be sounded as and when required
	17.5	
* Entrance Approach * Entrance Channel (18 0m)	17.5	
Littance Chamler (10.011)	17.7	
Entrance Channel (17.4m)	17.4	
Entrance Channel (16.8m)	16.8	
Entrance Channel (16.2m)	16.2	
Entrance Channel to Horseshoe	15.2	
* Horseshoe	15.2	
Steelworks Channel to Swinging Basin	15.2	
Swinging Basin	15.2	
Hunter River South Arm (Kooragang 6 to buoy 16)	15.2	
Hunter River South Arm (buoy 16 to buoy 20)	15.2	
Basin Cutting	12.6	
Basin Area to Eastern & Western Basin Berths	12.3	
Basin Area to Throsby 1	9.2	
Stockton Crossing	3.6	
* Indicates new or revised entry.	3.0	
mulcales new or revised entry.		

Chart temporarily affected - Aus 207 - Aus 208

285(T)/2015 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Western Channel - Scientific instruments recovered

Former Notice - 1130(T)/2014 is cancelled

Port Authority of New South Wales Notice 21/2014 (AA776227, AA776644)

Cancel this notice on receipt.

Chart formerly affected - Aus 200 - Aus 201 - AX 00200T - AX 00201T

286(T)/2015 AUSTRALIA - NEW SOUTH WALES - Yamba - Scientific instruments recovered

Former Notice - 181(T)/2015 is cancelled

Port of Clarence River (Yamba) Notice 003(T)/2015 (AA789829)

Cancel this notice on receipt.

Chart formerly affected - Aus 222 - Aus 812 - Aus 813

AUSTRALIA - QUEENSLAND - Bundaberg - Depth information 287(T)/2015

Former Notice - 634(T)/2014 is cancelled

Maritime Safety Queensland Notice 063(T)/2015 (AA795440)

Available depths as at 6 March 2015:

лv	anabic depins as at 6 march 2015.	
	·	Metres
	Sea Reach	8.0
	Middle Reach	8.5
*	Inner Reach	7.8
	Swing Basin	6.8
	Oil Berth	8.4
	BST Berth	8.9
*	Deep draught departure channel	8.3
*	Indicates revised entry	

Indicates revised entry.

Chart temporarily affected - Aus 242 - Aus 243

AUSTRALIA - QUEENSLAND - Gladstone - South Channel - Drilling operations completed 288(T)/2015

Former Notice - 184(T)/2015 is cancelled

Maritime Safety Queensland Notice 031(T)/2015 (AA789858)

Cancel this notice on receipt.

Chart formerly affected - Aus 245 - Aus 246 - Aus 819

AUSTRALIA - QUEENSLAND - Gold Coast - Broadwater - Dredging operations

Former Notice - 132(T)/2015 is cancelled

Maritime Safety Queensland Notice 027(T)/2015, 074(T)/2015 (AA788671, AA796714)

Dredging operations are being conducted between positions 27° 57'.50 S 153° 24'.83 E and 27° 56'.44 S 153° 24'.65 E and in Ray Newlyn Channel (27° 57'.35 S 153° 24'.94 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 230 - Aus 814

AUSTRALIA - QUEENSLAND - Hay Point - Harbour works completed 290(T)/2015

Former Notice - 134(T)/2015 is cancelled

Maritime Safety Queensland Notice 20(T)/2015 (AA788152)

Cancel this notice on receipt.

Chart formerly affected - Aus 250

AUSTRALIA - QUEENSLAND - High Peak island - Light relit 291(T)/2015

Former Notice - 243(T)/2015 is cancelled

AMSA AUSCOAST 062/2015, ATH 4/2015 (AA796494, AA796299)

Cancel this notice on receipt.

Chart formerly affected - Aus 367 - Aus 490 - Aus 822 - Aus 4060 (INT 60) - Aus 4602 (INT 602) - Aus 4620 (INT 620) -Aus 4621 (INT 621) - Aus 4635 (INT 635) - AX 00367S - AX 00822S - AX 04620U - AX 04621U

292(T)/2015 AUSTRALIA - QUEENSLAND - Joan Island - Light unreliable

AMSA AUSCOAST 71/2015 (AA797177)

The light, FI(4)WR.12s 10M (13° 56'.80 S 144° 20'.42 E), is unreliable

Chart temporarily affected - Aus 833

293(T)/2015 AUSTRALIA - QUEENSLAND - Karumba - Light unlit

Maritime Safety Queensland Notice 065(T)/2015 (AA795642)

The front lead light, (F Day (occas)) (17° 26'.81 S 140° 45'.52 E), is unlit.

Chart temporarily affected - Aus 6 - Aus 303

294(T)/2015 AUSTRALIA - QUEENSLAND - Kirkcaldie Reef to Derder Reef - Scientific instruments recovered

Former Notice - 1020(T)/2014 is cancelled

Australian Maritime Safety Authority (AA778456, AA778457)

Cancel this notice on receipt.

Chart formerly affected - Aus 376 - Aus 377 - Aus 837 - Aus 839 - Aus 841

295(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Scientific instrument recovered

Former Notice - 919(T)/2014 is cancelled

Maritime Safety Queensland Notice 554(T)/2014 (AA766827)

Cancel this notice on receipt.

Chart formerly affected - Aus 236

296(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Spitfire Channel to North West Channel - Scientific instruments recovered

Former Notice - 1184(T)/2014 is cancelled

Maritime Safety Queensland Notice 686(T)/2014 (AA779690)

Cancel this notice on receipt.

Chart formerly affected - Aus 235 - Aus 236 - Aus 814 - Aus 815

297(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - North West Channel to Fisherman Island - Dredging operations completed

Former Notice - 1235(T)/2014 is cancelled

Maritime Safety Queensland Notice 703(T)/2014 (AA781041)

Cancel this notice on receipt.

Chart formerly affected - Aus 235 - Aus 236 - Aus 237 - Aus 814 - Aus 815

298(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Brisbane River - Depth information

Former Notice - 246(T)/2015 is cancelled

Brisbane Port Corporation (AA796452, AA797348)

Available depths and under keel clearances (UKC) at	11 March 2015	:
Berth	Metres	Remarks
* Fisherman Islands No12	13.6	
Figherman Islande No.11	14.0	

*	Fisherman Islands No12	13.6
	Fisherman Islands No11	14.0
	Fisherman Islands No10	14.0
*	Fisherman Islands No9	14.0
	Fisherman Islands No8	14.0
	Fisherman Islands No7	14.0
	Fisherman Islands No6	14.0
	Fisherman Islands No5	13.6
*	Fisherman Islands No4	13.7
	Fisherman Islands No3	13.5
	Fisherman Islands No2	13.9
	Fisherman Islands No1	14.0
	Fisherman Islands Grain and Woodchip	13.0
	Caltex Fisherman Islands	14.3
*	Fisherman Islands Coal	13.2
*	Fisherman Islands General Purpose	11.5
	Luggage Point Pump Out Facility	13.0
*	BP Luggage Point	14.3
*	Caltex Products	10.2
*	Cement Australia Co Wharf	9.7
*	BP Products	10.4
	Viva Energy	10.9
	Graincorp Liquid Terminal	10.3
*	Incitec North	9.7
*	Incitec South	9.8
	Pinkenba 1	10.4
	Pinkenba 2	10.4
	Riverside Marina	-
	Sugar Terminal	9.9
	Cairncross Fitting Out Wharf	7.1
	Cairncross Breasting Wharf	4.4
	Brisbane Naval Wharf	4.3
*	Maritime No1	8.6
	Hamilton No4	10.3
	Hamilton No1	8.6
	Brisbane Cruise Ship Terminal	8.6

	Metres	UKC/Remarks
Moreton Bay:		
North West Channel	15.0	2.3 (280m width)
North West Bypass Channel	9.2	1.6
Spitfire Channel	15.0	1.5 (600m width)
East Knoll Bypass Channel	6.0	1.4
East Channel	15.0	1.5 (300m width from western side)
Main Channel (M8 - M9)	10.0	1.8
Entrance Channel (E5 - EBCN)	14.7	1.5
Brisbane River:		
Outer Bar Cutting	14.0	1.46

Brisi	bane	River:
-------	------	--------

	Outer bar Cutting	14.0	1.40
*	Inner Bar Cutting	14.0	1.46
*	Fisherman Islands Swing Basin	14.0	1.3
	Fisherman Islands Swing Basin (11.5)	11.5	0.6
	River	9.1	0.6 / 0.9 (draft/tide)
	Cement Australia Swing Basin	9.1	0.6 / 0.9 (draft/tide)
	Pinkenba Swing Basin	9.1	0.6 / 0.9 (draft/tide)
*	Hamilton Swing Basin	9.0	0.6 / 0.9 (draft/tide)
*	Indicates new or revised entry.		

Chart temporarily affected - Aus 235 - Aus 236 - Aus 237 - Aus 238 - Aus 814 - Aus 815

299(T)/2015 AUSTRALIA - QUEENSLAND - Pine Islets - Light restored

Former Notice - 248(T)/2015 is cancelled

AMSA AUSCOAST 056/2015, ATH 3/2015 (AA796495, AA794792)

Cancel this notice on receipt.

Chart formerly affected - Aus 367 - Aus 822 - Aus 823 - Aus 4060 (INT 60) - Aus 4602 (INT 602) - Aus 4620 (INT 620) - Aus 4621 (INT 621) - Aus 4635 (INT 635) - AX 00367S - AX 00822S - AX 00823S - AX 04620U - AX 04621U

300(T)/2015 AUSTRALIA - QUEENSLAND - Port Alma - Depth information

Former Notice - 210(T)/2013 is cancelled

Maritime Safety Queensland Notice 062(T)/2015 (AA795441)

Available depths as at 27 February 2015:

	Berth	Metre
	Balaclava Leads	7.5
	Kazatch Leads	7.0
	Eupatoria Leads	7.7
*	Shell Point Leads	6.5
	Swing Basin	5.6
*	Berth No 1	8.4
*	Berth No 2	8.3
*	Berth No 3	8.2
*	Indicates revised entry.	

Chart temporarily affected - Aus 265

301(T)/2015 AUSTRALIA - QUEENSLAND - Port Alma - Sea Reach - Buoy

Former Notice - 54(T)/2015 is cancelled

Maritime Safety Queensland Notice 066(T)/2015 (AA795637)

Port lateral light buoy, Fl.R.2·5s no12, (23° 32'.50 S 150° 55'.49 E) is off station. A special buoy exists in situ.

Chart temporarily affected - Aus 247 - Aus 265

302(T)/2015 AUSTRALIA - QUEENSLAND - Rosslyn Bay - Light beacons

Maritime Safety Queensland Notice 060(T)/2015 (AA794721)

Starboard lateral light beacons Fl.G.4s (23° 09'.55 S 150° 47'.26 E) and Fl.G.6s (23° 09'.54 S 150° 47'.11 E) have been destroyed.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 247

303(T)/2015 AUSTRALIA - QUEENSLAND - Shoalwater Bay - Live firing

Date - Until 3 April 2015

Maritime Safety Queensland Notice 072(T)/2015 (AA796713)

Live firing will be conducted in the Shoalwater Bay training area during the period 21 March to 2 April 2015.

A marine danger area extends to all internal waters bounded by the following positions:

22° 35'.87 S 150° 28'.80 E 22° 31'.72 S 150° 28'.41 E 22° 38'.07 S 150° 34'.01 E 22° 38'.18 S 150° 43'.15 E 22° 40'.00 S 150° 38'.80 E 22° 35'.87 S 150° 28'.80 E.

All waters, creeks, beaches and other areas within the declared marine danger area are not available for access.

Mariners are advised to keep clear of this area throughout the above times.

Chart temporarily affected - Aus 248 - Aus 367 - Aus 490 - Aus 820 - Aus 822 - AX 00367S - AX 00820S - AX 00822S

304(T)/2015 AUSTRALIA - QUEENSLAND - Shoalwater Bay - Live firing

Date - Until 18 March 2015

Maritime Safety Queensland Notice 075(T)/2015 (AA796893)

Live firing will be conducted in the Shoalwater Bay training area during the period 12 March to 17 March 2015.

A marine danger area extends to all internal waters bounded by the following positions:

22° 20'.94 S 150° 29'.15 E 22° 18'.70 S 150° 27'.39 E 22° 13'.28 S 150° 28'.22 E 22° 14'.73 S 150° 31'.78 E 22° 15'.28 S 150° 38'.10 E 22° 18'.98 S 150° 30'.98 E 22° 20'.94 S 150° 29'.15 E.

All waters, creeks, beaches and other areas within the declared marine danger area are not available for access.

Mariners are advised to keep clear of this area throughout the above times.

Chart temporarily affected - Aus 260 - Aus 261 - Aus 367 - Aus 490 - Aus 822 - AX 00260T - AX 00260S - AX 00367S -AX 00822S

305(T)/2015 PAPUA NEW GUINEA - Kitumala Point - Light unlit

National Maritime Safety Authority PNG Notice 06/2015 (AA796451)

The light, FI(2)8s 26m 10M (6° 19'.16 S 147° 48'.35 E), is unlit.

Chart temporarily affected - Aus 386 - Aus 387 - Aus 4622 (INT 622)

306(P)/2015 PAPUA NEW GUINEA - Tancred Reef - Shoaling northeastwards

AMSA Navarea X Warning 22/2015 (AA797178), HMAS Benalla (AA797217)

Shoaling, with least depth 5m, exists in position 08° 53'.42 S 149° 02'.61 E.

Mariners are advised to navigate with caution in the area.

Chart which will be affected - Aus 520

PAPUA NEW GUINEA - Tufi Harbour - Light unlit 307(T)/2015

National Maritime Safety Authority PNG Notice 07/2015 (AA796595)

The light, Fl.5s 122m 10M (9° 04'.12 S 149° 17'.98 E), is unlit.

Chart temporarily affected - Aus 519 - Aus 520 - Aus 644

AUSTRALIA - WESTERN AUSTRALIA - Ashburton Road - Diving operations 308(T)/2015

Date - Until 21 April 2015

Department for Transport WA (AA795897)

Diving operations are in progress in the following positions:

21° 38'.70S 114° 54'.30 E 21° 38'.18S 114° 55'.42 E 21° 38'.69S 114° 56'.82 E 21° 38'.81S 114° 58'.80 E 21° 31'.34S 114° 58'.17 E 21° 29'.69S 114° 58'.84 E

21° 26'.73S 115° 02'.44 E

21° 26'.41S 115° 03'.25 E

21° 28'.18S 115° 01'.46 E.

MV Samson Explorer is on site and will display appropriate lights and shapes and will monitor VHF channels 14 and 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 64 - Aus 328 - Aus 743 - Aus 744

309(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Ashburton Road - Pipeline operations completed

Former Notice - 929(T)/2014 is cancelled Chevron Australia Pty Ltd (AA767103)

Cancel this notice on receipt.

Chart formerly affected - Aus 64 - Aus 328 - Aus 743 - Aus 744

310(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Pipeline works completed

Former Notice - 1145(T)/2014 is cancelled

Apache Energy Ltd (AA796449)

Cancel this notice on receipt.

Chart formerly affected - Aus 327 - Aus 328

311(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Town Point - Mooring buoys

Port of Barrow Island Notice 04/2015 (AA796589)

Mooring buoys exist in the following positions:

20° 48' 43 S 115° 30'.57 E

20° 48'·55 S 115° 30'.53 E

20° 48'·66 S 115° 30'.95 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 62 - Aus 66

312(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Little Turtle Island to Weerdee Island - Scientific instruments recovered

Former Notice - 1090(T)/2014 is cancelled

Pilbara Ports Authority Notice 71(T)/2014 (AA772082, AA772157)

Cancel this notice on receipt.

Chart formerly affected - Aus 52 - Aus 53 - Aus 739

313(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Point Cloates to Bluff Point - Seismic survey westwards complete

Former Notice - 211(T)/2015 is cancelled

Scope Resources (AA796748), AMSA (AA796585)

Cancel this notice on receipt.

Chart formerly affected - Aus 329 - Aus 331 - Aus 332 - Aus 745 - Aus 746 - Aus 748 - Aus 749 - Aus 4723 (INT 723) - Aus 4725 (INT 725) - AX 04723U

314(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Port Hedland - Harbour works completed

Former Notice - 1095(T)/2014 is cancelled

Pilbara Ports Authority Notice 75(T)/2014 (AA774205)

Cancel this notice on receipt.

Chart formerly affected - Aus 52 - Aus 54

315(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Port Hedland - Stingray Creek - Dredging operations completed

Former Notice - 1094(T)/2014 is cancelled

Pilbara Ports Authority Notice 74(T)/2014 (AA774198)

Cancel this notice on receipt.

Chart formerly affected - Aus 52 - Aus 54

316(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Port Hedland - Light beacon restored

Former Notice - 1096(T)/2014 is cancelled

Pilbara Ports Authority Notice 77(T)/2014 (AA774842)

Cancel this notice on receipt.

Chart formerly affected - Aus 53 - Aus 739 - Aus 740

317(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - West Moore Island - Drilling operations completed

Former Notice - 890(T)/2014 is cancelled

Department of Transport WA (AA797188)

Cancel this notice on receipt.

Chart formerly affected - Aus 740

318(T)/2015 AUSTRALIA - SOUTH AUSTRALIA - Cape Jaffa - Margaret Brock Reef - Light unlit

Former Notice - 1098(T)/2014 is cancelled

Department of Planning, Transport and Infrastructure SA Notice 04/2015 (AA795767)

The light, Fl.5s 17m 10M (36° 57'.08 S 139° 35'.70 E), is unlit.

Chart temporarily affected - Aus 127 - Aus 347

319(T)/2015 AUSTRALIA - SOUTH AUSTRALIA - Port Augusta - Curlew Island - Harbour works

Date - Until 1 June 2015

Department of Planning, Transport and Infrastructure SA Notice 06/2015 (AA795772)

Harbour works are being conducted on the power transmission towers in the following positions:

32° 32'. 43 S 137° 46'. 60 E

32° 32'. 46 S 137° 46'. 58 E

32° 32'. 48 S 137° 46'. 95 E

32° 32′. 48 S 137° 46′. 57 E

32° 32'. 51 S 137° 46'. 97 E.

Work platforms around each tower will be marked by lights, Q.Y.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 132

320(T)/2015 AUSTRALIA - VICTORIA - Barwon Head - Light buoy withdrawn eastwards

Date - Until 23 March 2015

Victorian Notices 055(T)/2015 (AA796301)

Special purpose light buoy, FI.Y.5s (38° 17'.95 S 144° 32'.64 E) has been temporarily withdrawn.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143 - Aus 158

321(T)/2015 AUSTRALIA - VICTORIA - Ninety Mile Beach - Survey operations

Date - Until 3 April 2015

Hibiscus Petroleum (AA796844)

MV Go Capella is conducting a geophysical survey in an area bounded by the following positions:

38° 10'.78 S 147° 32'.80 E

38° 10'.24 S 147° 32'.79 E

38° 10'.24 S 147° 33'.47 E

38° 10'.78 S 147° 33'.48 E.

Chart temporarily affected - Aus 357 - Aus 4644 (INT 644)

322(T)/2015 AUSTRALIA - VICTORIA - Port Phillip - Patterson River - Shoaling removed

Former Notice - 213(T)/2015 is cancelled Victorian Notice No 47(T)/2015 (AA793431)

Cancel this notice on receipt.

Chart formerly affected - Aus 143

323(T)/2015 AUSTRALIA - VICTORIA - Port Phillip - St Kilda - Harbour works

Date - Until 30 March 2015

Victorian Notice 052(T)/2015 (AA795562)

Works associated with the demolition of the eastern marina (37° 51'.74 S 144° 57'.92 E) are in progress.

Works will be marked by lights, Q.Y, in positions 37° 51'.66 S 144° 57'.94 E and 37° 51'.76 S 144° 57'.99 E.

Floating plant will be moored within the area.

All hazards to navigation will display appropriate lights and shapes.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 143 - Aus 155

324(T)/2015 AUSTRALIA - VICTORIA - Port Phillip - Port Melbourne - Station Pier - Diving operations completed

Former Notice - 1250(T)/2014 is cancelled

Port of Melbourne Corporation Notice 219(T)/2014 (AA782582)

Cancel this notice on receipt.

Chart formerly affected - Aus 154

325(T)/2015 AUSTRALIA - VICTORIA - Western Port - North Arm - Drilling operations completed

Former Notice - 667(T)/2014 is cancelled

Victorian Notice 114(T)/2014 (AA752019, AA752221)

Cancel this notice on receipt.

Chart formerly affected - Aus 150 - Aus 151 - Aus 152

326(T)/2015 AUSTRALIA - TASMANIA - D'Entrecasteaux Channel - Huon Point - Marine farm

Former Notice - 1153(T)/2014 is cancelled

Marine and Safety Tasmania Notice 111/2014 (AA775166)

Cancel this notice on receipt.

Chart formerly affected - Aus 173 - Aus 795

327(T)/2015 AUSTRALIA - TASMANIA - Hobart - Sullivans Cove - Harbour works

Date - Until 1 August 2015

MAST Notice 42/2015 (AA794673)

Harbour works are being conducted at Princes Wharf No 1 berth (42° 53'.14 S 147° 20'.01 E).

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 172

328(T)/2015 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instrument recovered

Former Notice - 553(T)/2014 is cancelled

Institute for Marine and Antarctic Studies (AA797461)

Cancel this notice on receipt.

Chart formerly affected - Aus 177 - Aus 792

329(T)/2015 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instruments

Institute for Marine and Antarctic Studies (AA797461)

Subsurface scientific instruments marked by subsurface buoys 3m above the seabed, exist in the following positions: 42° 22'.59 S 145° 31'.90 E

42° 23'.78 S 145° 28'.02 E.

Chart temporarily affected - Aus 177

330(T)/2015 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instruments recovered

Former Notice - 1189(T)/2013 is cancelled

Institute for Marine and Antarctic Studies (AA797461)

Cancel this notice on receipt.

Chart formerly affected - Aus 177 - Aus 792

331(T)/2015 AUSTRALIA - TASMANIA - Norfolk Bay - Sommers Beach - Beacon destroyed

Marine and Safety Tasmania Notice M45/2015 (AA797179)

The isolated danger beacon, (42° 58'.65 S 147° 49'.40 E), has been destroyed.

Chart temporarily affected - Aus 171

332(T)/2015 AUSTRALIA - TASMANIA - Paddys Island - Scientific instruments recovered eastwards

Former Notice - 216(T)/2015 is cancelled

MAST Notice 28/2015 (AA791023)

Cancel this notice on receipt.

Chart formerly affected - Aus 767

333(T)/2015 AUSTRALIA - TASMANIA - Port of Hobart - River Derwent - Harbour works

Date - Until 21 May 2015

MAST Notice 43/2015 (AA794672)

Harbour works associated with Tasman Bridge will be conducted between 2 February 2015 and 21 May 2015.

Individual bridge spans will be closed to all vessels as follows;

Span	Start	Finish
MV1	02/02/2015	17/02/2015
MV2	17/02/2015	25/02/2015
MV3	25/02/2015	16/03/2015
MV4	16/03/2015	30/03/2015
MV5	30/03/2015	16/04/2015
MV6	16/04/2015	28/04/2015
MV7	28/04/2015	07/05/2015
MV8	08/05/2015	21/05/2015

Two lines of special spherical buoys will be strung across the span subject to maintenance.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 171 - Aus 172

334(T)/2015 AUSTRALIA - TASMANIA - River Tamar - Kings Wharf - Dredging operations Date - Until 31 March 2015

MAST Notice 44/2015 (AA796595)

The dredge *Milimili*, is conducting dredging operations at Kings Wharf, (41° 25'.72 S 147° 07'.43 E).

A discharge pipeline is marked by lights and special buoys.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 168

HYDROGRAPHIC REPORTS

NIL

NAVIGATION WARNINGS

The following radio messages have been received during the period to 13 March 2015. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNING

053	Cancelled.
054	Cancelled.
055	Cancelled.
056	Cancelled.
057	Cancelled.
058	Cancelled.
059	Drill rig <i>West Telesto</i> in position 39° 50'.69 S 145° 49'.15 E.
060	Robe racon ALRS Vol 2 K2122.8 in position 37° 09'.86 S 139° 44'.67 E has been permanently discontinued.
061	Cancelled.
062	Cancelled.
063	Pine Islet light K3020 re-established in position 21° 39'.42 S 150° 13'.04 E at range of 10NM.
064	High Peak Island light K3018 re-established in position 21° 57'.14 S 150° 42'.12 E at reduced range of 15NM.
065	Cancelled.
066	Howick Island light K3220 in position 14° 29'.52 S 144° 58'.66 E has reduced power.
067	Special purpose vessel Viking Vision is conducting seismic survey with 8100m towed array in an area bounded by 19°
	02'.20 S 115° 03'.30 E and 20° 26'.90 S 117° 16'.70 E, 7NM clearance requested.
068	Cancelled.
069	Cancelled.
070	Cancelled.
071	Joan Reef light in position 13° 56'.80 S 144° 20'.42 E sectors are unreliable.

NAVAREA X WARNINGS

020	Cancelled.
021	Warning in force.
022	Shoal reported in position 08° 53'.42 S 149° 02'.61 E.

Navigational warnings in force as at 130001UTC MAR 15.

Auscoast

2015 030 035 038 042 043 047 059 060 063 064 066 067 071

Navarea X

2015 017 019 021 022

Canadlad

050

Summary of mobile drilling rigs as at 130001UTC MAR 15.

Name	Position
Armada Claire	20° 03'.50 S 115° 11'.50 E
Atwood Eagle	21° 26'.00 S 114° 02'.00 E
Atwood Falcon	29° 51'.20 S 114° 30'.30 E
Atwood Osprey	19° 56'.70 S 115° 19'.50 E
Deepwater Millennium	16° 37'.00 S 115° 19'.50 E
Ensco 5006	13° 52'.80 S 123° 19'.10 E
Jack Bates	13° 54'.20 S 123° 10'.00 E
Nan Hai 6	09° 47'.60 S 130° 25'.40 E
Noble Clyde Boudreaux	13° 49'.00 S 123° 19'.40 E

Ocean America West Telesto 20° 25'.90 S 114° 19'.10 E 39° 50'.70 S 145° 49'.20 E

NAVAREA XIV WARNINGS

019 Cancelled.

020 Metarea xiv – por oceanic marine weather bulletins for areas subtropic, forties, pacific, islands transmitted via egc safetynet for metarea xiv - pacific ocean region are unavailable until further notice.

Navarea xiv radio telephone broadcasts by taupo maritime radio/zlm of areas subtropic, forties, pacific, islands are transmitted at the following times and frequencies: 6224 and 12356 khz at 0903 and 2103 utc and 8297 and 16531 khz at 1003 and 2203 utc.

021 Cancelled.

022 Cancelled.

023 Hazardous operations, falling space debris daily from 1100 to 1500 utc between 09 and 11 March 2015 in area bounded by: 17° 00′ S 133° 00′ W, 14° 30′ S 115° 00′ W, 08° 30′ S 093° 00′ W, 10° 30′ S 093° 00′ W, 16° 30′ S 115° 00′ W, 19° 00′ S 133° 00′ W.

Navarea XIV warnings in force as at 130001UTC MAR 15.

2014 096

2015 013 018 019 020 023

To accompany Australian Notice to Mariners 277/2015

(225-7 x 54-2mm)

