

29 January 2016 Edition 2

Australian Notices to Mariners are the authority for correcting Australian Charts and Publications

# AUSTRALIAN NOTICES TO MARINERS

## Notices 112 - 173



Published fortnightly by the Australian Hydrographic Service

Commodore B.K. BRACE RAN Hydrographer of Australia

#### SECTIONS.

- I. Australian Notices to Mariners, including blocks and notes.
- II. Hydrographic Reports.
- III. Navigational Warnings.

#### SUPPLEMENTS.

- I. Tracings
- II. Cumulative List of Australian Notices to Mariners.
- III. Cumulative List of Temporary and Preliminary Australian Notices to Mariners.
- IV. Temporary and Preliminary Notices in force.
- V. Amendments to Admiralty List of Lights and Fog Signals (Vol K), Radio Signals (NP 281(2), 282, 283(2), 285, 286(4)) and Sailing Directions (NP 9, 13, 14, 15, 33, 34, 35, 36, 39, 44, 51, 60, 61, 62, 100, 136).

#### © Commonwealth of Australia 2016

This work is copyright. Apart from any use permitted under the Copyright Act 1968, no part may be reproduced by any process, adapted, communicated or commercially exploited without prior written permission from The Commonwealth represented by the Australian Hydrographic Service.

#### **IMPORTANT NOTICE**

This edition of Notices to Mariners includes all significant information affecting AHS products which the AHS has become aware of since the last edition. All reasonable efforts have been made to ensure the accuracy and completeness of the information, including third party information, on which these updates are based. The AHS regards third parties from which it receives information as reliable, however the AHS cannot verify all such information and errors may therefore exist. The AHS does not accept liability for errors in third party information.

#### **GENERAL INSTRUCTIONS**

The substance of these notices should be inserted on the charts affected.

Bearings are referred to the true compass and are reckoned clockwise from North; those relating to lights are given as seen by an observer from seaward.

Positions quoted in notices relate to WGS84 which is the horizontal datum for all charts produced by the Australian Hydrographic Service.

The range quoted for a light is its nominal range.

Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices.

A star (\*) adjacent to the number of a notice indicates that the notice is based on original information.

#### **REPORTING OF DANGERS**

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 Wollongong, NSW 2500 (Fax 02-4223 6599, e-mail datacentre@hydro.gov.au or, alternatively by filling in and submitting the Hydrographic Notes forms located on the web site – www.hydro.gov.au), immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).

#### **AUTHORISED USE**

Copies of Australian notices are available free of charge from the Australian Hydrographic Service (AHS) website (www.hydro.gov.au) and through the eNotices (email) service (www.hydro.gov.au/enotices/enotices.htm).

Individual Notices may be copied for the purpose of inserting Notice substance on official charts and publications. Paper copies may be printed by chart agents and distributed to customers on a cost recovery basis. Participating chart agents are listed on the AHS website as providing a 'Paper Notices to Mariners' service (www.hydro.gov.au/prodserv/distributors/distributors.htm). Copies of the notices may not be sold for profit without prior written agreement.

# **NUMERICAL INDEX OF NOTICES TO MARINERS**

## **Edition No 2**

Notices	Aus Chart, INT Chart, ENC Cell, AHP, BA Pubs
112	Products - New Charts, New Editions, Withdrawn Charts
113	Cessation of dredged depth updates
114	Aus 195
115	Aus 193
116	Aus 254, 825
117	Aus 835, 4603, 4620, 4720, INT 603, 620, 720
118	Aus 254
119	Aus 251, 252, 824
120	Aus 270, 830
121	Aus 245, 246, 819
122	Aus 835
123	Aus 252, 254, 824
124	Aus 257
125	Aus 648
126	Aus 621, 622
127	Aus 62, 65, 67
128	Aus 111
129	Aus 57, 58
130	Aus 32
131	Aus 143, 158
132	Aus 172
133(T)	Aus 813
134(T)	Aus 806
135(T)	Aus 268
136(T)	Aus 249, 251, AX 00249S
137(T)	Aus 245, 272
138(T)	Aus 249, 823, AX 00249S, 00823S
139(T)	Aus 252, 254
140(T)	Aus 253, 268
141(T)	Aus 252, 253
142(T)	Aus 254
143(T)	Aus 621, 622
144(P)	Aus 622
145(T)	Aus 621, 622
146(T)	Aus 64, 328, 743, 744, 4723, 4725, INT 723, 725
147(T)	Aus 64, 328, 743, 744, 4723, 4725, INT 723, 725, AX 04723U
148(T)	Aus 61, 62, 65, 66, 67, 327, 328, 329, 742, 743, 4723, 4725, INT 723, 725
149(T)	Aus 319, 320, 4721, 4722, INT 721, 722
150(T)	Aus 319, 320, 322, 4721, 4722, INT 721, 722, AX 00319S, 00319U, 00320S, 00322U, 04721U, 04722U
151(T)	Aus 111, 117, 334, 754, AX 00117T, 00334S, 00754S, 06001S, AXA 0754S
152(T)	Aus 114, 117, AX 00117T
153(T)	Aus 328, 742, 4723, INT 723, AX 04723U
154(T)	Aus 754
155(T)	Aus 754, AX 00754S, AXA 0754S
156(T)	Aus 84
157(T)	Aus 328
158(T)	Aus 327
159(T)	Aus 328, 4723, INT 723
160(T)	Aus 328, 4723, INT 723, AX 04723U
161(T)	Aus 328
162(T)	Aus 43, 322, 4722, INT 722, AX 00322U, 04722U
163(T)	Aus 143
164(T)	Aus 154
165(T)	Aus 487, 4644, INT 644
166(T)	Aus 487, 798, 800
167(T)	Aus 173, 795
168(T)	Aus 173, 795
169(T)	Aus 177
170(T)	Aus 170, 766, 797
171(T)	Aus 171, 173
172(T)	Aus 172
173(T)	Aus 168

# **NUMERICAL INDEX OF CHARTS AFFECTED**

## **Edition No 2**

Aus Chart	Notices		
Aus 32	130		
Aus 43	162(T)		
Aus 57	129		
Aus 58	129		
Aus 61	148(T)		
Aus 62	127, 148(T)		
Aus 64	146(T), 147(T)		
Aus 65	127, 148(T)		
Aus 66	148(T)		
Aus 67	127, 148(T)		
Aus 84	156(T)		
Aus 111	128, 151(T)		
Aus 114 Aus 117	152(T) 151(T), 152(T)		
Aus 117 Aus 143	131, 163(T)		
Aus 154	164(T)		
Aus 158	131		
7.00 100			
Aus 168	173(T)		
Aus 170	170(T)		
Aus 171	171(T)		
Aus 172	132, 172(T)		
Aus 173	167(T), 168(T), 171(T)		
Aus 177	169(T)		
Aus 193	115		
Aus 195	114		
Aus 245	121, 137(T)		
Aus 246 Aus 249	121 136(T) 139(T)		
Aus 249 Aus 251	136(T), 138(T)   119, 136(T)		
Aus 252	119, 123, 139(T), 141(T)		
Aus 253	140(T), 141(T)		
Aus 254	116, 118, 123, 139(T), 142(T)		
Aus 257	124		
Aus 268	135(T), 140(T)		
Aus 270	120		
Aus 272	137(T)		
Aus 319	149(T), 150(T)		
Aus 320	149(T), 150(T)		
Aus 322	150(T), 162(T)		
Aus 327	148(T), 158(T)		
Aus 328	146(T), 147(T), 148(T), 153(T), 157(T),		
Aus 329	159(T), 160(T), 161(T) 148(T)		
Aus 334	151(T)		
Aus 487	165(T), 166(T)		
Aus 621	126, 143(T), 145(T)		
	, TO BOTTON		
Aus 622	126, 143(T), 144(P), 145(T)		
Aus 648	125		
Aus 742	148(T), 153(T)		
Aus 743	146(T), 147(T), 148(T)		
Aus 744	146(T), 147(T)		
Aus 754	151(T), 154(T), 155(T)		
Aus 766	170(T)		
Aus 795	167(T), 168(T)		
Aus 797	170(T)		

Aus Chart	Notices
Aus 798	166(T)
Aus 800	166(T)
Aus 806	134(T)
Aus 813	133(T)
Aus 819	121
Aus 823	138(T)
Aus 824	119, 123
Aus 825	116
Aus 830	120
Aus 835	117, 122
Aus 4603	117
Aus 4620	117
Aus 4644	165(T)
Aus 4720	117
Aus 4721	149(T), 150(T)
Aus 4722	149(T), 150(T), 162(T)
Aus 4723	146(T), 147(T), 148(T), 153(T), 159(T),
A	160(T)
Aus 4725	146(T), 147(T), 148(T)
AX 00117T	151(T), 152(T)
AX 00249S	136(T), 138(T)
AX 00319S	150(T)
AX 00319U AX 00320S	150(T)
AX 003203 AX 00322U	150(T) 150(T), 162(T)
AX 003220 AX 00334S	151(T)
AX 00354S AX 00754S	151(T) 151(T), 155(T)
AX 007348 AX 00823S	138(T)
AX 04721U	150(T)
AX 04722U	150(T), 162(T)
AX 04723U	147(T), 153(T), 160(T)
AX 06001S	151(T)
AXA 0754S	151(T), 155(T)

INT Chart	Notices
INT 603	117
INT 620	117
INT 644	165(T)
INT 720	117
INT 721	149(T), 150(T)
INT 722	149(T), 150(T), 162(T)
INT 723	146(T), 147(T), 148(T), 153(T), 159(T),
	160(T)
INT 725	146(T), 147(T), 148(T)

#### 112 AUSTRALIA - Products - New Charts, New Editions, Withdrawn Charts

Australian Hydrographic Service (AA853862)

**New Charts** 

Chart Title and Geographical limits Scale Publication Date Remarks

NIL

**New Electronic Navigation Chart (Aus ENC)** 

Cell Name Title Publication Date Remarks

NIL

**New Editions and Withdrawn Charts** 

Chart Title Scale Publication Date Remarks

NIL

#### Chart permanently withdrawn

Charts listed above as withdrawn no longer meet chart carriage requirements and should be marked as "superseded" and replaced with the new chart/ new edition listed prior to passage through the area covered by the new chart.

When placing orders with a chart agent between notice of forthcoming edition and its publication, mariners should advise whether their order pertains to the current edition or the new edition.

For further details refer to the AHS website at www.hydro.gov.au for new edition and new chart stock arrival information.

When placing orders with a chart agent, mariners should advise whether their order pertains to the current edition or the new edition.

#### 113 Cessation of dredged depth updates

Australian Hydrographic Service (AA350099)

The Australian Hydrographic Service will no longer publish temporary depth information for maintained dredged channels and berth pockets. Paper charts and ENC will reflect the intended design depth. For the latest depth information contact the relevant Port Authority.

#### 114\* AUSTRALIA - NEW SOUTH WALES - Bellambi Point - Light buoy

NSW Roads and Maritime Services (SIRF2016002920)

Aus 195 [773/2015]

Insert port lateral cylindrical light buoy, *Fl.R.3*s, without topmark 34° 21'.922 S 150° 55'.870 E

#### 115\* AUSTRALIA - NEW SOUTH WALES - Jervis Bay - Bombora Rock - Light buoy

NSW Roads and Maritime Services (SIRF2016002605)

Aus 193 [1244/2013]

Insert	south cardinal pillar light buoy, Q(6)+LFI.15s, with topmark	35° 05'.26 S	150° 46'.48 E
Delete	depth, 3 <sub>6</sub> m	35° 05'.21 S	150° 46′.52 E
	depth, 5₄m	35° 05'.14 S	150° 46'.49 E

#### 116\* AUSTRALIA - QUEENSLAND - Bait Reef - Beacon

Former Notice - 872(T)/2011 is cancelled

Maritime Safety Queensland Notice 23/2016 (SIRF2016002797)

Aus 254 (plan, Hook Reef) [NE 14/8/2015]

Delete	beacon	,.	•	19° 48′.6 S	149° 03'.8 E
Aus 825	[822/2015]				
Delete	beacon			19° 48'.6 S	149° 03'.8 E

# 117\* AUSTRALIA - QUEENSLAND - Clerke Island - Light Australian Maritime Safety Authority Final ATH 2/2016 (SIRF2016002867)

Aus 835 [NE 25/9/2015] Amend light to FI.WR.2-5s 21m 9/8M	11° 58'.5 S	143° 17'.4 E
Aus 4603 (INT 603) [1106/2015] Delete light, with legend Clerke Island	11° 58'.5 S	143° 17'.4 E
<b>Aus 4620 (INT 620)</b> [ <i>NE 18/12/2015</i> ] Delete light	11° 58'.5 S	143° 17'.4 E
<b>Aus 4720 (INT 720)</b> [521/2015] Delete light	11° 58'.5 S	143° 17'.4 E

# 118\* AUSTRALIA - QUEENSLAND - Hook Island - Stanley Point to Cockatoo Point - Light beacon removed; buoys withdrawn

Maritime Safety Queensland Notices 21/2016, 26/2016 (SIRF2016002795, SIRF2016002800)

Aus 254 (plan, Stonehaven Anchorage) [116/2016]						
Delete	buoy	20° 04'.54 S	148° 54'.08 E			
	buoy	20° 04'.34 S	148° 54'.17 E			
	light beacon	20° 04'.71 S	148° 54'.05 E			

# light beacon 20° 04'.71 S 148° 54'.08

# 119\* AUSTRALIA - QUEENSLAND - lo Reef - Light buoy Former Notice - 1188(T)/2010 is cancelled

Maritime Safety Queensland Notice 15/2016 (SIRF2016002749, SIRF2016002917)

<b>Aus 251</b> [ <i>NE 6/11/2015</i> ] Substitute west cardinal pillar light buoy, <i>Q(9)15s</i> , with topmark for light beacon	20° 41'.6 S	149° 07'.7 E
Aus 252 [1103/2015] Substitute west cardinal pillar light buoy, Q(9)15s, with topmark for light beacon	20° 41'.6 S	149° 07'.7 E
Aus 824 [1282/2015] Substitute west cardinal pillar light buoy, Q(9)15s, with topmark for light beacon	20° 41′.6 S	149° 07'.7 E

# 120\* AUSTRALIA - QUEENSLAND - Port Douglas - Island Point - Light

Australian Maritime Safety Authority Final ATH 1/2016 (SIRF2016002866)

Aus 270 (plan, Port Douglas) [1100/2015] Amend light range to 11/9M	16° 28'.92 S	145° 28'.02 E	
Aus 830 [570/2015] Amend light range to 11/9M	16° 28'.9 S	145° 28'.0 E	

# 121\* AUSTRALIA - QUEENSLAND - Rodds Bay to Sable Chief Rocks - Light buoys Maritime Safety Queensland (SIRF2015001751)

<b>Aus 245</b> [1346/2015] Delete light buoy	23° 47'.64 S	151° 22'.96 E
Aus 246 [32/2016]	22° E0! 04 S	151° 24' 00 F

Aus 246 (	32/2016]		
Delete	light buoy	23° 59'.91 S	151° 34'.99 E
	light buoy	23° 52'.03 S	151° 27'.19 E
	light buoy	23° 50'.04 S	151° 25′.70 E
Aus 819 [	1347/2015]		
Delete	light buoy	23° 59'.9 S	151° 35'.0 E
	light buoy	23° 52'.0 S	151° 27'.2 E
	light buoy	23° 50'.0 S	151° 25'.7 E
	light buoy	23° 47′.6 S	151° 23'.0 E

#### 122\* AUSTRALIA - QUEENSLAND - Shelburne Bay - Rock

HMAS Mermaid (SIRF2016002865), Australian Maritime Safety Authority Auscoast Warning 20/2016 (SIRF2016002908)

Aus 835	[117/201	61
---------	----------	----

underwater rock enclosed by danger circle, centred on 142° 59'.64 E Insert 11° 50'.82 S

#### AUSTRALIA - QUEENSLAND - Spitfire Rock - Light buoy 123\*

Former Notice - 592(T)/2015 is cancelled

light beacon

Maritime Safety Queensland Notice 32/2016 (SIRF2016002743, SIRF2016002808, SIRF2016002877)

Aus 252 [1 Insert	19/2016] west cardinal pillar light buoy, VQ(9)10s, with topmark	20° 28'.62 S	149° 01'.67 E
Delete	light beacon	20° 28'.6 S	149° 01'.7 E
Aus 254 (p Insert	lan, Lindeman Island) [118/2016] west cardinal pillar light buoy, VQ(9)10s, with topmark	20° 28'.619 S	149° 01'.670 E
Delete	light beacon	20° 28'.59 S	149° 01'.70 E
Aus 824 [1 Insert	19/2016] west cardinal pillar light buoy, V <i>Q</i> (9)10s, with topmark	20° 28'.62 S	149° 01'.67 E

#### 124\* AUSTRALIA - QUEENSLAND - Townsville - Ross River - Depths; infrastructure

Maritime Safety Queensland Notice 277/2015 (SIRF2015000553, SIRF2015000556, SIRF2015000892, SIRF2015000956)

20° 28'.6 S

9° 27'.55 S

149° 01'.7 E

147° 08'.34 E

#### Aus 257 [519/2015]

Delete

accompanying block 19° 16'.7 S 146° 49'.8 E Insert

### PAPUA NEW GUINEA - Caution Bay - Mooring buoys

National Maritime Safety Authority PNG Notice 6/2016 (SIRF2016002700, SIRF2016002739)

#### Aus 648 [869/2015]

Insert	yellow cylindrical mooring buoy, <i>TM2</i> yellow cylindrical mooring buoy, <i>TM3</i> yellow cylindrical mooring buoy, <i>TM4</i>	9° 20'.60 S 9° 20'.01 S 9° 19'.97 S	146° 58'.72 E 146° 58'.58 E 146° 59'.12 E
Move	mooring buoy to	9° 20'.80 S 9° 20'.77 S	146° 59'.28 E 146° 59'.28 E
Delete	mooring buoy	9° 19'.98 S	146° 59'.13 E

#### PAPUA NEW GUINEA - Port Moresby - Vahunabada Reef - Beacons; mooring buoy 126\*

National Maritime Safety Authority PNG (SIRF2016002758)

A	004	[40/0046]
Aus	621	[40/2016]

Move

beacon

	to	9° 27'.528 S	147° 08'.286 E
Aus 622	[721/2015]		
Move	beacon	9° 27'.40 S	147° 08'.17 E
	to	9° 27'.406 S	147° 08'.170 E
	beacon	9° 27'.55 S	147° 08'.34 E
	to	9° 27'.528 S	147° 08'.286 E

#### Aus 622 (plan, Port Moresby and Napa Napa Wharves) [721/2015]

beacon							9° 27'.40 S	147° 08'.17 E
to							9° 27'.406 S	147° 08'.170 E
beacon							9° 27'.55 S	147° 08'.34 E
to							9° 27'.528 S	147° 08'.286 E
mooring buoy							9° 27'.38 S	147° 08'.32 E
to							9° 27'.375 S	147° 08'.329 E
	to beacon to mooring buoy	to beacon to mooring buoy	to beacon to mooring buoy	to beacon to mooring buoy	to beacon to mooring buoy	to beacon to mooring buoy	to beacon to mooring buoy	to 9° 27'.406 S beacon 9° 27'.55 S to 9° 27'.528 S mooring buoy 9° 27'.38 S

29 January 2016 7 127\* AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Boomerang Island - Mooring buoy

Chevron Australia Pty Ltd Notice 2/2016 (SIRF2016002645, SIRF2016002652, SIRF2016002909)

Aus 62 [1289/2015]

Delete lit mooring buoy 20° 44'.0 S 115° 29'.2 E

Aus 65 [1289/2015]

Delete lit mooring buoy 20° 44′.0 S 115° 29′.2 E

Aus 67 [1232/2015]

Delete lit mooring buoy 20° 44'.00 S 115° 29'.16 E

128\* AUSTRALIA - WESTERN AUSTRALIA - Cockburn Sound - Careening Bay - Light beacon

Fremantle Ports (SIRF2015002472)

Aus 111 [NE 6/11/2015]

Move light beacon 32° 14'.36 S 115° 42'.08 E

to 32° 14'.370 S 115° 42'.079 E

129\* AUSTRALIA - WESTERN AUSTRALIA - Flying Foam Passage - Depths

Transport WA (SIRF2015001048)

Aus 57 [1234/2015]

Insert accompanying block A 20° 26'.0 S 116° 51'.0 E

accompanying block B 20° 42'.5 S 117° 03'.5 E

Aus 58 [43/2016]

Insert accompanying block A 20° 26'.6 S 116° 50'.3 E

accompanying block B 20° 39'.5 S 116° 47'.2 E

130\* AUSTRALIA - WESTERN AUSTRALIA - Wyndham - Light buoys

Former Notice - 1034(T)/2015 is cancelled

CGL Wyndham Port (SIRF2015000732, SIRF2015000733, SIRF2016002923)

Aus 32 (plan, Approaches to Wyndham Wharf) [1233/2015]

Move 15° 20'.25 S 128° 06'.86 E raft to 15° 19'.97 S 128° 06'.80 E 128° 06'.63 E raft 15° 20'.17 S 128° 06'.63 E 15° 20'.10 S to 128° 06'.37 E 15° 19'.84 S raft 15° 19'.81 S 128° 06'.37 E to

131\* AUSTRALIA - VICTORIA - Port Phillip - South Channel - Light beacon

Former Notice - 907(T)/2015 is cancelled

Port of Melbourne Corporation Notice 24/2016 (SIRF2016002814, SIRF2016002824)

Aus 143 [48/2016]

Amend light beacon to *Fl.3s 3M & F.Bu* 38° 19'.6 S 144° 53'.9 E

Aus 158 [1301/2015]

Amend light beacon to Fl.3s 11m 3M & F.Bu 38° 19'.63 S 144° 53'.92 E

132\* AUSTRALIA - TASMANIA - Sandy Bay - Infrastructure; navaids

Former Notices - 149(T)/2014, 508(T)/2015 are cancelled

Marine and Safety Tasmania (SIRF2015001860, SIRF2016002892)

Aus 172 [1306/2015]

Insert accompanying block 42° 54'.0 S 147° 20'.2 E

#### 133(T)/2016 AUSTRALIA - NEW SOUTH WALES - Ballina - Light buoy restored

Former Notice - 1249(T)/2015 is cancelled Manly Hydraulics Laboratory (SIRF2016002710)

Cancel this notice on receipt.

Chart formerly affected - Aus 813

#### 134(T)/2016 AUSTRALIA - NEW SOUTH WALES - Green Cape - Light buoy restored

Former Notice - 882(T)/2015 is cancelled Manly Hydraulics Laboratory (SIRF2016002710)

Cancel this notice on receipt.

Chart formerly affected - Aus 806

#### 135(T)/2016 AUSTRALIA - QUEENSLAND - Bowen - Dredging operations

Date - Until 30 April 2016

Maritime Safety Queensland Notice 13(T)/2016 (SIRF2016002753)

The dredge *Everglade* is conducting dredging operations in Bowen Harbour and the entrance channel (20° 01'.06 S 148° 15'.40 E).

A floating and submerged pipeline exists in the area and will be marked by special light buoys, *Fl.Y.2·5s*. The pipeline will be marked by a port lateral light buoy, *Fl.R.2·5s*, and a starboard lateral light buoy, *Fl.G.2·5s*, where the pipeline crosses the channel.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 268

#### 136(T)/2016 AUSTRALIA - QUEENSLAND - Freshwater Point to Keswick Island - Scientific instruments recovered

Former Notice - 947(T)/2015 is cancelled

Maritime Safety Queensland (SIRF2016002714)

Cancel this notice on receipt.

Chart formerly affected - Aus 249 - Aus 251 - AX 00249S

#### 137(T)/2016 AUSTRALIA - QUEENSLAND - Gladstone - Anchorage area revoked

Former Notice - 1232(T)/2014 is cancelled Maritime Safety Queensland (SIRF2016002780)

Cancel this notice on receipt.

Chart formerly affected - Aus 245 - Aus 272

#### 138(T)/2016 AUSTRALIA - QUEENSLAND - Hay Point - Obstruction removed

Former Notice - 1155(T)/2015 is cancelled Maritime Safety Queensland (SIRF2016002714)

Cancel this notice on receipt.

Chart formerly affected - Aus 249 - Aus 823 - AX 00249S - AX 00823S

#### 139(T)/2016 AUSTRALIA - QUEENSLAND - Hook Island - Cockatoo Point - Light beacon removed

Former Notice - 460(T)/2012 is cancelled

Maritime Safety Queensland Notice 21/2016 (SIRF2016002795)

Cancel this notice on receipt.

Chart formerly affected - Aus 252 - Aus 254

#### 140(T)/2016 AUSTRALIA - QUEENSLAND - Muddy Bay - Harbour works completed

Former Notice - 651(T)/2013 is cancelled Maritime Safety Queensland (SIRF2016002820)

Cancel this notice on receipt.

Chart formerly affected - Aus 253 - Aus 268

#### 141(T)/2016 AUSTRALIA - QUEENSLAND - Shute Harbour - Wreck

Maritime Safety Queensland Notice 16/2016 (SIRF2016002750)

A wreck marked by a special light buoy, Fl.Y.2.7s, exists in position 20° 17'.72 S 148° 47'.15 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 252 - Aus 253

## 142(T)/2016 AUSTRALIA - QUEENSLAND - Whitsundays - The Narrows - Buoy

Former Notice - 1394(T)/2010 is cancelled Maritime Safety Queensland (SIRF2016002820)

Cancel this notice on receipt.

Chart formerly affected - Aus 254

#### 143(T)/2016 PAPUA NEW GUINEA - Port Moresby - Wrecks

National Maritime Safety Authority PNG Notice 5(T)/2016 (SIRF2016002698)

Stranded wrecks exist in position 9° 26'.80 S 147° 08'.45 E.

Chart temporarily affected - Aus 621 - Aus 622

#### 144(P)/2016 PAPUA NEW GUINEA - Port Moresby - Harbour works; horizontal datum error

Australian Geospatial-Intelligence Organisation (SIRF2016002697)

Mariners are advised that new port infrastructure is under construction within Port Moresby including Fairfax Harbour. The coastline is in error by up to 50 metres. The Australian Hydrographic Service will update charts in due course. Mariners are advised to exercise caution when navigating these areas.

Chart which will be affected - Aus 622

#### 145(T)/2016 PAPUA NEW GUINEA - Port Moresby - Fairfax Harbour - Survey Operations completed

Former Notice - 963(T)/2015 is cancelled Aquamap Pty Ltd (SIRF2016002925)

Cancel this notice on receipt.

Chart formerly affected - Aus 621 - Aus 622

### 146(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Ashburton Island - Platforms unlit eastwards

Pilbara Ports Authority Notice A1(T)/2016 (SIRF2016002891)

The Skate platform, Mo(U)15s (21° 35'.8 S 114° 58'.8 E), and Roller C platform, Mo(U)15s (21° 36'.9 S 114° 56'.5 E), are unlit.

Chart temporarily affected - Aus 64 - Aus 328 - Aus 743 - Aus 744 - Aus 4723 (INT 723) - Aus 4725 (INT 725)

#### 147(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Ashburton Island - Platform unlit eastwards

Former Notice - 1383(T)/2015 is cancelled

Pilbara Ports Authority Notice A1(T)/2016 (SIRF2016002891)

Cancel this notice on receipt.

Chart formerly affected - Aus 64 - Aus 328 - Aus 743 - Aus 744 - Aus 4723 (INT 723) - Aus 4725 (INT 725) - AX 04723U

#### 148(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Barrow Island - Survey operations

Date - Until 21 February 2016

Fugro Survey Pty Ltd (SIRF2016002718)

MV Offshore Guardian is conducting survey operations in the area bounded by the following positions:

21° 00'.0 S 114° 00'.0 E

21° 00'.0 S 116° 00'.0 E

20° 00'.0 S 116° 00'.0 E

20° 00'.0 S 114° 00'.0 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 61 - Aus 62 - Aus 65 - Aus 66 - Aus 67 - Aus 327 - Aus 328 - Aus 329 - Aus 742 - Aus 743 - Aus 4723 (INT 723) - Aus 4725 (INT 725)

#### 149(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Browse Island - Drill rig norhtwestwards

MODU Jack Bates (SIRF2016002834), Australian Maritime Safety Authority Auscoast Warning 19/2016 (SIRF2016002884)

Drill rig Jack Bates is conducting drilling operations in position 13° 50'.8 S 123° 19'.2 E.

Chart temporarily affected - Aus 319 - Aus 320 - Aus 4721 (INT 721) - Aus 4722 (INT 722)

#### 150(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Browse Island - Drill rig norhtwestwards moved

Former Notice - 1165(T)/2015 is cancelled MODU Jack Bates (SIRF2016002834)

Cancel this notice on receipt.

Chart formerly affected - Aus 319 - Aus 320 - Aus 322 - Aus 4721 (INT 721) - Aus 4722 (INT 722) - AX 00319S - AX 00319U - AX 00322U - AX 04721U - AX 04722U

#### 151(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Direction Bank to Garden Island - Military exercise completed

Former Notice - 1077(T)/2015 is cancelled

Department of Defence (SIRF2015000516)

Cancel this notice on receipt.

Chart formerly affected - Aus 111 - Aus 117 - Aus 334 - Aus 754 - AX 00117T - AX 00334S - AX 00754S - AX 06001S - AXA 0754S

## 152(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Kwinana - Scientific instrument recovered

Former Notice - 1174(T)/2013 is cancelled

The University of Western Australia (SIRF2016002864)

Cancel this notice on receipt.

Chart formerly affected - Aus 114 - Aus 117 - AX 00117T

#### 153(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Drill rig westwards

Former Notice - 89(T)/2016 is cancelled

Date - Until 12 February 2016

MODU *Tom Prosser* (SIRF2016002804), Australian Maritime Safety Authority Auscoast Warning 14/2016 (SIRF2016002799)

Drill rig Noble Tom Prosser is conducting drilling operations in position 20° 27'.78 S 115° 10'.60 E.

Chart temporarily affected - Aus 328 - Aus 742 - Aus 4723 (INT 723) - AX 04723U

#### 154(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Mullaloo - Light buoy

Date - Until 31 December 2016

Department of Transport WA (SIRF2016002918)

An orange spherical light buoy, FI(5) Y.20s, exists in position 31° 47'.13 S 115° 43'.84 E.

Chart temporarily affected - Aus 754

#### 155(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Mullaloo - Light buoy

Former Notice - 94(T)/2015 is cancelled

Department of Transport WA (SIRF2016002918)

Cancel this notice on receipt.

Chart formerly affected - Aus 754 - AX 00754S - AXA 0754S

#### 156(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Port Gregory - Shoaling removed

Former Notice - 486(T)/2013 is cancelled

Department of Transport WA (SIRF2016002918)

Cancel this notice on receipt.

Chart formerly affected - Aus 84

#### 157(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Mooring buoys westwards

Date - Until 2 March 2016

Viking Seatech (SIRF2016002773), Australian Maritime Safety Authority Auscoast Warning 12/2016 (SIRF2016002775)

12 yellow mooring buoys, Fl.3s, exist within 1M radius of 19° 48'.76 S 115° 17'.82 E.

Chart temporarily affected - Aus 328

### 158(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Mooring buoys eastwards

Australian Maritime Safety Authority Auscoast Warning 13/2016 (SIRF2016002776), Viking Seatech (SIRF2016002772)

8 yellow mooring buoys, Fl.3s, exist within 1M radius of 19° 32'.42 S 116° 10'.85 E.

Chart temporarily affected - Aus 327

#### 159(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Drill rig southwestwards

MODU *Atwood Osprey* (SIRF2016002827), Australian Maritime Safety Authority Auscoast Warning 15/2016 (SIRF2016002828)

Drill rig Atwood Osprey is conducting drilling operations in position 19° 54'.35 S 115° 16'.12 E.

Chart temporarily affected - Aus 328 - Aus 4723 (INT 723)

#### 160(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Drill rig moved

Former Notice - 1268(T)/2015 is cancelled MODU Atwood Osprey (SIRF2016002827)

Cancel this notice on receipt.

Chart formerly affected - Aus 328 - Aus 4723 (INT 723) - AX 04723U

#### 161(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Mooring buoys southwestwards recovered

Former Notice - 104(T)/2016 is cancelled Viking Seatech (SIRF2016002833)

Cancel this notice on receipt.

Chart formerly affected - Aus 328

#### 162(T)/2016 AUSTRALIA - WESTERN AUSTRALIA - Scott Reef - Drilling operations completed

Former Notice - 1169(T)/2015 is cancelled Woodside Energy Ltd (SIRF2016002916)

Cancel this notice on receipt.

Chart formerly affected - Aus 43 - Aus 322 - Aus 4722 (INT 722) - AX 00322U - AX 04722U

#### 163(T)/2016 AUSTRALIA - VICTORIA - Mornington - Light relit

Former Notice - 1331(T)/2015 is cancelled Parks Victoria Notice 22/2016 (SIRF2016002792)

Cancel this notice on receipt.

Chart formerly affected - Aus 143

#### 164(T)/2016 AUSTRALIA - VICTORIA - Port Phillip - River Yarra - Yarraville - Harbour works completed

Former Notice - 600(T)/2015 is cancelled

Port of Melbourne Corporation Notice 26(T)/2016 (SIRF2016002878)

Cancel this notice on receipt.

Chart formerly affected - Aus 154

#### 165(T)/2016 AUSTRALIA - BASS STRAIT - Cable operations

Date - Until 31 March 2016

Alda Marine (SIRF2016002706, SIRF2016002733)

MV Ile De Re is conducting submarine cable repair works in the vicinity of position 40° 14'.37 S 146° 52'.25 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 487 - Aus 4644 (INT 644)

#### 166(T)/2016 AUSTRALIA - TASMANIA - Cape Barren Island - Scientific instruments

Former Notice - 1074(T)/2013 is cancelled

Institute for Marine and Antarctic Studies (SIRF2016002847)

Subsurface scientific instruments exist >30m below the surface in the following positions:

40° 27'.58 S 148° 33'.81 E 40° 27'.71 S 148° 34'.35 E 40° 27'.84 S 148° 34'.89 E 40° 28'.11 S 148° 35'.96 E 40° 28'.37 S 148° 37'.04 E 40° 28'.64 S 148° 38'.12 E 40° 28'.77 S 148° 38'.65 E 40° 28'.90 S 148° 39'.19 E 40° 29'.03 S 148° 39'.73 E 40° 29'.16 S 148° 40'.27 E 40° 29'.30 S 148° 40'.81 E 40° 30'.48 S 148° 45'.65 E 40° 30'.09 S 148° 44'.04 E

40° 31'.27 S 148° 48'.89 E.

Chart temporarily affected - Aus 487 - Aus 798 - Aus 800

#### 167(T)/2016 AUSTRALIA - TASMANIA - D'Entrecasteaux Channel - Great Taylors Bay - Marine farm

Former Notice - 764(T)/2015 is cancelled

Marine and Safety Tasmania (SIRF2016002927)

Cancel this notice on receipt.

Chart formerly affected - Aus 173 - Aus 795

#### 168(T)/2016 AUSTRALIA - TASMANIA - D'Entrecasteaux Channel - Great Taylors Bay - Butlers Point - Marine farm

Former Notice - 765(T)/2015 is cancelled

Marine and Safety Tasmania (SIRF2016002927)

Cancel this notice on receipt.

Chart formerly affected - Aus 173 - Aus 795

#### 169(T)/2016 AUSTRALIA - TASMANIA - Macquarie Harbour - Scientific instruments

Former Notice - 329(T)/2015 is cancelled

Date - Until 31 December 2016

Institute for Marine and Antarctic Studies (AA797461, SIRF2016002911)

Subsurface scientific instruments, marked by subsurface buoys 3m above the seabed, exist in the following positions: 42° 22'.59 S 145° 31'.90 E

42° 23'.78 S 145° 28'.02 E.

Chart temporarily affected - Aus 177

#### 170(T)/2016 **AUSTRALIA - TASMANIA - Maria Island - Scientific instruments**

Former Notice - 122(T)/2013 is cancelled

Date - Until 30 June 2017

Sydney Institute of Marine Science (SIRF2016002846)

Subsurface scientific instruments exist on the seabed in the following positions:

42° 40'.08 S 147° 58'.04 E

42° 39'.99 S 147° 58'.60 E

42° 39'.91 S 147° 59'.16 E

42° 39'.82 S 147° 59'.72 E

42° 39'.74 S 148° 00'.28 E.

Subsurface scientific instruments exist 30m below the surface in the following positions:

42° 39'.08 S 148° 10'.40 E

42° 39'.28 S 148° 10'.92 E

42° 39'.48 S 148° 11'.44 E

42° 39'.68 S 148° 11'.96 E

42° 39'.88 S 148° 12'.49 E

42° 40'.08 S 148° 13'.01 E

42° 40'.28 S 148° 13'.53 E

42° 40'.48 S 148° 14'.05 E

42° 40'.68 S 148° 14'.57 E

42° 40'.88 S 148° 15'.10 E

42° 41'.08 S 148° 15'.62 E

42° 41'.28 S 148° 16'.14 E

42° 41'.48 S 148° 16'.66 E

42° 41'.68 S 148° 17'.18 E

42° 41'.88 S 148° 17'.71 E

42° 42'.08 S 148° 18'.23 E

42° 42'.28 S 148° 18'.75 E

42° 42'.48 S 148° 19'.27 E

42° 42'.68 S 148° 19'.79 E

42° 42'.87 S 148° 20'.32 E

42° 43'.07 S 148° 20'.84 E

42° 43'.26 S 148° 21'.26 E.

Chart temporarily affected - Aus 170 - Aus 766 - Aus 797

#### 171(T)/2016 AUSTRALIA - TASMANIA - River Derwent - Scientific instrument recovered

Former Notice - 659(T)/2015 is cancelled

Marine and Safety Tasmania (SIRF2016002726)

Cancel this notice on receipt.

Chart formerly affected - Aus 171 - Aus 173

#### 172(T)/2016 AUSTRALIA - TASMANIA - River Derwent - Stanhope Point - Light buoy damaged

Marine and Safety Tasmania Notice M10/2016 (SIRF2016002874)

The port lateral light buoy, VQ.R, has been damaged; a temporary light exists on the buoy, FI.R.3s.

Chart temporarily affected - Aus 172

#### 173(T)/2016 AUSTRALIA - TASMANIA - River Tamar - Oak Bluff - Light buoy recovered

Former Notice - 707(T)/2015 is cancelled

Marine and Safety Tasmania (SIRF2016002832)

Cancel this notice on receipt.

#### Chart formerly affected - Aus 168

29 January 2016 15

## **HYDROGRAPHIC REPORTS**

Locality	Report	Ship/Authority	Observer
QLD- Shelburne Bay	Rock	HMAS Mermaid	

#### **NAVIGATION WARNINGS**

The following radio messages have been received during the period to 28 January 2016. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

#### **AUSCOAST WARNING**

009	Cancelled.
010	Cancelled.
011	Cancelled.
012	12 six metre yellow buoys, Fl.3s, deployed in vicinity 19° 48'.76 S 115° 17'.82 E. 2M clearance requested.
013	8 six metre yellow buoys, Fl.3s, deployed in vicinity 19° 32'.4 S 116° 10'.8 E. 2M clearance requested.
014	Drill rig Noble Tom Prosser in position 20° 27'.78 S 115° 10'.60 E. 2.5M clearance requested.
015	Drill rig Atwood Osprey in position 19° 54'.20 S 115° 16'.07 E. 2.5M clearance requested.
016	Clerke Island light K3244 in position 11° 58'.48 S 143° 17'.42 E white and red sectors permanently altered (white) 10M
	to 9M and (red) 7M to 8M.
017	Cancelled.
018	Drill rig <i>Atwood Eagle</i> in position 19° 40'.76 S 117° 21'.08 E. 2.5M clearance requested.
019	Drill rig <i>Jack Bates</i> in position 13° 50'.80 S 123° 19'.20 E. 2.5M clearance requested.
020	Uncharted underwater rock, depth unknown but considered dangerous to surface navigation, in position 11° 50'.82 S
	142° 59' 64 F

#### **NAVAREA X WARNINGS**

002	Cancelled.
003	Cancelled.

### Navigational warnings in force as at 280001UTC JAN 16.

#### **Auscoast**

**2015** 295 298 306 309 323 329 335

**2016** 003 004 008 012 013 014 015 016 018 019 020

#### Navarea X 2015 Nil.

Summary of mobile drilling rigs as at 280001UTC JAN 16.

Name	Position
Stena Clyde	12° 07'.00 S 130° 26'.00 E
Ensco 5006	13° 52'.80 S 123° 19'.00 E
Jack Bates	13° 50'.80 S 123° 19'.20 E
Noble Tom Prosser	18° 52'.81 S 118° 49'.32 E
Modec Venture 11	19° 16'.60 S 116° 36'.70 E
Atwood Eagle	19° 32'.42 S 116° 10'.85 E
Atwood Osprey	19° 48'.67 S 115° 17'.72 E
Ocean Monarch	20° 01'.80 S 115° 12'.10 E
Armada Claire	20° 03'.50 S 115° 11'.50 E
Atwood Falcon	21° 31′.80 S 114° 05′.15 E

#### **NAVAREA XIV WARNINGS**

102	Cancelled.	
103	Cancelled.	
104	Cancelled.	
105	Cancelled.	
		No. 200 MN/ 200 To face to fac

Navarea XIV warnings in force as at 280001UTC JAN 16.

**2015** 101