3 January 1997 Edition 1



Australian Notices to Mariners are the authority for correcting Australian Charts

AUSTRALIAN NOTICES TO MARINERS

© Commonwealth of Australia 1997 - Copyright restrictions apply to Notices to Mariners

Notices 326-343

List of T and P Notices in Force

Published fortnightly by the RAN Hydrographic Service

R. J. WILLIS, Hydrographer, RAN

SECTIONS. I. Australian Notices to Mariners.

III. Navigational Warnings. IV. Hydrog ic Reports.

New Zealand Notices to Mariners

The substance of these notices should be inserted on the charts affected.

Notices to Mariners information unavailable on this web site at this stage but still available in printed form:-

British Admiralty Notices to Mariners.
Section II. Corrections to Admiralty List of Lights, Vol K.
Section V. Corrections to Admiralty List of Radio Signals.
Section VI. Corrections to Sailing Directions.
Blocks included after Section VI.

Bearings are referred to the true compass and are reckoned clockwise from 000° (North) to 359°: those relating to lights are given as seen by an observer from seaward. The range quoted for a light is its nominal range. Fog signals are sounded only during thick or foggy weather, unless otherwise stated Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices. A star (*) adjacent to the number of a notice indicates that the notice is based on original information.

Mariners are particularly requested to notify the HYDROGRAPHER, RAN, Locked Bag 8801 South Coast Mail Centre, NSW 2521 (Fax 042-21 8599), e-mail hni@hydro.navy.gov.au or, alternatively by filling in and submitting the Hydrographic Notes forms, immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AMSA (Fax 06-257 2036).

Copies of these notices can be obtained from the HYDROGRAPHIC OFFICE, 8 Station Street, Wollongong, the Agents for the sale of Australian and Admiralty charts in Australia, and from the Australian Maritime Safety Authority (AMSA) Offices, in the major ports of Australia

The Commonwealth of Australia is the owner of the copyright in Notices to Mariners (NtoM). NtoM are protected under the Copyright Act 1968 and international convention. Except as expressly authorised below, NtoM may not be copied, reproduced, adapted, changed or commercially exploited in whole or in part, without the prior written permission of the Australian Hydrographic Office.

NtoM may be copied for the purpose of inserting their substance on official charts and other publication. However, any copies of NtoM may not be sold for profit.

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 1 3 January 1997

Notices	Aus Chart
34	Aus 141,199,428,4620
35	Aus 410,426,4621 (INT 621)
36	Aus 365,817
37	Aus 366,818,819
38	Aus 292,293,299
39	Aus 32
40	Aus 116
41	Aus 115,334,335,755
42	Aus 344,444,777
43	Aus 125
44	Aus 143,158
45	Aus 143,157
46(T)	Aus 199
47(T)	Aus 238
48(T)	Aus 243
49(T)	Aus 301,701
50(T)	Aus 326,414,415,4060, 4070 (INT 70), 4603 (INT 603), 4708 (int 708)
51(T)	Aus 57,741
52(T)	Aus 327,741,742
53(T)	Aus 113
54(T)	Aus 112,113
55(T)	Aus 157

34 AUSTRALIA - Publications

RAN Hydrographic Service (AH 17/3)

(1) New metric chart

Chart Published Title and limits Scale Folio Index Charts Price
Aus 4620 1/11/96 Australia - North East Coast - Percy Isles to 1:1 500 000 1 Australia - Percy Isles to 1:1 500 000 1 Australia - Percy Isles to 1:1 500 000 1 Australia - Percy Isles

Aus 5020B

Booby Island including Gulf of Papua

7° 00' 01" S - 22° 36' 05" S 141° 30' 00" E - 151° 00' 36" E

A metric replacement for chart Aus 428. The chart includes details of the Ship Reporting System for Torres Strait and the Great Barrier

Reef.

(2) New edition

Chart Published Title and limits Scale Folio Index Charts Price
Aus 14 4/10/96 Australia - North Coast - Northern Territory - 1:75 000 2 Aus5020A \$24.25

Groote Eylandt Approaches to Milner Bay

Plan: Milner Bay 1:7 500

Includes general updating throughout, with

RAN surveys of 1994.

(3) Chart permanently withdrawn

Chart On publication of new chart/new edition

Aus 14 Aus 14

Aus 199 Aus 199 (notification of publication was in edition 32/96)

Aus 428 Aus 4620

35* AUSTRALIA - Miscellaneous chart corrections. RAN hydrographic Office. $(AH\ 17/3)$

Aus 410 [636/96] Substitute legend, *Aus 4620*, for Aus 428 in E border at 10° 23' S

Aus 426 [506/96]

legend, Adjoining Chart Aus 4620, in N border centred on Insert 149° 30' E

Aus 4621 (INT 621) [634/96] Substitute legend, *Aus 4620,* for Aus 428 in W border at 12° 19' S

36* AUSTRALIA - QUEENSLAND - Hervey Bay - Theodolite Creek - Wreck northeastward.

Former Notice - 519(T)/96 is cancelled DOTQ Notice 403/96. (AH 58/150)

Aus 365 [117/96]

Insert non dangerous wreck 25° 00'.24 S 152° 43'.20 E

Aus 817 [530/95]

Insert non dangerous wreck 25° 00'.24 S 152° 43'.20 E

AUSTRALIA - QUEENSLAND - Bustard Head - Wreck eastward.

Former Notice - 434(T)/95 is cancelled DOTQ Notice 404/96. (AH 58/150)

Aus 366 [5	506/961
------------	---------

Insert non dangerous wreck	24° 02′.6 S	151° 55′.2 E
Aus 818 [530/95] Insert non dangerous wreck	24° 02'.6 S	151° 55'.2 E
Aus 819 [506/96] Insert non dangerous wreck	24° 02′.6 S	151° 55'.2 E

38* AUSTRALIA - QUEENSLAND - Ellis Channel - Hovell Bar - Light buoys repositioned; depths.

Former Notice - 578(T)/96 is cancelled DOTQ Sheet K560-041. (AH 70/80,126)

Delete

depth 1₈ m

Aus 292 [656/96]				
Move	south cardinal light buoy to		10° 33'.95 S 10° 34'.15 S	142° 15'.51 E 142° 15'.39 E
Insert	depth, $O_9 m$, and extend 2 m contour S to enclose		10° 34'.29 S	142° 15′.46 E
Delete	depth 1 ₄ m		10° 34′.27 S	142° 15′.49 E
Aus 293 [6	56/961			
Move	south cardinal light buoy		10° 33′.95 S	142° 15'.51 E
	to		10° 34′.15 S	142° 15′.39 E
Insert	depth, $0_9 m$, and extend 2 m contour S to enclose		10° 34′.29 S	142° 15′.46 E
Delete	depth 1 ₄ m		10° 34′.27 S	142° 15′.49 E
Aus 299 [6	556/961			
Move	south cardinal light buoy		10° 33′.950 S	142° 15′.510 E
	to		10° 34′.148 S	142° 15′.387 E
	port lateral light buoy		10° 34′.222 S	142° 15'.335 E
	to		10° 34'.199 S	142° 15'.343 E
Insert	depth 0 ₉ m	(a)	10° 34′.288 S	142° 15′.461 E
	depth 1 ₁ m	(<i>b</i>)	10° 34′.262 S	142° 15′.405 E
	enclose depths at (a & b) with a contour			
	depth, 19 m, enclosed by a contour		10° 34′.213 S	142° 15′.323 E

10° 34′.046 S

10° 34′.04 S

142° 15′.360 E

142° 15′.37 E

depth, 14 m, and extend 2m contour W to enclose

39* WESTERN AUSTRALIA - Wyndham - West Arm - Mooring buoy. Hr
Mr Wyndham. (AH~64/84)

Aus 32 [*569/96*] Insert mooring buoy 15° 06'.0 S 128° 05'.3 E

40* WESTERN AUSTRALIA - Mandurah - Buoyage. DOTWA Chart WA 848. *(AH 68/80,8,9)*

Aus 116 (plan, Entrance to Mandurah Estuary) [NE 29/6/93]

Insert	spar buoy	32° 30′.80 S 32° 30′.88 S	115° 43′.67 E 115° 43′.62 E
Delete	starboard lateral light buoy	32° 31'.44 S	115° 42'.67 E
	port lateral beacon	32° 31'.72 S	115° 43'.13 E

41* WESTERN AUSTRALIA - Bunbury - Amendment to lights. List of Lights Vol K/96 - 1785.00,1784.00,1785.10,1786.80,1787.40 BPA. *(AH 68/78)*

Aus 115 [501/94]		
Amend	light range to 10/7M	33° 18′.1 S	115° 38′.7 E
	light range to 3M	33° 18'.9 S	115° 39′.5 E
		33° 19'.1 S	115° 39'.6 E
Aus 115 (plan, Port of Bunbury)		
Amend	light range to 10/7M	33° 18′.14 S	115° 38′.68 E
	light range to 3M	33° 18′.92 S	115° 39′.48 E
		33° 19′.14 S	115° 39′.60 E
	light beacon to FI(2) G. 3s	33° 17'.75 S	115° 38′.84 E
	light beacon to Fl. G. 3s	33° 19'.01 S	115° 39'.05 E
Aus 334 [-	413/95		
Amend	light range to 10/7M	33° 18′.1 S	115° 38′.7 E
Aus 335 [-	473/Q21		
Amend	light range to 10/7M	33° 18′.1 S	115° 38′.7 E
Aus 755 [•		
Amend	light range to 10/7M	33° 18'.1 S	115° 38′.7 E

42* SOUTH AUSTRALIA - Tiparra Reef - Light altered.

List of Lights Vol K/96 - 1982.00 ATH 1996/S/016. (AH 71/78)

Aus 344 [610/9

Amend	light range to 8M	34° 04′.0 S	137° 23′.4 E

Aus 444 [*489/96*] Amend light range to *8M* 34° 04'.0 S 137° 23'.4 E

Aus 777 [610/96] Amend light to *FI(2) 10s 16m 8M* 34° 04′.0 S 137° 23′.4 E

43* SOUTH AUSTRALIA - Glenelg - Mooring buoy. Former Notice - 578(T)/94 is cancelled MHSA Notice 16/94. (AH 71/84)

Aus 125 (plan, Glenelg) [444/96] Insert mooring buoy

34° 58′.747 S 138° 30′.208 E

44* AUSTRALIA - VICTORIA - Port Phillip - Drapers Reef - Light buoy replaced by light beacon.

Former Notice - 306(P)/96 is cancelled VCA Notice 50/96. (AH 66/78,80)

Substitute	port lateral light beacon, Q. R, with topmark for port lateral	38° 16′.42 S	144° 39′.93 E
	light buoy		

Aus 158 [638/96]
Substitute port lateral light beacon, *Q. R,* with topmark for port lateral 38° 16′.42 S 144° 39′.93 E

light buoy

45* AUSTRALIA - VICTORIA - Port Phillip - Geelong - Spoil grounds; explosive anchorage revoked. VCA Notice 49/96. (66/78)

Aus 143 [4	14/97		
Insert	pecked line between	38° 05′.95 S	144° 24′.10 E
		38° 05′.95 S	144° 24′.99 E
		38° 07′.19 S	144° 24′.99 E
		38° 07'.19 S	144° 24′.10 E
	pecked line between	38° 04′.51 S	144° 34′.66 E
		38° 04′.51 S	144° 36′.13 E
		38° 05′.43 S	144° 36′.13 E
		38° 05′.90 S	144° 35′.14 E
		38° 05′.90 S	144° 34′.66 E
	legend, Spoil Ground, centred on	38° 06′.5 S	144° 24′.5 E
		38° 05'.2 S	144° 35′.3 E
Delete	explosive anchorage centred on	38° 05'.5 S	144° 34′.8 E
A - 457 (10.4/03		
Aus 157 [4		200 051 05 0	4449 04140 5
Insert	pecked line between	38° 05′.95 S	144° 24′.10 E
		38° 05'.95 S 38° 07'.19 S	144° 24′.99 E 144° 24′.99 E
		38° 07'.19 S 38° 07'.19 S	144° 24'.99 E 144° 24'.10 E
	necked line between	38° 04'.51 S	144 24.10 E 144° 34'.66 E
	pecked line between	38° 04'.51 S	144° 36'.13 E
		38° 05'.43 S	144° 36'.13 E
		38° 05'.90 S	144° 35'.14 E
		38° 05'.90 S	144° 34'.66 E
	legend, Spoil Ground, centred on	38° 06'.5 S	144° 34'.5 E
	legena, opon oroana, centrea on	38° 05'.2 S	144° 35'.3 E
		30 03.23	144 33.3 L
Delete	explosive anchorage centred on	38° 05′.5 S	144° 34′.8 E

46(T) AUSTRALIA - NEW SOUTH WALES - Botany Bay - Ramsgate - Waverecorder. *Date* - Until 31 October 1997

Date - Until 31 October 1997 Sydney Ports Marine Notice 28/96 (AH 61/80)

A lit wave recording buoy, FI(5) 20s, has been temporarily established in position 33° 59'.27 S 151° 09'.72 E.

Mariners are asked to keep well clear.

Chart temporarily affected - Aus 199.

47(T) AUSTRALIA - QUEENSLAND - Brisbane River - Hamilton Reach - Shoaling removed. Former Notice - 451(T)/96 is cancelled DOTQ (AH 62/22)

Cancel this notice on receipt.

Chart formerly affected - Aus 238

48(T) AUSTRALIA - QUEENSLAND - Bundaberg - Long Reach - Cable ferry operations completed. Former Notice - 303(T)/96 is cancelled. DOTQ Notice 415/96 (AH 58/107)

Cancel this notice on receipt.

Chart formerly affected - Aus 243

49(T) AUSTRALIA - QUEENSLAND - Gulf of Carpentaria - Pennefather River - Scientific instruments southwestward.

Date - Until 30 June 1997

DOTQ Notice 418/96. (AH 70/8)

A wave recording buoy has been temporarily established in position 12° 17'.26 S 141° 40'.49 E.

A current meter, marked by a buoy labelled *DoE.Phone 07-3269 4555*, has been temporarily established in position 12° 17′.244 S 141° 40′.406 E.

Mariners are asked to keep well clear.

Chart temporarily affected - Aus 301 - Aus 701.

50(T) WESTERN AUSTRALIA - Cunningham Island - Submarine cable operations completed.

50(T) WESTERN AUSTRALIA - Cur *Former Notice* - 380(T)/96 is cancelled RAN Hydrographic Service. (AH 72/22)

Cancel this notice on receipt.

Chart formerly affected - Aus 326 - Aus 414 - Aus 415 - Aus 4060 - Aus 4070 - Aus 4603 - Aus 4708.

51(T) WESTERN AUSTRALIA - Dampier - Hammersley Shoals - Scientific instruments southwestward. *Date* - Until 30 April 1997

Port of Dampier Marine Notice 2/96. (AH 64/80)

Two lit wave recording buoys, FI(5) Y. 20s, have been temporarily established in position 20° 24'.8 S 116° 45'.8 E.

Mariners are asked to keep well clear.

Chart temporarily affected - Aus 57 - Aus 741.

52(T) WESTERN AUSTRALIA - Dampier Archipelago - Rosemary Island - Waverecorder northwestward.

Date - Until further notice

WNI Science & Engineering (AH 64/80)

Lit waverecording buoys have been temporarily established in the following positions:

(a)	20° 25′.0 S	116° 30′.0 E	FI(5) Y. 20
(b)	20° 25′.0 S	116° 30′.0 E	Fl. Y. 3s
(c)	20° 15′.0 S	116° 20′.0 E	Fl. Y. 3s
(d)	20° 02′.5 S	116° 10′.0 E	Fl. Y. 3s
(e)	19° 43′.3 S	116° 06′.5 E	Fl. Y. 3s

Mariners are asked to keep well clear of the buoys.

Chart temporarily affected - Aus 327 - Aus 741 - Aus 742.

53(T) WESTERN AUSTRALIA - Fremantle - Dredging operations completed. Former Notice - 525(T)/95 is cancelled FPA Notice 4/96 (AH 72/22)

Cancel this notice on receipt.

Chart formerly affected - Aus 113

54(T) WESTERN AUSTRALIA - Fremantle - Wreck salvaged; light buoy removed. Former Notice - 504(T)/95 is cancelled FPA (AH 72/150)

Cancel this notice on receipt.

Chart formerly affected - Aus 112 - Aus 113

55(T) AUSTRALIA - VICTORIA - Geelong - Depth information.

Date - Until further notice

Victorian Channels Authority Notices 52 & 53/96 (AH 66/22)

Available depth of berth and channels as at 12 December 1996:

(1) Corio Quay

(a) in the area delimited by a line joining positions as follows:

			Depth
i.	38° 06′.515 S	144° 21′.720 E	7.2m
ii.	38° 06′.589 S	144° 21′.957 E	
iii.	38° 06′.673 S	144° 22′.046 E	
iv.	38° 06′.852 S	144° 21′.983 E	
٧.	38° 06′.824 S	144° 21′.939 E	
vi.	38° 06′.667 S	144° 21′.994 E	
vii	38° 06′.570 S	144° 21′.869 E	
viii	38° 06′.527 S	144° 21′.740 E	

(b) area (Dredged to 9.7m (1990)

shown immediately north of the area in (a) 8.8m

(c) area inshore of area in (a) less than 7.0m

(2) Corio Quay Wharfs: No 1 South

 No 1 South
 9.0m

 No 1 North
 10.2m

 No 2 North
 9.7m

 NO 3 North
 9.0m

(3) Refinery Pier:

 No 1
 10.2m

 No 2
 10.6m

 No 3
 10.2m

 No 4
 10.3m

(4) Point Henry Pier 9.9m

(5) Bulk Grain Pier No 2 9.5m

Chart temporarily affected - Aus 157.

56(T) AUSTRALIA - Ocean yacht races. Former Notice - 386(T)/96 is cancelled RAN Hydrographic Service (56/151)

Cancel this notice on receipt.

57(T) AUSTRALIA - TEMPORARY AND PRELIMINARY NOTICES. Former Notice - 561(T)/96 is cancelled RAN Hydrographic Service (AH 17/106)

Notice	Charts affected	Locality and Subject
Notice	Charts affected	Locality and Subject NEW SOUTH WALES
		NEW 300 III WALLO
		Botany Bay
46/97	Aus199	Waverecorder
		Brisbane Water
460/95	Aus204	Aids to navigation
		Cross Cons to Reint Densey
426/96	Aus197-806-807-808-810-812	Green Cape to Point Danger -Waverider and research buoys
0,00	813	Travelladi ana receatori sacyo
548/96	Aus193	Jervis Bay Light buoy re-established in position; light buoy off station
340/30	Au3133	Light budy re-established in position, light budy on station
		Newcastle
582/95	Aus207	Lights altered
123/96		Depth information
		Port Jackson
167/95	Aus200-202	Harbour works
		Port Kembla
137/94	Aus195	Spoil ground
420/02	Aug 220 844 842	Trial Bay
420/93	Aus220-811-812	Leading lights temporarily discontinued
		Tweed River
144/96	Aus814	Waverider buoy
		NORTHERN TERRITORY
		NORTHERN TERRITORT
		Beagle Gulf
466/96	Aus27-722	Buoy off station
		Darwin
134/95	Aus27	Harbour works
185/96	Aus28	Depth information
		Fish Reef
554/96	Aus309-316-411-413-722	Scientific instrument westward
		Observation Observ
194/95	Aus309-411-413-722	Shepparton Shoal Depth
134/33	7.03000 411 410 722	Бериг
		QUEENSLAND
		Abbot Point
46/95	Aus255	Depth information
		4
670/06	A050 000	Bowen
672/96	Aus250-826	Light tempoarily altered
		Brisbane River
43/96	Aus237	Light beacon established
618/93 666/96	Aus236-237 Aus237	Dredging operations Lights temporarily unlit
596/96	Aus238	Harbour works
402/96	Aus238	Harbour works
		Broadwater
552/94	Aus814	Harbour works; temporary buoy
		
400/04	A.:.=2.42	Bundaberg
196/94 597/96	Aus243 Aus243	Shoaling Depth information
551755	,	Sopar anomination

Notice	Charts affected	Locality and Subject
		QUEENSLAND (continued)
		Cairns
462/96	Aus262-830	Depth information
229/96	Aus819	Capricorn Group Lit wave recorder
620/96	Aus819	Waverecorder
		Clews Point
643/96	Aus818-819	Wreck
		Cooktown
648/96	Aus831	Dredging
240/00	A., 2045 040	Gladstone
318/96 376/96	Aus245-246 Aus245	Pipeline Buoys
182/96	Aus244-245-246	Depth information
		Gulf of Carpentaria
292/96 49/97	Aus301-701 Aus301-701	Hydrographic survey operations northward Scientific instruments southwestward
		Hay Point
446/95	Aus249	Depth information
644/96	Aus249-823	Obstruction marked by buoy
		Hervey Bay
155/96 493/96	Aus241 Aus241-365-817	Groyne construction; light buoy Light beacon destroyed; replaced by light buoy
91/96	Aus259-828	Hinchinbrook Channel Marine farm marked by light buoy westward
		Karumba
328/96	Aus303	Light beacon established
579/96	Aus303-410	Lights
495/96	Aus247-819	Keppel Bay Waverider buoy
		Lindeman Island
621/96	Aus252-824	Waverecorder
518/94	Aus259	Lucinda Depth information
646/96	Aus259	Ramp
		Mackay
218/95	Aus250	Depth information
		Moreton Bay
592/96 181/96	Aus236 Aus236	Light beacons Pipeline
101,00	7.00200	
501/95	Aus235-236-237-238-814	Moreton Bay and Brisbane River Depth information and keel clearances in channels
		Mourilyan
475/95	Aus829	Depth information
		North Stradbroke Island
665/96	Aus364-814	Waverecorder southeastward
		Pioneer Bay
520/96	Aus252	Dangerous wreck marked by light buoy
618/96	Aus4-236-249-255-256-814-	Point Danger to Karumba Waverecorder and research buoys
010/30	828-830-832	vvaverecorder and research buoys

Notice	Charts affected	Locality and Subject
		QUEENSLAND (continued)
		Port Alma
72/94	Aus247	Depth information
		Port Douglas
622/96	Aus830	Light beacon destroyed; replaced by light buoy
499/96	Aus373-428-830	Light
		Prudhoe Island
375/96	Aus249	Wreck
		Red Cliff Point
647/96	Aus830	Obstruction
		Repulse Bay
459/96	Aus824	Channel siltation
		Thursday Island
80/94	Aus293-299	Depth information
		Townsville
673/96	Aus256	Light beacon replaced by light buoy
645/96	Aus256-257	Depth information
100/00		Urangan
492/96	Aus241	Light buoy
		Weipa
465/96	Aus4	Depth information
		Whitsunday Group
122/95	Aus252-254	Buoys
		SOUTH AUSTRALIA
		Ballast Head
464/95	Aus125-780	Mussel culture; light buoys
		Boston Bay
231/96	Aus134	Buoys removed
		Franklin Harbour
319/96	Aus777	Light extinguished
		Glenelg
93/96	Aus780-781	Buoys missing
		Gulf of St Vincent
324/94	Aus137-781	Jetties damaged
		Port Lincoln
448/95	Aus134	Mussel culture; light buoys
326/95	Aus134	Mussel culture; light buoys
471/96	Aus134-776	Fish farms
48455	4 405	Port Stanvac
451/95 677/96	Aus125 Aus125	Mussel culture; light buoys Mooring buoy; restricted area
011130	74312J	ויוססוווואַ טעסץ, ופטנווטנפע מופמ
652/06	Aug700 704	Port Vincent
652/96	Aus780-781	Yachting buoys
		TASMANIA
		Barnes Bay
563/95	Aus171-173	Mussel spat collection equipment
		D'Entrecasteaux Channel
380/95	Aus173	Marine farm

Notice	Charts affected	Locality and Subject
		TASMANIA (continued)
558/96 123/95	Aus170-355	Great Oyster Bay Longlines Longlines
536/95 396/93	Aus171 Aus172	Hobart Long lines Wharf to be demolished.
360/95	Aus171-173	Little Oyster Cove Marina to be established
474/96 529/94 600/96	Aus177 Aus177 Aus177	Macquarie Harbour Beacon destroyed Jetty damaged Buoy withdrawn
252/96 557/96	Aus171-173	North Bruny Island Lights Marine farm
475/96 330/96	Aus172	River Derwent Buoys Raft replaced by light buoy
207/96	Aus173-174	Southport Jetty damaged
		TIMOR SEA
230/96 409/96	Aus312 Aus312-314	Sahul Banks Current meter Waverider
		TORRES STRAIT
598/96	Aus376-839	Ackers Shoal Beacon to be established
624/96	Aus292-294	Boat Channel Light beacon destroyed; replaced by light buoy
599/96	Aus376-839	Caldbeck Reef Beacon to be established
511/95	Aus289-292-293-294-296-299- 301-375-376-377-378-700- 701-839-840	Horn Island -Differential global positioning system
		VICTORIA
362/95	Aus357A-358-422-423-445A	Bass Strait Current meters
151/94	Aus349-350-357-357A-422- 445A-445B-789	Cape Schanck Differential Global Positioning System
157/96	Aus182	Cunninghame Arm Harbour works
584/95 679/96 54/97	Aus143-157 Aus157 Aus157	Geelong Environment monitoring piles Temporary lights Depth information
88/95	Aus182	Gippsland Lakes Shoaling

Notice	Charts affected	Locality and Subject
-		VICTORIA
		Lakes Entrance
231/95	Aus182	Vessel control
		Port Phillip
87/95	Aus158	Light beacon destroyed; temporary buoy
242/96	Aus143	Beacons to be removed; beacon to be established
173/96	Aus154-155	Reclamation work; light beacon
533/96	Aus154-155	Dredging operations
601/96	Aus154-155	Light altered
310/96	Aus154	Bridge construction
559/96 592/06	Aus154	Light extinguished
582/96 465/95	Aus154 Aus157-158	Light beacons moved, island constructed Beacon destroyed
58/93	Aus143	Depth information
502/96	Aus154	Harbour works
426/95	Aus143-155-158	Waverider buoys and current meter
		Western Port
278/96	Aus152	Lights
584/94 247/95	Aus151 Aus151-152	Buoys Depth information
241/93	Aus 151-152	Depth information
		WESTERN AUSTRALIA
		Albany
204/96	Aus109-118	Harbour works
		Complexisters Could
476/95	Aus726	Cambridge Gulf Lit structure eastward
470/93	Au37 20	Lit Structure eastward
		Carnarvon
277/96	Aus747	Beacon destroyed
4.47/05	A. (2442-447	Cockburn Sound
447/95	Aus113-117	Navigation light synchronisation trials
		Cunningham Island to Rottnest Island
293/96	Aus117-327-741-742-743-74	4-Scientific instruments, fishery research and waverider buoys
	752-754	
		Dominion
50/97	Aus57-741	Dampier Scientific instruments southwestward
30/97	Aus57-741	Scientific instruments southwestward
		Dampier Archipelago
51/97	Aus327-741-742	Waverecorder northwestward
675/96	Aus327-415-741-742	Waverecorder
555/96	Aus327-415-741-742	Wandoo oilfield
		Fanaranaa
180/90	Aus119	Esperance Groyne under construction
491/95	Aus119	Dredging
101700	7.00 . 70	2.039.119
		Garden Island
676/96	Aus111	Magnetic Variation
		Orandellan
46/96	Aus81	Geraldton Light beacon destoyed; replaced by light buoy
169/96	Aus81	Harbour works completed; new leading lights established
. 55/65	, 1,000	
		James Service Reef
470/96	Aus755	Light buoy off station
40/0E	Aug 225 220 227 200 445 445	Karratha
49/95	Aus325-326-327-328-415-410 739-740-741-742-743	6-Differential global positioning system
	133-140-141-142-143	
		Mandurah
528/96	Aus116-755	Buoy established

Notice	Charts affected	Locality and Subject
		WESTERN AUSTRALIA (continued)
500/96	Aus754	Ocean Reef Boat Harbour Shoaling
203/96	Aus52-53	Port Hedland Light beacon destroyed; replaced by light buoy
		SOUTHERN OCEAN
524/93	Aus605	Heard Island Tide gauge
		PAPUA NEW GUINEA
674/96	Aus628	Goschen Strait Buoy off station
328/90	Aus399-461- BA1708-3994.	Bougainville Island Closed area
560/96		MISCELLANEOUS Summer time

III NAVIGATION WARNINGS

The following radio messages have been received during the period to 20 December 1996. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNINGS

326	Cancelled
327	Cancelled.
328	NW Coast. Seismic survey vessel Ross Seal towing 2.5 NM cable in area 11° 30' S to 13° 00' S and
	122° 00' E to 124° 00' E.
329	E Coast. Port Stephens. Corrie Island directional light K2770.8 (32° 41'.0 S 152° 07'.8 E) temporarily replaced by
0_0	backup leads, front <i>Fl.</i> 3s 5M, rear Q. 5M. Leading lights will only operate during hours of darkness.
330	Cancelled
331	Cancelled.
332	Cancelled.
333	S Coast. Support legs from the drill rig <i>Maersk Victory</i> remain submerged in position 35°12'.6 S 138°06'.5 E and are
	marked by special light buoys, Q. Vessels are requested to remain 2.5 NM clear.
334	SE Coast. Drill rig Sedco 703 in position 38° 27'.1 S 148° 37'.6 E 2.5 NM clearance requested.
335	NW Coast. Drill rig Sedco 702 in position 19° 45′.0 S 115° 46′.5 E 2.5NM clearance requested.
336	Cancelled.
337	Cancelled.
338	NW Coast. Drill rig Gulf explorer in position 14° 17'.6 S 127° 51'.5 E 2.5 NM clearance requested.
339	Cancelled.
340	NW Coast. Seismic survey vessel Geco ResolutionI towing 4x2.5 NM cables in area 19° 19' S to 19° 49' S and 115°
	20' E to 116° 40' E.
341	NW Coast. Seismic survey vessel Odin Explorer towing 3.3 NM cable in area 9° 20' S to 11° 00' S and 128° 05' E to
	129° 50' E.
342	NW Coast. Drill rig <i>Peregrine III</i> in position 19° 54'.2 S 113° 11'.2 E 2.5NM clearance requested.

NAVAREA X WARNINGS

O26 Canadlad			
	036	Cancelled	

O37 Seismic survey vessel *Rig Seismic* towing 2.5 NM cable in area 32° 00' S to 38° 50' S and 163° 30' E 173° 30 E.

Torres Strait/Great Barrier Reef (GBR) Mandatory Ship Reporting System (REEFREP) for all vessels 50m or more in length will enter into force 010001UTC JAN 97. Ships operating in Torres Strait between 141° 45' E and 144° 00 E and the area of the coast to the outer edge of the GBR to 22° 00' S are required to report to REEFCENTRE at mandatory reporting points using designated VHF Channels.

Detailed instructions and further information will be available from agents, AMSA Offices and coastal pilotage companies. 1997 Annual Australian Notice to Mariners 22A and Queensland Notice to Mariner 413/96 also refer.

Navigational warnings in force as at 191400UTC DEC 96.

Auscoast warning:

225 299 304 321 324 328 329 333 334 335 338 339 340 341 342.

Docition

Navarea X:

005 020 024 034 037 038.

Mama

Summary of mobile drilling rigs as at 191400UTC DEC 96.

Ivairie	POSITION
Gulf Explorer	14° 17'.6 S 127° 51'.5 E
Ocean Bounty	10° 54'.5 S 126° 14'.4 E
Sedco 702	19° 45'.0 S 115° 46'.5 E
Hakuryu 7	20° 08'.3 S 116° 25'.3 E
Ron Tappmeyer	20° 07'.7 S 116° 26'.1 E
Java Constructor	20° 40'.0 S 115° 29'.5 E
Peregine III	19° 54'.2 S 113° 11'.2 E
Sedco 703	38° 27'.1 S 148° 37'.6 E

NAVAREA XIV WARNINGS

199	Cancelled.	
200	Cancelled.	
201	Not received.	
202	Cancelled.	
203	Cancelled.	
204	Cancelled.	
205	Cancelled.	
206	Cancelled.	
207	New Zealand.	Cape Brett light K3709 (35° 10'.0 S 174° 20'.0 E) altered to Fl. 15s.
208	Cancelled.	

Navarea XIV warnings in force as at 190100UTC DEC 96.

173 184 207.

HYDROGRAPHIC REPORTS

	Locality	Report	Ship/Authority	Observer
•	PNG- China Strait Raven Channel	Beacon Buoy	HMAS <i>Paluma</i> HMAS <i>Mermaid</i>	_
	WA- Albany	Harbour works	HMAS <i>Brisbane</i>	
	QLD- Hay Point	Port radio	MV Iron Chieftan	