

*To accompany Australian Notice to Mariners 530/2002*

PORT ALTERATIONS

The dredged channels have been realigned; centreline of Sea Reach Channel lies 13.5m N of its charted position. Buoyage has been altered accordingly, Notice to Mariner 544(P)/2002 refers.

Note: a new chart Aus 242 is in production.

*Note for chart Aus 243*