

UPDATES TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2013/14 , Weekly Edition No. 20, Dated 16 May 2013. <i>Last Updates: Weekly Edition No. 19, dated 09 May 2013.</i>							
K1034 ID., 1960	- Gosong Mampango (ID)	3 34-78 S 109 09-88 E	Fl W 5s	13	12 Red and white framework structure 20	<i>fl 0.5</i> , Ra refl. PA. TE 2010	
*	*	*	*	*	*	*	*
K1687-88	- Angel	19 29-78 S 116 35-98 E	Mo(U)W 15s	..	10 Platform		
	--	..	Racon				
	--	..	AIS	..		TD 2013	*
K1691-655	DAMPIER ARCHIPELAGO, PORT OF CAPE PRESTON - Cape Preston	20 49-40 S 116 11-32 E	Oc WRGBu 5s	20	10 ..	R000°-040°(40°), G040°-090°(50°), Bu090°-130°(40°), W130°-210°(80°), R210°-220°(10°)	
				*	*		
K1773-6	-	32 08-10 S 115 40-65 E	Fl Y 4s	..		(T) 2013	
*	*	*	*	*	*	*	*
K1801-09	-	35 00-02 S 117 56-84 E	Fl R 3s	..	.. □ on beacon		
*	*	*	*	*	*	*	*
K1801-1	-	34 59-90 S 117 56-94 E	Fl R 3s	..	.. □ on beacon		
*	*	*	*	*	*	*	*
K1801-16	KING GEORGE SOUND, OYSTER HARBOUR -	34 59-70 S 117 57-13 E	Fl G 3s	..	.. Green △ on green beacon		
*	*	*	*	*	*	*	*
K1801-19	-	34 59-61 S 117 57-14 E	Fl G 3s	..	.. Green △ on green beacon		
*	*	*	*	*	*	*	*
K1801-24	-	34 59-50 S 117 57-11 E	Fl G 3s	..	.. Green △ on green beacon		
*	*	*	*	*	*	*	*
K1801-65	- Green Island, W	34 59-16 S 117 57-02 E	Fl G 3s	..	.. Green △ on green beacon		
*	*	*	*	*	*	*	*
K1801-67	-	34 58-93 S 117 57-61 E	Fl Y 3s	..	.. Yellow × on yellow beacon		
*	*	*	*	*	*	*	*
K1801-7	-	34 58-80 S 117 57-02 E	Fl Y 3s	..	.. Yellow × on yellow beacon		
*	*	*	*	*	*	*	*
K1801-72	-	34 58-84 S 117 56-98 E	Fl G 3s	..	.. Green △ on green beacon		
*	*	*	*	*	*	*	*
K1801-73	- Bayonet Head, E	34 58-84 S 117 56-89 E	Fl R 3s	..	.. Red □ on red beacon		
*	*	*	*	*	*	*	*
K1801-75	-	34 58-33 S 117 57-05 E	Fl Y 3s	..	.. Yellow × on yellow beacon		
*	*	*	*	*	*	*	*

K1801-77	-	34 58-08 S 117 57-03 E	Fl G 3s	..	.. Green $\triangle$ on green beacon	
*	*	*	*	*	*	*
K1801-78	-	34 58-08 S 117 56-90 E	Fl R 3s	..	.. Red $\square$ on red beacon	
*	*	*	*	*	*	*
K1801-8	-	34 57-76 S 117 57-00 E	Fl R 3s	..	.. Red $\square$ on red beacon	
*	*	*	*	*	*	*
K1801-82	-	34 57-65 S 117 57-01 E	Fl R 3s	..	.. Red $\square$ on red beacon	
*	*	*	*	*	*	*
K1801-83	-	34 57-58 S 117 56-97 E	Fl R 3s	..	.. Red $\square$ on red beacon	
*	*	*	*	*	*	*
K1801-84	-	34 57-54 S 117 56-92 E	Fl R 3s	..	.. Red $\square$ on red beacon	
*	*	*	*	*	*	*
K1801-85	-	34 57-52 S 117 56-90 E	Fl G 3s	..	.. Green $\triangle$ on green beacon	
*	*	*	*	*	*	*
K1801-86	-	34 57-48 S 117 57-14 E	Fl G 3s	..	.. Green $\triangle$ on green beacon	
*	*	*	*	*	*	*
K1801-89	-	34 57-16 S 117 57-23 E	Fl R 3s	..	.. Red $\square$ on red beacon	
*	*	*	*	*	*	*
K1802	KING GEORGE SOUND. ALBANY - PRINCESS ROYAL HARBOUR - King Point	35 02-10 S 117 55-10 E	Iso WRG 2s	42	11 $\triangle$ on metal column, red stripe	<i>fl</i> 0-3, G289-5°-292°(2-5°), W292°-296°(4°), R296°-298-5°(2-5°)
*	--	..	Fl W 3s	..	9	
		*	*	*	*	*
K1935	SPENCER GULF. PORT WHYALLA - Ore Jetty Dredged Channel. Ldg Lts 280-6°. Front	33 02-13 S 137 35-46 E	Iso Y 2s	15	.. White $\triangle$ on metal tripod	Neon $\triangle$. (P) 2013
*	*	*	*	*	*	*
K1935-1	- Ore Jetty Dredged Channel. Ldg Lts 280-6°. Rear. 402m from front	33 02-10 S 137 35-56 E	Iso Y 6s	..	.. White $\triangle$ on ore bin	Neon ∇ . (P) 2013
*	*	*	*	*	*	*
K1936	- Ore Jetty Dredged Channel. Ldg Lts 251-2°. Front. Ore Jetty. Head	33 02-20 S 137 35-99 E	Iso Bu 2s	..	.. White $\triangle$ on tower	(P) 2013
*	*	*	*	*	*	*
K1936-1	- Ore Jetty Dredged Channel. Ldg Lts 251-2°. Rear. 0-9M from front	33 02-35 S 137 35-46 E	Iso Bu 6s	18	.. White ∇ on tower	(P) 2013
*	*	*	*	*	*	*
K2426-2	-	38 28-01 S 145 03-20 E	Oc WRG 6s	..	.. Beacon	W336°-011°(35°), R011°-296°(285°), G296°-336°(40°) *

K2998	GREAT BARRIER REEF (COASTAL WATERS). KEPPEL BAY - Double Head. Rosslyn Bay. Jetty. Head	23 09-54 S 150 47-34 E	Fl R 2s	..	..	..	(T) 2013	*
K3066-4	GREAT BARRIER REEF (COASTAL WATERS). WHITSUNDAY PASSAGE. MOLLE CHANNEL. DAYDREAM ISLAND - Ldg Lts 240°30'. Front - - -	20 15-09 S 148 48-92 E ..	F Bu	..	5	Orange △	TE 2013	*
K3227	GREAT BARRIER REEF (COASTAL WATERS). PRINCESS CHARLOTTE BAY Remove from list; deleted							
K3230	GREAT BARRIER REEF (COASTAL WATERS). FIFE ISLAND Remove from list; deleted							
K3458-4	- Lark Patch	9 31-53 S 147 08-53 E	Fl R 3s	5	3	White pile, red bands 3	fl 0.3. Destroyed (T) 2013	*
K3909	- Sulphur Point Wharf. N End *	37 39-47 S 176 10-53 E *	2 F R(ver)	..	..	..	(P) 2013	*
K4706 FJ, F201, 4706	- Navula Point	17 53-17 S 177 14-91 E	Fl G 2s	..	5	..	TE 2013	*
K4746-5 FJ, F201, 4746-5	VANUA LEVU ISLAND. NORTH COAST. KIA ISLAND - Kia Island. N End	16 13-41 S 179 05-77 E	Fl W 5s	70	15	Metal tower 8	W109°-008°(259°)	*
K5020-1 FR, LC, 70101	- Passe de Te Ara Moana. Ldg Lts 156°. Rear. 150m from front (FR)	23 21-10 S 149 30-10 W	Iso G 4s	10	6	White beacon, red bands 10	Sync with front. TE 2013	*

UPDATES TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 20 dated 16 May 2013

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from www.ukho.gov.uk/msi. To obtain the colour versions select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-12-PAGE149_Week01_2012.pdf)

VOLUME 1, PART 2, NP 281(2), 2012/13

Published Wk 35/12

(Last Updates: Weekly Edition No. 17 dated 25 April 2013)

MARITIME RADIO STATIONS

PAGE 149, GUAM (Northern Mariana Islands - USA), GUAM (US COAST GUARD) (NRV).

Delete entry and replace by:

GUAM (US COAST GUARD) (NRV)						
13°29'N 144°50'E		MMSI 003669994	DSC VHF HF	AMVER	OBS	Diagram page 225
 +1 671 3554824			 +1 671 3554831			
			e-mail: RCCGuam@uscg.mil			
NOTE: Distress, Urgency and Safety traffic only.						
VHF						
		Ch 16 22A			H24	
RT (MF)						
		Transmits	Receives		Hours of Watch	
		2182	2182		H24	
RT (HF)						
		Transmits	Receives		Hours of Watch	
		4125	4125		HX	
		6215	6215		1930-0730 LT	
		8291	8291		HX	
		12290	12290		0730-1930 LT	
		16420	16420		HX	

[United States Coast Guard \(RSDRA2013000093859\) 20/13](#)

PAGE 225, diagram, NORTH PACIFIC, SOUTHWESTERN PART, MARITIME RADIO STATIONS, MRCC & MRSC, in approximate position 10°00'N 143°00'E, Guam & U.S. Coastguard, row 1, column 1.

Add the symbol for DSC VHF

[United States Coast Guard \(RSDRA2013000093859\) 20/13](#)

VOLUME 2, NP 282, 2013/14

Published Wk 9/13

(Last Updates: Weekly Edition No. 19 dated 9 May 2013)

RADAR BEACONS

PAGE 54, BENIN.

73005 Cotonou Landfall Lt Buoy.

Delete position and replace by: 6°19'·64N 2°27'·51E

(former update 15/13)

[French Notice 14/146/13 \(RSDRA2013000073959\) 20/13](#)

PAGE 130, below PANAMA (Pacific Coast) section.

Insert:

COLOMBIA (Pacific Coast)								
Buenaventura Safe Water Lt Buoy	3°47'·68N 77°19'·61W					B		91665

Colombian Notice 53/13 (RSDRA2013000086726) 20/13

PAGE 144, UNITED STATES (Atlantic Coast).

Insert:

Garden State Offshore Energy Lt Buoy GS	39°04'·60N 74°18'·60W					G		97015
---	-----------------------	--	--	--	--	---	--	-------

United States Coast Guard Notice 16/12200/13 (RSDRA2013000085428) 20/13

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 162, BENIN, below Benin Lt Buoy BN-20 entry.

Insert:

Cotonou Landfall Lt Buoy	6°19'·64N 2°27'·51E				Real	
--------------------------	---------------------	--	--	--	------	--

French Notice 14/146/13 (RSDRA2013000073959) 20/13

PAGE 186, IRELAND, above Ballycotton Lt entry.

Insert:

Ballybunion Lt Buoy	52°32'·53N 9°46'·94W	992501146		Real	
---------------------	----------------------	-----------	--	------	--

Commissioners of Irish Lights (RSDRA2013000087204) 20/13

PAGE 206, SICILIA (Italy), above Capo Cefalù Lt entry: Capo Scalambri Lt.

Delete entry

(former update 17/13)
UKHO 20/13

VOLUME 3, PART 2, NP 283(2), 2012/13

Published Wk 50/12
(Last Updates: Weekly Edition No. 11 dated 14 March 2013)

RADIO WEATHER SERVICES AND NAVIGATIONAL WARNINGS

PAGE 144, CUBA, HABANA (CLT).

Delete and replace by:

HABANA (CLT)				23°10′.00N 82°19′.00W
	2760	RT (MF)		
Navigational Warnings				
1003 2203	Navigational Warnings in Spanish.			
0203 1403	Artillery practice warnings in Spanish.			
NOTE: After prior announcement on 2182 kHz.				

(former update 7/13)
Cuba Notice to Mariners 63/13 (RSDRA2013000089533) 20/13

VOLUME 5, NP 285, 2012/13

Published Wk 23/12

(Last Updates: Weekly Edition No. 13 dated 28 March 2013)

SECTION 9: VHF DSC, LIST OF COAST STATIONS FOR SEA AREA A1

PAGE 116, below Ghana.

Insert new entry:

Gibraltar (UK)

Gibraltar VTS 002361001 36°08'90N 5°21'90W Operational (VTS Gibraltar)

Gibraltar VTS (RSDRA2013000080286) 20/13

SECTION 11: HF DSC, LIST OF COAST STATIONS FOR SEA AREAS A3 AND A4

PAGE 182, Guam (Northern Mariana Islands - USA).

Delete entry and replace by:

Guam (Northern Mariana Islands - USA)

Guam 003669994 4¹,6²,8¹,12³ & 16¹ MHz Operational (RSC Guam/JRCC Honolulu)

¹ HX

² Operational Hours 1930-0730 LT

³ Operational Hours 0730-1930 LT

United States Coast Guard (RSDRA2013000093859) 20/13

SECTION 13: MARITIME SAFETY INFORMATION (MSI) UNDER THE GMDSS

PAGE 208, NAVAREA COORDINATORS, NAVAREA I (United Kingdom), (Baltic Sea Sub-Area Coordinator), contact details.

Delete and replace by:

(Baltic Sea Sub-Area Coordinator)

Swedish Maritime Administration

BALTICO

SE-601 78 NORRKÖPING

Sweden

Telephone: +46 711 630685

email: msi@sjofartsverket.se

Website: <http://www.sjofartsverket.se/baltico>

Swedish Notice 445/8468/13 (RSDRA2013000085701) 20/13

SECTION 15: NAVTEX, STATIONS WITH OPERATIONAL NAVTEX FACILITIES

PAGE 280, SWEDEN.

Delete MSI SWEDEN-BALTIC contact table and replace by:

MSI SWEDEN-BALTIC [H] [J] [I] 59°17'N 18°43'E

TELEPHONE: +46 711 630685 Diagram X2

Range: 300 n miles

EMAIL: msi@sjofartsverket.se

www.sjofartsverket.se/baltico

MMSI: 002653500

Swedish Notice 445/8468/13 (RSDRA2013000085701) 20/13

SECTION 16: DISTRESS, SEARCH AND RESCUE

PAGE 378, GIBRALTAR (UK)

Delete entry and replace by:

GIBRALTAR (UK)

See diagram R5

National SAR Agency: Gibraltar VTS
Address: North Mole, Gibraltar, GX11 1AA
Tel: +350 200 46254
Fax: +350 200 77011
email: ops@port.gov.gi
Others: MMSI: 002361001

Gibraltar VTS is manned H24 and is responsible for the co-ordination of SAR operations within British Gibraltar Territorial Waters (BGTW)

Gibraltar VTS (RSDRA2013000080286) 20/13

UPDATES TO ADMIRALTY SAILING DIRECTIONS

NP44 Malacca Strait and West Coast of Sumatera Pilot (2011 Edition)

Malacca Strait – Pelabuhan Klang and Approaches — Controlling depths

189

Paragraph 6.157 1 lines 3-8 *Replace by:*

From N, in the vicinity of Pulau Angsa at the N end of Selat Klang Utara, 11.3 m (2011), to a position in the vicinity of 3°03'22N 101°20'76E.

From a position in the vicinity of 3°03'22N 101°20'76E at the N extremity of Pelabuhan Utara (North Port), 13.5 m (2011), to a position in the vicinity of 3°01'90N 101°21'25E off central Pelabuhan Utara (North Port).

From S, in the vicinity of 2°59'68N 101°20'43E at the N end of Selat Klang Selatan, 15.0 m (2011), to a position in the vicinity of 3°01'90N 101°21'25E off central Pelabuhan Utara (North Port).

Malaysian NM 69/13
(SDD 2013000 086578)

[20/13]

UPDATES TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2013/14. Weekly Edition No. 21, Dated 23 May 2013.

Last Updates: Weekly Edition No. 20, dated 16 May 2013.

K0844-3 ID, , 2673-1 *	Sasak (ID) *	0 00-10 S 99 41-55 E *	Fl W 3s *	12 *	12 White beacon 10 *	<i>fl 0-5</i> *
K0844-6 ID, , 2673-2 *	Katiagan (ID) *	0 05-70 S 99 46-00 E *	Fl W 4s *	12 *	12 White beacon 10 *	<i>fl 0-5</i> *
K0875-2 ID, , 2660-1 *	GOSONG NAMBI - Gosong Nambi (ID) *	1 44-47 S 100 30-53 E *	Fl W 4s *	12 *	12 White beacon 10 *	<i>fl 0-5</i> *
K1300 ID, , 4198	SELAT ALAS. PULAU LOMBOK - Tg Ringgit (ID)	8 52-12 S 116 35-23 E	Fl(2)W 10s	110	27 White metal framework tower 40	<i>fl 0-25, ec 2-25, fl 0-25, ec 7-25.</i> Destroyed; White beacon Fl(2)W 10s 80m 12M in situ (T) 2013 *
K1380-3	- Oil Depot (ID)	7 59-70 S 131 17-40 E	Q(4)W 8s	11	10 . .	TE 2013 *
K1630-6 ID, , 5882-1	PULAU-PULAU KAI - Karang Tegal (ID)	5 28-53 S 132 49-09 E *	Fl W 4s	14	10 White metal framework tower	<i>fl 0-5.</i> TE 2013 *
K1904 * * *	- Entrance. Ldg Lts 330°. Front - - - - *	33 43-86 S 136 58-37 E .. *	F Bu Fl W 3s *	. . *	. . Red △ on beacon * *	* *
K1904-01 * *	Renumbered; was previously K1904.1 - Entrance. Ldg Lts 330°. Rear. 180m from front *	33 43-78 S 136 58-31 E *	F Bu *	. . *	. . ▽ on beacon * *	* *
K1904-1	Remove from list; renumbered to K1904.01					
K1906 * *	- No 1 *	33 43-89 S 136 57-90 E *	Fl G 4s *	. . *	. . Green △ on green beacon *	* *
K1906-1 * *	- No 2 *	33 43-97 S 136 57-86 E *	Fl R 4s *	. . *	. . Red □ on red beacon * *	* *
K1907 * *	- No 3 *	33 43-82 S 136 57-42 E *	Fl G 2s *	. . *	. . Green △ on green beacon *	* *
K1908 * *	- Ldg Lts 277-6°. Front - - - No 6 *	33 43-85 S 136 57-10 E .. *	F Bu Fl R 2s *	. . *	. . Red □ on pile beacon * *	* *
K1908-01 * *	Renumbered; was previously K1908.1 - Ldg Lts 277-6°. Rear. 180m from front *	33 43-84 S 136 56-99 E *	F Bu *	. . *	. . Pile beacon *	* *
K1908-1	Remove from list; renumbered to K1908.01					

K1908-5	- No 5	33 43-56 S 136 57-35 E	Fl G 3s	..	.. Green △ on green beacon	
*	*	*	*	*	*	*
K1909-9	Remove from list; renumbered to K1910.011					
K1910	- Ldg Lts 023-9°. Common front	33 42-97 S 136 57-58 E	F Bu	..	.. Green △ on green beacon	Rear K1910-01
	- Ldg Lts 156-8°. Common front	..	F Bu	..		Rear K1910-011
*	- No 11	..	Fl G 2s	*	*	*
K1910-01	- Ldg Lts 023-9°. Rear. 295m from front	33 42-82 S 136 57-66 E	F Bu	..	.. Beacon	Common front K1910
*	*	*	*	*	*	*
K1910-011	Renumbered; was previously K1909.9					
	- Ldg Lts 156-8°. Rear. 186m from front	33 43-05 S 136 57-62 E	F Bu	..	.. Beacon	Common front K1910
*	*	*	*	*	*	*
K1910-1	Remove from list; renumbered to K1910.31					
K1910-14	- No 12	33 42-95 S 136 57-47 E	Fl R 5s	..	.. Red □ on red beacon	
*	*	*	*	*	*	*
K1910-15	- No 14	33 42-78 S 136 57-45 E	Fl R 2s	..	.. Red □ on red beacon	
*	*	*	*	*	*	*
K1910-2	- No 13	33 42-46 S 136 57-34 E	Fl G 4s	..	.. Green △ on green beacon	
*	*	*	*	*	*	*
K1910-3	- Ldg Lts 135-2°. Front	33 42-18 S 136 57-20 E	F Bu	..	.. Green △ on green beacon	
*	- - - No 15	..	Fl G 2s	*	*	*
K1910-31	Renumbered; was previously K1910.1					
	- Ldg Lts 135-2°. Rear. 300m from front	33 42-30 S 136 57-33 E	F Bu	..	.. Beacon	
*	*	*	*	*	*	*
K1911	- No 17	33 41-74 S 136 56-71 E	Fl G 2s	..	.. Green △ on green beacon	
*	*	*	*	*	*	*
K1911-1	- No 18	33 41-78 S 136 56-66 E	Fl R 2s	..	.. Red □ on red beacon	
*	*	*	*	*	*	*
K1912	- No 1A	33 41-94 S 136 56-10 E	Fl G 4s	..	.. Green △ on green beacon	
*	*	*	*	*	*	*
K1912-1	- No 2A	33 41-95 S 136 56-04 E	Fl R 4s	..	.. Red □ on red beacon	
*	*	*	*	*	*	*
K1914	- Cowell. Entrance	33 41-38 S 136 56-19 E	Fl R 1-5s	..	.. Red □ on red beacon	
	*	*	*		*	

K1915-1	- Cowell. Inner Breakwater. Off Head	33 41-22 S 136 55-95 E	Fl G 4s	..	..	Green Δ on green beacon	*
	*	*	*				
K2790	PORT MACQUARIE - Southern Breakwater	31 25-61 S 152 54-87 E	Oc WRG 4s	..	..	..	W244°-249°(5°), R249°-269°(20°), G239°-244°(5°)
							*
K2850-7	- Gold Coast Bridge. Centre	27 58-61 S 153 25-28 E	F Bu	..	..	..	1 each side. TE 2013
							*
K3144-55	- Mourilyan Harbour	17 36-08 S 146 07-28 E	F G				
*	*	*	*	*	*	*	*
K4734	VITI LEVU ISLAND. EAST COAST. GAU ISLAND - Siguma Harbour. Ldg Lts FJ, F201, 4734 138°. Front	17 56-86 S 179 16-35 E	F Bu	3	5	Orange Δ on mast 6	*

UPDATES TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 21 dated 23 May 2013

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from www.ukho.gov.uk/msi. To obtain the colour versions select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-12-PAGE149_Week01_2012.pdf)

VOLUME 2, NP 282, 2013/14

Published Wk 9/13
(Last Updates: Weekly Edition No. 20 dated 16 May 2013)

RADAR BEACONS

PAGE 66, UNITED ARAB EMIRATES (Persian Gulf Coast).

77140 Dalmā Lt Buoy.

Delete position and replace by: 24°32'·82N 52°27'·96E

[ADNOC - PPA Notice PPA/003/01/05/13 \(RSDRA2013000096191\) 21/13](#)

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 190, KOREA, SOUTH, above Bakgeunyeo Lt Bn entry.

Insert:

Baekgeum Lt	34°29'·79N 127°49'·58E	994402913		Real	
Baekseo Lt	34°37'·88N 127°59'·62E	994403108		Real	

[Korean Notices 18/315/13 & 18/313/13 \(RSDRA2013000095760\) 21/13](#)

PAGE 192, KOREA, SOUTH, below Daechon Hang North Breakwater Lt entry.

Insert:

Daedan Lt	34°39'·65N 127°48'·37E	994402944		Real	
Daedo Lt	34°40'·56N 127°56'·94E	994403107		Real	

Korean Notices 18/314/13 & 18/313/13 (RSDRA2013000095760) 21/13

PAGE 194, KOREA, SOUTH, below Dokgedo Lt entry.

Insert:

Dolsando Lt	34°42'·18N 127°47'·30E	994402912		Real	
Dolsan Hang East Breakwater Lt	34°36'·79N 127°43'·34E	994402948		Real	

(former update 15/13)

Korean Notice 18/317/13 (RSDRA2013000095760) 21/13

PAGE 194, KOREA, SOUTH, below Donseo Lt Bn entry.

Insert:

Dunpyeongtan Lt Bn	34°47'·33N 127°45'·97E	994402918		Real	
--------------------	------------------------	-----------	--	------	--

(former update 17/13)

Korean Notice 18/314/13 (RSDRA2013000095760) 21/13

PAGE 194, KOREA, SOUTH, below Ganseo Lt Bn entry.

Insert:

Ganyeoam Lt	34°17'·27N 127°51'·29E	994402942		Real	
-------------	------------------------	-----------	--	------	--

Korean Notice 18/316/13 (RSDRA2013000095760) 21/13

PAGE 194, KOREA, SOUTH, above Gudo Lt entry.

Insert:

Goseo Lt	34°32'·62N 127°38'·89E	994402956		Real	
----------	------------------------	-----------	--	------	--

(former update 17/13)

Korean Notice 18/313/13 (RSDRA2013000095760) 21/13

PAGE 194, KOREA, SOUTH, below Gukdong Hang Lt entry.

Insert:

Gumongam Lt	34°28'·38N 127°45'·96E	994402911		Real	
-------------	------------------------	-----------	--	------	--

(former update 19/13)

Korean Notice 18/315/13 (RSDRA2013000095760) 21/13

PAGE 194, KOREA, SOUTH, below Hajodo Lt entry.

Insert:

Hamgumi Lt Bn	34°32'·34N 127°41'·81E	994402916		Real	
---------------	------------------------	-----------	--	------	--

(former update 15/13)

Korean Notice 18/315/13 (RSDRA2013000095760) 21/13

PAGE 196, KOREA, SOUTH, below Jakdo Lt entry.

Insert:

Jakgeum Hang Lt	34°35'·50N 127°45'·93E	994402915		Real	
-----------------	------------------------	-----------	--	------	--

(former update 19/13)

Korean Notice 18/317/13 (RSDRA2013000095760) 21/13

PAGE 196, KOREA, SOUTH, below Nokdong Hang Lt entry.

Insert:

Nokdong Hang South Breakwater Lt	34°31′.24N 127°08′.40E	994402940		Real	
----------------------------------	------------------------	-----------	--	------	--

(former update 19/13)

Korean Notice 18/319/13 (RSDRA2013000095760) 21/13**PAGE 196, KOREA, SOUTH, above Oebeomhyeonseo Lt Bn entry.**

Insert:

Odongdo Lt	34°44′.65N 127°46′.06E	994403321		Real	
------------	------------------------	-----------	--	------	--

Korean Notice 18/314/13 (RSDRA2013000095760) 21/13**PAGE 198, KOREA, SOUTH, below Samgilpohang Breakwater Lt entry.**

Insert:

Samyeo Lt Bn	34°47′.91N 127°48′.95E	994402928		Real	
--------------	------------------------	-----------	--	------	--

Korean Notice 18/314/13 (RSDRA2013000095760) 21/13**PAGE 198, KOREA, SOUTH, below Sohenggyeongdo Lt entry.**

Insert:

Sohoenggando Lt Bn	34°33′.79N 127°45′.96E	994402945		Real	
--------------------	------------------------	-----------	--	------	--

(former update 9/13)

Korean Notice 18/315/13 (RSDRA2013000095760) 21/13**PAGE 198, KOREA, SOUTH, above Udo Lt entry.**

Insert:

Uam Lt Bn	34°43′.03N 127°47′.87E	994402920		Real	
-----------	------------------------	-----------	--	------	--

(former update 11/13)

Korean Notice 18/314/13 (RSDRA2013000095760) 21/13**PAGE 198, KOREA, SOUTH, above Yeocho Lt Bn entry.**

Insert:

Yangam Lt Bn	34°44′.60N 127°46′.66E	994402919		Real	
--------------	------------------------	-----------	--	------	--

(former update 19/13)

Korean Notice 18/314/13 (RSDRA2013000095760) 21/13**PAGE 198, KOREA, SOUTH, above Yeondo Lt entry.**

Insert:

Yeoho Hang Lt Buoy	34°39′.64N 127°28′.61E	994402950		Real	
--------------------	------------------------	-----------	--	------	--

(former update 9/13)

Korean Notice 18/318/13 (RSDRA2013000095760) 21/13**PAGE 198, KOREA, SOUTH, above Yeosugu Hang Lt entry.**

Insert:

Yeosu Gu Hang Breakwater Lt	34°44′.19N 127°44′.82E	994402914		Real	
-----------------------------	------------------------	-----------	--	------	--

(former update 19/13)

Korean Notice 18/314/13 (RSDRA2013000095760) 21/13

Yeosu Haeman Lt Buoy A	34°35'·68N 127°56'·72E	994402910		Real	
Yeosu Haeman Lt Buoy B	34°41'·75N 127°53'·20E	994402900		Real	
Yeosu Haeman Lt Buoy C	34°43'·25N 127°50'·20E	994402911		Real	
Yeosu Haeman Lt Buoy DW 1	34°45'·62N 127°49'·10E	994401540		Real	
Yeosu Haeman Lt Buoy DW 2	34°45'·68N 127°49'·47E	994401541		Real	
Yeosu Haeman Lt Buoy DW 7	34°50'·00N 127°47'·88E	994401542		Real	
Yeosu Haeman Lt Buoy DW 8	34°50'·00N 127°48'·27E	994401543		Real	
Yeosu Lt Buoy	34°38'·20N 127°56'·20E	994403008		Real	

Korean Notices 18/313/13 & 18/314/13 (RSDRA2013000095760) 21/13

Bajo Pego Lt Buoy	43°20'·78N 8°33'·03W			Real	
-------------------	----------------------	--	--	------	--

Spanish Notice 16/03689/13 (RSDRA2013000088131) 21/13

Punta Langosteira Breakwater Lt Bn	43°20'·75N 8°32'·00W			Real	
------------------------------------	----------------------	--	--	------	--

Spanish Notice 16/03686/13 (RSDRA2013000088131) 21/13

VOLUME 3, PART 2, NP 283(2), 2012/13
Published Wk 50/12
(Last Updates: Weekly Edition No. 20 dated 16 May 2013)

RADIO-FACSIMILE

MAGALLANES (CBM)				53°09'·93S 70°54'·26W	
	4228				
	8677				
DIAGRAM: page 46					
Map Areas					
10°S.120°W 10°S.50°W 80°S.130°W 80°S.30°W					
Schedule					
	48 hour surface forecast	0350		120/576	
	Satellite image	0405(24)			
	CBV / CBM schedule	1550			
	24 hour surface forecast	1605			
	Satellite image	1620(12)			
	Surface analysis	1730(12)			
	Satellite image	1745(15)			
	24 hour wave forecast	2005			
	Satellite image	2020(18)			
	36 hour surface forecast	2240			
	Surface analysis	2255(18)			
	24 hour wind forecast	2310			

Chile Navarea XV Warning 38/13 (RSDRA2013000091517) 21/13

PAGE 73, VALPARAÍSO PLAYA ANCHA (CBV).
Delete entry and replace by:

VALPARAÍSO PLAYA ANCHA (CBV)			33°01'·24S 71°38'·55W	
	4228			
	8677			
	17146-5			
DIAGRAM: page 46				
Map Areas				
10°S.120°W 10°S.50°W 80°S.130°W 80°S.30°W				
Schedule				
	CBV / CBM schedule	1100	120/576	
	12 hour surface analysis	1115(06)		
	Satellite image	1130(09)		
	24 hour surface forecast	1630		
	Satellite image	1645(15)		
	Surface analysis	1915(12)		
	Satellite image	1930(18)		
	24 hour wave forecast	2200		
	Surface analysis	2215(18)		
	24 hour wind forecast	2230		
	48 hour surface forecast	2310		
	Satellite image	2325(21)		

Chile Navarea XV Warning 37/13 (RSDRA2013000091517) 21/13

VOLUME 6, PART 4, NP 286(4), 2012/13
Published Wk 31/12

(Last Updates: Weekly Edition No. 19 dated 9 May 2013)

PAGE 388, UNITED ARAB EMIRATES, KHALIFA PORT (MĪNĀ KHALĪFA), Pilots, section (6).
Delete and replace by:

(6) Pilot boards in position 24°57'·10N 54°33'·90E.

(former update 50/12)
ADPC Notice 4/13. (RSDRA2013000096205). 21/13

UPDATES TO ADMIRALTY SAILING DIRECTIONS

NP34 Indonesia Pilot Volume 2 (2012 Edition)

Indonesia – Java Sea – Through Routes — Directions; buoyage

69

Paragraph 4.40 *2* line 3 *For* (starboard hand) *Read*
(isolated danger)

70

Paragraph 4.44 *1* line 10 *For* a buoy *Read* a buoy (isolated
danger)

82

Paragraph 4.150 *3* line 1 *Replace by*:

3 A dangerous wreck (6°44'·22S 114°17'·00E) marked
by a buoy (isolated danger) and an...

90

Paragraph 4.228 *1* line 3 *For* (starboard hand) *Read*
(isolated danger)

BA Chart 3726 [21/13]

Indonesia – Approaches to Linkgas — Directions; buoyage

290

Paragraph 12.147 *2* lines 3 and 4 *Replace by*:

...marked by a buoy (isolated danger) moored to the
S.

BA Chart 1852 [21/13]

NP44 Malacca Strait and West Coast of Sumatera Pilot (2011 Edition)

Singapore – West Johor Strait – North part — Directions; wreck

286

After Paragraph 9.57 *1* line 8 *Insert*:

Clear of a 13·5 m wreck (1°23'·04N 103°39'·08E),
thence:

Singapore Notice 4/35/2013
(*SDD 2013000 093457*)

[21/13]