

UPDATES TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2012/13. Weekly Edition No. 6, Dated 07 February 2013.
Last Updates: Weekly Edition No. 5, dated 31 January 2013.

DAMPIER ARCHIPELAGO. PORT OF DAMPIER. MERMAID SOUND								
K1691-8604	- Pluto LNG Channel. P6	20 32-68 S 116 42-87 E	Fl R 3s	..	..	Red □ on red beacon		
*	*	*	*	*	*	*	*	
K1691-861	- Pluto LNG Channel. Ldg Lts 195-1°. Front. P5	20 32-91 S 116 42-65 E	AlFl GBuBu 6s	13	G 7 Bu 7	Orange △ on beacon	G fl 0-5, ec 0-5, Bu fl 0-5, ec 0-5, Bu fl 3-5, ec 0-5. Bu190-85°-199-35°(8-5°). Sync with K1691-863 and K1691-862	
*	*	*	*	*	*	*	*	
K1691-8615	Remove from list; deleted							
K1691-862	- Pluto LNG Channel. Ldg Lts 195-1°. Common rear. PR1	20 33-23 S 116 42-56 E	AlFl WBuBu 6s	24	W 7 Bu 7	Orange ▽ on beacon	W fl 0-5, ec 0-5, Bu fl 0-5, ec 0-5, Bu fl 3-5, ec 0-5. Bu190-85°-199-35°(8-5°). Sync with front K1691-861	
	- - Ldg Lts 320-8°. Common rear. PR1	..	AlFl WBuBu 6s	24	W 7 Bu 7	..	W fl 0-5, ec 0-5, Bu fl 0-5, ec 0-5, Bu fl 3-5, ec 0-5. Bu316-55°-325-05°(8-5°). Sync with front K1691-863	
	*		*	*	*	*	*	
K1691-863	- Pluto LNG Channel. Ldg Lts 320-8°. Front. P7	20 33-49 S 116 42-78 E	AlFl GBuBu 6s	13	G 7 Bu 7	Orange △ on beacon	G fl 0-5, ec 0-5, Bu fl 0-5, ec 0-5, Bu fl 3-5, ec 0-5. Bu316-55°-325-05°(8-5°). Sync with K1691-861 and K1691-862	
*	*	*	*	*	*	*	*	
K1879-2	SPENCER GULF. EYRE PENINSULA. BOSTON BAY - Entrance				..	W 6 R 4 *	W260°-269°(9°), R269°-260°(351°)	
		34 39-75 S 135 54-73 E	Fl WR 4s					
K1879-3	- No 1	34 39-78 S 135 54-38 E	Q WG	..	W 6 G 4 *	Green △ on beacon	W259°-268°(9°), G268°-259°(351°)	
						*		
K3742-5	HAURAKI GULF Remove from list; deleted							
K4010-1	COOK STRAIT. WELLINGTON HARBOUR (PORT NICHOLSON) - Main Entrance. Ldg Lts 016°24'. Rear. 1-34M from front. Hope Shoal				17	W22 R 8 G11	Orange and yellow stripes on seaward side of round metal structure	W(Intens)014°-019°(5°), W019°-123°(104°), W(Intens)123°-124°(1°), G(Intens)124°-133°(9°), G133°-183°(50°), W183°-218°(35°), R218°-357°(139°), W357°-014°(17°) Intens 014°-019°(5°) on request
	-----	..	By day Iso W 4s	..	4	..	*	
K4018	- Point Halswell	41 17-04 S 174 49-57 E	Fl W 3s	8	15	Black and white chequered concrete tower 6	fl 0-3. W070°-294°(224°)	
							*	
K4746-5	VANUA LEVU ISLAND. NORTH COAST. KIA ISLAND - Kia Island. N End				70	15	Metal tower 8	W109°-008°(259°). TE 2013
FJ, F201, 4746-5		16 13-41 S 179 05-77 E	Fl W 5s				*	

K4758 FJ, F201, 4758	SOUTHERN LAU GROUP. TOTOYA ISLAND - Totoya Island . SW Point	18 59-97 S 179 52-94 W	Fl(3)W 10s	76	20 Framework tower 15	<i>(fl 0-5, ec 2) x 2, fl 0-5, ec 4-5.</i> W251°-164°(273°). TE 2013
		*				*
K4759 FJ, F201, 4759	SOUTHERN LAU GROUP. VATOA (TURTLE) ISLAND - Vatoa Island	19 48-41 S 178 14-40 W	Fl W 5s	70	21 Framework tower 30	W300°-325°(25°), W340°-005°(25°). Partially obscured by trees. TE 2013
		*				*
K4858	ÉFATÉ ISLAND - ÉrétoKa Island	17 38-23 S 168 09-28 E	Fl(2)W 10s	96	8 Pylon 20	<i>fl 0-5, ec 1, fl 0-5, ec 8.</i> TE 2013
						*
K4862	EPI ISLAND - Cape Foreland	16 41-42 S 168 07-32 E	Fl(4)W 20s	207	10 White metal framework tower 20	<i>(fl 0-5, ec 1) x 3, fl 0-5, ec 15.</i> TE 2013
						*
K4873	MALAKULA ISLAND - Uripiv Islet	16 04-18 S 167 27-48 E	Fl(3)W 10s	12	8 White pylon 6	TE 2013
						*
K4877	ESPIRITU SANTO ISLAND. TUTUBA ISLAND - Tutuba Island	15 33-89 S 167 17-88 E	LFl W 5s	24	7 White pylon 21	<i>fl 2.</i> TE 2013
		*				*
K4880	ESPIRITU SANTO ISLAND - Palikulo. Naoréuré Point	15 28-39 S 167 15-35 E	Fl(3)W 15s	23	14 White pylon 21	<i>(fl 0-5, ec 1) x 2, fl 0-5, ec 11-5.</i> TE 2013
		*				*
K4880-6	- Luganville. Aoré Island. Chapuis Point	15 31-89 S 167 12-83 E	Fl(2)WRG 10s	24	W 8 Pylon R 6 20 G 6	<i>fl 0-5, ec 1-5, fl 0-5, ec 7-5.</i> W262°-270°(8°), G270°-321°(51°), W321°-325°(4°), R325°-262°(297°)
						*

UPDATES TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 6 dated 7 February 2013

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from www.ukho.gov.uk/msi. To obtain the colour versions select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-12-PAGE149_Week01_2012.pdf)

VOLUME 2, NP 282, 2012/13

Published Wk 11/12

(Last Updates: Weekly Edition No. 5 dated 31 January 2013)

RADAR BEACONS

PAGE 144, UNITED STATES (Atlantic Coast).

97140 Sandy Hook Channel Front Ldg Lt.

Delete position and replace by: 40°29'·15N 73°59'·35W

[United States Notice 12324/13 \(RSDRA2013000014276\)](#) 6/13

PAGE 144, UNITED STATES (Atlantic Coast).

97220 Montauk Point Lt Buoy MP.

Delete entry

[United States Notice 12300/13 \(RSDRA2013000014276\)](#) 6/13

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 196, NORWAY, Yme Oil Field Vessel Nesborg.

Delete entry and replace by:

Yme Oil Rig (4 n miles N)	57°52'·93N 4°32'·04E	992576101		Virtual	
Yme Oil Rig (4 n miles S)	57°44'·93N 4°32'·04E	992576102		Virtual	

(former update 4/13)

[Talisman Energy Norge AS \(RSDRA2013000014644\)](#) 6/13

LEGAL TIME

PAGE 241, Brazil, zones 4 & 5.

Delete and replace by:

Zone 4 Espírito Santo, Paraná, Rio de Janeiro, Rio Grand do Sul, Santa Catarina and São Paulo	+3	+2	Third Sunday in October 0000h	16 February 2013 2400h 15 February 2014 2400h
Zone 5 Mato Grosso and Mato Grosso do Sul	+4	+3	Third Sunday in October 0000h	16 February 2013 2400h 15 February 2014 2400h

[OAG Worldwide Limited \(RSDRA2012000237983\)](#) 6/13

UPDATES TO ADMIRALTY SAILING DIRECTIONS

Nil.

UPDATES TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2012/13. Weekly Edition No. 7, Dated 14 February 2013.

Last Updates: Weekly Edition No. 6, dated 07 February 2013.

K2053-1	GULF SAINT VINCENT. ADELAIDE. PORT ADELAIDE - Outer Harbour Outward. 34 46-71 S Fl Bu 4s ▽ on beacon Ldg Lts 281-3°. Rear. 350m 138 21-59 E from front ----- .. F Bu	*
K3454-5	MILNE BAY. KAWANASAU (CHINA) STRAIT. NORTH ENTRANCE - Samarai Island. Kiapara 10 36-67 S Q G Green △ on green 150 39-60 E beacon	*
K3510-53	BISMARCK ARCHIPELAGO. NEW IRELAND - Edmago Island. E 2 37-02 S Fl R 2-5s Red □ on red beacon 150 44-88 E	*

UPDATES TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 7 dated 14 February 2013

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from www.ukho.gov.uk/msi. To obtain the colour versions select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-12-PAGE149_Week01_2012.pdf)

VOLUME 2, NP 282, 2012/13

Published Wk 11/12

(Last Updates: Weekly Edition No. 6 dated 7 February 2013)

RADAR BEACONS

PAGE 28, POLAND.

Insert:

Petrobaltic Platform	55°24'00N 18°43'30E					U		57650
-----------------------------	---------------------	--	--	--	--	----------	--	--------------

[Polish Notice 3/2013 LL Vol 1 \(RSDRA2013000018424\)](#) 7/13

PAGE 28, POLAND.

57670 Port Pólnocny Lt Buoy P1.

Delete entry

[Polish Notice 3/33/13 \(RSDRA2013000018424\)](#) 7/13

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 204, UNITED KINGDOM (Northern Ireland), above Belfast Fairway Lt Buoy entry.

Insert:

Ardtole Bn	54°15'67N 5°36'03W	992356007		Synthetic	
-------------------	--------------------	-----------	--	-----------	--

(former updates 31/12 & 42/12)

[Commissioners of Irish Lights \(RSDRA2013000018663\)](#) 7/13

VOLUME 3, PART 2, NP 283(2), 2012/13

Published Wk 50/12
(Last Updates: Weekly Edition No. 52 dated 27 December 2012)

RADIO WEATHER SERVICES AND NAVIGATIONAL WARNINGS**PAGE 144, CUBA, HABANA.**

Delete and replace by:

HABANA (CLT)				23°10′·00N 82°19′·00W	
	2760	RT (MF)			
Navigational Warnings					
0203 1103 1403 2303	Navigational Warnings in Spanish. Artillery firing exercise warnings in Spanish.				
NOTE: After prior announcement on 2182 kHz.					

Cuba Notice to Mariners 7/13 (RSDRA2012000262279) 7/13

PAGE 188, PERU.

Insert below NAVTEX section:

LOCAL COASTAL STATIONS THAT BROADCAST SPECIAL WEATHER WARNINGS			
Station	Call Sign	VHF Channel	Position
Callao	OBC3	Ch 16	12°04'·34S 77°10'·13W
Chimbote	OBZ3	Ch 16	9°04'·82S 78°37'·43W
Huacho		Ch 16	11°06'·30S 77°37'·02W
Ilo		Ch 16	17°38'·68S 71°20'·20W
Mollendo	OBF4	Ch 16	17°01'·06S 72°01'·34W
Paita	OBY2	Chs 12, 16	5°05'·29S 81°06'·39W
Pimentel	OBH2	Ch 16	6°56'·70S 79°51'·51W
Pisco		Ch 16	13°42'·70S 76°12'·97W
Salaverry	OBR3	Ch 16	8°13'·00S 78°59'·00W
Talara	OBT2	Ch 16	4°35'·00S 81°17'·00W
Zorritos	OBV2	Ch 16	3°40'·17S 80°39'·54W
Navigational Warnings			
On receipt	Special weather warnings.		

Peru, MSI Self Assessment NAVAREA XVI (RSDRA2013000018318) 7/13

VOLUME 5, NP 285, 2012/13

Published Wk 23/12
(Last Updates: Weekly Edition No. 3 dated 17 January 2013)

SECTION 11: HF DSC, LIST OF COAST STATIONS FOR SEA AREAS A3 AND A4**PAGE 183, below Romania.**

Insert new entry:

Russia (Baltic Sea Coast)

Sankt Peterburg 002733700 4 MHz Operational (MRCC Sankt Peturburg)

Russian Annual Notice (RSDRA2013000004710) 7/13

Insert in approximate position 59°53'N 29°56'E:

●Sankt Peterburg 002733700

(former updates 29/12 & 47/12)

Russian Annual Notice (RSDRA2013000004710) 7/13

UPDATES TO ADMIRALTY SAILING DIRECTIONS

NP36 Indonesia Pilot Volume 1 (2012 Edition)

Selat Riau – Through Route – Directions — Racons

174

After Paragraph 10.72 4 line 6 *Insert*:

Other aids to navigation

10.72a

1 Racons

Pangkil Light (0°49'·00N 104°21'·00E).
Lobam Kecil Light (0°58'·90N 104°13'·50E).
Karang Galang Light (1°09'·50N 104°11'·30E).

Selat Durian – Directions — Racons

192

After Paragraph 11.62 1 line 7 *Add*:

Rukan Utara Light (0°37'·45N 103°45'·40E).
Pelangkat Light (0°45'·00N 103°35'·00E).

DG SeaComm

(SDD 2012000 231195)

[07/13]

NP44 Malacca Strait and West Coast of Sumatera Pilot (2011 Edition)

Malacca Strait - Gosong Raleigh to Mudah Selatan — Directions

69

Paragraph 2.82 2 *Replace by*:

- 2 Disturbed water and eddies may be encountered in this section of the traffic lane. The deep-water route (2.84) rejoins the main ESE traffic lane at a shallow angle. Thence:

Paragraph 2.84 1 lines 6-7 *Replace by*:

...SE traffic lane (2.82) at a shallow angle.

Malaysian Notice 11/178/12

(SDD 2013000 014598)

[07/13]

Tanjung Babi to the South China Sea – Directions — Racons

226

After Paragraph 7.60 1 line 3 *Add*:

Karang Galang Light (1°09'·50N 104°11'·30E).
Lobam Kecil Light (0°58'·90N 104°13'·50E).

DG Sea Comm

(SDD 2012000 231195)

[07/13]

West Johor Strait - South part — Directions

285

Paragraph 9.44 3 lines 1-4 *Delete*

Paragraph 9.44 6 lines 1-2 *Delete*

Maritime and Port Authority of Singapore

(SDD 2013000 006284)

[07/13]