

UPDATES TO ADMIRALTY LIST OF LIGHTS AND FOG SIGNALS

Vol K Edition 2013/14. Weekly Edition No. 12, Dated 21 March 2013.
Last Updates: Weekly Edition No. 11, dated 14 March 2013.

K1771-9	PORT OF FREMANTLE. OWEN ANCHORAGE						
	- Port Coogee Marina. N	32 06-06 S	Fl R 5s				
*	Breakwater. Head	115 45-47 E		*	*	*	*
K1771-92	- Port Coogee Marina. S	32 06-06 S	Fl G 5s				
	Breakwater. Head	115 45-39 E		*	*	*	*
K1833-25	DENIAL BAY. YATALA CHANNEL						
	- Daphne Rock	32 09-53 S	Fl G 3s	..	..	Green Δ on beacon	
*		133 38-45 E		*	*	*	*
K1879-9	SPENCER GULF. EYRE PENINSULA. BOSTON BAY						
	- No 6	34 41-91 S	Fl R 2s				
		135 52-74 E		*			*
K1880	SPENCER GULF. EYRE PENINSULA. BOSTON BAY. PORT LINCOLN. BOSTON ISLAND						
	- Point Fanny	34 43-98 S	Fl W 1-5s	8	4	Metal framework tower	
		135 55-72 E			*		
K1881-4	SPENCER GULF. EYRE PENINSULA. BOSTON BAY. PORT LINCOLN						
	- S Side	34 45-12 S	Q R	..	3	Red □ on beacon	
		135 53-87 E					*
K2055-6	GULF SAINT VINCENT. ADELAIDE. PORT ADELAIDE						
	- No 2 Outward Ldg Lts	34 47-58 S	F Bu	..	..	Orange Δ on beacon	Vis 7° each side of leading line.
	257-7°. Front	138 26-64 E					A dull glow is also visible from 7° to 90° each side of leading line
	- - - No 11	..	Fl G 2s				
			*				
K2055-81	- No 1 Inward Ldg Lts	34 47-62 S	F Bu	..	..	Orange ▽ on beacon	Vis 7° each side of leading line.
	101-3°. Common rear	138 27-18 E					Faint dull glow 011-3°-093-3°(82°).
	- No 3 Outward Ldg Lts	..	F Bu	..	..	..	Faint dull glow 108-3°-191-3°(83°).
	240-4°. Common rear						Front K2055-8 F Bu
	-	..	Fl W 4s				Vis 7° each side of leading line.
		*	*				Faint dull glow 150-4°-223-4°(73°).
K2055-82	- No 15	34 47-50 S	Fl G 2s	..	..	Orange Δ on beacon	Faint dull glow 247-4°-330-4°(83°).
	- No 3 Outward Ldg Lts	..	F Bu	..	..	..	Front K2055-82 F Bu
	240-4°. Front						
			*				
K2057	- Southern Revetment	34 47-34 S	Q W	5	..	Orange Δ on beacon	Vis 7° each side of leading line.
	Mound	138 27-96 E					Faint dull glow 337-7°-070-7°(93°).
	- No 2 Inward Ldg Lts	..	F Bu	7	..	..	Faint dull glow 084-7°-167-7°(83°).
	077-7°. Front						Common rear K2057-1
			*				
K2059-5	- No 14	34 46-79 S	Q R				
		138 28-64 E		*			

K2059-53	- No 16	34 46-53 S 138 28-70 E	Fl R 2s *	..	.. Red □ on beacon *
K2059-6	- No 18A	34 46-18 S 138 29-02 E	Fl R 2s *	..	.. Red □ on beacon
K2059-61	- No 18B	34 46-06 S 138 29-04 E *	Fl R 2s *	..	.. Red □ on beacon
K2059-7	- No 18C	34 45-96 S 138 29-12 E *	Q R *	..	.. Red □ on beacon
K2062-4	- No 24	34 45-62 S 138 30-07 E *	Q R *	..	.. Red □ on beacon
K2062-5	- No 26. Rear Swinging Head	34 45-62 S 138 30-36 E	Fl R 2s *	..	.. Red □ on beacon *
K2062-7	- No 27	34 45-72 S 138 30-31 E	Fl G 2s *	..	.. Green △ on beacon
K2063-4	- No 28	34 45-66 S 138 30-57 E	Q R *	..	.. Red □ on beacon
K2064	- No 31	34 45-95 S 138 30-86 E *	Fl G 2s *	..	.. Green △ on beacon
K2064-2	- No 30	34 45-88 S 138 30-96 E	Fl R 2s *	..	.. Red □ on beacon
K2065	- No 32 - No 10 Outward Ldg Lts 011-1°, Front	34 46-13 S 138 31-12 E ..	Q R F Bu		.. Orange △ on beacon Vis 7° each side of leading line. Faint dull glow 281-07°-004-07°(83°). Faint dull glow 018-07°-101-07°(83°). A dull glow is also visible from 7° to 90° each side of leading line. Rear K2065-1
	*		*		
K2065-5	- No 35	34 46-42 S 138 30-99 E *	Fl G 2s *	..	.. Green △ on beacon
K2065-6	- No 34	34 46-41 S 138 31-11 E	Fl R 2s *	..	.. Red □ on beacon
K2067	- No 37	34 46-68 S 138 30-92 E	Fl G 2s *	..	.. Green △ on beacon
K2068-4	- No 36	34 47-07 S 138 30-95 E *	Fl R 2s *	..	.. Red □ on beacon
K2069	- No 39	34 47-40 S 138 30-76 E	Q G *	..	.. Green △ on beacon

K2069-5	- No 38	34 47-66 S 138 30-81 E *	Fl R 2s *	..	..	Red □ on beacon	
K2074-7	- No 42	34 48-52 S 138 30-88 E *	Fl R 2s *	..	..	Red □ on beacon	
K2074-75	- No 41	34 48-52 S 138 30-76 E *	Fl G 2s *	..	..	Green △ on beacon	
K2508	CORNER INLET - Lewis Channel. No 3	38 44-45 S 146 25-68 E *	Fl G 4s *	5	2	Green △ on beacon	<i>fl 0.5</i>
K2510	- Lewis Channel. E Side. No 5	38 44-05 S 146 25-59 E *	Fl G 4s *	6	2		
K2512	- Lewis Channel. W Side. No 6	38 43-92 S 146 25-34 E *	Fl R 4s *	4	3	□ on red beacon	<i>fl 0.5</i>
K2513	- No 9	38 43-62 S 146 25-49 E *	Fl G 4s *	*	*	*	*
K2515	- Lewis Channel. SE Side. No 11	38 43-22 S 146 25-76 E *	Fl G 4s *	..	..	Green △ on green beacon	
K2516	- Lewis Channel. NW Side. No 10	38 43-02 S 146 25-74 E *	Fl R 4s *	5	2	Framework tower on piles	
K2517	- Lewis Channel. SE Side. No 13	38 42-98 S 146 25-95 E *	Fl G 4s *	..	..	Green △ on green beacon	
K2517-5	- Lewis Channel. SE Side. No 15	38 42-78 S 146 26-18 E *	Fl G 4s *	..	..	Green △ on green beacon	
K2520	- Lewis Channel. N Side. No 14	38 42-37 S 146 26-72 E *	Fl R 4s *	4	3	□ on red beacon	
K2520-5	- Lewis Channel. S Side. No 19	38 42-47 S 146 26-77 E *	Fl G 4s *	..	..	Green △ on green beacon	
K2521	- Lewis Channel. No 17	38 42-54 S 146 26-51 E *	Fl G 4s *	..	..	△ on green beacon	
K2523-5	- Lewis Channel. N Side. No 16	38 42-30 S 146 27-16 E *	Fl R 4s *	..	..	Red □ on red beacon	
K2523-7	- Lewis Channel. S Side. No 21	38 42-35 S 146 27-17 E *	Fl G 4s *	..	..	Green △ on green beacon	*

K2523-8	- Lewis Channel. N Side. No 18	38 42-31 S 146 27-43 E	Fl R 4s *	..	..	Red □ on red beacon	
K2523-85	- Lewis Channel. S Side. No 23	38 42-36 S 146 27-55 E	Fl G 4s *	..	..	Green △ on green beacon	
K2523-9	- Lewis Channel. N Side. No 20	38 42-28 S 146 27-61 E	Fl R 4s *	..	..	Red □ on red beacon	
K4243	COOK STRAIT. MAHAU SOUND - Havelock Harbour. No 1	41 14-83 S 173 50-77 E	Fl G 2s *	2	3 ..		<i>fl 0-5</i>
	*	*	*			*	
K4243-15	- Havelock Harbour. No 5	41 15-36 S 173 49-93 E	Fl G 4s *	..	3 ..		<i>fl 0-5</i>
*	*	*	*	*	*	*	*
K4243-17	- Havelock Harbour. No 7	41 15-51 S 173 49-13 E	Fl G 5s *	2	3	Green pile beacon	<i>fl 0-5</i>
*	*	*	*	*	*	*	*
K4243-27	- Havelock Harbour. No 4	41 15-60 S 173 47-81 E	Fl(2)R 4s *	..	3 ..		<i>fl 0-5, ec 1, fl 0-5, ec 2</i>
*	*	*	*	*	*	*	*
K4243-44	- Havelock Harbour. No 6	41 15-76 S 173 47-11 E	Q(3)R 5s *	..	3 ..		<i>(fl 0-5, ec 0-5) x 2, fl 0-5, ec 2-5</i>
*	*	*	*	*	*	*	*
K4243-48	- Havelock Harbour. No 11	41 15-70 S 173 47-00 E	Fl G 3s *	..	3		
*	*	*	*	*	*	*	*
K4243-504	- Havelock Harbour. No 10	41 15-79 S 173 46-61 E	Fl R 3s *	1	3	Red wooden pile beacon	
	*		*		*	*	
K4243-506	- Havelock Harbour. No 12	41 15-92 S 173 46-46 E	Fl R 3s *	2	3	Red wooden pile beacon	
	*	*	*		*	*	
K4243-508	- Havelock Harbour. No 14	41 15-95 S 173 46-37 E	Fl R 3s *	1	3	Red wooden pile beacon	
	*		*		*	*	
K4243-517	- Havelock Harbour. No 13	41 15-95 S 173 46-27 E	Fl G 3s *	..	3		
*	*	*	*	*	*	*	*
K4710-5	VITI LEVU ISLAND. NORTH-WEST COAST. LAUTOKA HARBOUR - Pinder Reef. S	17 36-26 S 177 24-19 E	Fl W 8s	6	6	White structure, black stripe	TE 2013
FJ, F201, 4710-5							*
K4969-7	ÎLES SOUS-LE-VENT. ÎLE DE HUAHINE - Passe Farerea. Ldg Lts	16 44-86 S 150 59-05 W	Iso G 4s	7	6	Green metal pylon, white top	TE 2013
FR, LC, 66600	262-4°. Front. Vaihi (FR)				8		*

UPDATES TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 12 dated 21 March 2013

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from www.ukho.gov.uk/msi. To obtain the colour versions select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-12-PAGE149_Week01_2012.pdf)

VOLUME 2, NP 282, 2013/14

Published Wk 9/13

(Last Updates: Weekly Edition No. 11 dated 14 March 2013)

RADAR BEACONS

PAGE 36, NORWAY.

64450 Yme Oil Field Platform.

Delete morse ident **D** and replace by: **M**

[Norwegian Notice 4/46417/13 \(RSDRA2013000042482\)](#) 12/13

PAGE 102, CHINA.

82200 Lushan Xingang Lt Buoy No 1.

Delete position and replace by: 38°47'·33N 121°04'·90E

[Chinese Notice 8/239/13 \(RSDRA2013000048297\)](#) 12/13

PAGE 110, JAPAN.

83980 Mikomoto Shima Lt.

Delete See Note and replace by morse ident **X**

Delete Note: The Racon signal appears as a succession of 7 dashes

[Japanese Lights List updates \(RSDRA2013000007706\)](#) 12/13

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 170, CHINA.

Lianhua Shan Lt Float, columns 3 and 4.

Delete MMSI and replace by: 994131644

Insert Service Details: Broadcasts every 3 minutes

[Chinese Notices 8/13 \(RSDRA2013000048297\)](#) 12/13

PAGE 186, GERMANY (North Sea Coast), below R-W Lt Buoy entry.

Insert:

TG/A Lt Buoy	53°50'·20N 6°41'·20E				
TG/B Lt Buoy	53°53'·10N 7°00'·70E				
TG/C Lt Buoy	53°55'·60N 7°19'·50E				

[German Notices 9/13 \(RSDRA2013000049203\)](#) 12/13

PAGE 206, SINGAPORE, Sebarok Lt.

Delete entry

[Singapore Notices 2/13 \(RSDRA2013000049444\)](#) 12/13

PAGE 214, below URUGUAY section.
Insert:

YEMEN (473) (475)					
Balfe Point Lt	12°39′.37N 43°23′.24E			Real	
Elephant’s Back Lt	12°45′.86N 44°59′.28E			Real	
Ḥanīsh al Kubrá Lt	13°39′.96N 42°40′.62E			Real	
Mayyūn Island Lt	12°39′.28N 43°25′.88E			Real	
Ra’s Marshaq Lt	12°45′.80N 45°03′.24E			Real	

(former update 9/13)
UKHO 12/13

UNIVERSAL TIME

PAGE 263, LEAP SECONDS, IMPLEMENTATION DATES, TABLE 2.
Insert:

0 hours	31 Jan 2013	+0.2 seconds	12/13
---------	-------------	--------------	-------

International Earth Rotation and Reference Systems Service (IERS) Bulletin D114 (RSDRA2013000049374) 12/13

UPDATES TO ADMIRALTY SAILING DIRECTIONS

Nil.

K1062-5	TELUK JAKARTA - LNG Terminal (ID)	5 58-40 S 106 47-98 E	Lit	..	..	Platform	
*	*	*	*	*	*	*	*
K1459-21	TELUK BALIKPAPAN. APPROACHES - Ldg Lts 306°. Rear. 0-8M ID, , 4702 from front. No 2 (ID)	1 18-40 S 116 52-34 E	Iso W 5s	15	11	White ▽ on white beacon 15	*
K1691-895	DAMPIER ARCHIPELAGO. PORT OF DAMPIER. MERMAID SOUND - Withnell Bay Terminal. Channel Beacon. No 13	20 34-72 S 116 45-51 E	Fl R 3s	..	..	Red beacon	TE; replaced by special light buoy (T) 2013 *
K1691-897	- Withnell Bay Terminal. Channel Beacon. No 14	20 34-80 S 116 45-66 E	Fl Y 1-5s	..	..	Yellow beacon	TE; replaced by special buoy (T) 2013 *
K3172-31	GREAT BARRIER REEF (COASTAL WATERS). PORT OF CAIRNS - Outer Cutting. Ldg Lts 209-2°. Rear	16 55-17 S 145 46-83 E	Dir WRG 4s	18	11	..	F G208-85°-209-05°(0-2°). Al WG209-05°-209-2°(0-15°). F W209-2°-209-3°(0-1°). Al WR209-3°-209-45°(0-15°). F R209-45°-209-65°(0-2°)
			*				
K4682	VITI LEVU ISLAND. SOUTH COAST. SUVA HARBOUR - Lami Beacon FJ, F201, 4682	18 07-59 S 178 24-55 E	Q R	5	4	Red 6-sided tower, round top	

VI

UPDATES TO ADMIRALTY LIST OF RADIO SIGNALS

Weekly Edition No. 13 dated 28 March 2013

The **Admiralty List of Radio Signals diagrams** included in the paper version of the weekly Notice to Mariners (Section VI) are printed in black and white. If required, a colour version of these diagrams can be downloaded from www.ukho.gov.uk/msi. To obtain the colour versions select **View and download NMs** - select **Weekly** - select **Year** - select **Week** - go to **Selected Week Content** - select **File** (for example: NP286(3)-WK01-12-PAGE149_Week01_2012.pdf)

VOLUME 2, NP 282, 2013/14

Published Wk 9/13
 (Last Updates: Weekly Edition No. 12 dated 21 March 2013)

RADAR BEACONS

PAGE 10, UNITED KINGDOM.

50130 Nab East Lt Buoy.

Delete position and replace by: 50°40'·02N 0°56'·96W

[Trinity House \(RSDRA2013000054407\)](#) 13/13

PAGE 74, SRI LANKA.

Insert:

Great Basses Reef Lt	6°11'·01N 81°28'·86E	10 cm				0		79490
----------------------	----------------------	-------	--	--	--	---	--	-------

[MV British Ruby \(RSDRA2013000049803\)](#) 13/13

UPDATES TO ADMIRALTY SAILING DIRECTIONS

Nil.