

To accompany Australian Notice to Mariners 319/2024

COCONUT ISLAND SPEED LIMIT

To minimise ship wake and enhance personnel safety at Coconut Island, coastal pilots and shipmasters are requested not to exceed 15 knots when within 10 miles of the island, if safe and practical to do so. Ships are encouraged to navigate as far west of the island as safe and practical, while remaining within the IMO-adopted Two-Way Route.

Note for chart Aus 837

To accompany Australian Notice to Mariners 319/2024

COCONUT ISLAND SPEED LIMIT

To minimise ship wake and enhance personnel safety at Coconut Island, coastal pilots and shipmasters are requested not to exceed 15 knots when within 10 miles of the island, if safe and practical to do so. Ships are encouraged to navigate as far west of the island as safe and practical, while remaining within the IMO-adopted Two-Way Route.

Note for chart Aus 839


To accompany Australian Notice to Mariners 319/2024

COCONUT ISLAND SPEED LIMIT

To minimise ship wake and enhance personnel safety at Coconut Island, coastal pilots and shipmasters are requested not to exceed 15 knots when within 10 miles of the island, if safe and practical to do so. Ships are encouraged to navigate as far west of the island as safe and practical, while remaining within the IMO-adopted Two-Way Route.

Note for chart Aus 840


To accompany Australian Notice to Mariners 320/2024



Block A for chart Aus 318 (51.0 x 40.9mm)


© Commonwealth of Australia 2024

To accompany Australian Notice to Mariners 320/2024



Block B for chart Aus 318 (52.4 x 44.4mm)
© Commonwealth of Australia 2024

To accompany Australian Notice to Mariners 320/2024



Block for chart Aus 319 (51.3 x 40.9mm)
© Commonwealth of Australia 2024

