



11 September 2015

Edition 18

Australian Notices to Mariners are the authority for correcting Australian Charts and Publications

AUSTRALIAN NOTICES TO MARINERS

Notices 985 - 1040



Published fortnightly by the Australian Hydrographic Service

Commodore B.K. BRACE RAN
Hydrographer of Australia

SECTIONS.

- I. Australian Notices to Mariners, including blocks and notes.
- II. Hydrographic Reports.
- III. Navigational Warnings.

SUPPLEMENTS.

- I. Tracings
- II. Cumulative List of Australian Notices to Mariners.
- III. Cumulative List of Temporary and Preliminary Australian Notices to Mariners.
- IV. Temporary and Preliminary Notices in force.
- V. Amendments to Admiralty List of Lights and Fog Signals (Vol K), Radio Signals (NP 281(2), 282, 283(2), 285, 286(4)) and Sailing Directions (NP 9, 13, 14, 15, 33, 34, 35, 36, 39, 44, 51, 60, 61, 62, 100, 136).

© Commonwealth of Australia 2015

This work is copyright. Apart from any use permitted under the Copyright Act 1968, no part may be reproduced by any process, adapted, communicated or commercially exploited without prior written permission from The Commonwealth represented by the Australian Hydrographic Service.

IMPORTANT NOTICE

This edition of Notices to Mariners includes all significant information affecting AHS products which the AHS has become aware of since the last edition. All reasonable efforts have been made to ensure the accuracy and completeness of the information, including third party information, on which these updates are based. The AHS regards third parties from which it receives information as reliable, however the AHS cannot verify all such information and errors may therefore exist. The AHS does not accept liability for errors in third party information.

GENERAL INSTRUCTIONS

The substance of these notices should be inserted on the charts affected.

Bearings are referred to the true compass and are reckoned clockwise from North; those relating to lights are given as seen by an observer from seaward.

Positions quoted in notices relate to WGS84 which is the horizontal datum for all charts produced by the Australian Hydrographic Service.

The range quoted for a light is its nominal range.

Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices.

A star (*) adjacent to the number of a notice indicates that the notice is based on original information.

REPORTING OF DANGERS

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 Wollongong, NSW 2500 (Fax 02-4223 6599, e-mail datacentre@hydro.gov.au or, alternatively by filling in and submitting the [Hydrographic Notes](#) forms located on the web site – www.hydro.gov.au), immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).

AUTHORISED USE

Copies of Australian notices are available free of charge from the Australian Hydrographic Service (AHS) website (www.hydro.gov.au) and through the eNotices (email) service (www.hydro.gov.au/enotices/enotices.htm).

Individual Notices may be copied for the purpose of inserting Notice substance on official charts and publications. Paper copies may be printed by chart agents and distributed to customers on a cost recovery basis. Participating chart agents are listed on the AHS website as providing a 'Paper Notices to Mariners' service (www.hydro.gov.au/prodserv/distributors/distributors.htm). Copies of the notices may not be sold for profit without prior written agreement.

NUMERICAL INDEX OF NOTICES TO MARINERS

Edition No 18

Notices	Aus Chart, INT Chart, ENC Cell, AHP, BA Pubs
985	Products- New Charts, New Editions, Withdrawn Charts
986	Products - New Charts and New Editions to be published shortly
987	Cessation of dredged depth updates
988	Aus 200, 201, AX 00200T, 00201T
989	Aus 293, 299
990	Aus 832
991	Aus 240, 815, 817
992	Aus 505, 621
993	Aus 520
994	Aus 58, 59
995	Aus 332, 333, 751, 752, 4725, INT 725
996	Aus 32
997	Aus 130, 137
998	Aus 125
999	Aus 485, 776, AX 00776S
1000	Aus 155
1001	Aus 157
1002	Aus 798
1003	Aus 167
1004(T)	Aus 200, 202, AX 00202T
1005(T)	Aus 301
1006(T)	Aus 832
1007(T)	Aus 244, 245, 271
1008(T)	Aus 245, 272, 819
1009(T)	Aus 230
1010(T)	Aus 230
1011(T)	Aus 230
1012(T)	Aus 230
1013(T)	Aus 259, 267
1014(T)	Aus 6
1015(T)	Aus 236
1016(T)	Aus 236
1017(T)	Aus 236
1018(T)	Aus 236
1019(T)	Aus 236
1020(T)	Aus 236
1021(T)	Aus 236
1022(T)	Aus 236
1023(T)	Aus 247, 265
1024(T)	Aus 247
1025(T)	Aus 257
1026(T)	Aus 257
1027(T)	Aus 386, 387, 673
1028(T)	Aus 319, 320, AX 00319U
1029(T)	Aus 314, 319, 4721, 4722, INT 721, 722, AX 00314U, 00319S, 00319U, 04721U, 04722U
1030(T)	Aus 328, 4723, INT 723, AX 04723U
1031(T)	Aus 328, 4723, INT 723, AX 04723U
1032(T)	Aus 52, 53, 326, 739, 740
1033(T)	Aus 328
1034(T)	Aus 32
1035(T)	Aus 153, 157
1036(T)	Aus 155
1037(T)	Aus 143, 155
1038(T)	Aus 357, AX 00357S
1039(T)	Aus 175
1040(T)	Aus 798

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 18

Aus Chart	Notices
Aus 6	1014(T)
Aus 32	996, 1034(T)
Aus 52	1032(T)
Aus 53	1032(T)
Aus 58	994
Aus 59	994
Aus 125	998
Aus 130	997
Aus 137	997
Aus 143	1037(T)
Aus 153	1035(T)
Aus 155	1000, 1036(T), 1037(T)
Aus 157	1001, 1035(T)
Aus 167	1003
Aus 175	1039(T)
Aus 200	988, 1004(T)
Aus 201	988
Aus 202	1004(T)
Aus 230	1009(T), 1010(T), 1011(T), 1012(T)
Aus 236	1015(T), 1016(T), 1017(T), 1018(T), 1019(T), 1020(T), 1021(T), 1022(T)
Aus 240	991
Aus 244	1007(T)
Aus 245	1007(T), 1008(T)
Aus 247	1023(T), 1024(T)
Aus 257	1025(T), 1026(T)
Aus 259	1013(T)
Aus 265	1023(T)
Aus 267	1013(T)
Aus 271	1007(T)
Aus 272	1008(T)
Aus 293	989
Aus 299	989
Aus 301	1005(T)
Aus 314	1029(T)
Aus 319	1028(T), 1029(T)
Aus 320	1028(T)
Aus 326	1032(T)
Aus 328	1030(T), 1031(T), 1033(T)
Aus 332	995
Aus 333	995
Aus 357	1038(T)
Aus 386	1027(T)
Aus 387	1027(T)
Aus 485	999
Aus 505	992
Aus 520	993
Aus 621	992
Aus 673	1027(T)
Aus 739	1032(T)
Aus 740	1032(T)
Aus 751	995
Aus 752	995
Aus 776	999
Aus 798	1002, 1040(T)

Aus Chart	Notices
Aus 815	991
Aus 817	991
Aus 819	1008(T)
Aus 832	990, 1006(T)
Aus 4721	1029(T)
Aus 4722	1029(T)
Aus 4723	1030(T), 1031(T)
Aus 4725	995
AX 00200T	988
AX 00201T	988
AX 00202T	1004(T)
AX 00314U	1029(T)
AX 00319S	1029(T)
AX 00319U	1028(T), 1029(T)
AX 00357S	1038(T)
AX 00776S	999
AX 04721U	1029(T)
AX 04722U	1029(T)
AX 04723U	1030(T), 1031(T)

INT Chart	Notices
INT 721	1029(T)
INT 722	1029(T)
INT 723	1030(T), 1031(T)
INT 725	995

985 AUSTRALIA - Products- New Charts, New Editions, Withdrawn Charts

Australian Hydrographic Service (AA828998)

New Charts

<i>Chart</i>	<i>Title and Geographical limits</i>	<i>Scale</i>	<i>Publication Date</i>	<i>Remarks</i>
NIL				

New Electronic Navigation Chart (Aus ENC)

<i>Cell Name</i>	<i>Title</i>	<i>Publication Date</i>	<i>Remarks</i>
NIL			

New Editions and Withdrawn Charts

<i>Chart</i>	<i>Title</i>	<i>Scale</i>	<i>Publication Date</i>	<i>Remarks</i>
NIL				

New Miscellaneous Editions

<i>Chart</i>	<i>Title</i>	<i>Scale</i>	<i>Publication Date</i>	<i>Remarks</i>
AZB0003G	Eastern Australia Exercise Area - FCPE	1 : 900 000	11 September 2015	Fleet use only.

Chart permanently withdrawn

Charts listed above as withdrawn no longer meet chart carriage requirements and should be marked as "superseded" and replaced with the new chart/ new edition listed prior to passage through the area covered by the new chart.

When placing orders with a chart agent between notice of forthcoming edition and its publication, mariners should advise whether their order pertains to the current edition or the new edition.

For further details refer to the AHS website at www.hydro.gov.au for new edition and new chart stock arrival information.

When placing orders with a chart agent, mariners should advise whether their order pertains to the current edition or the new edition.

986 AUSTRALIA - Products - New Charts and New Editions to be published shortly
 Australian Hydrographic Service (AA829037)

New Charts to be published shortly

<i>Chart</i>	<i>Title</i>	<i>Scale</i>	<i>Expected Publication Date</i>	<i>Remarks</i>
NIL	NIL			

New Editions to be published shortly

<i>Chart</i>	<i>Title</i>	<i>Scale</i>	<i>Expected Publication Date</i>	<i>Remarks</i>
Aus 154 <i>Edition 9</i>	Australia - South Coast - Victoria - Port Melbourne, Williamstown and River Yarra Plan: River Yarra	1:7 500	25 September 2015	New edition with general updating throughout.
Aus 309 <i>Edition 2</i>	Australia - North Coast - Darwin to Penguin Shoal - (Eastern Sheet)	1:300 000	25 September 2015	New edition incorporating new pipeline.
Aus 315 <i>Edition 4</i>	Timor Sea - Darwin to Penguin Shoal - (Western Sheet)	1:300 000	25 September 2015	New edition incorporating new pipeline.
Aus 316 <i>Edition 3</i>	Australia - North Coast - Northern Territory - Charles Point to Pelican Island	1:300 000	25 September 2015	New edition incorporating new pipeline.
Aus 835 <i>Edition 5</i>	Australia East Coast - Queensland - Cape Weymouth to Carincross Islets	1:150 000	25 September 2015	New edition with general updating throughout.

987 Cessation of dredged depth updates

Australian Hydrographic Service (AA350099)

The Australian Hydrographic Service will no longer publish temporary depth information for maintained dredged channels and berth pockets. Paper charts and ENC will reflect the intended design depth. For the latest depth information contact the relevant Port Authority.

988* AUSTRALIA - NEW SOUTH WALES - Port Jackson - North Harbour - Wreck

S Willan (AA714795, AA714797, AA714799, AA714801)

Aus 200 [916/2015]

Insert depth, 12_gm, enclosed by danger circle with legend *Wk* 33° 48'.657 S 151° 16'.592 E

Aus 201 [916/2015]

Insert depth, 12_gm, enclosed by danger circle with legend *Wk* 33° 48'.657 S 151° 16'.592 E

AX 00200T [916/2015]

Insert depth, 12_gm, enclosed by danger circle with legend *Wk* 33° 48'.657 S 151° 16'.592 E

AX 00201T [916/2015]

Insert depth, 12_gm, enclosed by danger circle with legend *Wk* 33° 48'.657 S 151° 16'.592 E

989* AUSTRALIA - QUEENSLAND - Goods Island - Mooring buoy

Maritime Safety Queensland Notice 257/2015 (SIRF2015000736)

Aus 293 [824/2015]

Insert lit orange cylindrical mooring buoy, Q 10° 34'.20 S 142° 10'.00 E

Delete # 10° 34'.2 S 142° 10'.0 E

Aus 299 [610/2015]

Insert lit orange cylindrical mooring buoy, Q 10° 34'.20 S 142° 10'.00 E

Delete # 10° 34'.2 S 142° 10'.0 E

990* AUSTRALIA - QUEENSLAND - Maxwell Reef - Light range amended

AMSA ATH 28/2015 (SIRF2015000809)

Aus 832 [664/2015]

Amend light range to 9/7M 14° 47'.1 S 145° 18'.9 E

991* AUSTRALIA - QUEENSLAND - Wide Bay - Hook Point - Navlines

Maritime Safety Queensland Notice 239/2015 (SIRF2015000546)

Aus 240 [466/2015]Insert a dashed line in a direction 097° 5' for a distance of 2750m, thence a continuous line for 5900m, with legend *Dir 277° 5'*, emanating from light 25° 47'.03 S 153° 04'.73 Ea dashed line in a direction 058° for a distance of 2000m, thence a continuous line for 3000m, with legend *238°*, emanating from light 25° 48'.67 S 153° 03'.81 EAmend legend to *Fl.WRG.3s (F Day)* 25° 47'.0 S 153° 04'.7 EDelete dashed and continuous line with legend, emanating from light 25° 47'.0 S 153° 04'.7 E
dashed and continuous line with legend, emanating from light 25° 48'.7 S 153° 03'.8 E**Aus 815 [466/2015]**Insert a dashed line in a direction 097° 5' for a distance of 2750m, thence a continuous line for 5900m, with legend *Dir 277° 5'*, emanating from light 25° 47'.03 S 153° 04'.73 Ea dashed line in a direction 058° for a distance of 2000m, thence a continuous line for 3000m, with legend *238°*, emanating from light 25° 48'.67 S 153° 03'.81 EAmend legend to *Fl.WRG.3s (F Day)* 25° 47'.0 S 153° 04'.7 EDelete dashed and continuous line with legend, emanating from light 25° 47'.0 S 153° 04'.7 E
dashed and continuous line with legend, emanating from light 25° 48'.7 S 153° 03'.8 E**Aus 817 [664/2015]**

Insert accompanying block 25° 50'.5 S 153° 09'.1 E

992* PAPUA NEW GUINEA - Basilisk Passage - Lark Patch - Light beacon

National Maritime Safety Authority PNG Notice 26/2015 (SIRF2015000826)

Aus 505 [721/2015]Insert light beacon, *Fl.R.3s 7m 4M*, with port lateral topmark 9° 31'.56 S 147° 08'.53 E**Aus 621 [867/2015]**Insert light beacon, *Fl.R.3s 7m 4M*, with port lateral topmark 9° 31'.562 S 147° 08'.528 E**993* PAPUA NEW GUINEA - Tancred Reef - Reef**

Australian Hydrographic Service (SIRF2015000722)

Aus 520 [467/2015]Insert legend (*PD*) 8° 55'.13 S 148° 59'.20 E

994* AUSTRALIA - WESTERN AUSTRALIA - Dampier - Phillip Point - Anchorage

Pilbara Ports Authority Notice D31/2015 (SIRF2015000933)

Aus 58 [830/2015]

Delete anchorage centred on 20° 36'.93 S 116° 44'.30 E

Aus 59 [777/2015]

Delete anchorage centred on 20° 36'.93 S 116° 44'.30 E

995* AUSTRALIA - WESTERN AUSTRALIA - Pelsaert Island - Light range

AMSA AUSCOAST 229/15 (SIRF2015000635)

Aus 332 [158/2014]

Amend light range to 15M 28° 59'.1 S 113° 57'.7 E

Aus 333 [734/2015]

Amend light range to 15M 28° 59'.1 S 113° 57'.7 E

Aus 751 [727/2014]

Amend light range to 15M 28° 59'.1 S 113° 57'.7 E

Aus 752 [858/2011]

Amend light range to 15M 28° 59'.1 S 113° 57'.7 E

Aus 4725 (INT 725) [925/2015]

Amend light range to 15M 28° 59'.1 S 113° 57'.7 E

996* AUSTRALIA - WESTERN AUSTRALIA - Wyndham - Light buoy

CGL Wyndham Port (SIRF2015000946)

Aus 32 (plan, Approaches to Wyndham Wharf) [730/2014]

Delete light buoy 15° 20'.29 S 128° 06'.41 E

997* AUSTRALIA - SOUTH AUSTRALIA - Barker Inlet - Beacons

Department of Planning, Transport and Infrastructure SA (SIRF2015000825, SIRF2015000699)

Aus 130 [530/2015]

Insert	beacon with port lateral topmark	34° 46'.906 S	138° 32'.298 E
	beacon with port lateral topmark	34° 47'.014 S	138° 32'.409 E
	beacon with port lateral topmark	34° 45'.464 S	138° 31'.232 E
	beacon with port lateral topmark	34° 45'.527 S	138° 31'.309 E
	beacon with port lateral topmark	34° 45'.719 S	138° 31'.479 E

Delete	beacon	34° 46'.26 S	138° 31'.78 E
	beacon	34° 46'.42 S	138° 31'.88 E
	beacon	34° 45'.43 S	138° 31'.19 E
	beacon	34° 45'.54 S	138° 31'.32 E
	beacon	34° 45'.73 S	138° 31'.49 E
	beacon	34° 46'.52 S	138° 31'.99 E
	depth, 2 ₄ m	34° 46'.88 S	138° 32'.26 E

Aus 137 [833/2015]

Insert	beacon with port lateral topmark	34° 45'.464 S	138° 31'.232 E
	beacon with port lateral topmark	34° 45'.527 S	138° 31'.309 E
	beacon with port lateral topmark	34° 45'.719 S	138° 31'.479 E

Delete	beacon	34° 45'.43 S	138° 31'.19 E
	beacon	34° 45'.54 S	138° 31'.32 E
	beacon	34° 45'.73 S	138° 31'.49 E

998* AUSTRALIA - SOUTH AUSTRALIA - Glenelg - Nav aids

Department of Planning, Transport and Infrastructure SA (AA824127)

Aus 125 (plan, Glenelg) [349/2015]

Insert	special spherical light buoy, <i>Fl. Y. 3s</i> , with topmark	34° 57'.468 S	138° 29'.362 E
	special spherical light buoy, <i>Fl. Y. 3s</i> , with topmark	34° 57'.435 S	138° 29'.488 E
	accompanying block	34° 57'.7 S	138° 30'.2 E

999* AUSTRALIA - SOUTH AUSTRALIA - Yorke Peninsula - The Pines - light beacon

Department of Transport, Energy and Infrastructure SA (SIRF2015000794)

Aus 485 [583/2015]

Move	light beacon	34° 53'.18 S	137° 12'.38 E
	to	34° 53'.23 S	137° 11'.95 E

Aus 776 [281/2015]

Move	light beacon	34° 53'.18 S	137° 12'.38 E
	to	34° 53'.23 S	137° 11'.95 E

AX 00776S [NE 8/5/2015]

Move	light beacon	34° 53'.18 S	137° 12'.38 E
	to	34° 53'.23 S	137° 11'.95 E

1000* AUSTRALIA - VICTORIA - Port Phillip - Port Melbourne Channel - Light beacons

Port of Melbourne Corporation (SIRF2015000652)

Aus 155 [932/2015]

Insert	special purpose light beacon, <i>VQ(4)Y.4s T5</i> , with topmark	37° 58'.905 S	144° 55'.693 E
	special purpose light beacon, <i>VQ(4)Y.4s T6</i> , with topmark	37° 58'.889 S	144° 54'.950 E
	special purpose light beacon, <i>VQ(4)Y.4s T14</i> , with topmark	37° 56'.684 S	144° 55'.110 E
	special purpose light beacon, <i>VQ(4)Y.4s T13</i> , with topmark	37° 56'.714 S	144° 55'.765 E

1001* AUSTRALIA - VICTORIA - Port Phillip - Corio Bay - Buoys

Parks Victoria Notice 164/2015 (SIRF2015000630)

Aus 157 [931/2015]

Insert	special conical buoy with topmark	38° 05'.232 S	144° 25'.609 E
	special conical buoy with topmark	38° 05'.254 S	144° 25'.924 E

1002* AUSTRALIA - TASMANIA - Eddystone Point to Stony Head - Tidal streams

Australian Hydrographic Service (SIRF2015000755)

Aus 798 [625/2015]

Amend	longitude to <i>148 05.1E</i>	41° 00'.3 S	147° 34'.4 E
	longitude to <i>148 32.3E</i>	41° 00'.3 S	147° 35'.9 E
	latitude to <i>40° 58.9E</i>	41° 00'.1 S	147° 37'.4 E

1003* AUSTRALIA - TASMANIA - Long Reach - ZOC diagram

UKHO (SIRF2015000681)

Aus 167 [879/2015]

Delete	plan in ZOC diagram, centred on	41° 07'.95 S	146° 43'.34 E
--------	---------------------------------	--------------	---------------

1004(T)/2015 AUSTRALIA - NEW SOUTH WALES - Port Jackson - Millers Point - Harbour works completed*Former Notice - 241(T)/2015 is cancelled*

Port Authority of New South Wales (SIRF2015000942)

Cancel this notice on receipt.

Chart formerly affected - Aus 200 - Aus 202 - AX 00202T**1005(T)/2015 AUSTRALIA - QUEENSLAND - Boyd Point - Scientific instruments***Date - Until 7 July 2016*

Maritime Safety Queensland Notice 266(T)/2015 (SIRF2015000930), Maritime Operations (SIRF2015000887)

Scientific instruments exist as follows:

<i>Position</i>	<i>Remarks</i>
12° 53'.07 S 141° 39'.85 E	special spherical buoy, <i>Fl.Y.4s</i>
12° 54'.58 S 141° 37'.73 E	special spherical buoy, <i>Fl.Y.4s</i>
12° 56'.86 S 141° 35'.98 E	special spherical buoy, <i>Fl.Y.4s</i>
12° 57'.63 S 141° 34'.63 E	special spherical buoy, <i>Fl.Y.4s</i>
12° 53'.09 S 141° 39'.85 E	special spherical buoy, <i>Fl.Y.4s</i>
12° 56'.41 S 141° 26'.87 E	special spherical buoy, <i>Fl.Y.4s</i>
13° 00'.15 S 141° 34'.55 E	special spherical buoy, <i>Fl.Y.4s</i>

A 200m exclusion zone exists around each buoy.

Chart temporarily affected - Aus 301**1006(T)/2015 AUSTRALIA - QUEENSLAND - Decapolis Reef - Light beacon; light buoy***Former Notice - 447(T)/2014 is cancelled**Date - Until 1 March 2016*

Australian Maritime Safety Authority (SIRF2015000767)

The light beacon, *Fl.2.5s 6m 10M* (14° 51'.10 S 145° 16'.41 E), has been destroyed.A starboard lateral pillar light buoy, *Fl.G.2.5s*, exists in position 14° 50'.97 S 145° 16'.54 E.**Chart temporarily affected - Aus 832****1007(T)/2015 AUSTRALIA - QUEENSLAND - Gladstone - Dredging operations***Former Notice - 631(T)/2015 is cancelled**Date - Until 30 September 2015*

Maritime Safety Queensland Notice 261(T)/2015 (SIRF2015000769)

The dredge *Everglade* is conducting dredging operations in the Gladstone Boat Harbour 23° 49'.8 S 151° 14'.7 E.

A floating pipeline will be marked by special light buoys. A submerged pipeline will be marked by port and starboard lateral light buoys.

The dredge will display appropriate lights and shapes and monitor VHF Ch 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 244 - Aus 245 - Aus 271**1008(T)/2015 AUSTRALIA - QUEENSLAND - Gladstone - North Passage Island to Redcliffe Island - Scientific instruments recovered***Former Notice - 1233(T)/2014 is cancelled*

Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 245 - Aus 272 - Aus 819

1009(T)/2015 AUSTRALIA - QUEENSLAND - Gold Coast - Wave Break Island - Wreck salvaged*Former Notice* - 590(T)/2015 is cancelled

Maritime Safety Queensland (SIRF2015000960)

Cancel this notice on receipt.

Chart formerly affected - Aus 230**1010(T)/2015 AUSTRALIA - QUEENSLAND - Gold Coast - South Channel - Harbour works completed***Former Notice* - 589(T)/2015 is cancelled

Maritime Safety Queensland (SIRF2015000964)

Cancel this notice on receipt.

Chart formerly affected - Aus 230**1011(T)/2015 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Shoaling removed***Former Notice* - 694(T)/2012 is cancelled

Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 230**1012(T)/2015 AUSTRALIA - QUEENSLAND - Gold Coast Seaway - Shoaling removed***Former Notice* - 737(T)/2012 is cancelled

Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 230**1013(T)/2015 AUSTRALIA - QUEENSLAND - Hinchinbrook Channel - Light buoy restored***Former Notice* - 1182(T)/2014 is cancelled

Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 259 - Aus 267**1014(T)/2015 AUSTRALIA - QUEENSLAND - Karumba - Nav aids restored***Former Notice* - 742(T)/2015 is cancelled

Carins Charts (SIRF2015000913, SIRF2015000931)

Cancel this notice on receipt.

Chart formerly affected - Aus 6**1015(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Rainbow Channel - Light beacon restored***Former Notice* - 645(T)/2012 is cancelled

Maritime Safety Queensland (SIRF2015000770)

Cancel this notice on receipt.

Chart formerly affected - Aus 236

1016(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Coochiemudlo Island - Light beacon restored*Former Notice - 740(T)/2012 is cancelled*

Maritime Safety Queensland (SIRF2015000770)

Cancel this notice on receipt.

Chart formerly affected - Aus 236**1017(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Peel Island - Lazaret Gutter - Beacon restored***Former Notice - 1085(T)/2012 is cancelled*

Maritime Safety Queensland (SIRF2015000770)

Cancel this notice on receipt.

Chart formerly affected - Aus 236**1018(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Redland Bay - Light beacon restored***Former Notice - 1268(T)/2013 is cancelled*

Maritime Safety Queensland (SIRF2015000770)

Cancel this notice on receipt.

Chart formerly affected - Aus 236**1019(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Redcliffe - Light beacon restored***Former Notice - 229(T)/2014 is cancelled*

Maritime Safety Queensland (SIRF2015000770)

Cancel this notice on receipt.

Chart formerly affected - Aus 236**1020(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Manly - Light beacon restored***Former Notice - 426(T)/2015 is cancelled*

Maritime Safety Queensland (SIRF2015000770)

Cancel this notice on receipt.

Chart formerly affected - Aus 236**1021(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Fison Channel - Dredging operations completed***Former Notice - 188(T)/2015 is cancelled*

Maritime Safety Queensland (SIRF2015000793)

Cancel this notice on receipt.

Chart formerly affected - Aus 236**1022(T)/2015 AUSTRALIA - QUEENSLAND - Moreton Bay - Scarborough - Shoaling removed***Former Notice - 600(T)/2012 is cancelled*

Maritime Safety Queensland

Cancel this notice on receipt.

Chart formerly affected - Aus 236

1023(T)/2015 AUSTRALIA - QUEENSLAND - Port Alma - Sea Reach - Buoy recovered

Former Notice - 301(T)/2015 is cancelled
 Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 247 - Aus 265

1024(T)/2015 AUSTRALIA - QUEENSLAND - Rosslyn Bay - Light beacons restored

Former Notice - 302(T)/2015 is cancelled
 Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 247

1025(T)/2015 AUSTRALIA - QUEENSLAND - Townsville - Ross River - Harbour works completed; dredging operations completed

Former Notice - 924(T)/2014 is cancelled
 Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 257

1026(T)/2015 AUSTRALIA - QUEENSLAND - Townsville - Harbour works completed

Former Notice - 430(T)/2015 is cancelled
 Maritime Safety Queensland (AA828441)

Cancel this notice on receipt.

Chart formerly affected - Aus 257

1027(T)/2015 PAPUA NEW GUINEA - Nesup Island to Massmass Island - Light beacons unlit

National Maritime Safety Authority PNG Notices 27/15 and 28/15 (SIRF2015000826)

The light beacon, *Q.R. 7m 3M* (5° 58'.53 S 148° 07'.08 E), is unlit.

The light beacon, *Fl(2)8s 7m 10M* (5° 54'.95 S 148° 07'.82 E), is unlit.

Chart temporarily affected - Aus 386 - Aus 387 - Aus 673

1028(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Browse Island - Survey; pipeline operations completed

Former Notice - 647(T)/2015 is cancelled
 Technip (SIRF2015000939)

Cancel this notice on receipt.

Chart formerly affected - Aus 319 - Aus 320 - AX 00319U

1029(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Eugene McDermott Shoal - Drill rig northwestwards

Former Notice - 973(T)/2015 is cancelled
Date - Until 30 September 2015
 MODU *Stena Clyde* (SIRF2015000772, SIRF2015000805), AMSA (SIRF2015000774)

MODU *Stena Clyde* is conducting drilling operations in position 12° 55'.84 S 124° 28'.07 E.

Chart temporarily affected - Aus 314 - Aus 319 - Aus 4721 (INT 721) - Aus 4722 (INT 722) - AX 00314U - AX 00319S - AX 00319U - AX 04721U - AX 04722U

1030(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Pipeline works northwestwards*Date* - Until 31 March 2016

Technip (SIRF2015000765)

Various vessels are conducting pipeline and subsea operations in vicinity of position 19° 54'.18 S 115° 16'.67 E.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 328 - Aus 4723 (INT 723) - AX 04723U

1031(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Montebello Islands - Drill rig northwestwards*Former Notice* - 852(T)/2015 is cancelled*Date* - Until 1 February 2016MODU *Ocean Monarch* (SIRF2015000938)

Drill rig *Ocean Monarch* is conducting drilling operations in position 20° 01'.83 S 115° 12'.08 E.

Chart temporarily affected - Aus 328 - Aus 4723 (INT 723) - AX 04723U

1032(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Port Hedland - Cable operations*Date* - Until 20 October 2016

Pilbara Ports Authority PH17/2015(T) (SIRF2015000900)

Barge *Miclyn 256* and support vessels are conducting submarine cable laying operations between the following positions:

20° 18'.51 S 118° 36'.87 E

20° 18'.02 S 118° 36'.75 E

20° 17'.53 S 118° 36'.64 E

20° 16'.11 S 118° 38'.10 E

20° 13'.69 S 118° 39'.93 E

20° 10'.24 S 118° 40'.77 E

20° 09'.01 S 118° 40'.60 E

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 52 - Aus 53 - Aus 326 - Aus 739 - Aus 740

1033(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Rankin Bank - Mooring buoys recovered*Former Notice* - 702(T)/2015 is cancelled

Viking Seatech (SIRF2015000925)

Cancel this notice on receipt.

Chart formerly affected - Aus 328

1034(T)/2015 AUSTRALIA - WESTERN AUSTRALIA - Wyndham - Light buoys repositioned

CGL Wyndham Port (SIRF2015000732, SIRF2015000733)

The following light buoys have been repositioned:

<i>Characteristic</i>	<i>Charted Position</i>	<i>New Position</i>
<i>Fl.R.3s</i>	15° 20'.25 S 128° 06'.86 E	15° 19'.97 S 128° 06'.80 E
<i>Fl.G.3s</i>	15° 20'.17 S 128° 06'.63 E	15° 20'.10 S 128° 06'.63 E
<i>Fl.G.3s</i>	15° 19'.84 S 128° 06'.37 E	15° 19'.81 S 128° 06'.37 E

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 32

1035(T)/2015 AUSTRALIA - VICTORIA - Port Phillip - Corio Bay - Dredging; light buoy

Date - Until 31 October 2015

Victorian Notices 166(T)/2015, 170(T)/2015 (SIRF2015000766, SIRF2015000881)

The dredge *Machiavelli* with support vessels will be conducting dredging operations in Corio Channel in the vicinity of position 38° 05'.42 S 144° 23'.05 E.

Vessels will display appropriate lights and shapes and monitor VHF Ch 12.

A port lateral light buoy, *Iso.R.3s*, exists in position 36° 05'.53 S 144° 23'.15 E. The light beacon, *Iso.R.3s 10m 5M* (38° 05'.54 S 144° 23'.11 E) is to be removed shortly.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 153 - Aus 157

1036(T)/2015 AUSTRALIA - VICTORIA - Port Phillip - Brighton - Dredging operations

Parks Victoria Notice 172(T)/2015 (SIRF2015000897)

Dredging operations are being conducted between the following positions 37° 55'.92 S 144° 59'.24 E and 37° 55'.72 S 144° 59'.06 E.

All hazards to navigation will display appropriate lights and symbols.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 155

1037(T)/2015 AUSTRALIA - VICTORIA - Port Phillip - Port Melbourne Channel - Light beacons established

Former Notice - 560(P)/2015 is cancelled

Port of Melbourne Corporation (SIRF2015000652)

Cancel this notice on receipt.

Chart formerly affected - Aus 143 - Aus 155

1038(T)/2015 AUSTRALIA - BASS STRAIT - Ninety Mile Beach - Inspection works

Date - Until 31 December 2015

Transport Safety Victoria Notice 176(T)/2015 (SIRF2015000990)

MV *Silver Star* will be undertaking inspection works in an area bounded by the following positions:

38° 25'.9 S 147° 07'.5 E

38° 36'.0 S 147° 19'.8 E

38° 48'.4 S 148° 30'.0 E

38° 37'.0 S 148° 37'.1 E.

Vessel will monitor VHF channel 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 357 - AX 00357S

1039(T)/2015 AUSTRALIA - TASMANIA - Spring Bay - Triabunna - Light beacon destroyed

MAST M116/15 (SIRF2015000817)

The port lateral light beacon *Fl.R.8s No10*, (42° 30'.73 S 147° 54'.89 E), has been destroyed. An obstruction exists in situ.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected - Aus 175

1040(T)/2015 AUSTRALIA - TASMANIA - Swan Island - Scientific instrument

Date - Until 23 October 2015

MAST Notice M119/15 (SIRF2015000885)

A scientific instrument marked by a special buoy exists in position, 40° 45'.53 S 148° 05'.29 E.

Chart temporarily affected - Aus 798

II

HYDROGRAPHIC REPORTS

NIL

NAVIGATION WARNINGS

The following radio messages have been received during the period to 10 September 2015. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNING

- 232 Drill rig *Stena Clyde* in position 12° 55'.80 S 124° 28'.07 E.
- 233 Special purpose vessel *Joides Resolutions* conducting drilling operations in position 19° 49'.30 S 115° 42'.60 E. 2M clearance requested.
- 234 Cancelled.
- 235 Maxwell Reef light K3215.5 in position 14° 47'.14 S 145° 18'.88 E range changed to white 9M and red 7M.
- 236 Cancelled.
- 237 Cancelled.
- 238 Cancelled.
- 239 Cancelled.
- 240 Cancelled.
- 241 Cancelled.
- 242 Cancelled.
- 243 Cobia A platform light in position 38° 26'.97 S 148° 18'.56 E is unreliable.
- 244 Special purpose vessel *BGP Explorer* is conducting seismic survey towing 5M cable in an area bounded by 22° 37'.00 S 110° 40'.00 E and 27° 14'.00 S 113° 35'.00 E. 6M clearance is requested.

NAVAREA X WARNINGS

- 064 Special purpose vessel *L Atalante* is conducting a seismic survey in an area bounded by 22° 18'.00 S 164° 15'.00 E and 37° 31'.00 S 171° 31'.00 E. 5M clearance requested.
- 065 Cancelled.
- 066 95m tanker *No.7 Coam* abandoned and adrift 31° 45'.00 S 89° 17'.00 E.
- 067 Warnings in force.

Navigational warnings in force as at 100001UTC SEP 15.

Auscoast

2015 158 176 178 190 207 208 210 211 213 227 228 229 232 233 235 243 244

Navarea X

2015 051 064 066 067

Summary of mobile drilling rigs as at 100001UTC SEP 15.

<i>Name</i>	<i>Position</i>
Armada Claire	20° 03'.50 S 115° 11'.50 E
Atwood Eagle	19° 42'.40 S 115° 52'.50 E
Atwood Falcon	21° 31'.70 S 114° 06'.10 E
Atwood Osprey	19° 56'.70 S 115° 19'.50 E
Ensco 5006	13° 50'.80 S 123° 19'.20 E
Jack Bates	13° 49'.50 S 123° 12'.80 E
Modec Venture 11	19° 16'.60 S 116° 36'.70 E
Noble Clyde Boudreaux	13° 49'.00 S 123° 19'.40 E
Ocean Amercia	18° 11'.80 S 116° 51'.30 E
Ocean Monarch	20° 01'.80 S 115° 12'.10 E
Stena Clyde	12° 55'.80 S 124° 28'.10 E
West Telesto	39° 50'.70 S 145° 49'.20 E


NAVAREA XIV WARNINGS

- 076 Underwater operations by MV *L'Atalante* between 3 sep and 9 oct 15 in area bounded by the following positions: 22° 18'.00 S 171° 31'.00 E, 37° 31'.00 S 171° 31'.00 E, 37° 31'.00 S 164° 15'.00 E, 22° 18'.00 S 164° 15'.00 E. Vessel towing equipment 2.5nm from stern and is restricted in its ability to manoeuvre. 4M berth requested.

2015 076

Navarea XIV warnings in force as at 100001UTC SEP 15.

To accompany Australian Notice to Mariners 991/2015



Block for Chart Aus 817

© Commonwealth of Australia 2015

(131.2 x 140.1mm)

