



Australian Notices to Mariners are the authority for correcting Australian Charts

AUSTRALIAN NOTICES TO MARINERS

© Commonwealth of Australia 2003 - Copyright restrictions apply to Notices to Mariners

Notices 116-150

Published fortnightly by the Australian Hydrographic Service

B. J. KAHER,
Hydrographer of Australia

- SECTIONS. I. **Australian Notices to Mariners, including blocks and notes.**
 III. **Navigational Warnings.**
 IV. **Hydrographic Reports.**

British Admiralty Notices to Mariners
New Zealand Notices to Mariners

The substance of these notices should be inserted on the charts affected.

Bearings are referred to the true compass and are reckoned clockwise from 000° (North) to 359°: those relating to lights are given as seen by an observer from seaward. The range quoted for a light is its nominal range. Fog signals are sounded only during thick or foggy weather, unless otherwise stated. Depths are with reference to the chart datum of each chart. Heights are above mean high water springs or mean higher high water, as appropriate.

The capital letter (P) or (T) after the number of any notice denotes a preliminary or temporary notice respectively, which are contained separately at the end of the permanent notices. A star () adjacent to the number of a notice indicates that the notice is based on original information.*

Mariners are particularly requested to notify the AUSTRALIAN HYDROGRAPHIC SERVICE, Locked Bag 8801 South Coast Mail Centre, NSW 2521 (Fax 02-4221 8599, e-mail Hydro.NTM@defence.gov.au or, alternatively by filling in and submitting the [Hydrographic Notes](#) forms), immediately on the discovery of new dangers or suspected dangers to navigation. For changes or defects in aids to navigation notify AusSAR (Fax 02-6230 6868 or email rccaus@amsa.gov.au).

Copies of these notices can be obtained from the AUSTRALIAN HYDROGRAPHIC OFFICE, 8 Station Street, Wollongong, and Agents for the sale of charts and hydrographic publications.

The Commonwealth of Australia is the owner of, or is otherwise responsible for, the copyright in this work. It is protected under the Copyright Act 1968 and international convention. Except as expressly authorised below, the work may not be copied, reproduced, adapted, changed or commercially exploited, in whole or in part, or the format in which it is stored altered, without the prior written permission of the Australian Hydrographic Office. The Notices may be copied for the purpose of inserting their substance on official charts and other publications. However, any copies of the notices may not be sold for profit.

© Commonwealth of Australia 2003

NUMERICAL INDEX OF CHARTS AFFECTED

Edition No 4

21 February 2003

Notice	Aus Chart, INT Chart, ENC Cell
116.....	Aus 729, 730
117.....	Amendment to Annual Australian Notices to Mariners No 23
118.....	Agents for the sale of Navigational Products
119.....	Aus 216
120.....	Aus 216
121.....	Aus 817
122.....	Aus 262, 373, 830, AU4171045, 5262_4
123.....	Aus 831, AU416145
124.....	Aus 837
125.....	Aus 376, 837, 839, AU411143
126.....	Aus 306, 715
127.....	Aus 345, 444, 780
128.....	Aus 348, 4709, INT 709
129.....	Aus 171, 172
130.....	Aus 167
131.....	Aus 154
132(T).....	Aus 807
133(T).....	Aus 193
134(T).....	Aus 810
135(T).....	Aus 220, 813, 814
136(T).....	Aus 4, 236, 247, 249, 251, 256, 365, 814, 830, AU413141, 417145
137(T).....	Aus 243
138(T).....	Aus 244, 245
139(T).....	Aus 256, 827
140(P).....	Aus 833, AU414144
141(P).....	Aus 834, AU414143
142(P).....	Aus 834, AU414143
143(P).....	Aus 834, AU414143
144(P).....	Aus 834, AU413143
145(P).....	Aus 834, AU413143
146(P).....	Aus 834, AU413143
147(T).....	Aus 303, 410
148(T).....	Aus 137
149(T).....	Aus 143, 144, 155, 157, 158
150(T).....	Aus 150, 151, 152

116 AUSTRALIA - Publication.

AHS (A8205), British Admiralty Ed 4/2003 (A7673).

New edition to be published shortly

<i>Chart</i>	<i>Title</i>	<i>Scale</i>
Aus 729	Australia - North West Coast - Western Australia - Cape Voltaire to Lamark Island	1:150 000
Aus 730	Australia - North West Coast - Western Australia - Lamark Island to Degerando Island	1:150 000

Admiralty Publication

<i>NP No</i>	<i>Title</i>	<i>RRP(UK)</i>	<i>Date</i>	<i>Remarks</i>
NP 83	Admiralty List of Lights and Fog Signals, Volume K 2003/04, Indian and Pacific Oceans, South of the Equator	£22.00	2/1/2003	The 2002/03 edition of NP83 is thereby cancelled.

117 AUSTRALIA - Amendment to Annual Australian Notices to Mariners No 23.

AMSA (A8182 & A8184).

Page 121 amend entry Cairns (Cairns Fairway) position to read *16° 47' S 145° 53' E*.

Page 121 delete entry Torres Strait (Twin Island)

118 AUSTRALIA - Agents for the sale of Navigational Products.

AHS (A7665).

The following business has been appointed as a chart agent:

NELSONS BAY

Nelson Bay Sports

77 Victoria Parade

Nelson Bay 2315

Telephone

+61 (0)2 4981 2333

Fax

+61 (0)2 4981 2333

Email

sports@nelsonbay.com

N**119* AUSTRALIA - NEW SOUTH WALES - Broken Bay - Depths.**

AHS (A7660 & A7714).

Aus 216 [92/2003]

Insert	accompanying block A	33° 33'.0 S	151° 20'.0 E
	accompanying block B	33° 33'.0 S	151° 18'.5 E

120* AUSTRALIA - NEW SOUTH WALES - Brisbane Waters - Light beacons, beacons discontinued.

Former Notice - 839(P)/2002 is cancelled

List of Lights Vol K/2003 -- 2710.805, 2710.81, 2710.815, 2710.82, 2710.825

Waterways NSW (A7661, A8037, A8038 & A11559).

Aus 216 [119/2003]

Substitute	west cardinal light beacon, Q(9) 15s, with topmark, for west cardinal beacon	33° 29'.39 S	151° 21'.15 E
	port lateral light beacon, Fl. R. 3s, with topmark, for port lateral beacon	33° 29'.01 S	151° 20'.12 E
		33° 28'.91 S	151° 20'.82 E
		33° 28'.95 S	151° 21'.00 E
		33° 29'.05 S	151° 21'.14 E
		33° 29'.14 S	151° 21'.18 E
		33° 29'.19 S	151° 21'.16 E
		33° 29'.40 S	151° 21'.10 E
		33° 29'.39 S	151° 21'.25 E
		33° 29'.36 S	151° 21'.37 E
	starboard lateral light beacon, Fl. G. 3s, with topmark, for starboard lateral beacon	33° 29'.07 S	151° 19'.85 E
		33° 29'.01 S	151° 20'.20 E
		33° 29'.19 S	151° 20'.36 E
		33° 29'.41 S	151° 21'.13 E
		33° 29'.22 S	151° 21'.56 E
		33° 29'.23 S	151° 21'.66 E
		33° 29'.36 S	151° 21'.76 E
Delete	south cardinal light beacon	33° 28'.38 S	151° 19'.98 E
	port lateral light beacon	33° 28'.24 S	151° 20'.18 E
	port lateral beacon	33° 29'.03 S	151° 20'.03 E
		33° 28'.93 S	151° 20'.91 E
		33° 29'.00 S	151° 21'.08 E
		33° 29'.36 S	151° 21'.11 E
	starboard lateral light beacon	33° 28'.33 S	151° 20'.04 E
		33° 28'.29 S	151° 20'.09 E
		33° 28'.25 S	151° 20'.19 E
	starboard lateral beacon	33° 28'.93 S	151° 19'.50 E
		33° 29'.42 S	151° 21'.01 E
		33° 29'.39 S	151° 21'.34 E
		33° 29'.29 S	151° 21'.49 E

121* AUSTRALIA - QUEENSLAND - Hervey Bay - Woodgate - Light buoys permanently withdrawn.

Maritime Safety Queensland Notice 26/2003 (A7720).

Aus 817 [630/2002]

Delete	special light buoy	25° 05'.3 S	152° 34'.3 E
		25° 05'.7 S	152° 34'.5 E

122* AUSTRALIA - QUEENSLAND - Cairns - Pilot boarding place.

AMSA (zA253) & (A8630).

Aus 262 [76/2002]

Move	pilot boarding place from to	16° 46'.92 S	145° 52'.07 E
		16° 47'.0 S	145° 53'.0 E

Aus 373 [39/2003]

Move	pilot boarding place from to	16° 46'.9 S	145° 52'.1 E
		16° 47'.1 S	145° 52'.9 E

Aus 830 [NC 15/11/2002]

Move	pilot boarding place from to	16° 46'.92 S	145° 52'.07 E
		16° 47'.0 S	145° 53'.0 E

AU417145

Note: the ENC cell will be amended in the March 2003 update release.

AU5262_4

Note: the ENC cell will be amended in the March 2003 update release.

123* AUSTRALIA - QUEENSLAND - Osterland Reef - Depth northwards.
LADS HI 323, AHS MMI 2-5-21080 (A7635 & A8631).

Aus 831 [NE 17/05/2002]

Insert depth, 9₅ m, enclosed by contour

15° 30'.23 S

145° 28'.98 E

AU416145

Note: the ENC cell will be amended in the March 2003 update release.

124* AUSTRALIA - QUEENSLAND - Yule Entrance - Depths.
LADS HI 258(5), AHS MMI 3-1-20890 (A8134 & A8135) & (zA271).

Aus 837 [41/2003]

Insert accompanying block

10° 20'.0 S

143° 51'.0 E

125* AUSTRALIA - TORRES STRAIT - Caldbeck Reef - Light altered.

List of Lights Vol K/2003 -- 3282.00

Auscoast warning 015/03 (A8452), AMSA ATH 3/11 (A8454) & (zA270).

Aus 376 [97/2003]

Substitute beacon, Fl(4) 16s 10M, for east cardinal mark

10° 06'.4 S

143° 09'.9 E

Aus 837 [124/2003]

Substitute beacon, Fl(4) 16s 7m 10M, for east cardinal mark

10° 06'.3 S

143° 10'.0 E

Aus 839 [97/2003]

Substitute beacon, Fl(4) 16s 7m 10M, for east cardinal mark

10° 06'.3 S

143° 10'.0 E

AU411143

Note: the ENC cell will be amended in the March 2003 update release.

126* AUSTRALIA - NORTHERN TERRITORY - Cape Wessel - Light position.

List of Lights Vol K/2003 -- 3312.00

AMSA (A8130)

Aus 306 [184/2002]

Move light and racon from
to

11° 00'.22 S

136° 45'.33 E

11° 00'.37 S

136° 45'.50 E

Aus 715 [501/2002]

Move light and racon from
to

11° 00'.12 S

136° 45'.41 E

11° 00'.28 S

136° 45'.57 E

127* SOUTH AUSTRALIA - Fleurieu Peninsular - Wirrina Cove - Wreck; light buoy.

Former Notice - 757(P)/2002 is cancelled

Transport SA (A7666, A8126 & A8173).

Aus 345 [70/2003]

Insert danger circle, with legend Wk (2₃)
isolated danger spar light buoy, Fl(2) 10s, with topmark at
(a)

(a) 35° 29'.0 S

138° 09'.5 E

Aus 444 [70/2003]

Insert depth, 2₃ fm, enclosed by danger circle, with legend Wk

35° 29'.0 S

138° 09'.5 E

Delete depth 14fm

35° 29'.0 S

138° 10'.3 E

Aus 780 [697/2002]

Insert danger circle, with legend Wk (2₃)
isolated danger spar light buoy, Fl(2) 10s, with topmark at
(a)

(a) 35° 28'.95 S

138° 09'.51 E

128* SOUTH AUSTRALIA - Cape Banks - Well southwestwards.
OMV Australia Pty Ltd (A7685 & A8192).

Aus 348 [NC 9/11/2001]

Insert danger circle, with legend *Well*

38° 06'.22 S

140° 00'.58 E

Aus 4709 (INT 709) [322/2001]

Insert danger circle, with legend *Well*

38° 06'.22 S

140° 00'.58 E

129* AUSTRALIA - TASMANIA - Hobart - Little Sandy Bay - Pipeline.

Marine & Safety Tasmania (A8479), Hobart City Council (A8161).

Aus 171 [832/2002]

Insert discharge pipeline between

42° 54'.84 S

147° 21'.31 E

42° 54'.82 S

147° 21'.41 E

Aus 172 [45/2003]

Insert discharge pipeline between

42° 54'.837 S

147° 21'.332 E

42° 54'.823 S

147° 21'.405 E

130* AUSTRALIA - TASMANIA - Bell Bay - Beacon permanently discontinued.

Port of Launceston (A8169).

Aus 167 (plan, Bell Bay) [785/2002]

Delete port lateral beacon

41° 09'.37 S

146° 49'.63 E

131* AUSTRALIA - VICTORIA - Port Phillip - Williamstown - Harbour works completed.

Former Notice - 721(T)/2002 is cancelled

List of Lights Vol K/2003 -- 2351.00

Victorian Notice 02/2003 (A8492).

Aus 154 [672/2002]

Insert [accompanying block](#)

37° 52'.0 S

144° 54'.0 E

132(T)/2003 AUSTRALIA - NEW SOUTH WALES – Potato Point - Light buoy.
Fisheries New South Wales (A8636).

Fish aggregation device marked by a special light buoy, *Fl. Y. 5s*, exists in position 36° 07'.03 S 150° 09'.85 E.

Chart temporarily affected – Aus 807.

133(T)/2003 AUSTRALIA - NEW SOUTH WALES - Jervis Bay - Obstructions.

Date - Until 15 May 2003

MHQAUST (A8208, A8209 & A8589).

Ground mine shapes have been laid as follows:

<i>Position</i>	<i>Height above seabed</i>
35° 03'.75 S 150° 43'.04 E	
35° 03'.85 S 150° 43'.26 E	
35° 03'.94 S 150° 43'.45 E	
35° 05'.06 S 150° 43'.72 E	
35° 03'.66 S 150° 44'.75 E	
35° 03'.69 S 150° 44'.74 E	
35° 04'.09 S 150° 44'.57 E	
35° 04'.62 S 150° 44'.76 E	
35° 05'.43 S 150° 44'.53 E	
35° 05'.65 S 150° 45'.30 E	
35° 05'.97 S 150° 46'.52 E	0.5m
35° 06'.20 S 150° 46'.75 E	0.5m

Mariners are advised to navigate with caution in the area.

Chart temporarily affected – Aus 193.

134(T)/2003 AUSTRALIA - NEW SOUTH WALES - Forster - Light buoy.

Fisheries New South Wales (A8332).

Fish aggregation device marked by a special light buoy, *Fl. Y. 5s*, exists in position 32° 14'.27 S 152° 36'.95 E.

Chart temporarily affected – Aus 810.

135(T)/2003 AUSTRALIA - NEW SOUTH WALES - Tweed River - Dredging operations.

Date - Until 1 April 2003

NSW Dept Land & Water Conservation (A8622).

The dredge *Port Frederick* is operating 24 hours per day, at the entrance to the Tweed River (28° 10'.3 S 153° 33'.4 E). The dredge is discharging off Coolangatta Beach between 28° 10'.0 S 153° 33'.3 E and 28° 09'.7 S 153° 32'.2 E.

The dredge will maintain radio watch on VHF Ch 16.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected – Aus 220 – Aus 813 – Aus 814.

136(T)/2003 AUSTRALIA - QUEENSLAND - Point Danger to Weipa - Scientific instruments.

Former Notice - 610(T)/2002 is cancelled

Maritime Safety Queensland Notice 17(T)/2003 (A8400).

As of 21 January 2003 special light buoys, are on station in the positions (WGS 84) below. Craft are not to use these buoys as moorings. The most convenient chart is quoted.

<i>Location</i>	<i>Position</i>	<i>Characteristics</i>	<i>Chart affected</i>
* Main Beach	27° 57'.89 S 153° 26'.52 E	<i>Fl(5) Y. 20s</i>	Aus 814
* Point Lookout	27° 29'.58 S 153° 37'.53 E	<i>Fl(5) Y. 20s</i>	Aus 814
* Moreton Bay	27° 15'.01 S 153° 11'.92 E	<i>Fl(5) Y. 20s</i>	Aus 236
* Bribie Island	27° 04'.51 S 153° 12'.59 E	<i>Fl(5) Y. 20s</i>	Aus 236
* Arkwright Point	26° 34'.36 S 153° 07'.14 E	<i>Fl(5) Y. 20s</i>	Aus 365
* Lisa Jane Shoal	23° 18'.50 S 151° 04'.44 E	<i>Fl(5) Y. 20s</i>	Aus 247
* Bailey Islet	21° 02'.59 S 149° 32'.88 E	<i>Fl(5) Y. 20s</i>	Aus 249
* Townsville	19° 09'.37 S 147° 03'.80 E	<i>Fl(5) Y. 20s</i>	Aus 256
Double Island	16° 44'.04 S 145° 42'.54 E	<i>Fl(5) Y. 20s</i>	Aus 830
Albatross Bay	12° 40'.55 S 141° 45'.09 E	<i>Fl(5) Y. 20s</i>	Aus 4

* Indicates new or revised entry.

Chart temporarily affected – Aus 4 – Aus 236 – Aus 247 – Aus 249 – Aus 251 – Aus 256 – Aus 365 – Aus 814 – Aus 830 – AU413141– AU417145.

137(T)/2003 AUSTRALIA - QUEENSLAND - Bundaberg - Depth information.

Former Notice - 246(T)/2002 is cancelled

Maritime Safety Queensland Notice 32(T)/2002 (A8594).

Available depth as at 31 January 2003:

	<i>Metres</i>	
	<i>LAT</i>	<i>ISLW (Chart Datum)</i>
Sea Reach	9.5	9.7
Middle Reach	9.5	9.7
Inner Reach	9.5	9.7
Departure Channel	9.5	9.7
Swing Basin	8.0	8.2
Oil Berth	9.6	9.8
* BST Berth	12.0	12.2

* Indicates new or revised entry.

Chart temporarily affected – Aus 243.

138(T)/2003 AUSTRALIA - QUEENSLAND - Gladstone - Harbour works completed.

Former Notices - 249(T)/2000 & 248(T)/2002 are cancelled

Maritime Safety Queensland Notice 34/2003 (ZA268).

Cancel this notice on receipt.

Chart formerly affected – Aus 244 – Aus 245.

139(T)/2003 AUSTRALIA - QUEENSLAND - Magnetic Island – Bright Point – Harbour works completed.

Former Notice - 635(T)/2000 is cancelled

Maritime Safety Queensland Notice 323/2002 (A11558).

Cancel this notice on receipt.

Chart formerly affected – Aus 256 – Aus 827.

140(P)/2003 AUSTRALIA - QUEENSLAND - Fairway Channel - Light buoy; radar transponder to be established.

Date - On or about 10 March 2003

AMSA ATH 03/01 & 03/02 (A8510 & A8511).

West cardinal pillar light buoy, VQ(9) 10s, with topmark and *Racon(B)*, will be established in position 13° 54'.00 S 144° 17'.23 E.

Chart which will be affected – Aus 833 – AU414144.

141(P)/2003 AUSTRALIA - QUEENSLAND – Blanchard Reef - Light buoy to be established northeastward.

Date - On or about 11 March 2003

AMSA ATH 03/03 (A8512).

West cardinal pillar light buoy, Q(9) 15s, with topmark will be established in position 13° 17'.10 S 143° 51'.00 E.

Chart which will be affected – Aus 834 – AU414143.

142(P)/2003 AUSTRALIA - QUEENSLAND - Diamond Reign Reefs - Light buoy; radar transponder to be established.

Date - On or about 11 March 2003

AMSA ATH 03/04 & 03/05 (A8513 & A8514).

East cardinal pillar light buoy, Q(3) 10s, with topmark and *Racon(K)*, will be established in position 13° 11'.50 S 143° 47'.83 E.

Chart which will be affected – Aus 834 – AU414143.

143(P)/2003 AUSTRALIA - QUEENSLAND – New Reef - Light buoy to be established.

Date - On or about 12 March 2003

AMSA ATH 03/06 (A8515).

West cardinal pillar light buoy, VQ(9) 10s, with topmark will be established in position 13° 02'.10 S 143° 45'.60 E.

Chart which will be affected - Aus 834 – AU414143.

144(P)/2003 AUSTRALIA - QUEENSLAND – Osborn Channel - Light buoy; radar transponder to be established.

Date - On or about 12 March 2003

AMSA ATH 03/07 & 03/08 (A8516 & A8517).

East cardinal pillar light buoy, *VQ(3) 5s*, with topmark and *Racon(O)*, will be established in position 12° 59'.70 S 143° 43'.65 E.

Chart which will be affected – Aus 834 – AU413143.

145(P)/2003 AUSTRALIA - QUEENSLAND - Frederick Patches - Light buoy to be established.

Date - On or about 13 March 2003

AMSA ATH 03/09 (A8518).

Starboard lateral pillar light buoy, *Fl. G. 2.5s*, with topmark will be established in position 12° 52'.15 S 143° 38'.22 E.

Chart which will be affected – Aus 834 – AU413143.

146(P)/2003 AUSTRALIA - QUEENSLAND - Sunk Reef - Light buoy to be established.

Date - On or about 13 March 2003

AMSA ATH 03/10 (A8519).

Port lateral pillar light buoy, *Fl. R. 2.5s*, with topmark will be established in position 12° 51'.35 S 143° 38'.40 E.

Chart which will be affected – Aus 834 – AU413143.

147(T)/2003 AUSTRALIA - QUEENSLAND - Snake Creek - Wreck.

Maritime Safety Queensland Notice 30(T)/2003 (A8201). The wreck is MV *Teresa B.*

A dangerous wreck exists in position 16° 43'.1 S 141° 09'.1 E.

Chart temporarily affected – Aus 303 – Aus 410.

148(T)/2003 SOUTH AUSTRALIA - Port Adelaide - Light beacon re-established in position.

Former Notice - 87(T)/2003 is cancelled

List of Lights Vol K/2003 -- 2059.70

Transport SA Notice 5/2003 (A8620).

Cancel this notice on receipt.

Chart formerly affected – Aus 137

149(T)/2003 AUSTRALIA - VICTORIA - Port Phillip - Pile maintenance.

Date - Until 31 March 2003

Victorian Notice 06(T)/2003 (A8596).

Pile maintenance is taking place throughout Port Phillip, outside main shipping channels.

All work is carried out during daylight hours and floating plant, including MV *Pindar*, will be appropriately marked.

The work site can be contacted on VHF Ch 16 and mobile telephone number 0418 599 397.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected – Aus 143 – Aus 144 – Aus 155 – Aus 157 – Aus 158.

150(T)/2003 AUSTRALIA - VICTORIA - Western Port - Pile maintenance.

Date - Until 3 May 2003

Victorian Notice 05(T)/2003 (A8595).

Pile maintenance is taking place throughout Western Port, outside main shipping channels.

All work is carried out during daylight hours and floating plant, including MV *Perth*, will be appropriately marked.

The work site can be contacted on VHF Ch 12 and mobile telephone number 0418 657 402.

Mariners are advised to navigate with caution in the area.

Chart temporarily affected – Aus 150 – Aus 151 – Aus 152.

III

NAVIGATION WARNINGS

The following radio messages have been received during the period to 7 February 2003. Signal copies of these messages may be destroyed. It is recommended that the reprint of Navigational Warnings should be kept in a file or a book divided into areas. Cancellation should be made on receipt of signals and reprints.

Rigs on location other than those listed in the latest Section III summary are the subject of Radio Navigational Warnings. Rigs in transit will not be the subject of Warnings.

AUSCOAST WARNING

017 Cancelled.
 018 NW Coast. Drill rig *Glomar Jack Ryan* in position 13° 42'.3 S 121° 43'.9 E. 2.5M clearance requested.
 019 NW Coast. Drill rig *Atwood Falcon* in position 22° 52'.3 S 113° 17'.4 E. 2.5M clearance requested.
 020 Cancelled.
 021 Cancelled.
 022 Cancelled.
 023 Cancelled.
 024 Cancelled.
 025 NW Coast. Drill rig *Ensco 56* in position 20° 41'.9 S 115° 33'.9 E. 2.5M clearance requested.
 026 Cancelled.
 027 Cancelled.
 028 Cancelled.
 029 Cancelled.
 030 SW Coast. Drill rig *Ensco 53* in position 29° 22'.2 S 114° 53'.2 E. 2.5M clearance requested.
 031 SE Coast. Drill rig *Sedco 702* in position 38° 12'.8 S 148° 35'.5 E. 2.5M clearance requested.
 032 NW Coast. Rowley Shoals light K1674 (17° 31'.1 S 118° 56'.8 E) reported unlit.
 033 NW Coast. Cunningham Islet Racon ALARS 87300 (17° 31'.3 S 118° 57'.1 E) temporarily discontinued.
 034 Cancelled.
 035 Cancelled.
 036 Cancelled.

NAVAREA X WARNINGS

001 Cancelled.
 002 Cancelled.
 003 Cancelled.

Navigational warnings in force as at 060001UTC FEB 03.

Auscoast

2002 - 310 331 357 364 376.

2003 - 005 015 018 019 025 030 031 032 033.

Navarea X

2002 - 001.

Summary of mobile drilling rigs as at 060001UTC FEB 03.

Name	Position
Glomar Jack Ryan	13° 42'.3 S 121° 43'.9 E
Ensco 56	20° 41'.9 S 115° 33'.9 E
Atwood Falcon	22° 52'.3 S 113° 17'.4 E
Ensco 53	29° 22'.2 S 114° 53'.2 E
Sedco 702	38° 12'.8 S 148° 35'.5 E

NAVAREA XIV WARNINGS

021 Cancelled.
 022 Drill rig *Ocean Bounty* in position 39° 26'.00 S 173° 15'.00 E. 2.5m clearance requested.
 023 Cancelled.
 024 Cancelled.
 025 Cancelled.
 026 Cancelled.
 027 Cancelled.
 028 Cancelled.
 029 Cancelled.
 030 Cancelled.
 031 Hazardous operations commencing daily 06 through 09 February in area bounded by 21° 12'.0 S 135° 42'.0 W; 9° 14'.0 S 134° 29'.0 W; 10° 06'.0 S 121° 10'.0 W; 22° 04'.0 S 121° 35'.0 W.
 032 Cancelled.

Navarea XIV warnings in force as at 060001UTC FEB 03.

016 018 022 031.

IV

HYDROGRAPHIC REPORTS

<i>Locality</i>	<i>Report</i>	<i>Ship/Authority</i>	<i>Observer</i>
NT- Darwin	Buoyage	HMAS <i>Leeuwin</i>	
INDIAN OCEAN- Arabian Gulf	Chart discrepancies Obstructions Buoyage	HMAS <i>Arunta</i>	